

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

8-Oct-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8583 B

1 pc	Front o/s fender	\$	384.00
1 pc	Front o/s fender inner shield	\$	120.00
1 pc	Front o/s fender protector	\$	34.00
1 pc	Front o/s wheel cover	\$	116.00
1 pc	Front o/s door	\$	791.00
2 pcs	Front o/s door hinge @\$34.00	\$	68.00
1 pc	Rear o/s door	\$	765.00
2 pcs	Rear o/s door hinge @\$34.00	\$	68.00
1 pc	Rear o/s wheel cover	\$	116.00

S/NETT

1 pc	Front o/s fender sticker	\$	30.00
1 set	o/s door stickers	\$	100.00
1 pc	Rear o/s fender sticker	\$	60.00
1 set	Front o/s fender inner shield clips	\$	28.00

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Towing fee \$ 50.00

Sundry \$ 50.00

To check wheel alignment Front & Rear \$ 160.00

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. \$ 180.00

To dismantle / refit inner components of the Front o/s door into new shell door \$ 150.00

To dismantle / refit inner components of rear o/s door onto new shell door \$ 150.00

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, rear o/s fender, rear bumper, o/s rocker panel garnish \$ 850.00

To putty and spray painting on Front bumper, front o/s fender, front o/s door, rear o/s door, rear o/s fender, rear bumper, o/s rocker panel garnish \$ 1,400.00

To apply rustproofing on the repaired and replaced panels. \$ 250.00

\$ 5,673.80

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.



Victory Recovery (Business Reg No.: 53096358B)
65 Teban Gardens Rd #23-617, Singapore 600065.
Mobile: 9618 0311 Fax: 6267 8996

CASH /
W.O. No. 96501

TOW JOB WORKS ORDER

M Premier Taxi Svc Date 8/10/08
Car Make/Model Kia Vehicle No. S4B 8583B
M'ship/NRIC No./Card No. _____ Contact No. _____
Time - Rec'd 13.15 Arrived 14.00 Completed 15.00
Amount Charge S\$ _____ Tow Truck No 718888
Destination (from) 205 Boon Lay Dr (to) Changi
Remark (if any) _____

Tow Driver's Signature [Signature] Member's Signature _____

- | | | |
|---|---|--|
| <input type="checkbox"/> Change Tyres & Towing | <input type="checkbox"/> Using King Dolly | <input type="checkbox"/> Use Car Carrier |
| <input type="checkbox"/> Basement / Multi Carpark | <input type="checkbox"/> Low Spoiler / Low Oil Sump | <input type="checkbox"/> Release Brake / Shaft |
| <input type="checkbox"/> Causeway / 2nd Link | <input type="checkbox"/> Accident / Over-turn | <input type="checkbox"/> Loaded |

Note : The owner or his representative is required to follow along to the towing destination, failing which the tow operator shall not be liable for any alleged damages to the car nor missing items from the same. Vehicle is towed at owner's risk. The tow operator accepts no responsibility for any damages to the owner's vehicle whilst being towed.