

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

8-Oct-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8583 B

1 pc	Front o/s fender	Part	\$	384.00
1 pc	Front o/s fender inner shield	X on	\$	120.00
1 pc	Front o/s fender protector	X on	\$	34.00
1 pc	Front o/s wheel cover	hood	\$	116.00
1 pc	Front o/s door	Part	\$	791.00
2 pcs	Front o/s door hinge @\$34.00	X on	\$	68.00
1 pc	Rear o/s door	X on	\$	765.00
2 pcs	Rear o/s door hinge @\$34.00	X on	\$	68.00
1 pc	Rear o/s wheel cover	X on	\$	116.00

### S/NETT

1 pc	Front o/s fender sticker	X on	\$	30.00
1 set	o/s door stickers	on	\$	100.00
1 pc	Rear o/s fender sticker	on	\$	60.00
1 set	Front o/s fender inner shield clips	X on	\$	28.00

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Less 10%

Acknowledged by Repairer

Signature:

Date:

Towing fee	\$	50.00
Sundry	\$	50.00
To check wheel alignment Front & Rear	\$	160.00
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00
To dismantle / refit inner components of the Front o/s door into new shell door	\$	150.00
To dismantle / refit inner components of rear o/s door onto new shell door	\$	150.00
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, rear o/s fender, rear bumper, o/s rocker panel garnish	\$	850.00
To putty and spray painting on Front bumper, front o/s fender, front o/s door, rear o/s door, rear o/s fender, rear bumper, o/s rocker panel garnish	\$	1400.00
To apply rustproofing on the repaired and replaced panels.	\$	250.00
	\$	5,673.80

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.