

(08/11/17)

Surveysor

REF: ASM(AXA)

18486/11ear 75978

ASSIGNMENT

From: Date: 19/10/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLS 636Z
at Workshop m/s: Weemes Automotive
of: No. 2 Jalan pesawat

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Dereko 9818 7217

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLS 636Z Yr Regn: 2017 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BENTLY BENTAYHA 604T C.C. 5950

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 8467 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: S JAA B14V 6H C015585

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ order / Jammed / Leaked / Burnt orBrake: ☒ order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 265/45R21

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 67/10/18

D.O.I. 19/10/18

Survey held at

WEARNS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)