

SERVICE ESTIMATE

88160 - C00001 SL: SERVICE SALES - PC

Mr Jacky Choo See Wee
12A Cairnhill Rise
#10-06

Singapore 229746

Closed by : Richmond Ho
Svc Consultant :
Remarks : Mr Jacky Choo See Wee

GST Reg.No:M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 10/10/2018
WIP No. . : 31743
Veh.In/Out: 08/10/2018
*Tel.No. . : Mobile: 98155389
Reg.No. . : SLS636Z
Reg.date . : 01/11/2017
Mileage .. : 0
Chassis No: SJAAB14V6HC015589

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802 TO REPLACE REAR BUMPER, REAR
BRACKET, REAR CHROME TRIM,
REAR SPOILER, ETC

0 5600.00 0 5,600.00 S ~~2800~~

800 TO PUTTY SPRAY PAINT ON REAR
BUMPER, ETC

0 3300.00 0 3,300.00 S ~~1100~~

287 TO CHECK WIRING INCLUDE
RESETTING OF ALL ELECTRICAL
MODULES

0 1750.00 0 1,750.00 S

BUMPER COVER PRIMED
FRAME

1.0 EA 11638.40 11,638.40 S ~~at~~

MOUNTING PLATE

1.0 EA 2193.70 2,193.70 S ?

MOUNTING PLATE

1.0 EA 160.90 160.90 S ~~ne~~

MOUNTING

1.0 EA 160.90 160.90 S ~~ne~~

MOUNTING

1.0 EA 160.90 160.90 S ~~ne~~

RETAINER FOR ULTRASO

1.0 EA 102.40 102.40 S ~~ne~~

RETAINER FOR ULTRASO

1.0 EA 102.40 102.40 S ~~ne~~

RETAINER FOR ULTRASO

1.0 EA 102.40 102.40 S ~~ne~~

SERVICE ESTIMATE

88160 - C00001 SL: SERVICE SALES - PC

Mr Jacky Choo See Wee

12A Cairnhill Rise

#10-06

Singapore 229746

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Jacky Choo See Wee

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 10/10/2018

WIP No. . : 31743

Veh.In/Out: 08/10/2018

*Tel.No. . : Mobile: 98155389

Reg.No. . : SLS636Z

Reg.date. : 01/11/2017

Mileage . : 0

Chassis No: SJAAB14V6HC015589

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	RETAINER FOR ULTRASO	1.0 EA	102.40			102.40 S	ne
	COVER FOR TOWING EYE	1.0 EA	255.60			255.60 S	X
	COVER FOR TOWING EYE	1.0 EA	255.60			255.60 S	X
	HOLDING STRAP	1.0 EA	188.40			188.40 S	ne
	GUIDE PROFILE	1.0 EA	555.80			555.80 S	} ?
	GUIDE PROFILE	1.0 EA	555.80			555.80 S	
	GUIDE PROFILE	1.0 EA	175.20			175.20 S	
	GUIDE PROFILE	1.0 EA	175.20			175.20 S	
	BUMPER CARRIER	1.0 EA	1901.20			1,901.20 S	? ?
	GUIDE SECTION	1.0 EA	555.80			555.80 S	} ne
	TRIM FOR BUMPER CTR	1.0 EA	381.40			381.40 S	
	TRIM FOR BUMPER RHR	1.0 EA	409.60			409.60 S	
	TRIM FOR BUMPER LHR	1.0 EA	409.60			409.60 S	
	TRIM FOR LICENCE PLA	1.0 EA	410.20			410.20 S	X
	REFLECTOR LHR	1.0 EA	68.30			68.30 S	X
	REFLECTOR RHR	1.0 EA	68.30			68.30 S	X
	TRIM FOR EXHAUST TAI	1.0 EA	1407.60			1,407.60 S	B/-

SERVICE ESTIMATE

88160 - C00001 SL: SERVICE SALES - PC

Mr Jacky Choo See Wee
12A Cairnhill Rise
#10-06

Singapore 229746

Closed by : Richmond Ho

Svc Consultant :

Remarks : Mr Jacky Choo See Wee

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 3

Inv.date. : 10/10/2018

WIP No. . : 31743

Veh.In/Out: 08/10/2018

*Tel.No. . : Mobile: 98155389

Reg.No. . : SLS636Z

Reg.date. : 01/11/2017

Mileage . : 0

Chassis No: SJAAB14V6HC015589

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

BODY PANEL SEALANT X	1.0 EA	942.20				942.20	SX
ADHESIVE SEALER FL2	1.0 EA	549.10				549.10	SM
REAR SPOILER	1.0 EA	11802.50				11,802.50	SCRA

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair
Hp 90010068
4 days
19/10/18 @ 1230

Gross Total. 46,602.70

Labour Total	10,650.00
Parts Total	35,952.70
Package Total	0.00

Net.....	46,602.70
GST @ 7.0%	3,262.19
Total.....	49,864.90
Paid.....	0.00
Please Pay..	49,864.90

GST: S=StdRated; O=OutOfScope; Z=ZeroRated