


CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D



FALCON-AIR

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building 78 Shenton Way #07-16
079120

Attention : Motor Claim Department
Contact : 6419 3000

Estimate : ES707185

Date : 11/10/2018
Vehicle Num. : SGV 289K
Make/Model : TOYOTA WISH
Chassis/Eng# :
Accident Date : 11/10/2018
Claim No. :
Reference :
Policy No. :

not Allocated
nbl
n/s ~~44~~ 44501
11/10/18
take photo After repair
5 day.

S/N	Quantity	Particular	Unit Price	Amount S\$
		<i>Subs. of Mr. Ather</i>		

LIST ITEMS :				
1.	1PC	REAR BUMPER	266.10	1,258.30
2.	10PCS	REAR BUMPER CLIP		68.00
3.	2PCS	REAR BUMPER SIDE RETAINER		131.60
4.	1PC	N/S REAR FENDER		1,321.20
5.	1PC	N/S REAR FENDER GLASS MOULDING		128.80
6.	1PC	N/S REAR DOOR		1,345.60
7.	1PC	N/S REAR DOOR WEATHERSTRIP		245.30
8.	1PC	N/S TAILLAMP		586.40
9.	1PC	N/S REAR WHEEL BEARING		715.50
10.	1PC	N/S REAR SHOCK ABSORBER		355.10
11.	1PC	REAR AXLE		2,315.10
List TotalS\$:				8,470.90
25.00% Discount S\$:				2,117.73
				6,353.17

SPECIAL NETT ITEMS :			
1.	1PC	N/S REAR FENDER GLASS SEALANT	50.00
2.	1PC	N/S REAR FENDER GLASS INNER SEAL	50.00
3.	1PC	N/S REAR DOOR WIND DEFLECTOR	80.00
4.	1PC	N/S REAR RIM	300.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg **E-mail:** email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

FALCON-AIR

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building 78 Shenton Way #07-16
079120Attention : Motor Claim Department
Contact : 6419 3000**Estimate : ES707185**Date : 11/10/2018
Vehicle Num. : SGV 289K
Make/Model : TOYOTA WISH
Chassis/Eng# :
Accident Date : 11/10/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
5.	1PC	N/S REAR TYRE	11	200.00
6.	1PC	N/S REAR DOOR SEALANT	11	80.00
Special Nett Total S\$:				760.00
LABOUR :				
TO CHECK LIGHT SYSTEM AND WIRING				50.00
WATERTEST TO CHECK FOR LEAKAGE			11	50.00
TRANSFER DOOR PARTS				100.00
TO DROP FUEL TANK TO FACILIATE REPAIRS N FIX BACK				150.00
REPLACE REAR UNDERCARRIAGE			11	280.00
ANTI-RUST				100.00
TO APPLY BODY SEALANT ON BODY JOINTS				100.00
TO REMOVE/REFIT INNER TRIMS, GARNISHES, SEAT ETC				180.00
TO REMOVE/REFIT FENDER GLASS				120.00
LABOUR/PANEL BEATING				1,200.00
SPRAY PAINTING				1,200.00
INSTALL TYRE AND BALANCING			11	50.00
COMPUTERISED WHEEL ALIGNMENT				120.00
Labour Total S\$:				3,700.00

E. & O.E. Total S\$: 10,813.17

for FALCON AIR AUTO SERVICES PTE LTD

(TAMPINES BRANCH)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg