

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0020487
Ang Ah Pi

Page 1 of 1
Your ref. TP-SH 7403H India
Job No. 69902
Our ref. 18.10.16
Payment
Date 17/10/2018

Attn

Vehicle No SKJ 5386X
Vehicle Model : Honda Civic
Accident on ... 7/10/2018

Not Authorized
LLP & ?
Running After Paint 3days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Front headlamp RH	912.30	20.00	729.84
1.00	Pc	Front bumper	631.30	20.00	505.04
10.00	Pcs	Front bumper clips	3.00	20.00	24.00
1.00	Pc	Front bumper side holder RH	18.90	20.00	15.12
10.00	Pcs	Front radiator grille clips	3.00	20.00	24.00
1.00	Pc	Front radiator grille base	224.60	20.00	179.68
1.00	Pc	Front radiator grille logo emblem	28.60	20.00	22.88
1.00	Pc	Engine lower cover	87.50	20.00	70.00
Labour & Misc:					
1.00		To knock dents on front fender RH and renew of parts	300.00		300.00
1.00		To spray paint			400.00

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."