Ah Lim Motor Company 10 Ang Mo Kio Industrial Park 2A

#01-09 AMK Autopoint Singapore 568047



SGD

TBA

Claim Reference:

Assessment Number: AH000943

Version: AHLIM001/1

Date Calculated: 03/10/2018 06:10

Full Report - V1 Registration: SGL5148D Printed: 03/10/2018 13:10

# SURVEYOR COP

Able to Authorise Repairs: TBA

**Summary Information** 

Claim

Location:

Printed by:

Authorisation Status: Work Provider:

Claim Reference: Policy Number: Other Reference: Third Party: Insured Amount: Under Warranty: Warranty Expired: Singapore (SG) Ahlim ahlim

Interim

AXA Insurance S'pore Pte

Estimated Repair Time: Quote Due Date: Actual Repair Days: Parts Ordered Date: Hire Car Start:

Hire Car End: Vehicle Collected:

Vehicle Details

Vehicle Manufacturer:

Model: Sub Model:

Model Sheet Number:

Registration:

Registration Month: Registration Year:

VIN Number:

Manufacture Year:

Odometer:

Colour:

Engine Number: Fuel Level:

1ZZ2697869

TOYOTA

YCW 01 SGL5148D

BASE MODEL

September

Not Known

ZNE100326617

Wish

2006

2006

**Model Specs** 

Currency:

Date of Incident:

Repairs Authorised:

TWO COAT METALLIC

PREPARE OFF VEHICLE

Not Michary Repairs Eday,

**Vehicle Condition** 

**Vehicle Status** 

Pre-Accident Condition: Steering:

Brakes Pedal Travel: Place of Inspection: Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR: Damage Areas:

Severity of Impact:

Vehicle Status on Inspection:

Date of Inspection:

03/10/2018

Tread Depth RHF: Tread Depth RHR: Direction of Impact:

## **Ah Lim Motor Company**


Claim Reference:


**Assessment Number: AH000943** 

Version: AHLIM001/1

Date Calculated: 03/10/2018 06:10

Full Report - V1 Registration: SGL5148D Printed: 03/10/2018 13:10





#### **Addresses**

Cost Summary	Summary
--------------	---------

Total Labour	\$427.50	
Total Paint/Material	\$109.73	
Total Parts	\$883.20	
Excess:	TBA	
Grand Total Exc GST:	\$1,420.43	
7 % GST:	\$99.43	
Grand Total Inc GST:	\$1,519.86	

**Repair Information** 

LABOUR	Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
	Price/Dent = \$45.00/HR

		Price/ Delit = \$45.00/ 11K		
Repair /			0 - 1 D-1 (4)	
Guide Num	ber Repair Details	WU	Cost Price (\$)	
810151A	ADJUST HEADLAMP	3.0	13.50	
520011)	R + R FRONT BUMPER	3.0	13.50	
520011)	RENEW FRONT BUMPER (REMOVED)	6.0	27.00	
	INCLUDES: REQUIRED ATTACHED PARTS			
	REMOVE AND REFIT			
810051)	R + R RIGHT HEADLAMP	7.0	31.50	
0742	REPAIR R/F WING	~~ 10.0* X	45.00	
L	ABOUR COST			
	Total Work Units	29.0		
	<b>Corrosion Protection External Labour</b>	0.0HRS	0.00	
	<b>Corrosion Protection Internal Labour</b>	0.0HRS	0.00	
	Sub Total	2.9HRS	\$130.50	
	Paint Labour	6.6HRS	\$297.00	
	Total Labour	9.5HRS _	\$427.50	

PAINT WOR	K .	Time Basis 10 WU = 1 HR. Price	e = \$45.00/HR
<b>Guide Numb</b>	er Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
281	FRONT BUMPER REPAIR PAINT PLAST	IC <b>16.0</b>	
742	R/F WING REPAIR PAINTING >50%	17.0	
LA	ABOUR COST - PAINT		
	TIME(PAINT)	33.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Pair	nt 0.0	
	Total Work Units (10WU/HR)	66.0	
	Total Paintwork Labour	6.6HRS	\$297.00

### **Ah Lim Motor Company**

Claim Reference:

**Assessment Number: AH000943** 

Version: AHLIM001/1

Date Calculated: 03/10/2018 06:10

Full Report - V1 Registration: SGL5148D Printed: 03/10/2018 13:10

MATERIAL COST - PAINT	Cost Price
Repair Painting	\$16.59
Repair Painting Plastic	\$51.84
Material-Const Main Work Plastic	\$12.70
Total Excluding Pearlescent Uplift	\$109.73
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$109.73

					Pr	ice Valid	1: 01/06/2015
Guide No.	.Qty	Description	Part Number	Supplier	2 10.	Bet.	Price (\$)
281	1	FRONT BUMPER	52119 68010A0	"	m/mg	0% 01	
318	1	R/F BUMPER BRACKET	52115 68010			0%	₹ 30.00* X
340	1	FRONT BUMPER SUPPORT	52021 68010			0%	95.00* 7
341	1	FRT BUMPER ABSORBER	52611 68010			0%	68.00U X
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS	S		0%	30.00*
562	1	R/F HEADLAMP	81130 68010			0%	64 325.00° €
f: OEM Par	rts		Sub Total				\$768.00
g: Original			Mark Up Fro	om Cost	(15%)		\$115.20
h: Second			Total Parts		,		\$883.20
n: Darallel							

p: Parallel x: Exchange

**PARTS** 

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

<b>Total Extras</b>		\$0.00
		\$883.20
85.50	\$130.50	
	\$297.00	
		\$427.50
		\$109.73
		\$1,420.43
		\$99.43
		\$1,519.86
		85.50 \$130.50

#### **Assessment Notes**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: