



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/III(SHD4692K)
DOA:04/10/2018@1420

INDIA INTERNATIONAL INSURANCE PTE LTD

10/10/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SKE 2380 H - B.M.W. 116I AT ABS D/AIRBAG 2WD HID 5DR

CHASSIS NO: WBA1A12040E948809 (2012)

1 pc	Front headlamp LH	\$	1,801.75	Panel
1 pc	Front headlamp lower bracket LH	\$	81.50	4p 90010068
1 pc	Front fender LH	\$	546.00	5 days
1 pc	Front bumper	\$	825.50	4/3
1 pc	Front bumper retainer LH	\$	12.00	12/10/18 @ 1135
		\$	3,266.75	
		\$	326.68	
		\$	2,940.07	
	Alignment	\$	70.00	Refy after repair
	Repair and respray front rim LH	\$	100.00	
	check wiring function	\$	40.00	
	Remove necessary parts: jacking, panel beating, repair and straighten front fender LH and front door LH bumper	\$	500.00	
	Putty and respray front fender LH and front bumper.	\$	450.00	
		\$	4,100.07	
		\$	287.00	
		\$	4,387.07	

Note: The above is an estimate only. If other parts requested during the course of repair, we will inform you accordingly.

All new/O.E.M/used parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: