

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #24-01 AXA TOWER
068811

Attention : Motor Claim Department
Contact : 68804888 Fax No. : 880 4838

Estimate : ES201884

Date : 05/10/2018
Vehicle Num. : SLK 4378J (LCR)
Make/Model : HONDA VEZEL HYBRID
Chassis/Eng# :
Accident Date : 04/10/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT DOOR - LH		1,042.00
2.	1	REAR DOOR - LH		1,080.00
3.	1	REAR DOOR LOWER HINGE LH		98.20
4.	1	REAR DOOR SUB RUBBER SEAL LH CENTRE		68.00
5.	1	REAR FENDER WHEEL ARCH MOULDING LH		163.80
6.	1	SIDE SKIRT LH		258.60
7.	1	REAR DOOR POWER WINDOW REGULATOR LH		399.40
List Total S\$:			2544.40	3,110.00
20.00% Discount S\$:				622.00
			2035.52	2,488.00
SPECIAL NETT ITEMS :				
1.	1SET	FRONT DOOR INNER TRIM COVER CLIPS		30.00
2.	1SET	REAR DOOR INNER TRIM BOARD CLIPS		30.00
3.	1SET	REAR FENDER WHEEL ARCH MOULDING CLIPS		30.00
4.	1SET	SIDE SKIRT CLIPS		30.00
Special Nett Total S\$:			60	120.00
LABOUR :				
TRANSFER DOOR MECHANISM (X2 DOORS)				
WIRINGS CHECK AND RECTIFY WHERE NECESSARY				
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS				
			120	360.00
			30	1,200.00
			900	800

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #24-01 AXA TOWER
 068811

Attention : Motor Claim Department
 Contact : 68804888 Fax No. : 880 4838

Estimate : ES201884

Date : 05/10/2018
 Vehicle Num. : SLK 4378J (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 04/10/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

PUTTY AND SPRAY PAINT ALL AFFECTED AREAS
 (PEARL WHITE, INNER/OUTER)

800 / 1000 1,400.00

DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE
 REPAIRS AND REACTIVATE BACK SAME
 (HV HYBRID SYSTEM SAFETY PROCEDURES)

300 450.00

PERFORM VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT
 CODES AND REINITIALISING HV HYBRID SYSTEM
 (HV HYBRID SYSTEM SAFETY PROCEDURES)

300 450.00

Labour Total S\$:

\$2350 3,860.00

NBZ LKK
 11/10/18 1200
 P/P
 6 DAYS

CHECK ITEMS PHOTOS
 BEFORE PAINT PHOTOS.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

E. & O.E.

Total S\$: 6,468.00

for WORLD AUTO PTE LTD

PARTS \$2544.40
 LESS 20% \$2035.52

SINNET \$ 60

LABOUR \$2350

\$4445.52 / 6 REPAIR DAYS