

INS. CASE OWNER:

cc3, MG180 18527, Gea3s2

LKK: IDAC:

Surveyor: X6W

ASSIGNMENT
DOI: 5-10-18

Date / Time: 5-10-18
Registered in Merimen: 11-10-18

Pre-assign / CCU / FTE

SLX 4052E



Insured Vehicle No. : _____
Name of Insured : _____
Insured Tel No. : _____ HP: _____
Excess Sec II :SS _____ D.O.A: 3-10-18
Is driver the owner? (YES / NO) Nature of Accident : _____

Claim No. : _____
Policy No. : _____
Make / Model : _____
Place of Accident : _____

If NO, Driver Name / Age : _____
Driver Tel No. : _____

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Insured Liability : % Final ? Yes / No

SHF 615 A



INSRS: Trans Cab
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/Time	STAGE	DATE / PIC
<u>16/10</u>	Non-Reporting ltr (1st):	
<u>16/10</u>	Non-Reporting ltr (2nd):	
<u>16/10</u>	Non-Reporting ltr (Final):	
<u>16/10</u>	Notification ltr (if non-pickup):	
<u>15/11/19</u>	Call OI: <u>MSMR 01-03-19</u>	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE	Date/Time: _____	Sent By: _____
FINALIZATION	Date/Time: _____	Confirm with: _____
Repair Cost: <u>45</u>	S\$ <u>5,150</u> (<u>5</u> days) Reduction: <u>90</u> %	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: <u>15/11/19</u> Confirm with: <u>Ng Wai Yin</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% IOD (Agreed / Assessed) BOLA S/N No. : <u>37</u>	If NO or B 28, Ass. Lia :
Repair Cost: <u>(21/450)</u>	S\$ <u>5,510.50</u> <u>OID REPR ENDED TP.</u>	
Loss of Rental (LOR):	S\$ <u>695.24</u> (<u>7</u> days) x \$ <u>99.32</u>	
Loss of Use (LOU):	S\$ - (\$ - x - days)	
Loss of Income (LOI):	S\$ - (\$ - x - days)	
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]	
GIA/LTA Search	S\$ <u>7.49</u>	
Medical:	S\$ -	1) Claim status: <u>Normal/Reject/Private Settle</u>
Disbursement:	S\$ - (e.g. Tow/Independent)	2) Report Format: <u>TP</u>
Legal Cost	S\$ -	3) Survey fee: <u>\$320</u>
Total:	S\$ <u>6,213.23</u> Global Sum SS:	
FINAL PAYMENT	Date/Time: _____	Confirm with: _____
Payee 1:	S\$ <u>6,213.23</u> Name 1: <u>TRANS-CAB SERVICES PTE LTD</u>	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 2: (Strike if N.A.)	SS _____ Name 2: _____	
Payee 3: (Strike if N.A.)	SS _____ Name 3: _____	

Signature

Xme

C3878K

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Trans - awb
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SUF615A Yr Regn: 27 Jun 2014
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Renault Latitude c.c 1995
 Colour: Whitened A/C: Insured / Std / NI / NA
 Sp. Reading: 295215 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: VFIABCL15AUC278 494
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or _____
 Brake: Good / Jammed / Leaked / Burnt or _____
 Modi: Nil S/Rim / STD A/Rim or _____
 Tyre Size: F: 215/60R16
 R: 4

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rport.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

N/S	O/S
	<u>0</u>

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FALKEN
 Front _____ Rear _____
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. _____ D.O.I. 05-10-18
 Survey held at W/S 3:10pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	(L/S \$ 5,150.00 / Red \$ 44,682.55 / 90%)
	5 days + 1 Sunday + 1 PRS = 7 days

Date/Time, File Pass to? : Preli. Report : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Survey Fee: _____
 Transportation: _____

Report Format : _____
 Lump Sum / I.B.I: (\$) _____

Add Fee: : Site Insp (\$) _____) S + RS, SI
 : Interview (\$) _____) Photos
 : Tech. Invs (\$) _____) Others
 : Weekend (\$) _____) _____

TOTAL _____

Trans-cab Auto Services Pte Ltd

AAD1810-058

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 615A

VF1ABL15AUC278494

RENAULT

LATITUDE

3.10.2018

AIG

	PART		LIST
1	1 BUMPER COVER REAR <i>Re</i>	\$	1,108.46 -
2	1 BUMPER LOWER REAR <i>cut</i>	\$	768.84 -
3	1 BUMPER BRACKET CTR REAR <i>? NN</i>	\$	113.47
4	1 BUMPR BRACKET SIDE RH REAR <i>? NN</i>	\$	135.97
5	1 BUMPR RETAINER RH REAR <i>X S/NP NN</i>	\$	44.99
6	1 BUMPER REFLECTOR RH <i>X</i>	\$	43.61
7	1 BUMPR BRACKET SIDE LH REAR <i>? NN</i>	\$	135.97
8	1 BUMPR RETAINER LH REAR <i>X NN</i>	\$	44.99
9	1 BUMPER REFLECTOR LH <i>cut</i>	\$	43.61 -
10	1 BUMPER BEAM REAR <i>X BT</i>	\$	777.52 -
11	1 BUMPER BEAM BRACKET LH REAR <i>? NN</i>	\$	225.95
12	1 BUMPER BEAM BRACKET RH REAR <i>? NN</i>	\$	225.95
13	1 BOOT REAR <i>X repair.</i>	\$	2,872.68
14	1 BOOT FINISHER <i>X NN</i>	\$	470.06
15	1 BOOT WHEATERSTRIP <i>cut</i>	\$	323.05 -
16	1 BOOT REFLECTOR LAMP LH <i>X S/NP</i>	\$	493.35
17	1 BOOT REFLECTOR LAMP RH <i>X S/NP</i>	\$	493.35
18	1 BOOT BADGE 'RENAULT' <i>cut</i>	\$	225.36 -
19	1 BOOT BADGE <i>cut</i>	\$	225.36 -
20	1 BOOT STRUT LH <i>X</i>	\$	276.08
21	1 BOOT STRUT RH <i>X</i>	\$	276.08
22	1 BOOT HINGE LH <i>X</i>	\$	367.84
23	1 BOOT HINGE RH <i>X</i>	\$	367.84
24	1 BOOT INNER TRIM <i>X</i>	\$	586.45
25	1 BOOT SWITCH <i>X</i>	\$	168.13
26	1 BOOT LOCK <i>X</i>	\$	202.67
27	1 BOOT LOCK CATCH <i>X</i>	\$	74.40
28	2 LICENCE PLATE LAMP <i>X</i>	\$	50.52
29	2 BOOT RUBBER PLUG <i>X</i>	\$	221.81

Trans-cab Auto Services Pte Ltd

AAD1810-058

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

30	1 FENDER PANEL REAR LH	X		\$	3,299.13
31	1 WHEELARCH REAR LH	X		\$	543.47
32	1 FENDER PANEL INNER TRIM REAR RH	X	} <i>an</i>	\$	671.45
33	1 FENDER PANEL REAR RH	X		\$	3,299.13
34	1 WHEELARCH REAR RH	X		\$	543.47
35	1 TAILLAMP RH	X		\$	552.55
36	1 TAILLAMP PANEL RH	X		\$	986.70
37	1 TAILLAMP LH	X		\$	552.55
38	1 TAILLAMP PANEL LH	X		\$	986.70
39	1 OUTER PANEL REAR (End Panel)		<i>Buc</i>	\$	1,471.77
40	1 OUTER PANEL REAR (End Panel)TRIM		<i>Re</i>	\$	404.56
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)		<i>x repair</i>	\$	2,189.88
42	1 SPARE WHEEL PANEL TRIM	X	<i>NA</i>	\$	612.21
43	1 EXHAUST REAR	X		\$	7,489.05
44	1 EXHAUST CAP REAR	X	} <i>an</i>	\$	230.49
45	1 CHASSIS PANEL REAR RH	X		\$	3,766.43

TOTAL	\$	38,963.92
10%	\$	3,896.39
	\$	35,067.53

Special Nett

1	1SET PARKING AID	<i>PM</i>		\$	700.00	<i>200-</i>
2	1SET REAR BUMPER CLIP	<i>an</i>		\$	66.00	
3	1SET BUMPER BRACKET CTR CLIP	X		\$	33.00	
4	1SET BUMPER BRACKET SIDE CLIP RH RR	X	} <i>an</i>	\$	10.00	
5	1SET BUMPR RETAINER RH CLIP RR	X		\$	20.00	
6	1SET BUMPR BRACKET SIDE CLIP LH RR	X		\$	10.00	
7	1SET BUMPR RETAINER CLIP LH RR	X		\$	20.00	
8	1SET BUMPER LOWER REAR RIVET	<i>2 NA</i>		\$	22.00	
9	1SET BUMPER LOWER REAR CLIP	<i>1 NA</i>		\$	66.00	
10	1 EXHAUST MOUNTING REAR	X		} <i>an</i>	\$	17.82
11	1SET BOOT FINISHER CLIP	X	\$		24.20	
12	1 BOOT STICKER "Trans-cab"		} <i>an</i>	\$	30.00	
13	1 BOOT STICKER "6555-3333"			\$	30.00	
14	1 BOOT INNER TRIM CLIP	X		\$	45.00	
15	1SET FENDER WHEELARCH REAR RH CLIP	X	} <i>an</i>	\$	35.00	
16	1SET FENDER WHEELARCH REAR LH CLIP	X		\$	35.00	

Trans-cab Auto Services Pte Ltd

AAD1810-058

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

17	1 FENDER INNER TRIM CLIP LH	X	\$	28.00
18	1 FENDER INNER TRIM CLIP LH	X	\$	28.00
19	1 TAILLAMP CLIP RH	X	\$	5.00
20	1 TAILLAMP CLIP LH	X	\$	5.00
21	2 REAR WINDSCREEN SELANT	X	\$	80.00
22	1 WINDSCREEN MOULDING	X	\$	100.00
23	1 REAR WINDSCREEN INNER SPONGE SEAL	X	\$	100.00
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	X	\$	385.00
25	1 SPARE TYRE	X	\$	330.00

TOTAL \$ 2,225.02

TOTAL PARTS \$ 37,292.55

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	600
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	600
To Rust-Proofing Of The Affected Areas.	\$	170.00	60
To reinstall rear bumper parking sensor.	\$	170.00	40
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X

Trans-cab Auto Services Pte Ltd

AAD1810-058

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	380.00	X
TOTAL	\$	12,540.00	

mu

5 Days.

Lump sum repair.

After repair photos.

Gua Qi ng.

05/10/18.

Over All Total \$ 49,832.55

50212.534

(LUMP SUM)

Repair Days

20 DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHF615A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001747
Chassis No.:	VF1ABL15AUC278494
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	27 Jun 2014
First Registration Date:	27 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	26 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$26,717.00
Total Rebate Amount:	\$36,090.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 04 Oct 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHF615A
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001747
Chassis No.:	VF1ABL15AUC278494
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	27 Jun 2014
First Registration Date:	27 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	26 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$26,598.00
Total Rebate Amount:	\$35,971.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Oct 2018

OK

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 29 July 2019 11:50 AM
To: Ng Wai Yin; Jasmine Tan
Cc: claims@transcab.com.sg; Admin A
Subject: OFFER - MVA BETWEEN SHF 615A & SLX 4052E (OI) ON 03/10/2018

Our Ref: CC3/AIG18018527/Gka3
Your Ref: AAD1810-058

**Without Prejudice
(save as to costs)**

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 5,510.50
2. Loss of Rental (5days x \$99.32)	\$ 496.60
3. LTA/GIA Search Fee	\$ 7.49
TOTAL	\$ 6,014.59

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 14 August 2019 2:00 PM
To: Jasmine Tan; 'Ng Wai Yin'
Cc: claims@transcab.com.sg; Admin A
Subject: RE: OFFER - MVA BETWEEN SHF 615A & SLX 4052E (OI) ON 03/10/2018
Attachments: AIG DV.pdf

Tracking:	Recipient	Delivery
	Jasmine Tan	
	'Ng Wai Yin'	
	claims@transcab.com.sg	
	Admin A	
	Meikwan@lkkauto.com	Delivered: 14/8/2019 2:00 PM
	shupei@lkkauto.com	Delivered: 14/8/2019 2:00 PM
	olivialau@lkkauto.com	Delivered: 14/8/2019 2:00 PM

Our Ref: CC3/AIG18018527/Gka3
Your Ref: AAD1810-058

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement as follows: -

1. Cost of Repair (w/GST)	\$ 5,510.50
2. Loss of Rental (7 days x \$99.32)	\$ 695.24
3. LTA/GIA Search Fee	\$ 7.49
TOTAL	\$ 6,213.23

We attach herewith a copy of the DV for your further action.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Oct 2018 Edit Reg		05 Oct 2018 00:00 Edit Adj Rpt	S\$5,150.00 Edit Estimates	S\$5,150.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	AMA RENTAL PTE LTD, Co. Reg. No.: 201708966M								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHF615A	Date of Loss: 03/10/2018 15:00 - :59 [51 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 8743008218SG	Policy/Cover Note No.: 0999994495 (Third Party Only)							
Vehicle Reg. No. (Insured):	SLX4052E	Policy No. (Claimant): VPX/P1680520							
		Excess:							
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 22/10/2018]								
ASSOCIATED MAIL RECEIVED									
	View All	Compose Case Mail							
<ul style="list-style-type: none"> AIG_SG (12/10/2018): Request to upload TP GIA Report 									
ALL ASSOCIATED TASKS									
	View All	Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHF615A (8743008218SG)
[SLX4052E]**

TP

TRANS-CAB SERVICES PTE LTD

Oct 3 2018 3:00PM

[AMA RENTAL PTE LTD]

Trans-cab Auto Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser ▼	
Letters/Correspondences															1 per page ▼		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown												Edit				
Photos/Images															3 per page ▼		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print				
1	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
2	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
3	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
4	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
5	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
6	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
7	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
8	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
9	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
10	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
11	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
12	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
13	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
14	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
15	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
16	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
17	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
18	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
19	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
20	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
21	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
22	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
23	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
24	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
25	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
26	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
27	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
28	01/04/19 15:59	General View												Load JPG <input checked="" type="checkbox"/>				
29	01/04/19 15:59	Odometer Reading												Load JPG <input checked="" type="checkbox"/>				
30	01/04/19 15:59	Chassis Number												Load JPG <input checked="" type="checkbox"/>				
Documentation															1 per page ▼		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print				
1	13/10/18 19:50	TP ESTIMATE-MARKED												Load PDF				
2	13/10/18 19:50	TP GIA REPORT												Load PDF				
3	01/04/19 15:57	LETTER TO OI												Load PDF				
4	10/10/19 13:41	LOD												Load PDF				
5	10/10/19 13:41	AUTHORISATION TO ACT												Load PDF				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLX4052E (Insd veh)	Model:	RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A)
	SHF615A (TP veh)		
Date of Accident:	03/10/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:\$		53,727.41
Final Repair Cost	:\$		5,510.50
Loss of Use	:\$		_____ days at \$0.00 per day
Rental (if any)	:\$		695.24 7 days
LTA / GIA Search Fee	:\$		7.49
Others:	:\$		
	:\$		
Final Settlement Sum	:\$		6,213.23

Is Third Party Workshop GIA Registered?	[] YES	[X] NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:	Agreed Liability ___100___ (%)		
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: ____		
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)		
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>			
Remarks	_____		

Payment Instruction: Payee's Breakdown			
1)	Trans-Cab Auto Services Pte Ltd	:\$	6,213.23
2)		:\$	
3)		:\$	
4)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

10 Oct
2019

Date

**Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
Bill (if any)**

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18018527/GKA3S2
Date: 10/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994495
Claimant Vehicle No : SHF615A **Insured Vehicle No :** SLX4052E
Date of Loss: 03/10/2018 Nature of Claim: TP Claim No: 8743008218SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHF615A**
Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) Engine No: M9R8839C001747
Reg. Date: 27/06/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC278494
Colour: White/Red Odometer: 295215 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm
Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,292.53	5,139.68	32,152.85	86.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,920.00	1,300.00	11,620.00	89.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,212.53	6,439.68	43,772.85	87.18
Approved Total (Overridden) (S\$)		5,150.00		
(S\$)	50,212.53	5,150.00	45,062.53	89.74
+ GST 7.00/7.00% (S\$)	3,514.88	360.50	3,154.38	89.74
Nett Amount (S\$)	53,727.41	5,510.50	48,216.91	89.74
+ Car Rental (7.0 x S\$99.32/day) (S\$)		695.24		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		6,213.23		

INSPECTION

Date of Assignment: 05/10/2018
Date Inspected: 05/10/2018 Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111
Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Deformed	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Not Necessary	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Not Necessary	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Not Necessary	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Not Necessary	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Not Necessary	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Not Necessary	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Cracked	43.61 FL	*43.61 FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Not Necessary	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Not Necessary	225.95 FL	*- FL
13	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
14	1		*BOOT FINISHER	Not Necessary	470.06 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Twisted	323.05 FL	*323.05 FL
16	1		*BOOT REFLECTOR LAMP LH	Not Necessary	493.35 FL	*- FL
17	1		*BOOT REFLECTOR LAMP RH	Not Necessary	493.35 FL	*- FL
18	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1		*BOOT STRUT LH	Not Necessary	276.08 FL	*- FL
21	1		*BOOT STRUT RH	Not Necessary	276.08 FL	*- FL
22	1		*BOOT HINGE LH	Not Necessary	367.84 FL	*- FL
23	1		*BOOT HINGE RH	Not Necessary	367.84 FL	*- FL
24	1		*BOOT INNER TRIM	Not Necessary	586.45 FL	*- FL
25	1		*BOOT SWITCH	Not Necessary	168.13 FL	*- FL
26	1		*BOOT LOCK	Not Necessary	202.67 FL	*- FL
27	1		*BOOT LOCK CATCH	Not Necessary	74.40 FL	*- FL
28	2		*LICENCE PLATE LAMP	Not Necessary	50.52 FL	*- FL
29	2		*BOOT RUBBER PLUG	Not Necessary	221.81 FL	*- FL
30	1		*FENDER PANEL REAR LH	Not Necessary	3,299.13 FL	*- FL
31	1		*WHEELARCH REAR LH	Not Necessary	543.47 FL	*- FL
32	1		*FENDER PANEL INNER TRIM REAR RH	Not Necessary	671.45 FL	*- FL
33	1		*FENDER PANEL REAR RH	Not Necessary	3,299.13 FL	*- FL
34	1		*WHEELARCH REAR RH	Not Necessary	543.47 FL	*- FL
35	1		*TAILLAMP RH	Not Necessary	552.55 FL	*- FL
36	1		*TAILLAMP PANEL RH	Not Necessary	986.70 FL	*- FL
37	1		*TAILLAMP LH	Not Necessary	552.55 FL	*- FL
38	1		*TAILLAMP PANEL LH	Not Necessary	986.70 FL	*- FL
39	1		*OUTER PANEL REAR (END PANEL)	Buckled	1,471.77 FL	*1,471.77 FL
40	1		*OUTER PANEL REAR (END PANEL) TRIM	Deformed	404.56 FL	*404.56 FL
41	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
42	1		*SPARE WHEEL PANEL TRIM	Not Necessary	612.21 FL	*- FL
43	1		*EXHAUST REAR	Not Necessary	7,489.05 FL	*- FL
44	1		*EXHAUST CAP REAR	Not Necessary	230.49 FL	*- FL
45	1		*CHASSIS PANEL REAR RH	Not Necessary	3,766.43 FL	*- FL
46	1		*SET PARKING AID	Damaged	700.00 FS	*200.00 FS
47	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
48	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
49	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
50	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
51	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
52	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
53	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
54	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS
55	1		*EXHAUST MOUNTING REAR	Not Necessary	17.82 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SE BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
57	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
58	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
59	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
60	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
61	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
62	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
63	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
64	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
65	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
66	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
67	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
68	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
69	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Not Necessary	385.00 FS	*- FS
70	1		*SPARE TYRE	Not Necessary	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	41,188.92	5,674.53
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,896.39	534.85
Total Parts (\$\$)	37,292.53	5,139.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	6,000.00	600.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	4,200.00	600.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	60.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	40.00
5	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	New	380.00	0.00
11	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
14	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
Gross Labour Cost (S\$)			12,920.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >