

Trans-cab Auto Services Pte Ltd

AAD1810-058

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

Vehicle No.:	SHF 615A
Chassis No.:	VF1ABL15AUC278494
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	3.10.2018
Third Party Insurer :	AIG

	PART		LIST
1	1 BUMPER COVER REAR <i>/ Re</i>	\$	1,108.46
2	1 BUMPER LOWER REAR <i>/ cut</i>	\$	768.84
3	1 BUMPER BRACKET CTR REAR <i>?</i>	\$	113.47
4	1 BUMEP R BRACKET SIDE RH REAR <i>?</i>	\$	135.97
5	1 BUMEP R RETAINER RH REAR <i>X</i> <i>SHF NN</i>	\$	44.99
6	1 BUMPER REFLECTOR RH <i>X</i>	\$	43.61
7	1 BUMEP R BRACKET SIDE LH REAR <i>?</i>	\$	135.97
8	1 BUMEP R RETAINER LH REAR <i>X</i>	\$	44.99
9	1 BUMPER REFLECTOR LH <i>/ CUA</i>	\$	43.61
10	1 BUMPER BEAM REAR <i>/ BT</i>	\$	777.52
11	1 BUMPER BEAM BRACKET LH REAR <i>?</i>	\$	225.95
12	1 BUMPER BEAM BRACKET RH REAR <i>?</i>	\$	225.95
13	1 BOOT REAR <i>X repair.</i>	\$	2,872.68
14	1 BOOT FINISHER <i>X NN</i>	\$	470.06
15	1 BOOT WHEATER STRIP <i>/ cut</i>	\$	323.05
16	1 BOOT REFLECTOR LAMP LH <i>X</i> <i>SM</i>	\$	493.35
17	1 BOOT REFLECTOR LAMP RH <i>X</i> <i>SM</i>	\$	493.35
18	1 BOOT BADGE 'RENAULT' <i>/</i> <i>SM</i>	\$	225.36
19	1 BOOT BADGE <i>/</i>	\$	225.36
20	1 BOOT STRUT LH <i>X</i>	\$	276.08
21	1 BOOT STRUT RH <i>X</i>	\$	276.08
22	1 BOOT HINGE LH <i>X</i>	\$	367.84
23	1 BOOT HINGE RH <i>X</i>	\$	367.84
24	1 BOOT INNER TRIM <i>X</i>	\$	586.45
25	1 BOOT SWITCH <i>X</i>	\$	168.13
26	1 BOOT LOCK <i>X</i>	\$	202.67
27	1 BOOT LOCK CATCH <i>X</i>	\$	74.40
28	2 LICENCE PLATE LAMP <i>X</i>	\$	50.52
29	2 BOOT RUBBER PLUG <i>X</i>	\$	221.81

Trans-cab Auto Services Pte Ltd

AAD1810-058

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

30	1 FENDER PANEL REAR LH	X		\$	3,299.13	
31	1 WHEELARCH REAR LH	X		\$	543.47	
32	1 FENDER PANEL INNER TRIM REAR RH	X	} <i>an</i>	\$	671.45	
33	1 FENDER PANEL REAR RH	X		\$	3,299.13	
34	1 WHEELARCH REAR RH	X		\$	543.47	
35	1 TAILLAMP RH	X		\$	552.55	
36	1 TAILLAMP PANEL RH	X		\$	986.70	
37	1 TAILLAMP LH	X		\$	552.55	
38	1 TAILLAMP PANEL LH	X		\$	986.70	
39	1 OUTER PANEL REAR (End Panel)			<i>Buc</i>	\$	1,471.77
40	1 OUTER PANEL REAR (End Panel)TRIM			<i>Re</i>	\$	404.56
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	X		<i>repair</i>	\$	2,189.88
42	1 SPARE WHEEL PANEL TRIM	X		\$	612.21	
43	1 EXHAUST REAR	X		\$	7,489.05	
44	1 EXHAUST CAP REAR	X	} <i>an</i>	\$	230.49	
45	1 CHASSIS PANEL REAR RH	X		\$	3,766.43	

TOTAL	\$	38,963.92
10%	\$	3,896.39
	\$	35,067.53

Special Nett

1	1SET PARKING AID	<i>/ pm</i>		\$	700.00	<i>200</i>
2	1SET REAR BUMPER CLIP	<i>/ ncc</i>		\$	66.00	
3	1SET BUMPER BRACKET CTR CLIP	X		\$	33.00	
4	1SET BUMPER BRACKET SIDE CLIP RH RR	X	} <i>an</i>	\$	10.00	
5	1SET BUMPR RETAINER RH CLIP RR	X		\$	20.00	
6	1SET BUMPR BRACKET SIDE CLIP LH RR	X		\$	10.00	
7	1SET BUMPR RETAINER CLIP LH RR	X		\$	20.00	
8	1SET BUMPER LOWER REAR RIVET	?		\$	22.00	
9	1SET BUMPER LOWER REAR CLIP	?	\$	66.00		
10	1 EXHAUST MOUNTING REAR	X	} <i>an</i>	\$	17.82	
11	1SET BOOT FINISHER CLIP	X		\$	24.20	
12	1 BOOT STICKER "Trans-cab"	<i>/</i>	} <i>an</i>	\$	30.00	
13	1 BOOT STICKER "6555-3333"	<i>/</i>		\$	30.00	
14	1 BOOT INNER TRIM CLIP	X		\$	45.00	
15	1SET FENDER WHEELARCH REAR RH CLIP	X	} <i>an</i>	\$	35.00	
16	1SET FENDER WHEELARCH REAR LH CLIP	X		\$	35.00	

Trans-cab Auto Services Pte Ltd

AAD1810-058

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

17	1 FENDER INNER TRIM CLIP LH	X	\$	28.00
18	1 FENDER INNER TRIM CLIP LH	X	\$	28.00
19	1 TAILLAMP CLIP RH	X	\$	5.00
20	1 TAILLAMP CLIP LH	X	\$	5.00
21	2 REAR WINDSCREEN SELANT	X	\$	80.00
22	1 WINDSCREEN MOULDING	X	\$	100.00
23	1 REAR WINDSCREEN INNER SPONGE SEAL	X	\$	100.00
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	X	\$	385.00
25	1 SPARE TYRE	X	\$	330.00

} ~ ~

TOTAL \$ 2,225.02

TOTAL PARTS \$ 37,292.55

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	600
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	600
To Rust-Proofing Of The Affected Areas.	\$	170.00	60
To reinstall rear bumper parking sensor.	\$	170.00	40
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X

} ~ ~

Trans-cab Auto Services Pte Ltd

AAD1810-058

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 615A

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	380.00	X

mn

TOTAL \$ 12,540.00

Over All Total \$ 49,832.55

5 Days.

Lump sum repair

After repair photos.

Good Q. r. p.

05/10/18.

**(LUMP SUM)
Repair Days 20 DAYS**