

Surveyor:

X612

DOI:

5-10-18

Date / Year:

5-10-18

Registered in Merit:

11-10-18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SCH 1591 U

Name of Insured:

Chee Yook Leng

Insured Tel No.:

HP:

Claim No.:

Excess Sec II : S\$

D.O.A.:

4-10-18

Policy No.:

Make / Model:

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SHC 5264L



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans car



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE: 183119 001111

After call ltr to OE: 3/4/19 001111

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: X612

Repair Cost:

S\$ 8,750.00

(6 days)

Reduction:

91 %

FINAL SETTLEMENT

Date/Time: 06.09.19

Confirm with: 06.09.19

Email: [] Call: []

Final Liability:

100 %

(Agreed / Assessed) BOLA S/N No.:

9

If NO or B 28, Ast. Lin:

Repair Cost:

S\$ 9,362.50

COI FROM WINDRO ROAD

Loss of Rental (LOR):

S\$ 144.50

(8 days)

= +99.50

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only [] LOU only []

LOR + LOU []

LOR + LOI []

[Tick only one]

GIA/LTA Search:

S\$ 1.44

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost:

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: IF

3) Survey fee: +500

Total:

S\$ 10,144.55

Global Sum S\$:

FINAL PAYMENT

Date/Time: 06.09.19

Confirm with: 06.09.19

Email: [] Call: []

Payee 1:

S\$ 10,144.55

Name 1:

TRANS-AS AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

Trans-cab Auto Services Pte Ltd

AAD1810-063

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5264L

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5264L

VF1ABL15AUC276190

RENAULT

LATITUDE

4.10.2018

AIG**PART****LIST**

1	1	BUMPER COVER FRT	/ re	\$	1,259.42
2	1	BUMPER SPOILER FRT	X { re	\$	181.75
3	1	BUMPER ABSORBER FRT	X { re	\$	394.68
4	1	BUMPER RETAINER FRT LH	- re	\$	151.41
5	1	BUMPER SUPPORT FRT	X { re	\$	123.88
6	1	BUMPER RETAINER FRT RH	X { re	\$	150.77
7	1	BUMPER SUPPORT FRT	X { re	\$	123.88
8	1	BUMPER UNDERTRAY FRT	X { re	\$	472.83
9	1	BUMPER GRILLE LOWER FRT	X { re	\$	266.80
10	1	BUMPER FOG LAMP GRILLE LH	- crA	\$	207.21
11	1	BUMPER FOG LAMP GRILLE RH	X re	\$	207.21
12	1	BUMPER BEAM FRT	/ BT	\$	914.08
13	1	TOW COVER FRT	X re	\$	28.61
14	1	RADIATOR GRILLE	? re	\$	1,707.78
15	1	RADIATOR GRILLE BADGE 'RENAULT'	? re	\$	225.36
16	1	RADIATOR GRILLE FRAME	? re	\$	1,353.75
17	1	FRAME FULL SUPPORT PANEL	? re	\$	615.90
18	1	FRAME FULL SUPPORT BRACKET	? re	\$	89.79
19	1	FRONT BRACE PANEL	X { re	\$	177.22
20	1	HORN	X { re	\$	314.17
21	1	HORN BRACKET	X { re	\$	40.45
22	1	HEADLAMP LH	- crA	\$	1,184.43
23	1	HEADLAMP HARNESS	? re	\$	928.29
24	1	HEADLAMP PANEL FRT LH	? re	\$	152.15
25	1	BONNET	X repair.	\$	1,941.63
26	1	BONNET INSULATOR	X { re	\$	405.73
27	1	BONNET STRUT LH	X { re	\$	88.61
28	1	BONNET STRUT RH	X { re	\$	88.61

Trans-cab Auto Services Pte Ltd**AAD1810-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5264L

29	1	BONNET HINGE LH	X		\$	348.31
30	1	BONNET HINGE RH	X		\$	348.31
31	1	BONNET LOCK	X		\$	305.48
32	1	BONNET CABLE	X		\$	119.19
33	1	BONNET CABLE COVER	X		\$	161.03
34	1	BONNET SEAL OUTER	X		\$	92.36
35	1	BONNET SEAL INNER	X		\$	157.28
36	1	FENDER PANEL FRT LH		bmc	\$	783.83
37	1	WHEELARCH FRT LH	X	rv	\$	278.84
38	1	FENDER BRACKET LOWER LH		2 NH	\$	15.79
39	1	FENDER INSULATOR LH		re	\$	130.84
40	1	WIPER RESERVOIR		2 NH	\$	348.25
41	1	WIPER RESERVOIR NECK		2 NH	\$	136.11
42	1	WIPER RESERVOIR MOTOR		2 NH	\$	270.06
43	1	AIR CLEANER LOWER		2 NH	\$	271.26
44	1	AIR CLEANER HOSE		2 NH	\$	76.14
45	1	ENGINE TOP COVER 2.0	X		\$	555.12
46	1	ENGINE OIL SUMP	X		\$	484.67
47	1	BASE BATTERY TRAY	X		\$	363.40
48	1	AIR CLEANER BOX	X		\$	464.20
49	1	TURBO DUCT	X		\$	1,027.80
50	1	A/C HEATER VALVE	X		\$	484.50
51	1	SUBFRAME OUTER FRT	X		\$	2,652.45
52	1	SUBFRAME BRACKET OUTER LH	X		\$	92.36
53	1	SUBFRAME BRACKET OUTER RH	X		\$	92.36
54	1	ENGINE UNDERTRAY	X		\$	564.98
55	1	A/C CONDENSER	X		\$	2,020.37
56	1	A/C CONDENSER GARNISH LH UPPER	X		\$	39.67
57	1	A/C CONDENSER GARNISH RH UPPER	X		\$	39.67
58	1	A/C CONDENSER GARNISH LH	X		\$	58.81
59	1	A/C CONDENSER GARNISH RH	X		\$	59.60
60	1	A/C PIPE CONDENSER TO COMPRESSOR	X		\$	208.39
61	1	A/C PIPE CONDENSER TO EXPENSION VALVE	X		\$	658.72
62	1	A/C PIPE COMPRESSOR	X		\$	334.29
63	1	A/C PIPE	X		\$	658.72
64	1	A/C COMRPESSOR	X		\$	2,684.61
65	1	AIR COOLER	X		\$	792.60
66	1	AIR INTERCOOLER HOSE (LONG)	X		\$	1,014.13

Trans-cab Auto Services Pte Ltd

AAD1810-063

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5264L

67	1	AIR INTERCOOLER HOSE (Short)	X	\$	375.14
68	1	TRANSMISSION COOLER	X	\$	1,219.30
69	1	TRANSMISSION COOLER PAD	X	\$	17.96
70	1	RADIATOR	X	\$	1,202.20
71	2	RADIATOR STUD UPPER	X	\$	14.41
72	2	RADIATOR BUSH UPPER	X	\$	50.12
73	2	RADIATOR MTG LOWER	X	\$	55.85
74	1	RADIATOR FAN COWLING	X	\$	820.54
75	1	RADIATOR FAN MOTOR LH	X	\$	967.36
76	1	RADIATOR FAN MOTOR RH	X	\$	1,479.46
77	1	RADIATOR TANK	X	\$	324.62
78	1	RADIATOR HOSE UPPER	X	\$	240.56
79	1	RADIATOR HOSE LOWER	X	\$	491.18
80	1	RADIATOR TANK HOSE	X	\$	61.18
81	1	AUTO COMPUTER	X	\$	5,032.17
82	1	INJECTION COMPUTER	X	\$	4,706.30
83	1	RHD HYDRAULIC POWER(ROCK&PINION)	X	\$	5,154.52
84	1	STEERING PUMP ELECTRIC	X	\$	2,306.90
85	1	STEERING PINION RACK	X	\$	4,413.11
86	1	DOOR PANEL FRT LH	X	\$	2,844.66
87	1	DOOR HINGE UPPER LH	X	\$	261.28
88	1	DOOR HINGE LOWER LH	X	\$	300.55
89	1	DOOR CHECK FRT LH	X	\$	194.77
90	1	DOOR LOCK FRT LH	X	\$	908.75
91	1	DOOR CATCH FRT LH	X	\$	131.23
92	1	DOOR HANDLE OUTER FRT LH	X	\$	477.76
93	1	DOOR HANDLE COVER FRT LH	X	\$	13.22
94	1	DOOR HANDLE MODULE FRT LH	X	\$	133.60
95	1	DOOR REGULATOR FRT LH	X	\$	505.19
96	1	DOOR REGULATOR MOTOR FRT LH	X	\$	796.46
97	1	DOOR REGULATOR GUIDE FRT LH	X	\$	120.97
98	1	DOOR PANEL REAR LH	X	\$	2,844.66
99	1	DOOR GUIDE REAR LH	X	\$	176.82
100	1	DOOR HINGE UPPER LH	X	\$	274.50
101	1	DOOR HINGE LOWER LH	X	\$	300.55
102	1	DOOR CHECK REAR LH	X	\$	203.06
103	1	DOOR LOCK REAR LH	X	\$	908.75
104	1	DOOR HANDLE OUTER REAR LH	X	\$	126.49

Trans-cab Auto Services Pte Ltd

AAD1810-063

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5264L

105	1	DOOR HANDLE CAP REAR LH	X	\$	35.52
106	1	DOOR HANDLE SEAL REAR LH	X	\$	7.89
107	1	DOOR HANDLE COVER REAR LH	X	\$	13.22
108	1	DOOR HANDLE MODULE REAR LH	X	\$	133.60
109	1	DOOR REGULATOR REAR LH	X	\$	1,135.10
110	1	DOOR REGULATOR MOTOR REAR LH	X	\$	893.75
111	1	DOOR REGULATOR NUT REAR LH	X	\$	12.43
112	1	DOOR REGULATOR MOTOR SCREW REAR L70Y	X	\$	6.31
113	1	DOOR FINISHER REAR LH	X	\$	423.10
114	1	DOOR MOULDING REAR LH	X	\$	176.82
115	1	DOOR MOULDING CLIP L70Y	X	\$	5.92
116	1	DOOR MOULDING SCREW L70Y	X	\$	6.91
117	1	DOOR CASING REAR LH	X	\$	1,509.06
118	1	DOOR WATER SHIELD REAR LH	X	\$	30.39
119	1	DOOR CASING CLIP	X	\$	12.63
120	1	DOOR CASING LIGHT L70Y	X	\$	48.74
121	1	DOOR FINISHER INNER REAR LH	X	\$	323.44
122	1	DOOR FINISHER BRACKET INNER REAR LH	X	\$	46.97
123	1	DOOR FINISHER BRACKET INNER REAR LH	X	\$	20.33
124	1	DOOR FINISHER BRACKET INNER REAR LH	X	\$	20.33
125	1	DOOR FINISHER BRACKET INNER REAR LH	X	\$	20.33
126	1	DOOR GRAB HANDLE REAR LH	X	\$	210.96
127	1	DOOR BLIND REAR LH	X	\$	741.80
128	1	DOOR WHEATHESTRIIP REAR LH	X	\$	410.66
129	1	DOOR SEAL REAR LH	X	\$	162.02
130	1	DOOR GLASS RUNNER SEAL REAR LH	X	\$	229.31
131	1	DOOR WAIST SEAL OUTER REAR LH	X	\$	334.69
132	1	DOOR WAIST SEAL INNER REAR LH	X	\$	115.64
133	1	DOOR MIRROR ASSY LH	CA	\$	1,483.40
134	1	ROCKER PANEL INNER GARNISH LH	X Repair X Repair NN	\$	466.51
135	1	ROCKER PANEL INNER LH	X NN	\$	1,024.79
136	1	ROCKER PANEL CENTER LH	X Repair	\$	990.25
137	1	DOOR HARNESS WIRE	X NN	\$	2,670.00
138	1	LOWER ARM LH L70Y	X NN	\$	685.76
139	1	KUNCKLE ARM LH L70Y	X NN	\$	846.98
140	1	ABSORBER FRT LH L70Y	X NN	\$	360.54

Trans-cab Auto Services Pte Ltd

AAD1810-063

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5264L

TOTAL	\$	89,063.12
10%	\$	8,906.31
	\$	80,156.81

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	X NN	\$	52.00
2	1SET	BUMPER CLIP FRT	/ MC	\$	66.00
3	1	BUMPER BRACKET CLIP FRT LH	X	\$	12.00
4	1	BUMPER SUPPORT CLIP FRT LH	X	\$	10.50
5	1	BUMPER BRACKET CLIP FRT RH	X	\$	12.00
6	1	BUMPER SUPPORT CLIP FRT RH	X	\$	10.50
7	1	TOW COVER FRT	X	\$	14.50
8	1SET	RADAIOR GRILLE SCREW	X	\$	16.00
9	1SET	BUMPER GRILLE LOWER CLIP	X	\$	69.00
10	1SET	FRAME FULL SUPPORT PANEL CLIP	X	\$	70.00
11	2	FRAME FULL SUPPORT PANEL NUT	X	\$	20.00
12	2	FRAME FULL SUPPORT PANEL STUD	X	\$	30.00
21	1	Windscreen moulding	X	\$	100.00
22	1SET	Front licence plate with holder	X	\$	80.00
22	1	FRONT DOOR STICKER 'Trans-cab'	/	\$	80.00
22	1	FRONT DOOR STICKER 'Chassis'	/ MC	\$	50.00
22	1	REAR DOOR STICKER '6555 3333'	/	\$	80.00
22	1	DOOR CHECK BOLT	X	\$	22.69
22	1	DOOR GUIDE SCREW	X	\$	10.85
22	1	DOOR HINGE BOLT	X	\$	10.85
22	1	DOOR HINGE NUT RH	X	\$	14.60
22	1	DOOR CHECK BOLT	X	\$	22.69
22	1	DOOR CHECK NUT	X	\$	3.75
22	1	DOOR LOCK SCREW L70Y	X	\$	6.12
22	1	DOOR CATCH SCREW L70Y	X	\$	10.06
22	1	FRONT LEFT TYRE RIM	/ CA	\$	380.00
22	1	FRONT LEFT TYRE	X NIV	\$	300.00

TOTAL	\$	1,554.13
TOTAL PARTS	\$	81,710.94

Trans-cab Auto Services Pte Ltd**AAD1810-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5264L**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	600	5,400.00
Towing Fees.	\$	2	120.00
To apply paint protection system (PPS) maintain and enhancement	\$	NN X	380.00
Putty and spray painting of the affected portion.	\$	1300	5,000.00
To rust-proofing of the affected areas.	\$	60	170.00
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	NN X	380.00
To check steering geometry and computer wheel alignment	\$	60	220.00
To transfer of tire, rim and on wheel balancing.	\$	NN X	170.00
To Check Electrical Lighting Concerned.	\$	30	170.00
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	X	380.00
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	NN { X	380.00
To lift-up engine with gear box and refit.	\$	X	440.00

Trans-cab Auto Services Pte Ltd

AAD1810-063

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5264L

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	X	440.00
To remove and refit air bag system and reset.	\$	X	480.00
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	NN	X 380.00
To vacuum, replace, refix and recharge air condenser	\$	X	380.00
To replace, refix and top up coolant for radiator	\$	X	170.00
To vacuum, replace, refix and recharge Air Intercooler	\$	X	170.00
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	X	170.00

6 Days.

TOTAL \$ 15,400.00

1 month repair.

Over All Total \$ 97,110.94

After repair photos.

Repair Days (LUMP SUM)**20 DAYS**

Gmo. Aup.

05/10/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHC5264L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000843
Chassis No.:	VF1ABL15AUC276190
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	07 Mar 2014
First Registration Date:	07 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Mar 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	06 Mar 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$58,745.00
COE Rebate Amount:	\$25,128.00
Total Rebate Amount:	\$34,501.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 04 Oct 2018

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5264L
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000843
Chassis No.:	VF1ABL15AUC276190
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	07 Mar 2014
First Registration Date:	07 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Mar 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	06 Mar 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$58,745.00
COE Rebate Amount:	\$24,988.00
Total Rebate Amount:	\$34,361.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 Oct 2018

OK

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	11 Oct 2018 21:14	Cim Veh Model Changed	(205736) RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A).	[A] HOW MEI KWAN
2	11 Oct 2018 21:14	Cim Created	Reg No: SHC5264L, Acct Date: 2018/10/04. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). TP Insurer: AXA Insurance Pte Ltd (HQ). Workshop: Trans-cab Auto Services Pte Ltd ()	[A] HOW MEI KWAN
3	11 Oct 2018 21:14	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
4	11 Oct 2018 21:14	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/10/22	[A] HOW MEI KWAN
5	11 Oct 2018 21:14	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
6	11 Oct 2018 21:14	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
7	11 Oct 2018 21:15	Label Added	(23):Express.	[A] HOW MEI KWAN
8	11 Oct 2018 21:15	Adj Adjuster Assigned	[None] -> XING GUO QIANG	[A] HOW MEI KWAN
9	25 Jul 2019 15:19	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
10	25 Jul 2019 15:19	Cim Dtl Modified	JPJ Reg. Date: -> 2014/03/07.	[A] Elaine Kuan Hwa Meen
11	25 Jul 2019 15:19	Cim Details Notified		[A] Elaine Kuan Hwa Meen
12	27 Aug 2019 11:07	Adj Mandate Request	Cur.Req:10164.55:LIABILITY: 100% B:9 OI TURNING INTO MAIN ROAD	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2224858	25/07/2019 15:19	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SHC5264L	SLH1591U	11.77

Print Received Message

This mail is associated with :

***SHC5264L (6561621464SG)**
[SLH1591U]

TP

TRANS-CAB SERVICES PTE LTD

Oct 4 2018 7:00AM

[CHEE YEOK LENG]

Trans-cab Auto Services Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 05/09/2019 17:38 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10164.55) - SHC5264L - Claim Handler: Chan, Kian-Meng

Approved:10164.55:kindly ensure docs in order.

To : Asher

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1810-063

Your Ref : SLH1591U

Date : 28 June 2019

AIG ASIA PACIFIC INSURANCE

Dear Sir/Madam,

ACCIDENT INVOLVING SHC5264L AND SLH1591U ON 04/10/18 07:50 AM ALONG AMBER ROAD

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	9,362.50
2.	Loss of Rental for <u>8</u> days @ \$ <u>99.32</u> per day	\$	794.56
3.	Loss of Income for <u> </u> days @ \$ <u> </u> per day	\$	0.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	10,164.55

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18018528/Gha3

03 April 2019

CHEE YEOK LENG
29 AMBER ROAD
#10-04
SINGAPORE 439942

Dear Sir/Madam,

ACCIDENT INVOLVING SLH 1591U AND SHC 5264L ON 04/10/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

As spoken, kindly forward accident scene photos for our reference.

Please call us if you have further queries.

Yours faithfully,

Cecilia Chong
Case Handler
DID: 6749 4274
FAX: 6741 4108
EMAIL: ceciliachong@lkkauto.com

c.c AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Authorization To Act

We, Trans-cab Services Pte Ltd of Company Registration No. 200303878K hereby authorize Trans-cab Auto Services Pte Ltd to act on behalf to claim for all losses incurred for the accident involving SHC5264L and SLH1591U along AMBER ROAD on 04/10/18 07:50 AM.

In addition, we also hereby authorize the above payment to be made in favour of Trans-cab Auto Services Pte Ltd upon settlement.

Dated this 18 (day) of December 2018

Yours Faithfully

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **TRANS-CAB AUTO SERVICES PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$9,362.50** (Repair Cost), **S\$794.56** (Loss of ~~Use~~/Rental), **S\$7.49** (Disbursement) for vehicle no. **SHC 5264L** that was damaged pursuant to the accident which occurred on **04/10/2018** (date) along **AMBER ROAD** (location) involving vehicle no/s **SLH 1591U**.

This is pursuant to the inspection conducted on **05/10/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **TRANS-CAB SERVICES PTE LTD** ("the third party claimant") of vehicle no. **SHC 5264L** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SHC 5264L** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 18 (day) of SEP (month) 2019 (year)



XGQ

XGQ

Signed by appointed surveyor



+

Signed by "the workshop" (with chop)

Trans-Cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666

Fax: 6287 7764

Co. Reg. No.: 201019626G

GST Reg. No.: 201019626G

Tax Invoice / Debit Note

TO: AIG ASIA PACIFIC INSURANCE PTE LTD 78 Shenton Way #07-16 CHARTIS Building 079120 Singapore ATTENTION:	INVOICE NO. : INV1906-278 DATE : 28. June 2019 REFERENCE NO : AAD1810-063 TERMS : Net 30 Days DUE DATE : 28. July 2019 PAGE : 1
--	--

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
		Invoice No. INV1811-310:			
1.	6050101	REPAIR-SHC5264L DOA 04.10.18(LUMP SUM-18)	1	9,362.50	9,362.50

Total SGD Excl. GST :	8,750.00
7% GST :	612.50
Total SGD Incl. GST :	9,362.50

****** NINE THOUSAND THREE HUNDRED SIXTY TWO AND FIFTY SGD ONLY ******

- 1) All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"
- 2) Please quote our Invoice Number during payment.
- 3) We reserve the right to charge interest @ 1.5% per month on overdue invoice.
- 4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

E. & O. E.**THIS IS A COMPUTER GENERATED INVOICE WHICH REQUIRES NO SIGNATURE**

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

18 December, 2018

To Whom It May Concern

Dear Sir / Madam,

Accident on 04/10/18 07:50 AM at AMBER ROAD

1. We refer to the above-mentioned accident and wish to inform that Trans-Cab Services Pte Ltd is the registered owner of the taxi bearing vehicle registration no. SHC5264L. The taxi was hired to LIM CHOON SENG a registered hirer-operator of Trans-Cab Services Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$99.32 per day (inclusive of GST).
2. Please be advised that the Taxi is insured with AXA INSURANCE PTE LTD on a third party basis at the material time of the accident.
3. Please liaise with us directly for any settlement of claims in respect of the said accident.

Yours faithfully,

Jasmine Tan

General Manager

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

04-10-2018

Dear Sir/Madam,

Please be informed that the taxi was undergo accident repair in the workshop as follow:

Date In	Date Out	Vehicle No.
Accident No.	AAD1810-063	Accident Date 04-10-2018
10/4/2018 15:20	10/11/2018 14:00	SHC5264L

Yours Faithfully,

Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

[> Back to OneMotoring](#)

Vehicle Insurance Particulars Result

Vehicle No.	Incident Date/Time	Insurance Company Name
SJL236E	04 Oct 2018 / 03:30:00	AXA INSURANCE PTE LTD
SLH1591U	04 Oct 2018 / 07:50:00	AIG ASIA PACIFIC INSURANCE PTE. LTD.

[Print](#)[OK](#)[Save as PDF](#)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Oct 2018 Edit Reg		05 Oct 2018 00:00 Edit Adj Rpt	S\$8,750.00 Edit Estimates	S\$8,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	CHEE YEOK LENG, ID: S2174434D								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHC5264L	Date of Loss:	04/10/2018 07:00 - :59 [54 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6561621464SG	Policy/Cover Note No.:	2100487226 (Comprehensive) Coverage: 26/10/2017 - 25/10/2018						
Vehicle Reg. No. (Insured):	SLH1591U	Policy No. (Claimant):	VPX/P1680520						
		Excess:							
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 22/10/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (05/09/2019): Alert - Adj Mandate Approved (S\$10164.55) - SHC5264L - Claim Handler: Chan, Kian... - AIG_SG (12/10/2018): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC5264L (6561621464SG)
[SLH1591U]
TP
TRANS-CAB SERVICES PTE LTD
Oct 4 2018 7:00AM
[CHEE YEOK LENG]
Trans-cab Auto Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement - Payment Breakdown															Edit		
Photos/Images															3 per page			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	27/08/19 11:08		General View															Load JPG		
2	27/08/19 11:08		General View															Load JPG		
3	27/08/19 11:08		General View															Load JPG		
4	27/08/19 11:08		General View															Load JPG		
5	27/08/19 11:08		General View															Load JPG		
6	27/08/19 11:08		General View															Load JPG		
7	27/08/19 11:08		General View															Load JPG		
8	27/08/19 11:08		General View															Load JPG		
9	27/08/19 11:08		General View															Load JPG		
10	27/08/19 11:08		General View															Load JPG		
11	27/08/19 11:08		General View															Load JPG		
12	27/08/19 11:08		General View															Load JPG		
13	27/08/19 11:08		General View															Load JPG		
14	27/08/19 11:08		General View															Load JPG		
15	27/08/19 11:08		General View															Load JPG		
16	27/08/19 11:08		General View															Load JPG		
17	27/08/19 11:08		General View															Load JPG		
18	27/08/19 11:08		General View															Load JPG		
19	27/08/19 11:08		General View															Load JPG		
20	27/08/19 11:08		General View															Load JPG		
21	27/08/19 11:08		General View															Load JPG		
22	27/08/19 11:08		General View															Load JPG		
23	27/08/19 11:08		General View															Load JPG		
24	27/08/19 11:08		General View															Load JPG		
25	27/08/19 11:08		General View															Load JPG		
26	27/08/19 11:08		General View															Load JPG		
27	27/08/19 11:08		General View															Load JPG		
28	27/08/19 11:08		General View															Load JPG		
29	27/08/19 11:08		General View															Load JPG		
30	27/08/19 11:08		General View															Load JPG		
31	27/08/19 11:08		General View															Load JPG		
32	27/08/19 11:08		General View															Load JPG		
33	27/08/19 11:08		General View															Load JPG		
34	27/08/19 11:08		General View															Load JPG		
35	27/08/19 11:08		General View															Load JPG		
36	27/08/19 11:08		General View															Load JPG		
37	27/08/19 11:08		General View															Load JPG		
38	27/08/19 11:08		General View															Load JPG		
39	27/08/19 11:08		General View															Load JPG		
40	27/08/19 11:08		General View															Load JPG		

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					☒
41	27/08/19 11:08	General View		Load JPG	☒
42	27/08/19 11:08	General View		Load JPG	☒
43	27/08/19 11:08	General View		Load JPG	☒
44	27/08/19 11:08	General View		Load JPG	☒
45	27/08/19 11:08	General View		Load JPG	☒
46	27/08/19 11:08	General View		Load JPG	☒
47	27/08/19 11:08	General View		Load JPG	☒
48	27/08/19 11:08	General View		Load JPG	☒
49	27/08/19 11:08	General View		Load JPG	☒
50	27/08/19 11:08	Odometer Reading		Load JPG	☒
51	27/08/19 11:08	Chassis Number		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/10/18 20:03	TP ESTIMATE-MARKED		Load PDF	
2	13/10/18 20:03	TP GIA REPORT		Load PDF	
3	23/08/19 12:46	RENTAL RECEIPT		Load PDF	
4	23/08/19 12:46	RENTAL MILEAGE		Load PDF	
5	23/08/19 12:46	LTA SEARCH		Load PDF	
6	23/08/19 12:46	LETTER TO OI		Load PDF	
7	24/09/19 10:53	WORKSHOP INVOICE		Load PDF	
8	24/09/19 10:53	AUTHORISATION TO ACT FORM		Load PDF	
9	24/09/19 10:53	Release Voucher		Load PDF	
10	24/09/19 10:53	LOD		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	12/10/18 08:51	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLH1591U (Insd veh)	Model:	RENAULT LATITUDE 2.0 L
	SHC5264L (TP veh)		DCI AUTO D/AB 4DR (A)
Date of Accident:	04/10/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	103,908.71
Final Repair Cost	:	\$	9,362.50
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	794.56 8 days
LTA / GIA Search Fee	:	\$	7.49
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	10,164.55

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Trans-cab Auto Services Pte Ltd	:	\$ 10,164.55
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

24 Sep
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18018528/GEA3Q2

Date: 24/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100487226
Claimant
Vehicle No : SHC5264L **Insured Vehicle No :** SLH1591U
Date of Loss: 04/10/2018 **Nature of Claim:** TP **Claim No:** 6561621464SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC5264L
Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) **Engine No:** M9R8839C000843
Reg. Date: 07/03/2014 (Man. Year: 2013) **Chassis No:** VF1ABL15AUC276190
Colour: Red **Odometer:** 362425 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 **Rear Tyre Size:** 215/60 R16
Front Left Side: Giti 5 mm **Rear Left Side:** Giti 5 mm
Front Right Side: Giti 5 mm **Rear Right Side:** Giti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	81,710.94	8,882.93	72,828.01	89.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,400.00	2,050.00	13,350.00	86.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	97,110.94	10,932.93	86,178.01	88.74
Approved Total (Overridden) (S\$)		8,750.00		
(S\$)	97,110.94	8,750.00	88,360.94	90.99
+ GST 7.00/7.00% (S\$)	6,797.77	612.50	6,185.27	90.99
Nett Amount (S\$)	103,908.71	9,362.50	94,546.21	90.99
+ Car Rental (8.0 x S\$99.32/day) (S\$)		794.56		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		10,164.55		

INSPECTION

Date of Assignment: 05/10/2018
Date Inspected: 05/10/2018 **Inspected At:** Trans-cab Auto Services Pte Ltd
 No 2 Ang Mo Kio Street 63
 Singapore 569111
Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER REAR	Deformed	1,259.42 FL	*1,259.42 FL
2	1	*BUMPER SPOILER FRT	Deformed	181.75 FL	*181.75 FL
3	1	*BUMPER ABSORBER FRT	Not Necessary	394.68 FL	*- FL
4	1	*BUMPER RETAINER FRT LH	Deformed	151.41 FL	*151.41 FL
5	1	*BUMPER SUPPORT FRT	Not Necessary	123.88 FL	*- FL
6	1	*BUMPER RETAINER FRT RH	Not Necessary	150.77 FL	*- FL
7	1	*BUMPER SUPPORT FRT	Not Necessary	123.88 FL	*- FL
8	1	*BUMPER UNDERTRAY FRT	Not Necessary	472.83 FL	*- FL
9	1	*BUMPER GRILLE LOWER FRT	Not Necessary	266.80 FL	*- FL
10	1	*BUMPER FOG LAMP GRILLE LH	Cracked	207.21 FL	*207.21 FL
11	1	*BUMPER FOG LAMP GRILLE RH	Not Necessary	207.21 FL	*- FL
12	1	*BUMPER BEAM FRT	Bent	914.08 FL	*914.08 FL
13	1	*TOW COVER FRT	Not Necessary	28.61 FL	*- FL
14	1	*RADIATOR GRILLE	Not Necessary	1,707.78 FL	*- FL
15	1	*RADIATOR GRILLE BADGE RENAULT	Not Necessary	225.36 FL	*- FL
16	1	*RADIATOR GRILLE FRAME	Not Necessary	1,353.75 FL	*- FL
17	1	*FRAME FULL SUPPORT PANEL	Not Necessary	615.90 FL	*- FL
18	1	*FRAME FULL SUPPORT BRACKET	Not Necessary	89.79 FL	*- FL
19	1	*FRONT BRACE PANEL	Not Necessary	177.22 FL	*- FL
20	1	*HORN	Not Necessary	314.17 FL	*- FL
21	1	*HORN BRACKET	Not Necessary	40.45 FL	*- FL
22	1	*HEADLAMP LH	Cracked	1,184.43 FL	*1,184.43 FL
23	1	*HEADLAMP HARNESS	Not Necessary	928.29 FL	*- FL
24	1	*HEADLAMP PANEL FRT LH	Not Necessary	152.15 FL	*- FL
25	1	*BONNET	Repair	1,941.63 FL	*- FL
26	1	*BONNET INSULATOR	Not Necessary	405.73 FL	*- FL
27	1	*BONNET STRUT LH	Not Necessary	88.61 FL	*- FL
28	1	*BONNET STRUT RH	Not Necessary	88.61 FL	*- FL
29	1	*BONNET HINGE LH	Not Necessary	348.31 FL	*- FL
30	1	*BONNET HINGE RH	Not Necessary	348.31 FL	*- FL
31	1	*BONNET LOCK	Not Necessary	305.48 FL	*- FL
32	1	*BONNET CABLE	Not Necessary	119.19 FL	*- FL
33	1	*BONNET CABLE COVER	Not Necessary	161.03 FL	*- FL
34	1	*BONNET SEAL OUTER	Not Necessary	92.36 FL	*- FL
35	1	*BONNET SEAL INNER	Not Necessary	157.28 FL	*- FL
36	1	*FENDER PANEL FRT LH	Buckled	783.83 FL	*783.83 FL
37	1	*WHEELARCH FRT LH	Not Necessary	278.84 FL	*- FL
38	1	*FENDER BRACKET LOWER LH	Not Necessary	15.79 FL	*- FL
39	1	*FENDER INSULATOR LH	Deformed	130.84 FL	*130.84 FL
40	1	*WIPER RESERVOIR	Not Necessary	348.25 FL	*- FL
41	1	*WIPER RESERVOIR NECK	Not Necessary	136.11 FL	*- FL
42	1	*WIPER RESERVOIR MOTOR	Not Necessary	270.06 FL	*- FL
43	1	*AIR CLEANER LOWER	Not Necessary	271.26 FL	*- FL
44	1	*AIR CLEANER HOSE	Not Necessary	76.14 FL	*- FL
45	1	*ENGINE TOP COVER 2.0	Not Necessary	555.12 FL	*- FL
46	1	*ENGINE OIL SUMP	Not Necessary	484.67 FL	*- FL
47	1	*BASE BATTERY TRAY	Not Necessary	363.40 FL	*- FL
48	1	*AIR CLEANER BOX	Not Necessary	464.20 FL	*- FL
49	1	*TURBO DUCT	Not Necessary	1,027.80 FL	*- FL
50	1	*A/C HEATER VALVE	Not Necessary	484.50 FL	*- FL
51	1	*SUBFRAME OUTER FRT	Not Necessary	2,652.45 FL	*- FL
52	1	*SUBFRAME BRACKET OUTER LH	Not Necessary	92.36 FL	*- FL
53	1	*SUBFRAME BRACKET OUTER RH	Not Necessary	92.36 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*ENGINE UNDERTRAY	Not Necessary	564.98 FL	*- FL
55	1		*A/C CONDENSER	Not Necessary	2,020.37 FL	*- FL
56	1		*A/C CONDENSER GARNISH LH UPPER	Not Necessary	39.67 FL	*- FL
57	1		*A/C CONDENSER GARNISH RH UPPER	Not Necessary	39.67 FL	*- FL
58	1		*A/C CONDENSER GARNISH LH	Not Necessary	58.81 FL	*- FL
59	1		*A/C CONDENSER GARNISH RH	Not Necessary	59.60 FL	*- FL
60	1		*A/C PIPE CONDENSER TO COMPRESSOR	Not Necessary	208.39 FL	*- FL
61	1		*A/C PIPE CONDENSER TO EXPENSION VALVE	Not Necessary	658.72 FL	*- FL
62	1		*A/C PIPE COMPRESSOR	Not Necessary	334.29 FL	*- FL
63	1		*A/C PIPE	Not Necessary	658.72 FL	*- FL
64	1		*A/C COMPRESSOR	Not Necessary	2,684.61 FL	*- FL
65	1		*AIR COOLER	Not Necessary	792.60 FL	*- FL
66	1		*AIR INTERCOOLER HOSE (LONG)	Not Necessary	1,014.13 FL	*- FL
67	1		*AIR INTERCOOLER HOSE (SHORT)	Not Necessary	375.14 FL	*- FL
68	1		*TRANSMISSION COOLER	Not Necessary	1,219.30 FL	*- FL
69	1		*TRANSMISSION COOLER PAD	Not Necessary	17.96 FL	*- FL
70	1		*RADIATOR	Not Necessary	1,202.20 FL	*- FL
71	2		*RADIATOR STUD UPPER	Not Necessary	14.41 FL	*- FL
72	2		*RADIATOR BUSH UPPER	Not Necessary	50.12 FL	*- FL
73	1		*RADIATOR MTG LOWER	Not Necessary	55.85 FL	*- FL
74	1		*RADIATOR FAN COWLING	Not Necessary	820.54 FL	*- FL
75	1		*RADIATOR FAN MOTOR LH	Not Necessary	967.36 FL	*- FL
76	1		*RADIATOR FAN MOTOR RH	Not Necessary	1,479.46 FL	*- FL
77	1		*RADIATOR TANK	Not Necessary	324.62 FL	*- FL
78	1		*RADIATOR HOSE UPPER	Not Necessary	240.56 FL	*- FL
79	1		*RADIATOR HOSE LOWER	Not Necessary	491.18 FL	*- FL
80	1		*RADIATOR TANK HOSE	Not Necessary	61.18 FL	*- FL
81	1		*AUTO COMPUTER	Not Necessary	5,032.17 FL	*- FL
82	1		*INJECTION COMPUTER	Not Necessary	4,706.30 FL	*- FL
83	1		*RHD HYDRAULIC POWER (ROCK & PINION)	Not Necessary	5,154.52 FL	*- FL
84	1		*STEERING PUMP ELECTRIC	Not Necessary	2,306.90 FL	*- FL
85	1		*STEERING PINION RACK	Not Necessary	4,413.11 FL	*- FL
86	1		*DOOR PANEL FRT LH	Buckled	2,844.66 FL	*2,844.66 FL
87	1		*DOOR HINGE UPPER LH	Not Necessary	261.28 FL	*- FL
88	1		*DOOR HINGE LOWER LH	Not Necessary	300.55 FL	*- FL
89	1		*DOOR CHECK FRT LH	Not Necessary	194.77 FL	*- FL
90	1		*DOOR LOCK FRT LH	Not Necessary	908.75 FL	*- FL
91	1		*DOOR CATCH FRT LH	Not Necessary	131.23 FL	*- FL
92	1		*DOOR HANDLE OUTER FRT LH	Not Necessary	477.76 FL	*- FL
93	1		*DOOR HANDLE COVER FRT LH	Not Necessary	13.22 FL	*- FL
94	1		*DOOR HANDLE MODULE FRT LH	Not Necessary	133.60 FL	*- FL
95	1		*DOOR REGULATOR FRT LH	Not Necessary	505.19 FL	*- FL
96	1		*DOOR REGULATOR MOTOR FRT LH	Not Necessary	796.46 FL	*- FL
97	1		*DOOR REGULATOR GUIDE FRT LH	Not Necessary	120.97 FL	*- FL
98	1		*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
99	1		*DOOR GUIDE REAR LH	Not Necessary	176.82 FL	*- FL
100	1		*DOOR HINGE UPPER LH	Not Necessary	274.50 FL	*- FL
101	1		*DOOR HINGE LOWER LH	Not Necessary	300.55 FL	*- FL
102	1		*DOOR CHECK REAR LH	Not Necessary	203.06 FL	*- FL
103	1		*DOOR LOCK REAR LH	Not Necessary	908.75 FL	*- FL
104	1		*DOOR HANDLE OUTER REAR LH	Not Necessary	126.49 FL	*- FL
105	1		*DOOR HANDLE CAP REAR LH	Not Necessary	35.52 FL	*- FL
106	1		*DOOR HANDLE SEAL REAR LH	Not Necessary	7.89 FL	*- FL
107	1		*DOOR HANDLE COVER REAR LH	Not Necessary	13.22 FL	*- FL
108	1		*DOOR HANDLE MODULE REAR LH	Not Necessary	133.60 FL	*- FL
109	1		*DOOR REGULATOR REAR LH	Not Necessary	1,135.10 FL	*- FL
110	1		*DOOR REGULATOR MOTOR REAR LH	Not Necessary	893.75 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
111	1		*DOOR REGULATOR NUT REAR LH	Not Necessary	12.43 FL	*- FL
112	1		*DOOR REGULATOR MOTOR SCREW REAR L70Y	Not Necessary	6.31 FL	*- FL
113	1		*DOOR FINISHER REAR LH	Not Necessary	423.10 FL	*- FL
114	1		*DOOR MOULDING REAR LH	Not Necessary	176.82 FL	*- FL
115	1		*DOOR MOULDING CLIP L70Y	Not Necessary	5.92 FL	*- FL
116	1		*DOOR MOULDING SCREW L70Y	Not Necessary	6.91 FL	*- FL
117	1		*DOOR CASING REAR LH	Not Necessary	1,509.06 FL	*- FL
118	1		*DOOR WATER SHIELD REAR LH	Not Necessary	30.39 FL	*- FL
119	1		*DOOR CASING CLIP	Not Necessary	12.63 FL	*- FL
120	1		*DOOR CASING LIGHT L70Y	Not Necessary	48.74 FL	*- FL
121	1		*DOOR FINISHER INNER REAR LH	Not Necessary	323.44 FL	*- FL
122	1		*DOOR FINISHER BRACKET INNER REAR LH	Not Necessary	46.97 FL	*- FL
123	1		*DOOR FINISHER BRACKET INNER REAR LH	Not Necessary	20.33 FL	*- FL
124	1		*DOOR FINISHER BRACKET INNER REAR LH	Not Necessary	20.33 FL	*- FL
125	1		*DOOR FINISHER BRACKET INNER REAR LH	Not Necessary	20.33 FL	*- FL
126	1		*DOOR GRAB HANDLE REAR LH	Not Necessary	210.96 FL	*- FL
127	1		*DOOR BLIND REAR LH	Not Necessary	741.80 FL	*- FL
128	1		*DOOR WEATHERSTRIP REAR LH	Not Necessary	410.66 FL	*- FL
129	1		*DOOR SEAL REAR LH	Not Necessary	162.02 FL	*- FL
130	1		*DOOR GLASS RUBBER SEAL REAR LH	Not Necessary	229.31 FL	*- FL
131	1		*DOOR WAIST SEAL OUTER REAR LH	Not Necessary	334.69 FL	*- FL
132	1		*DOOR WAIST SEAL INNER REAR LH	Not Necessary	115.64 FL	*- FL
133	1		*DOOR MIRROR ASSY LH	Cut	1,483.40 FL	*1,483.40 FL
134	1		*ROCKER PANEL INNER GARNISH LH	Not Necessary	466.51 FL	*- FL
135	1		*ROCKER PANEL INNER LH	Not Necessary	1,024.79 FL	*- FL
136	1		*ROCKER PANEL CENTER LH	Repair	990.25 FL	*- FL
137	1		*DOOR CHASSIS WIRE	Not Necessary	2,670.00 FL	*- FL
138	1		*LOWER ARM LH L70Y	Not Necessary	685.76 FL	*- FL
139	1		*KNUCKLE ARM LH L70Y	Not Necessary	846.98 FL	*- FL
140	1		*ABSORBER FRT LH L70Y	Not Necessary	360.54 FL	*- FL
141	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*- FS
142	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
143	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
144	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
145	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
146	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
147	1		*TOW COVER FRT	Not Necessary	14.50 FS	*- FS
148	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
149	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
150	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
151	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
152	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
153	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
154	1		*SET FRONT LICENCE PLATE WITH HOLDER	Not Necessary	80.00 FS	*- FS
155	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*80.00 FS
156	1		*FRONT DOOR STICKER CHASSIS	Necessary	50.00 FS	*50.00 FS
157	1		*REAR DOOR STICKER 6555-3333	Necessary	80.00 FS	*80.00 FS
158	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
159	1		*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*- FS
160	1		*DOOR HINGE BOLT	Not Necessary	10.85 FS	*- FS
161	1		*DOOR HINGE NUT RH	Not Necessary	14.60 FS	*- FS
162	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
163	1		*DOOR CHECK NUT	Not Necessary	3.75 FS	*- FS
164	1		*DOOR LOCK SCREW L70Y	Not Necessary	6.12 FS	*- FS
165	1		*DOOR CATCH SCREW L70Y	Not Necessary	10.06 FS	*- FS
166	1		*FRONT LEFT TYRE RIM	Cut	380.00 FS	*380.00 FS
167	1		*FRONT LEFT TYRE	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	90,617.26	9,797.03
				- List Item Discount on L Items 10.00/10.00% (S\$)	8,906.32	914.10
				Total Parts (S\$)	81,710.94	8,882.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	5,400.00	600.00
2	TOWING FEES	New	120.00	0.00
3	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	5,000.00	1,300.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
8	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALACING	New	170.00	0.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	30.00
10	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
11	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
12	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
13	TO REMOVE AND RENEW POWER STEERING PUMP ,OIL COOLER PIPE AND FINAL CHECKING AND TESTING	New	440.00	0.00
14	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET	New	480.00	0.00
15	TO DROP DIESEL TANK ,PIPES ,HOSES TO FACILITATE BODYWORK REPAIR ,FINAL CHECKING AND TESTING	New	380.00	0.00
16	TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR CONDENSER	New	380.00	0.00
17	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
18	TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR INRRERCOOLER	New	170.00	0.00
19	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (S\$)			15,400.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >