

Trans-cab Auto Services Pte Ltd**AAD1810-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5264L

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5264L

VF1ABL15AUC276190

RENAULT

LATITUDE

4.10.2018

AIG

		PART		LIST
1	1	BUMPER COVER FRT	/ ee	\$ 1,259.42
2	1	BUMPER SPOILER FRT	X ee	\$ 181.75
3	1	BUMPER ABSORBER FRT	X } nn	\$ 394.68
4	1	BUMPER RETAINER FRT LH	- ne	\$ 151.41
5	1	BUMPER SUPPORT FRT	X	\$ 123.88
6	1	BUMPER RETAINER FRT RH	X } nn	\$ 150.77
7	1	BUMPER SUPPORT FRT	X	\$ 123.88
8	1	BUMPER UNDERTRAY FRT	X	\$ 472.83
9	1	BUMPER GRILLE LOWER FRT	X	\$ 266.80
10	1	BUMPER FOG LAMP GRILLE LH	- cna	\$ 207.21
11	1	BUMPER FOG LAMP GRILLE RH	X nn	\$ 207.21
12	1	BUMPER BEAM FRT	/ BT	\$ 914.08
13	1	TOW COVER FRT	X nn	\$ 28.61
14	1	RADIATOR GRILLE	?	\$ 1,707.78
15	1	RADIATOR GRILLE BADGE 'RENAULT'	?	\$ 225.36
16	1	RADIATOR GRILLE FRAME	?	\$ 1,353.75
17	1	FRAME FULL SUPPORT PANEL	?	\$ 615.90
18	1	FRAME FULL SUPPORT BRACKET	?	\$ 89.79
19	1	FRONT BRACE PANEL	X	\$ 177.22
20	1	HORN	X } nn.	\$ 314.17
21	1	HORN BRACKET	X	\$ 40.45
22	1	HEADLAMP LH	- cna	\$ 1,184.43
23	1	HEADLAMP HARNESS	?	\$ 928.29
24	1	HEADLAMP PANEL FRT LH	?	\$ 152.15
25	1	BONNET	X repair.	\$ 1,941.63
26	1	BONNET INSULATOR	X	\$ 405.73
27	1	BONNET STRUT LH	X } nn	\$ 88.61
28	1	BONNET STRUT RH	X	\$ 88.61

Trans-cab Auto Services Pte Ltd**AAD1810-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5264L

29	1	BONNET HINGE LH	X		\$	348.31
30	1	BONNET HINGE RH	X		\$	348.31
31	1	BONNET LOCK	X		\$	305.48
32	1	BONNET CABLE	X		\$	119.19
33	1	BONNET CABLE COVER	X		\$	161.03
34	1	BONNET SEAL OUTER	X		\$	92.36
35	1	BONNET SEAL INNER	X		\$	157.28
36	1	FENDER PANEL FRT LH	- buc		\$	783.83
37	1	WHEELARCH FRT LH	X	nn	\$	278.84
38	1	FENDER BRACKET LOWER LH	?		\$	15.79
39	1	FENDER INSULATOR LH	- ee		\$	130.84
40	1	WIPER RESERVOIR	?		\$	348.25
41	1	WIPER RESERVOIR NECK	?		\$	136.11
42	1	WIPER RESERVOIR MOTOR	?		\$	270.06
43	1	AIR CLEANER LOWER	?		\$	271.26
44	1	AIR CLEANER HOSE	?		\$	76.14
45	1	ENGINE TOP COVER 2.0	X		\$	555.12
46	1	ENGINE OIL SUMP	X		\$	484.67
47	1	BASE BATTERY TRAY	X		\$	363.40
48	1	AIR CLEANER BOX	X		\$	464.20
49	1	TURBO DUCT	X		\$	1,027.80
50	1	A/C HEATER VALVE	X		\$	484.50
51	1	SUBFRAME OUTER FRT	X		\$	2,652.45
52	1	SUBFRAME BRACKET OUTER LH	X		\$	92.36
53	1	SUBFRAME BRACKET OUTER RH	X		\$	92.36
54	1	ENGINE UNDERTRAY	X		\$	564.98
55	1	A/C CONDENSER	X		\$	2,020.37
56	1	A/C CONDENSER GARNISH LH UPPER	X		\$	39.67
57	1	A/C CONDENSER GARNISH RH UPPER	X		\$	39.67
58	1	A/C CONDENSER GARNISH LH	X		\$	58.81
59	1	A/C CONDENSER GARNISH RH	X		\$	59.60
60	1	A/C PIPE CONDENSER TO COMPRESSOR	X		\$	208.39
61	1	A/C PIPE CONDENSER TO EXPENSION VALVE	X		\$	658.72
62	1	A/C PIPE COMPRESSOR	X		\$	334.29
63	1	A/C PIPE	X		\$	658.72
64	1	A/C COMRPRESSOR	X		\$	2,684.61
65	1	AIR COOLER	X		\$	792.60
66	1	AIR INTERCOOLER HOSE (LONG)	X		\$	1,014.13

Trans-cab Auto Services Pte Ltd**AAD1810-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5264L

67	1	AIR INTERCOOLER HOSE (Short)	X	\$	375.14
68	1	TRANSMISSION COOLER	X	\$	1,219.30
69	1	TRANSMISSION COOLER PAD	X	\$	17.96
70	1	RADIATOR	X	\$	1,202.20
71	2	RADIATOR STUD UPPER	X	\$	14.41
72	2	RADIATOR BUSH UPPER	X	\$	50.12
73	2	RADIATOR MTG LOWER	X	\$	55.85
74	1	RADIATOR FAN COWLING	X	\$	820.54
75	1	RADIATOR FAN MOTOR LH	X	\$	967.36
76	1	RADIATOR FAN MOTOR RH	X	\$	1,479.46
77	1	RADIATOR TANK	X	\$	324.62
78	1	RADIATOR HOSE UPPER	X	\$	240.56
79	1	RADIATOR HOSE LOWER	X	\$	491.18
80	1	RADIATOR TANK HOSE	X	\$	61.18
81	1	AUTO COMPUTER	X	\$	5,032.17
82	1	INJECTION COMPUTER	X	\$	4,706.30
83	1	RHD HYDRAULIC POWER(ROCK&PINION)	X	\$	5,154.52
84	1	STEERING PUMP ELECTRIC	X	\$	2,306.90
85	1	STEERING PINION RACK	X	\$	4,413.11
86	1	DOOR PANEL FRT LH	X	\$	2,844.66
87	1	DOOR HINGE UPPER LH	X	\$	261.28
88	1	DOOR HINGE LOWER LH	X	\$	300.55
89	1	DOOR CHECK FRT LH	X	\$	194.77
90	1	DOOR LOCK FRT LH	X	\$	908.75
91	1	DOOR CATCH FRT LH	X	\$	131.23
92	1	DOOR HANDLE OUTER FRT LH	X	\$	477.76
93	1	DOOR HANDLE COVER FRT LH	X	\$	13.22
94	1	DOOR HANDLE MODULE FRT LH	X	\$	133.60
95	1	DOOR REGULATOR FRT LH	X	\$	505.19
96	1	DOOR REGULATOR MOTOR FRT LH	X	\$	796.46
97	1	DOOR REGULATOR GUIDE FRT LH	X	\$	120.97
98	1	DOOR PANEL REAR LH	X	\$	2,844.66
99	1	DOOR GUIDE REAR LH	X	\$	176.82
100	1	DOOR HINGE UPPER LH	X	\$	274.50
101	1	DOOR HINGE LOWER LH	X	\$	300.55
102	1	DOOR CHECK REAR LH	X	\$	203.06
103	1	DOOR LOCK REAR LH	X	\$	908.75
104	1	DOOR HANDLE OUTER REAR LH	X	\$	126.49

Trans-cab Auto Services Pte Ltd**AAD1810-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5264L

105	1	DOOR HANDLE CAP REAR LH	X	\$	35.52
106	1	DOOR HANDLE SEAL REAR LH	X	\$	7.89
107	1	DOOR HANDLE COVER REAR LH	X	\$	13.22
108	1	DOOR HANDLE MODULE REAR LH	X	\$	133.60
109	1	DOOR REGULATOR REAR LH	X	\$	1,135.10
110	1	DOOR REGULATOR MOTOR REAR LH	X	\$	893.75
111	1	DOOR REGULATOR NUT REAR LH	X	\$	12.43
112	1	DOOR REGULATOR MOTOR SCREW REAR L70Y	X	\$	6.31
113	1	DOOR FINISHER REAR LH	X	\$	423.10
114	1	DOOR MOULDING REAR LH	X	\$	176.82
115	1	DOOR MOULDING CLIP L70Y	X	\$	5.92
116	1	DOOR MOULDING SCREW L70Y	X	\$	6.91
117	1	DOOR CASING REAR LH	X	\$	1,509.06
118	1	DOOR WATER SHIELD REAR LH	X	\$	30.39
119	1	DOOR CASING CLIP	X	\$	12.63
120	1	DOOR CASING LIGHT L70Y	X	\$	48.74
121	1	DOOR FINISHER INNER REAR LH	X	\$	323.44
122	1	DOOR FINISHER BRACKET INNER REAR LH	X	\$	46.97
123	1	DOOR FINISHER BRACKET INNER REAR LH	X	\$	20.33
124	1	DOOR FINISHER BRACKET INNER REAR LH	X	\$	20.33
125	1	DOOR FINISHER BRACKET INNER REAR LH	X	\$	20.33
126	1	DOOR GRAB HANDLE REAR LH	X	\$	210.96
127	1	DOOR BLIND REAR LH	X	\$	741.80
128	1	DOOR WHEATHESTRIIP REAR LH	X	\$	410.66
129	1	DOOR SEAL REAR LH	X	\$	162.02
130	1	DOOR GLASS RUNNER SEAL REAR LH	X	\$	229.31
131	1	DOOR WAIST SEAL OUTER REAR LH	X	\$	334.69
132	1	DOOR WAIST SEAL INNER REAR LH	X	\$	115.64
133	1	DOOR MIRROR ASSY LH	CA	\$	1,483.40
134	1	ROCKER PANEL INNER GARNISH LH	X Repair X Repair NN	\$	466.51
135	1	ROCKER PANEL INNER LH	X NN	\$	1,024.79
136	1	ROCKER PANEL CENTER LH	X Repair NN	\$	990.25
137	1	DOOR HARNESS WIRE	X NN	\$	2,670.00
138	1	LOWER ARM LH L70Y	?	\$	685.76
139	1	KUNCKLE ARM LH L70Y	?	\$	846.98
140	1	ABSORBER FRT LH L70Y	X NN	\$	360.54

Trans-cab Auto Services Pte Ltd**AAD1810-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5264L

TOTAL	\$	89,063.12
10%	\$	8,906.31
	\$	80,156.81

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	X NN	\$	52.00
2	1SET	BUMPER CLIP FRT	/ ml	\$	66.00
3	1	BUMPER BRACKET CLIP FRT LH	X	\$	12.00
4	1	BUMPER SUPPORT CLIP FRT LH	X	\$	10.50
5	1	BUMPER BRACKET CLIP FRT RH	X	\$	12.00
6	1	BUMPER SUPPORT CLIP FRT RH	X	\$	10.50
7	1	TOW COVER FRT	X	\$	14.50
8	1SET	RADAIOR GRILLE SCREW	X	\$	16.00
9	1SET	BUMPER GRILLE LOWER CLIP	X	\$	69.00
10	1SET	FRAME FULL SUPPORT PANEL CLIP	X	\$	70.00
11	2	FRAME FULL SUPPORT PANEL NUT	X	\$	20.00
12	2	FRAME FULL SUPPORT PANEL STUD	X	\$	30.00
21	1	Windscreen moulding	X	\$	100.00
22	1SET	Front licence plate with holder	X	\$	80.00
22	1	FRONT DOOR STICKER 'Trans-cab'	/	\$	80.00
22	1	FRONT DOOR STICKER 'Chassis'	/	\$	50.00
22	1	REAR DOOR STICKER '6555 3333'	/	\$	80.00
22	1	DOOR CHECK BOLT	X	\$	22.69
22	1	DOOR GUIDE SCREW	X	\$	10.85
22	1	DOOR HINGE BOLT	X	\$	10.85
22	1	DOOR HINGE NUT RH	X	\$	14.60
22	1	DOOR CHECK BOLT	X	\$	22.69
22	1	DOOR CHECK NUT	X	\$	3.75
22	1	DOOR LOCK SCREW L70Y	X	\$	6.12
22	1	DOOR CATCH SCREW L70Y	X	\$	10.06
22	1	FRONT LEFT TYRE RIM	/ CnA	\$	380.00
22	1	FRONT LEFT TYRE	X N/V	\$	300.00

TOTAL	\$	1,554.13
TOTAL PARTS	\$	81,710.94

Trans-cab Auto Services Pte Ltd**AAD1810-063**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5264L**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	600	5,400.00
Towing Fees.	\$	?	120.00
To apply paint protection system (PPS) maintain and enhancement	\$	NN X	380.00
Putty and spray painting of the affected portion.	\$	1300	5,000.00
To rust-proofing of the affected areas.	\$	60	170.00
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	NN X	380.00
To check steering geometry and computer wheel alignment	\$	60	220.00
To transfer of tire, rim and on wheel balancing.	\$	NN X	170.00
To Check Electrical Lighting Concerned.	\$	30	170.00
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	X	380.00
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	NN { X	380.00
To lift-up engine with gear box and refit.	\$	X	440.00

Trans-cab Auto Services Pte Ltd

AAD1810-063

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5264L

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	X	440.00
To remove and refit air bag system and reset.	\$	X	480.00
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	NN	X 380.00
To vacuum, replace, refix and recharge air condenser	\$	X	380.00
To replace, refix and top up coolant for radiator	\$	X	170.00
To vacuum, replace, refix and recharge Air Intercooler	\$	X	170.00
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	X	170.00

6 Days.

TOTAL	\$	15,400.00
--------------	-----------	------------------

Lump sum repair.

Over All Total	\$	97,110.94
-----------------------	-----------	------------------

After repair photos.

Repair Days (LUMP SUM)**20 DAYS**

Gmo Corp.

05/10/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: