



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 11.10.2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SJR3349L MITSUBISHI LANCER (2008)

To Supply Nett Parts

1) 1pc	Rear bumper	\$	815.00	DE ✓
2) 1set	Rear bumper clip	\$	20.00	RA ✓
3) 1pc	Rear bumper right reflector	\$	22.00	CA ✓
4) 1pc	Rear bumper tow hook cover	\$	21.00	MS ✓

Sub Total Parts	\$	878.00
Less: 10% discount	\$	(87.80)
	\$	790.20

To supply S.Nett parts

1) 1pc	Rear number plate	\$	38.00	35 Bt ✓
2) 1set	Reverse sensor	\$	170.00	RM ✓
		\$	208.00	

L/charges

1) To remove & replace reverse sensor, check wiring	\$	40.00	✓
2) To remove rear bumper. Knock rear end panel. Replace rear	\$	400.00	200 ✓

bumper. Align & adjust rear bumper & boot lid.

3) To putty respray painting rear bumper & rear end panel. To polish. \$ 450.00 ~~300~~

Sub Total L/charges	\$ 890.00
	<u>\$ 1,888.20</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul

Hp 90010068

2 days

L/S

12/10/18 @ 1500hrs

Ready after repair