

22/03/2002

ASS. REC. BY:

REF: CS3/CTI 18018535/T1cd302 Special Instruction:

Surveyor:

Munim

Tau Hich

ASSIGNMENT (Office)

From (Person):

E Elaine Cheong

of

CTI

Date/Time:

11/10/18 @ 17:15pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 1374T

Insured:

GBA 4030H

at Workshop m/s

MS Car Auto

Tel:

6385 1838

of

8 Kaki Bkt Ave 4 # 01-07

Policy No:

DMCVSN1810721800

Claim No:

SNM18DO4817C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 5/10/2018

CA / REV / REP. / REV 24 HRS ^(up)

H.O.D. Endorsement:

Date/Time: 9:30am @ 12/10/18

Person Contacted:

June

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SKV 1374T - X
	GBA 4030H - C6/AIG/3020818/Ksa 392 DOA: 4/11/2013

Surveyor

Taylor

REF: CTF

ASSIGNMENT

From: _____ Date: 12/10/2018

Estimated Cost: _____

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKV 1374T

at Workshop m/s MS Car Auto

of 8 kaki Bkt Ave 4 # 01-07

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKV/374T Yr Regn: 1

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda C.C

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 5824/ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM 6 B M 44786.0308667

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 12/10/18

Survey held at MS Car Auto

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No G/A

Estimated repair range \$8,000 - \$9,500

24/10/2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9

Resurvey No. of Trip: -

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee: 150

Transportation: _____

S + RS: SI

Photos

Others

TOTAL

150

Report Format: PRG

Lump Sum / I.B.I: (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Oct 2018		11 Oct 2018 17:15 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SG LEASING PTE LTD, Co. Reg. No.: 201317520E		[Created by insurer]	
Main Claimant:	SIN MUN YEE MAY, ID: S2539158F			
Vehicle Reg. No.:	SKV1374T	Date of Loss:	05/10/2018 14:00 - :59	
Claim Type:	TP / SNM18D04817C02	Policy/Cover Note No.:	DMCVSN1810721800 (Comprehensive)	
Vehicle Reg. No. (Insured):	GBA4030H	Policy No. (Claimant):		
Repairer:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838		Excess:	S\$0.00
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/10/2018]			
Adj Asg. Remarks:	NO EST, CASE W/O SJE.			
ASSOCIATED MAIL RECEIVED				

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

ROY & PARTNERS

(Business Registration No. 53131170L)
Advocates & Solicitors
Commissioner For Oaths
Notary Public

MONOJ KUMAR ROY LLB (Hons.) S'pore
KERUSHNAN S/O SIVALINGKAM (Hons.) London

101 Cecil Street #11-09 Tong Eng Building, Singapore 069533
Tel : 6536 8466 Fax : 6536 1963 (Not For Service Of Documents)
Enquiries: roynpartners@roynpartners.com.sg

Your Ref : Your insured vehicle: GBA 4030H
Our Ref : MKR/307/7113/2018/as.wl;

10th October 2018

IMMEDIATE ATTENTION

M/S CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD BY FAX: 6224 7175 ONLY
3 Anson Road,
#16-00 Springleaf Tower,
Singapore 079909
(Attn: Motor Claims Department)

Dear Sirs,

Dear Sirs,

CLAIMANT: SIN MUN YEE, MAY (OWNER OF SKV 1374T)
ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKV 1374T AND GBA 4030H
ALONG 2 ANG MO KIO STREET 64 CAR PARK ON 05.10.2018 AT ABOUT 1445 HOURS.


We refer to the above matter.

We act for Sin Mun Yee, May, the owner of motor car No. **SKV 1374T**.

We are instructed by our client to notify you of a road traffic accident on 05.10.2018 at about 2.45 pm along 2 Ang Mo Kio Street 64 car park involving our client's motor car registration number **SKV 1374T** and motor lorry registration number **GBA 4030H** driven by your insured at the material time. A copy of the Singapore Accident Statement and traffic police report is enclosed.

As a result of the accident, our client's motor car **SKV 1374T** has been damaged. Before our client proceed to repair the damaged motor car, please let us know within **two (2) working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motor car **SKV 1374T** at our client's repairer workshop, M/s MS Car Auto Pte Ltd at No. 8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875, Your said surveyor may contact Mr. Desmond at 9725 4442. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor vehicle without further reference to you.

Yours faithfully



MONOJ KUMAR ROY
Encl.

Cc: Clients (MS CAR AUTO PTE LTD)
(SKV 1374T)

(By Fax: 6386 1838)



**SINGAPORE
POLICE FORCE**



T/20181006/2058

1 of 3

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

Report No. T/20181006/2058

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/10/2018 11:47	Vide Report No.:	Station Diary No.: 36
--	------------------	--------------------------

Informant's Particulars

Name of Informant: TAN ENG SIANG			Address: 22 BUKIT BATOK STREET 52 #30-03 SINGAPORE 659245	
ID Type / ID No.: NRIC NO / S2539158F			Contact No.: Home/Office:	Mobile: 94486395
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 64	Date of Birth: 26/04/1954	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: Chief operating officer/General Manager			Driving Licence Information: Class: 2B,2A,2,3	Date of Expiry:

General Information of the Accident

General Information of the Accident				
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 05/10/2018 14:45	Type of Location: Car Park
Location: Along Road 1 ANG MO KIO STREET 64				
Within the premises of Econ Industrial Building Driveway, 2 Ang Mo Kio St 64, S569084				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Rear to side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBA4030H	Lorry	TOYOTA	Pickup	White	Slightly Damaged	0
SKV1374T	Car	MAZDA	3	Blue	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL		



**SINGAPORE
POLICE FORCE**



T/20181006/2058

2 of 3

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

Report No. T/20181006/2058

CONTINUATION OF REPORT

Driver			
Name	Wong Kwok Meng	ID No.	S1794593I
Related Vehicle	GBA4030H (Lorry)	Contact No.	86211047
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN ENG SIANG	ID No.	S2539158F
Related Vehicle	SKV1374T (Car)	Contact No.	94486395
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 05/10/2018 at 1443hrs, I was driving out from my building carpark inside the premises of Econ Industrial building when a lorry bearing plate number GBA4030H who was earlier parked at the side suddenly reversed and hit onto the right side of my car bearing plate number SKV1374T. I have taken photo of the damages on the right side of the car. We then exchanged particulars and I informed him that I would be making a police report.

There were no injuries to both parties.

I have an in car camera but the camera recording is corrupted.

I am lodging this report for insurance record purposes.



**SINGAPORE
POLICE FORCE**



T/20181006/2058

3 of 3

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

Report No. T/20181006/2058

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Insp HENDRA DARMAWAN MOHD ISMAIL

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIA /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
06/10/2018 11:47

Classification Of Case:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Oct 2018		11 Oct 2018 17:15 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SG LEASING PTE LTD , Co. Reg. No.: 201317520E									
Main Claimant: SIN MUN YEE MAY , ID: S2539158F									
Vehicle Reg. No.: SKV1374T		Date of Loss: 05/10/2018 14:00 - :59							
Claim Type: TP / SNM18D04817C02		Policy/Cover Note No.: DMCVSN1810721800 (Comprehensive)							
Vehicle Reg. No. (Insured): GBA4030H		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 22/10/2018]									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKV1374T (SNM18D04817C02)
[GBA4030H]
TP
SIN MUN YEE MAY
Oct 5 2018 2:00PM
[SG LEASING PTE LTD]
Ms Car Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print			
1	08/10/18 12:10	Accident Statement		Load HTM				
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print			
1	08/10/18 12:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
2	08/10/18 12:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
3	08/10/18 12:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
4	08/10/18 12:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
5	08/10/18 12:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
6	08/10/18 12:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	23/10/18 18:04	General View		Load PDF				
Documentation							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print			
1	11/10/18 17:15	PRS WITH TP GIA		Load PDF				
2	11/10/18 17:15	OI GIA		Load PDF				
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print			
1	08/10/18 12:05	Sketch Plan [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
2	08/10/18 12:05	Sketch Plan #2 [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
3	08/10/18 12:05	Sketch Plan #3 [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		
1	08/10/18 12:10	Accident Statement		
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		
1	08/10/18 12:06	Accident Photo		
2	08/10/18 12:06	Accident Photo		
3	08/10/18 12:06	Accident Photo		
4	08/10/18 12:06	Accident Photo		
5	08/10/18 12:06	Accident Photo		
6	08/10/18 12:06	Accident Photo		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
				<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	08/10/18 12:05	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	08/10/18 12:05	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>
3	08/10/18 12:05	Sketch Plan #3	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118018535/T1CD3E2

Date: 02/11/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1810721800

Claimant Vehicle
No : SKV1374TInsured Vehicle
No : GBA4030H

Date of Loss: 05/10/2018

Nature of Claim: TP

Claim
No: SNM18D04817C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV1374T

Make & Model: MAZDA 5, 2.0 (A)

Reg. Date: (Man. Year:)

Colour: Blue

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: HIDDEN

Chassis No: JM6BM44A8G0308667

Odometer: 58241 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/10/2018

Date Inspected: 12/10/2018 Inspected At:

Ms Car Auto Pte Ltd (HQ)
8 KAKI BUKIT AVE 4 #01-07 PREMIER @
KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 -\$9,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Nov 2018)

Parts: M1-MPV MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV1374T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >