


Assessment Details

[General & Workshop Details](#)
[Vehicle & Driver Details](#)
[Vehicle Condition](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

General Details

Involving 1 2008 MITSUBISHI LANCER 2.0 (SJJ7331C)

Date of Loss 11 October 2018

Time of Loss 7.30

Loss Description SJJ7331C (INSD) C/W SJU8785L (TP)

Comment

Workshop Details

Total Rebate Amount

Nett Loss Amount \$19,488.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion *

Assessment Details

[General & Workshop Details](#)
[Vehicle & Driver Details](#)
[Vehicle Condition](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

Vehicle & Driver Details

Vehicle Registration# SJJ7331C

Purchase Date

Registration State SINGAPORE

Registration Date *

Mileage

Age of Vehicle 10

CATEGORY POLICY INFORMATION

ASSESSMENT INFORMATION

Driver Details

CATEGORY FNOL INFORMATION POST SURVEY INFORMATION

Manufacturing Year 2008

Driver Name

Make MITSUBISHI

LOW KEAN FONG

MITSUBISHI

Model LANCER 2.0

Date of Birth 7 October 1976

LANCER 2.0L MIV

Age 42

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Type			Occupation	Unknown	
Type of Paint			Education Qualification	Other	
Chassis No	JMYSTCY4A9U000369	JMYSTCY4A9U001	Driving Experience	14	
Engine No	4B11CA2580	4B11CA2580	Driver License #		
Engine Capacity		1998	License Type		
Sum Insured	0	0	License Issue Date		dd/mm/yy
Market Value	0	36000	License Expiration Date		dd/mm/yy
			Address	BLK 273 YISHUN STREET 22, #09-94, 760273, Singapore	
			Address type	Residential	

POST SURVEY
INFORMATION

FNOL INFORMATION

CATEGORY

Gender

Male

Marital
status

Married

Identification
#

S7630529C



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *

12/10/2018



General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

600

Young/Inexperienced/Unnamed Driver Excess

0

Engine Modification

Yes No

Other Excess

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

215/50R17

Rear Tyre Size

215/50R17

Front left side

YOKOHAMA6mm

Rear left side

YOKOHAMA7mm

Front right side

YOKOHAMA6mm

Rear right side

YOKOHAMA7mm

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BITTR%	DISC OUNT%	SALY AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1	FRONT NUMBER PLATE					Serviceable	0	0	0	0	0	Deny	
	2	1	FRONT BUMPER COVER (WCP) (10%)					Bent	385				385	Reviewing	
	3	1	LVR RADIATOR GRILLE (WCP) (10%)					Damaged	82.5				82.5	Reviewing	
	4	1	FRT BUMPER REINF (WCP) (10%)					Bent	60.5				60.5	Reviewing	
	5	1	FRONT BUMPER SUPPORT (WCP)(10%)					Buckled	209				209	Reviewing	
	6	1	FRT BUMPER CLAMP KIT - 6PCS (WCP) (10%)					Necessary	11				11	Reviewing	
	7	1	L/LOWER AIR GRILLE (WCP) (10%)					Damaged	38.5				38.5	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./BITTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	8	1			L/F BUMPER BRACKET (WCP) (10%)			Damaged	19.8				19.8	Reviewing	
	9	1			R/F BUMPER BRACKET (WCP) (10%)			Damaged	19.8				19.8	Reviewing	
	10	1			L/F SPOILER			Serviceable	0	0	0	0	0	Deny	
	11	1			R/F SPOILER			Serviceable	0	0	0	0	0	Deny	
	12	1			GRILLE (WCP) (10%)			Dented	143				143	Reviewing	
	13	1			BONNET (WCP) (10%)			Buckled	385				385	Reviewing	
	14	1			LEFT BONNET HINGE			Repair	0	0	0	0	0	Deny	
	15	1			RIGHT BONNET HINGE			Repair	0	0	0	0	0	Deny	
	16	1			BONNET LOCK (WCP) (10%)			Damaged	49.5				49.5	Reviewing	
	17	1			BONNET FRONT SEAL (WCP) (10%)			Damaged	27.5				27.5	Reviewing	
	18	1			L/F HEADLAMP CPL (WCP) (10%)			Cracked	638				638	Reviewing	
	19	1			R/F HEADLAMP CPL (WCP) (10%)			Cracked	638				638	Reviewing	
	20	1			FRT LWR CROSSMEMBER			Repair	0	0	0	0	0	Deny	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BITTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	21	1			FRT UPP LOCK CARRIER (WCP) (10%)			Bent	165				165	Reviewing	
	22	1			L/F PANEL		Repair	Repair	0	0	0	0	0	Deny	
	23	1			R/F PANEL		Repair	Repair	0	0	0	0	0	Deny	
	24	1			L/F OUT S-MEMBER PNL		Repair	Repair	0	0	0	0	0	Deny	
	25	1			R/F OUT S-MEMBER PNL		Repair	Repair	0	0	0	0	0	Deny	
	26	1			CONDENSER (WCP) (10%)		Bent	Bent	528				528	Reviewing	
	27	1			RADIATOR (WCP) (10%)		Damaged	Damaged	528				528	Reviewing	
	28	1			RADIATOR SHROUD		Serviceable	Serviceable	0	0	0	0	0	Deny	
	29	1			L/BLOWER FAN		Serviceable	Serviceable	0	0	0	0	0	Deny	
	30	1			R/BLOWER FAN		Serviceable	Serviceable	0	0	0	0	0	Deny	
	31	1			L/FAN MOTOR		Serviceable	Serviceable	0	0	0	0	0	Deny	
	32	1			R/FAN MOTOR		Serviceable	Serviceable	0	0	0	0	0	Deny	
	33	1			INN UPP FR PANELLING (WCP) (10%)		Damaged	Damaged	60.5				60.5	Reviewing	
	34	1			LOW TONE HORN		Serviceable	Serviceable	0	0	0	0	0	Deny	
	35	12			FRT BUMPER RIVETS (WCP) (10%)		Necessary	Necessary	1.1				13.2	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BITRS%	DISC COUNT%	SALV AGE%	PART PRICE/NET	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		36	1		L/F BUMP SUP BRKT		Repair	Repair	0	0	0	0	0	Deny	
<input type="checkbox"/>		37	1		R/F BUMP SUP BRKT		Repair	Repair	0	0	0	0	0	Deny	
<input type="checkbox"/>		38	8		F/BUMP TOP SEAL CLIP (WCP)(10%)		Necessary	Necessary	1.1				8.8	Reviewing	
<input type="checkbox"/>		39	1		L/F FOG LAMP		Serviceable	Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		40	10		BONNET INSULATOR CLIP (WCP) (10%)		Necessary	Necessary	1.65				16.5	Reviewing	
<input type="checkbox"/>		41	1		L/F LWR CTR GRILL CVR (WCP)(10%)		Missing	Missing	5.5				5.5	Reviewing	
<input type="checkbox"/>		42	1		R/F LWR CTR GRILL CVR (WCP)(10%)		Missing	Missing	5.5				5.5	Reviewing	
<input type="checkbox"/>		43	10		RAD TOP GAR CLIP (WCP) (10%)		Necessary	Necessary	1.1				11	Reviewing	
<input type="checkbox"/>		44	1		L/ RAD LWR BRKT		Repair	Repair	0	0	0	0	0	Deny	
<input type="checkbox"/>		45	1		R/RAD LWR BRKT		Repair	Repair	0	0	0	0	0	Deny	
<input type="checkbox"/>		46	1		LH HEADLAMP BACK CVR (WCP)(10%)		Dented	Dented	19.8				19.8	Reviewing	

Labour

<input type="button" value="Add"/>	<input type="button" value="Approve"/>	<input type="button" value="Deny"/>	<input type="button" value="Submit All"/>						
EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
<input type="checkbox"/>	1		PANEL / MECHANICAL	319.5	0	0	Reviewing		
<input type="checkbox"/>	2		PAINTWORK	540	0	0	Reviewing		
<input type="checkbox"/>	3		PAINT / MATERIAL COSTS	227.51	0	0	Reviewing		

◀ Assessment Details

[General & Workshop Details](#)
[Vehicle & Driver Details](#)
[Vehicle Condition](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR : 5 DAYS	Reviewing			
	2	FRT NUMBER PLATE	Reviewing	40	BENT	
	3	ANTIFREEZE 4 LTR	Reviewing	48	NECESSARY	
	4	TOP UP AIRCON GAS	Reviewing	100	NECESSARY	

Assessment Details

[General & Workshop Details](#)
[Vehicle & Driver Details](#)
[Vehicle Condition](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

Claim Amount \$4,743.91 Claim Amount \$4,743.91

CATEGORY	ESTIMATE	REVISED AMOUNT
----------	----------	----------------

Spare Parts	\$4,068.90	\$4,068.90
-------------	------------	------------

Labour	\$1,087.01	\$1,087.01
--------	------------	------------

Miscellaneous	\$188.00	\$188.00
---------------	----------	----------

Excess	-\$600.00	-\$600.00
--------	-----------	-----------

Submit for Review