

Surveyor: NAZ

REF:

CS/CTI 18018539/NS2302

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBA 9845 R Yr Regn: 12 MAY 2008
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN CABSTAR C.C. 2953
Colour: WHITE A/C: Insur. d / Std / NI / NA
Sp. Reading: 283,163 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JN1SC2F2430800320

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15C
R: 195 R13C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or HI-FLY

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5</u> mm
D.O.A. <u>2/10/18</u>	D.O.I. <u>15/10/18</u>

Survey held at CONNECT 3

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
8/4/19	FINALIZED LUMP SUM REPAIR \$2200.00 / 4 DAY <u>NAZ, (\$4,670.60 Ref - 70%)</u> <u>PLS see my rem ark</u>
12/4/19	1st DOC. PH1119, 1st copy ret only <u>RECEIVED 14 JAN 2019</u>
01/04/19	Re-open case for findu <u>1/10/19</u> <u>File pass to typist after re-open.</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

Date/Time, File Return to?

☒ : Final Report

2)

Report Format :

Lump Sum / I.B.I. (\$ 2,200/- 2/5)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____) S + RS \$ _____
☐ : Interview (\$ _____) Photos
☐ : Tech. Invs (\$ _____) Others
☐ : Weekend (\$ _____)

TOTAL

220

220

Shirley Hiew (LKK Auto)

From: Winnie Chai <connect3winnie@gmail.com>
Sent: Monday, 8 April 2019 11:16 AM
To: Naz (LKKAuto)
Cc: SUR; Shirley Hiew (LKK Auto)
Subject: Re: GBA 9845R Finalization

Ok

Thanks & regards

On 8 Apr 2019, at 11:12 AM, Naz (LKKAuto) <Naz@lkkauto.com> wrote:

Dear Ms Chai,

Apologies for the late reply. Attached herewith is the amended marked estimate following a check on the part prices. We will proceed to finalize if you are agreeable with the amended COR;

PARTS - \$2683.10
LESS 30% - \$1878.17
SPECIAL NET ITEMS - \$20
LABOUR - \$890
LESS LUMP SUM 20% - \$2230.53
TOTAL - \$2200.00 / 4 REPAIR DAYS

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

From: Winnie Chai <connect3winnie@gmail.com>

Sent: Saturday, 6 April 2019 9:48 AM

To: Naz (LKKAuto); SUR

Subject: REMINDER : Finalization for GBA9845R

Hi Naz

Pls kindly revert on the finalization.

Thanks

On Sat, Mar 30, 2019 at 10:19 AM Winnie Chai <connect3winnie@gmail.com> wrote:

Hi Naz

Attached is the after repair photos.

Pls kindly revert on finalization.

Thanks

--

Winnie Chai
Connect3
HP:9850-9666

--

Winnie Chai
Connect3
HP:9850-9666
<FINALIZED.pdf>

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

QT18/GBA9845R/TPC-324

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Rd #15-02

Springleaf Tower

Singapore 079909

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

QUOTATION

Dear Sir,

Cost of Repair to Vehicle GBA9845R

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front bumper	1	903.10	903.10
2.	Front bumper reinforcement	1	480.00	480.00
3.	Front LH corner panel	1	380.00	380.00
4.	Front LH headlamp under cover	1	162.50	162.50
5.	Front Absorber	2	270.00	540.00
6.	Front LH passenger door	1	\$1,400 1,575.00	1,575.00
7.	Front LH passenger door hinge	1	180.00	180.00
8.	Apply anti rust	1	80.00	80.00
9.	Transfer door fittings	1	150.00	150.00
10.	Spray painting	1	900.00	900.00
11.	Labour charges	1	1,500.00	1,500.00
12.	Company address sticker	1	20.00	20.00
SUB-TOTAL				S\$6,870.60

Thank you.
Yours faithfully,

Winnie Chai
HP: 9850-9666



PARTS \$2,683.10

LESS 30% \$1,878.17

STNETT \$ 20

LABOUR \$ 890

\$2,788.17

LESS US 20% \$2,230.53

1.66m \$2,230.53

NAZ LKK

15/10/18 1030

LIS

4. DAYS

AFTER REPAIR PHOTOS

1/4 REPAIR DONE

Handwritten signature and date 17/10/18.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Oct 2018		12 Oct 2018 11:42 Edit Adj Rpt	S\$2,200.00 Edit Estimates	S\$2,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN HENG LEE , ID: S8707694F								
Main Claimant:	A.B.T. BUS TRANSPORT SERVICE , Co. Reg. No.: NA								
Vehicle Reg. No.:	GBA9845R	Date of Loss:	02/10/2018 12:00 - :59 [124 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04750C02	Policy/Cover Note No.:	DMPCSN3053601700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLK8084E	Policy No. (Claimant):	M497078						
		Excess:	S\$0.00						
Repairer:	Connect 3 (HQ) 7 OLD TOH TUCK ROAD, 597648 Bukit Batok - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 10/04/2019]								
Driver/Custodian (Insured):	TAN HENG LEE (31 / Male) , NRIC: S8707694F Email:								
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (08/04/2019): Report Send Back Alerts - GBA9845R (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBA9845R (SNM18D04750C02)
[SLK8084E]
TP
A.B.T. BUS TRANSPORT SERVICE
Oct 2 2018 12:00PM
[TAN HENG LEE]
Connect 3

Upload Documents			Upload Photos			Compose New Letter			View View in Browser			
Video									1 per page			
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)							Thumbnail		Print	
1	03/10/18 13:28	Video - Accident [Linked Accident Report Documents]							Load MP4			
Assessment Reports									1 per page			
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)							Thumbnail		Print	
1	03/10/18 13:33	Accident Statement							Load HTM			
Photos/Images									3 per page			
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)							Thumbnail		Print	
1	03/10/18 13:27	Accident Photo [Linked Accident Report Documents]							Load JPG			
2	03/10/18 13:27	Accident Photo [Linked Accident Report Documents]							Load JPG			
3	03/10/18 13:27	Accident Photo [Linked Accident Report Documents]							Load JPG			
4	03/10/18 13:27	Accident Photo [Linked Accident Report Documents]							Load JPG			
5	03/10/18 13:27	Accident Photo [Linked Accident Report Documents]							Load JPG			
6	03/10/18 13:27	Accident Photo [Linked Accident Report Documents]							Load JPG			
7	03/10/18 13:27	Accident Photo [Linked Accident Report Documents]							Load JPG			
8	03/10/18 13:27	Accident Photo [Linked Accident Report Documents]							Load JPG			
9	03/10/18 13:27	Accident Photo [Linked Accident Report Documents]							Load JPG			
10	03/10/18 13:27	Accident Photo [Linked Accident Report Documents]							Load JPG			
11	03/10/18 13:27	Accident Photo [Linked Accident Report Documents]							Load JPG			
12	03/10/18 13:27	Accident Photo [Linked Accident Report Documents]							Load JPG			
13	03/10/18 13:27	Accident Photo [Linked Accident Report Documents]							Load JPG			
14	03/10/18 13:27	Accident Photo [Linked Accident Report Documents]							Load JPG			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	17/10/18 17:32	General View							Load JPG			
2	17/10/18 17:32	General View							Load JPG			
3	17/10/18 17:32	General View							Load JPG			
4	17/10/18 17:32	General View							Load JPG			
5	17/10/18 17:32	General View							Load JPG			
6	17/10/18 17:32	General View							Load JPG			
7	17/10/18 17:32	General View							Load JPG			
8	17/10/18 17:32	General View							Load JPG			
9	17/10/18 17:32	General View							Load JPG			
10	17/10/18 17:32	General View							Load JPG			

Video			1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
11	17/10/18 17:32	General View	 Load JPG	☒
12	17/10/18 17:32	General View	 Load JPG	☒
13	17/10/18 17:32	General View	 Load JPG	☒
14	17/10/18 17:32	General View	 Load JPG	☒
15	17/10/18 17:32	General View	 Load JPG	☒
16	17/10/18 17:32	General View	 Load JPG	☒
17	17/10/18 17:32	General View	 Load JPG	☒
18	17/10/18 17:32	Odometer Reading	 Load JPG	☒
19	17/10/18 17:32	Chassis Number	 Load JPG	☒
20	08/04/19 11:26	Photo After Spray	 Load JPG	☒
21	08/04/19 11:26	Photo After Spray	 Load JPG	☒
22	08/04/19 11:26	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/10/18 11:41	PRS	 Load PDF	
2	12/10/18 11:41	TP GIA	 Load PDF	
3	12/10/18 11:41	OI GIA	 Load PDF	
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	03/10/18 13:30	Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	03/10/18 13:30	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	☒

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	03/10/18 13:28	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	03/10/18 13:33	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	03/10/18 13:27	Accident Photo	 Load JPG	☒
2	03/10/18 13:27	Accident Photo	 Load JPG	☒
3	03/10/18 13:27	Accident Photo	 Load JPG	☒
4	03/10/18 13:27	Accident Photo	 Load JPG	☒
5	03/10/18 13:27	Accident Photo	 Load JPG	☒
6	03/10/18 13:27	Accident Photo	 Load JPG	☒
7	03/10/18 13:27	Accident Photo	 Load JPG	☒
8	03/10/18 13:27	Accident Photo	 Load JPG	☒
9	03/10/18 13:27	Accident Photo	 Load JPG	☒
10	03/10/18 13:27	Accident Photo	 Load JPG	☒
11	03/10/18 13:27	Accident Photo	 Load JPG	☒
12	03/10/18 13:27	Accident Photo	 Load JPG	☒
13	03/10/18 13:27	Accident Photo	 Load JPG	☒
14	03/10/18 13:27	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print

Video			1 per page	☒
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	03/10/18 13:30	Sketch Plan	 Load JPG	☒
2	03/10/18 13:30	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI18018539/NSD3E2**Date:** 12/04/2019REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3053601700

**Claimant Vehicle
No :** GBA9845R**Insured Vehicle
No :** SLK8084E

Date of Loss: 02/10/2018

Nature of Claim: TP

**Claim
No:** SNM18D04750C02DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBA9845R**

Make & Model: NISSAN CABSTAR, 3.0 (M)

Reg. Date: 12/05/2008 (Man. Year: 2008)

Colour: White

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

Engine No: ZD30173404K

Chassis No: JN1SC2F24Z0800320

Odometer: 283163 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/ R15C

Rear Tyre Size: 195 R13C (D)

Front Left Side: HIFLY 5 mm

Rear Left Side: HIFLY 5/5 mm

Front Right Side: HIFLY 5 mm

Rear Right Side: HIFLY 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,240.60	1,898.17	2,342.43	55.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	890.00	1,740.00	66.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,870.60	2,788.17	4,082.43	59.42
Approved Total (Overridden) (\$\$)		2,200.00		
(\$\$)	6,870.60	2,200.00	4,670.60	67.98
+ GST 7.00/7.00% (\$\$)	480.94	154.00	326.94	67.98
Nett Amount (\$\$)	7,351.54	2,354.00	4,997.54	67.98

INSPECTION

Date of Assignment: 12/10/2018

Date Inspected: 15/10/2018

Inspected At:

Connect 3 (HQ)
7 OLD TOH TUCK ROAD
Singapore 597648

Estimated Period of Repair: 4.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Apr 2019)	
Parts:	N/A	NISSAN CABSTAR 3.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA9845R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	903.10 F	*903.10 FL
2	1		*FRONT BUMPER REINFORCEMENT	Serviceable	480.00 F	*- FL
3	1		*FRONT LH CORNER PANEL	Deformed	380.00 F	*380.00 FL
4	1		*FRONT LH HEADLAMP UNDER COVER	Repair	162.50 F	*- FL
5	2		*FRONT ABSORBER	Serviceable	540.00 F	*- FL
6	1		*FRONT LH PASSENGER DOOR	Deformed	1,575.00 F	*1,400.00 FL
7	1		*FRONT LH PASSENGER DOOR HINGE	Serviceable	180.00 F	*- FL
8	1		*COMPANY ADDRESS STICKER	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,240.60	2,703.10
- List Item Discount on L Items 0.00/30.00% (S\$)	0.00	804.93
Total Parts (S\$)	4,240.60	1,898.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	APPLY ANTI RUST	New	80.00	40.00
2	TRANSFER DOOR FITTINGS	New	150.00	50.00
3	SPRAY PAINTING	New	900.00	400.00
4	LABOUR CHARGES	New	1,500.00	400.00
Gross Labour Cost (\$\$)			2,630.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >