

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBF7720D
 TP/AXA

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 10/10/2018

TP Veh Reg No: SMA5638T

Estimate No: ES1891171/YISHUN

Date: 11 Oct 2018

Policy No: 5088337101-01

Veh Reg No: GBF7720D

Make/Model: NISSAN NV200 DX-2 1.6
 AUTO

Chassis No: VM20102010

Engine No: HR16078546D

Reg. Date: 07/03/2017

Estimate Repair Cost to Vehicle No :GBF7720D

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 REAR TAILGATE	1,567.00	1 PC	B ₁ 1,567.00	✓
2 TAILGATE LOGO	59.80	1 PC	M ₂ 59.80	✓
3 TAILGATE EMBLEM (NV 200)	87.10	1 PC	M ₂ 87.10	✓
4 TAILGATE EMBLEM (VENETTE)	59.40	1 PC	M ₂ 59.40	✓
5 TAILGATE OUTER HANDLE	99.80	1 PC	99.80	?
6 TAILGATE INNER LOCK	261.00	1 PC	Ad 261.00	✓
7 TAILGATE INNER RUBBER	84.00	1 PC	Ad 84.00	✓
8 REAR BUMPER	437.30	1 PC	B ₂ 437.30	✓
9 REAR BUMPER INNER SPONGE	84.50	1 PC	84.50	?
10 REAR BUMPER CLIPS	5.00	6 PCS	M ₂ 30.00	✓
11 REAR END PANEL OUTER	189.00	1 PC	B ₂ 189.00	✓
12 REAR END PANEL INNER	544.00	1 PC	544.00	?
13 REAR END PANEL INNER TOP GARNISH	69.50	1 PC	M ₂ 69.50	✓
14 REAR END PANEL INNER TOP GARNISH CLIPS	5.00	5 PCS	M ₂ 25.00	✓
15 REAR FLOOR BOARD PANEL	1,350.00	1 PC	R 1,350.00	?
16 TAILGATE INNER BOARD INNER POCKET	39.80	1 PC	Ad 39.80	✓
			4,987.20	
		Less 10%	498.72	4,488.48
Special Net				
17 REAR FLOOR BOARD TOP CARPET	390.00	1 PC	C ₁ 390.00	✓
18 TAILGATE STICKER (600 KG)	40.00	1 PC	M ₂ 40.00	✓
19 STICKER (70KM/H)	10.00	1 PC	M ₂ 10.00	✓
20 REAR WINDSCREEN GLASS GUM	40.00	1 PC	M ₂ 40.00	✓
21 REVERSE SENSOR	200.00	1 SET	Sen 200.00	✓
			680.00	680.00

Sup 1pc tail gate inner trim board B₂ ✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 68804739
ATTN: Motor Claim Department

WS Ref: TP/AXA/YS
Claim Type: Third Party
Accident Date: 10/10/2018
TP Veh Reg No: SMA5638T

Estimate No: ES1891171/YISHUN
Date: 11 Oct 2018
Policy No: 5088337101-01
Veh Reg No: GBF7720D
Make/Model: NISSAN NV200 DX-2 1.6
AUTO
Chassis No: VM20102010
Engine No: HR16078546D
Reg. Date: 07/03/2017

Estimate Repair Cost to Vehicle No :GBF7720D

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Labour				
22 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
23 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE ASSY, REAR WIPER ASSY, LOCK ASSY, THIRD BRAKE LIGHT, TO STRAIGHTEN, KNOCK, CUT, WELD & RENEW REAR PANEL OUTER & INNER, REAR FLOOR BOARD PANEL, KNOCK & REPAIR REAR END PANEL REINFORCEMENT & REALIGN THE SAME	1,900.00	1 LA	1,900.00	?
24 REMOVE & REFIX REAR UNDER CARRIAGE & EXHAUST PIPE	350.00	1 LA	350.00	?
25 PUTTY & RESPRAY ON REAR FLOOR BOARD PANEL, REAR END PANEL, TAILGATE & REAR AFFECTED AREAS	1,200.00	1 LA	1,200.00	900
26 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	x
27 RUSTPROOFING	90.00	1 LA	90.00	✓
			3,720.00	3,720.00
Total				S\$ 8,888.48
Add GST @ 7%				622.19
Total Amount Payable				S\$ 9,510.67

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE