

聯成汽車維修

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787

Fax: 6748 5015

www.successunited.com.sg

Co. / GST Reg: 200402570G

SUCCESS UNITED PTE LTD

Estimate : TP/18-108

M/s EQ Insurance Co Ltd
5 Maxwell Road
#17-00 Tower Block MND Complex
Singapore 069110

Joy

20/1 Jan

Date : 11st Oct 2018

Vehicle No : SKA 1744U
Make/ Model : V/W Tiguan 2.0L
Chassis No : WVGZZZ5NZBW068449
Acc. Date : 09.10.18
Policy No : MP302015

Attn : Motor Claim

Tel: 62239433

Fax: 62243903

Email: eqiprs@eqinsurance.com.sg

Your Ref : GBG 2861H

S/n.	Qty	Particulars	Unit Price	Amount
<u>Materials</u>				
1	1 pc	Rear Boot Lid <i>Distorted</i>		\$ 2,178.52 ✓ 2018.25
2	1 pc	Rear Boot "Tiguan" Emblem <i>new</i>		\$ 156.31 ✓
3	1 pc	Rear Boot "Logo" <i>new</i>		\$ 132.70 ✓
4	1 pc	Rear Boot "2.0" Emblem <i>3 pc</i>		\$ 131.80 ✓
5	1 pc	Rear Boot "TSI" Emblem		\$ 85.21 ✓
6	1 pc	Rear Boot "4 motion" Emblem <i>new</i>		\$ 288.10 ✓
7	1 pc	Rear Boot Mechanism Lock <i>Paint</i>		\$ 353.58 ✓
8	1 pc	Rear Boot Weatherstrip <i>lit</i>		\$ 246.90 ✓
9	2 pc	Rear Boot Damper (L/RH) <i>new</i>	\$ 123.45	\$ 289.30 ✓
10	1 pc	Rear Boot Inner Trim Board <i>cracked</i>		\$ 127.78 ✓
11	2 pc	Rear Boot No. Plate Lamp (L/RH) <i>cracked</i>	\$ 63.89	\$ 59.83 ✓
12	1 pc	Rear Boot No. Plate Lamp Garnish <i>cracked</i>		\$ 173.10 ✓
13	1 pc	Rear Boot Inner Handle <i>new</i>		\$ 713.20 ✓
14	2 pc	Rear Boot Lid Lamp (L/RH) <i>new</i>	\$ 356.60	\$ 592.80 ✓
15	2 pc	Rear Lamp (L/RH) <i>new</i>	\$ 296.40	\$ 1,432.25 ✓ 1313
16	1 pc	Rear Bumper Top <i>Distorted</i>		\$ 32.00 ✓
17	10 pc	Rear Bumper Clips <i>new</i>	\$ 3.20	\$ 109.40 ✓
18	2 pc	Rear Bumper Side Holder (L/RH) <i>new</i>	\$ 54.75	\$ 76.00 ✓
19	2 pc	Rear Bumper Bracket (L/RH) <i>new</i>	\$ 38.00	\$ 789.15 ✓
20	1 pc	Rear Bumper Reinforcement <i>new</i>		\$ 537.15 ✓
21	1 pc	Rear Lower Bumper <i>Distorted</i>		\$ 35.23 ✓
22	1 pc	Rear Tow Hook Cover <i>new</i>		\$ 162.00 ✓
23	2 pc	Rear Bumper Reflector Lamp (L/RH) <i>cracked</i>	\$ 81.00	\$ 1,262.95 ✓ 1102.95
24	1 pc	Rear End Panel <i>Distorted</i>		\$ 216.05 ✓
25	1 pc	Rear End Panel Inner Top Garnish <i>new</i>		\$ 1,528.75 ✓
26	1 pc	Rear Spare Tyre Panel <i>new</i>		\$ 377.40 ✓ 188.70
27	2 pc	Rear Spare Tyre Sponge <i>cracked</i>	\$ 188.70	\$ 91.75 ✓
28	1 pc	Rear Fender Guard LH <i>new</i>		\$ 1,097.35 ✓
29	1 pc	Rear Exhaust Silencer Box Assy <i>new</i>		\$ 45.37 ✓
30	1 pc	Rear Exhaust Silencer Box Bush <i>new</i>		\$ 1,267.10 ✓
31	1 pc	Frt Bumper Assy <i>new</i>		\$ 833.54 ✓
32	1 pc	Frt Grille Assy <i>new</i>		\$ 721.85 ✓
33	1 pc	Frt Grille Chrome Trim		
34	1 pc	Frt Grille Reinforcement <i>new</i>		

110448.25

9925.83

- 35 1 pc Rear No. Plate With Frame *Best*
 36 1 pc Frt No. Plate With Frame *Best* 290.
 37 1 pc Reverse Sensor *Page*

	\$	16,144.42
Less 5%	\$	807.22
Total	\$	15,337.20
S/Nett	\$	45.00 ✓
S/Nett	\$	45.00 ✓
S/Nett	\$	380.00 200 ✓
Total Parts	\$	15,807.20

Labour

- 1 Towing
 2 To remove, rearrange electrical wirings, check lightings
 3 To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.
 4 R&R rear windscreen
 5 R&R rear Exhaust, to alight pipe line.
 6 R&R rear boot, transfer mechanism, gear & components.
 7 R&R inner trims, garnishes & upholetery.
 8 Respray tulf toke sealant.
 9 To putty and respray painting on affected area.

	\$	80.00 60 ✓
	\$	60.00 ✓
	\$	2,800.00 1200 ✓
	\$	250.00 120 ✓
	\$	200.00 x.
	\$	180.00 80 ✓
	\$	280.00 60 ✓
	\$	200.00 60 ✓
	\$	2,000.00 1000 ✓
Total Labour	\$	6,050.00

Total Parts & Labour : \$ 21,857.20

Success United Pte Ltd

No of Days _____

Re-Survey Before/After Paint

Part By Part/Lump Sum

Surveyed By _____ Contact No. _____

Date of Survey _____ Fax No. _____

NOTE: LUMP SUM WILL BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

Adrian Ling
 2/s 11/10/18.

10 Days.

Supplementary: 26842

total 13124.25

2/s: 10.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10.5K

10.5K

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub. Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

EQ Insurance Co Ltd
5 Maxwell Road
#17-00 Tower Block MND Complex
Singapore 069110
Attention : Motor Claim Department
Contact : 62239433 Fax No. : 62243903

Supplementary Estimate : TP18108S

Date : 10/10/2018
Vehicle Num. : SKA1744U
Make/Model : Volkswagon Tiguan-2010
Chassis/Eng# : WVGZZZ5NZBW068449
Accident Date : 09/10/2018
Claim No. : GBG 2861H
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS :		
2.	1	Rear Fender Wheel Arch RH <i>new</i>		544.85 81.75
3.	1	Rear Boot Lid Push Button <i>stem</i>		57.10
3.	2	Rear Bumper Reverse Lamp L/R <i>crushed.</i>	95.40	190.80
		List TotalS\$:		792.55
		5.00% Discount S\$:		39.63
				752.92

28255

26842

E. & O.E.

Total S\$: 752.92


for SUCCESS UNITED PTE LTD