



聯成汽車維修

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg Co. / GST Reg: 200402570G

Estimate : TP/18-108

M/s **EQ Insurance Co Ltd**
5 Maxwell Road
#17-00 Tower Block MND Complex
Singapore 069110

Date : 11st Oct 2018

Attn : Motor Claim

Vehicle No : **SKA 1744U**
Make/ Model : V/W Tiguan 2.0L
Chassis No : WVGZZZ5NZBW068449
Acc. Date : 09.10.18
Policy No : MP302015

Tel: 62239433

Fax: 62243903

Email: eqiprs@eqinsurance.com.sg

Your Ref : GBG 2861H

S/n.	Qty	Particulars	Unit Price	Amount
<u>Materials</u>				
1	1 pc	Rear Boot Lid		\$ 2,178.52
2	1 pc	Rear Boot "Tiguan" Emblem		\$ 156.31
3	1 pc	Rear Boot "Logo"		\$ 132.70
4	1 pc	Rear Boot "2.0" Emblem	}	\$ 131.80
5	1 pc	Rear Boot "TSI" Emblem		
6	1 pc	Rear Boot "4 motion" Emblem		
7	1 pc	Rear Boot Mechanism Lock		\$ 288.10
8	1 pc	Rear Boot Weatherstrip		\$ 353.58
9	2 pc	Rear Boot Damper (L/RH)	\$ 123.45	\$ 246.90
10	1 pc	Rear Boot Inner Trim Board		\$ 289.30
11	2 pc	Rear Boot No. Plate Lamp (L/RH)	\$ 63.89	\$ 127.78
12	1 pc	Rear Boot No. Plate Lamp Garnish		\$ 59.83
13	1 pc	Rear Boot Inner Handle		\$ 173.10
14	2 pc	Rear Boot Lid Lamp (L/RH)	\$ 356.60	\$ 713.20
15	2 pc	Rear Lamp (L/RH)	\$ 296.40	\$ 592.80
16	1 pc	Rear Bumper Top		\$ 1,432.25
17	10 pc	Rear Bumper Clips	\$ 3.20	\$ 32.00
18	2 pc	Rear Bumper Side Holder (L/RH)	\$ 54.75	\$ 109.40
19	2 pc	Rear Bumper Bracket (L/RH)	\$ 38.00	\$ 76.00
20	1 pc	Rear Bumper Reinforcement		\$ 789.15
21	1 pc	Rear Lower Bumper		\$ 537.15
22	1 pc	Rear Tow Hook Cover		\$ 35.23
23	2 pc	Rear Bumper Reflector Lamp (L/RH)	\$ 81.00	\$ 162.00
24	1 pc	Rear End Panel		\$ 1,262.95
25	1 pc	Rear End Panel Inner Top Garnish		\$ 216.05
26	1 pc	Rear Spare Tyre Panel		\$ 1,528.75
27	2 pc	Rear Spare Tyre Sponge	\$ 188.70	\$ 377.40
28	1 pc	Rear Fender Guard LH		\$ 91.75
29	1 pc	Rear Exhaust Silencer Box Assy		\$ 1,097.35
30	1 pc	Rear Exhaust Silencer Box Bush		\$ 45.37
31	1 pc	Frt Bumper Assy		\$ 1,267.10
32	1 pc	Frt Grille Assy	}	\$ 833.54
33	1 pc	Frt Grille Chrome Trim		
34	1 pc	Frt Grille Reinforcement		
				\$ 721.85



聯成汽車維修

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg

Co. / GST Reg: 200402570G

			\$	16,144.42
		Less 5%	\$	807.22
		Total	\$	15,337.20
35	1 pc	Rear No. Plate With Frame	S/Nett	\$ 45.00
36	1 pc	Frt No. Plate With Frame	S/Nett	\$ 45.00
37	1 pc	Reverse Sensor	S/Nett	\$ 380.00
		Total Parts	\$	15,807.20
		<u>Labour</u>		
1	Towing		\$	80.00
2	To remove, rearrange electrical wirings, check lightings		\$	60.00
3	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.		\$	2,800.00
4	R&R rear windscreen		\$	250.00
5	R&R rear Exhaust, to align pipe line.		\$	200.00
6	R&R rear boot, transfer mechanism, gear & components.		\$	180.00
7	R&R inner trims, garnishes & upholstery.		\$	280.00
8	Respray tuff toke sealant.		\$	200.00
9	To putty and respray painting on affected area.		\$	2,000.00
		Total Labour	\$	6,050.00
		Total Parts & Labour	\$	21,857.20

Success United Pte Ltd

No of Days _____

Re-Survey Before/After Paint

Part By Part/Lump Sum

Surveyed By _____ Contact No. _____

Date of Survey _____ Fax No. _____

NOTE: LUMP SUM WILL BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED