

## REPAIR ESTIMATE\*

MAKE :

DATE 11/10/2018

## LKK - Kalvin

MODEL	: HYUNDAI i40		Qty	Parts Description/ Labour	Type	Unit Price	Amount
				Rear Bumper			\$ 553.00
				Rear Bumper Clip 10 pcs			\$ 22.00
				Rear Bumper Under Cover			\$ 228.00
				SUB TOTAL			\$ 803.00
				LESS 20%			\$ 160.60
				DISCOUNTED TOTAL			\$ 642.40
				Rear Bumper Rubber Mat			\$ 50.00
				Rear Bumper Advertisement Logo			\$ 50.00
				Rear Bumper Advertisement Logo			\$ 200
							\$ 100.00
				Labour Charge			
				Panel Beating			\$ 220.00
				Spray Painting Charge			\$ 220.00
				Wiring Charge			\$ 30.00
				Remove/Refix Reverse Sensor			\$ 80.00
				TOTAL LABOUR			\$ 550.00
				ESTIMATE TOTAL			\$ 1,292.40
				<p>1/Calvin 1/CKK</p> <p>11/10/18 1105hrs</p> <p>2 Days.</p> <p>PIP</p> <p>Before Paint photo</p>			
				<p>KKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "without prejudice" basis</li> <li>• No illegal claimant actions is allowed</li> <li>• Supplemental claims must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>			
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>							

[illegible]