

# SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721

TEL : 6452 8211 FAX : 6451 7420

## ESTIMATE

PN SHIPPING PTE LTD

c/o 46 Lentor Plain

Singapore 786548

Date: 12/10/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
<b>RE : VOLKSWAGEN JETTA / SJR7976A</b>		
1 pc	front head lamp assy	825.90
1 pc	front head lamp lower bracket R/H	75.60
1 pc	front bumper	1373.80
1 pc	front bumper side retainer R/H	73.60
1 pc	front bumper reinforcement	726.80
1 pc	front bumper sponge	87.10
1 pc	front bumper fog lamp cover	163.50
1 pc	front bumper grille	283.70
1 pc	front bumper garnish	110.80
1 pc	front bumper chrome moulding	386.80
1 pc	front fender R/H	792.10
1 pc	front fender dust cover assy	263.70
	sub-total	5,163.40
	Less 10%	516.34
	sub-total	4,647.06
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	750.00
	To check wiring system.	50.00
	To apply putty and spray painting on affected areas.	900.00
	<b>Total</b>	<b>6,347.06</b>

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Notchwork  
L1 Day 87  
Putty After Paint