

INS. CASE OWNER:

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :S\$

Is driver the owner? (YES / NO)

If NO, Driver Name / Age:

Driver Tel No.:

HP: 8-10-18

D.O.A:

Nature of Accident:

(V/L) YES / NO

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

INSRS:
WSP: Sushay.
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Man date/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

confirm with

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

11,021.49

Loss of Rental (LOR):

S\$

-

(

days)

Loss of Use (LOU):

S\$

900

(\$100 x

9

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

7.49

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

11,928.49

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

11,928.49

Name 1:

SIN SHENG ENGINEERING SERVICES

Payee 2: (Strike if N.A.)

S\$

X

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

X

Name 3:

X

COPY SENT
11/7/19

Qumayyeh

P. S. S. S.

COE EXPIRY: 2023/July

$$R(\$4,087.54 / 28\%)$$

TOTAL

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT
SINGAPORE 638129
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

C & P LEASING PTE LTD
41 PANDAN ROAD
SINGAPORE 603263

Attention : Motor Claim Department
Contact : 6349 3836

Estimate : ES002628

Date : 10/10/2018
Vehicle Num. : YM8974Y
Make/Model : HINO GHBJRKA
Chassis/Eng# : GHBJRK 10253
Accident Date : 08/10/2018
Claim No.
Reference : YN8557M
Policy No.

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS				
1	1	FRONT PANEL		2,958.50 <i>Bl</i>
2	1	PANEL BRACKET	<i>RH</i> 298.50 <i>Bl</i>	597.00 <i>Bl</i>
3	2	STRIKER, FR PANEL LATCH	95.20	190.40 <i>Bl</i>
4	2	LATCH, FR PANEL OPENER	195.20	390.40 <i>Bl</i>
5	1	CABLE ASSY		165.20 <i>Xve</i>
6	1	FRONT GRILLE		495.20 <i>Bl</i>
7	1	HINO LOGO		175.50 <i>Bl</i>
8	1	WIPER PANEL		698.50 <i>Bl</i>
9	1	CORNER PANEL, RHS		408.20 <i>Bl</i>
10	2	SIGNAL LAMP	265.50	531.00 <i>Bl</i>
11	1	BUMPER		798.20 <i>Bl</i>
12	1	HEADLAMP, RHS		765.20 <i>Bl</i>
13	1	FRONT DOOR, RHS		2,945.50 <i>Bl</i>
14	1	FRONT DOOR LOCK, INR		288.20 <i>Bl</i>
15	2	DOOR HINGE	<i>Lower</i> - 220.20 <i>Bl</i>	440.40 <i>Xve</i>
16	1	PILLAR, RHS		695.50 <i>Bl</i>
17	1	WASHER TANK		278.20 <i>Bl</i>
18	1	WEATHERSTRIP, WINDSHIELD		396.20 <i>Bl</i>
19	2	HOSE, HEATER PIPING	195.20	390.40 <i>Xve</i>
List Totl S\$				13,667.70
15.00% Discount S\$				2,050.16
				11,617.54

CONTINUE

12891.50
1520
10,958.11

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT
SINGAPORE 638129
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

C & P LEASING PTE LTD
41 PANDAN ROAD
SINGAPORE 609283

Attention : Motor Claim Department
Contact : 6349 3836

Estimate : ES002628

Date : 10/10/2018
Vehicle Num. : YM8974Y
Make/Model : HINO GH8JRK
Chassis/Eng# : GH8JRK 10253
Accident Date : 08/10/2018
Claim No. :
Reference : YN8557M
Policy No. :

S.N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR
TO REMOVE/REFIT FRONT WINDSCREEN TO FACILITATE REPAIRS
TO PANEL BEAT/REPAIR RH BODY
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS
SPRAY PAINTING
TO APPLY NEW LOGO
TO APPLY TUFF KOTE
TOWING CHARGES
LOSS OF USE - 9 DAYS @ \$ 250/DAY
Labour Total S\$

150.00 X
1,200.00 900
950.00 750
250.00 150
100.00 60
120.00 receipt ?
2,770.00

Total S\$: 14,387.54

SIN SHENG ENGINEERING SERVICES

USE Auto Consultant's notice to the Repairer of the following:

- To remove, alter and spray painting
- To repair, damaged bodywork and body
- To repair and replace damaged parts
- To repair and replace damaged parts
- To repair and replace damaged parts
- To repair and replace damaged parts
- To repair and replace damaged parts
- To repair and replace damaged parts

Authorised by (Name):

Signature:

Date:

Case
Hq 90010068
7 1/2 days
43
12/10/18 @ 1420
Repair after repair
10,958.11
1,980.00
12,938.11
20%
10,350.49
43-10,350
7 days

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

C & P LEASING PTE LTD

41 PANDAN ROAD

SINGAPORE 609283

Attention : Motor Claim Department

Contact : 6349 3836

Estimate : ES002628

Date : 10/10/2018

Vehicle Num. : YM8974Y

Make/Model : HINO GH8JRKA

Chassis/Eng# : GH8JRK 10253

Accident Date : 08/10/2018

Claim No. :

Reference : YN8557M

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT PANEL		2,958.50 <i>BT</i>
2.	2	PANEL BRACKET	<i>RH</i> 298.50 <i>BT</i>	597.00 <i>XHB</i>
3.	2	STRIKER, FR PANEL LATCH	95.20	190.40 <i>BT</i>
4.	2	LATCH, FR PANEL OPENER	195.20	390.40 <i>BT</i>
5.	1	CABLE ASSY		165.20 <i>X</i>
6.	1	FRONT GRILLE		495.20 <i>SCR</i>
7.	1	HINO LOGO		175.50 <i>new</i>
8.	1	WIPER PANEL		698.50 <i>cut</i>
9.	1	CORNER PANEL, RHS		468.20 <i>blo</i>
10.	2	SIGNAL LAMP	265.50	531.00 <i>blo</i>
11.	1	BUMPER		798.20 <i>BT</i>
12.	1	HEADLAMP, RHS		765.20 <i>SCR</i>
13.	1	FRONT DOOR, RHS		2,945.50 <i>BT</i>
14.	1	FRONT DOOR LOCK, INR		288.20 <i>BT</i>
15.	2	DOOR HINGE	<i>Lower</i> - 220.20 <i>BT</i>	440.40 <i>XTOP X</i>
16.	1	PILLAR, RHS		695.50 <i>BT</i>
17.	1	WASHER TANK		278.20 <i>DE</i>
18.	1	WEATHERSTRIP, WINDSHIELD		396.20 <i>new</i>
19.	2	HOSE, HEATER PIPING	195.20	390.40 <i>X</i>
List TotalS\$:				13,667.70
15.00% Discount S\$:				2,050.16
				11,617.54

CONTINUE / ...

R-10958.12

L-1860

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT
SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

C & P LEASING PTE LTD
41 PANDAN ROAD
SINGAPORE 609283

Attention : Motor Claim Department

Contact : 6349 3836

Estimate : ES002628

Date : 10/10/2018

Vehicle Num. : YM8974Y

Make/Model : HINO GH8JRKA

Chassis/Eng# : GH8JRK 10253

Accident Date : 08/10/2018

Claim No. :

Reference : YN8557M

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		TO REMOVE/REFIT FRONT WINDSCREEN TO FACILITATE REPAIRS	150.00	X
		TO PANEL BEAT/REPAIR RH BODY	1,200.00	900
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		
		SPRAY PAINTING	950.00	750
		TO APPLY NEW LOGO	250.00	150
		TO APPLY TUFF KOTE	100.00	60
		TOWING CHARGES	120.00	receipt ?
		LOSS OF USE : 9 DAYS @ \$ 250/DAY		
		Labour Total S\$:		2,770.00

SIN SHENG ENGINEERING SERVICES

Total S\$: 14,387.54

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hy 90010068

7 1/2 days

4s

12/10/18 @ 1420

Resay after repair



YISHUN TOWING PTE LTD

Blk 4015 Ang Mo Kio Industrial Park 1, #01-502, Singapore 569631

Tel: 6458 8480 HP: 9628 8480 Fax: 6288 8480

Website: www.yishuntowing.com

Reg. No. 200106908W GST No. 200106908W

Mr Sin sheng engineering

WORK ORDER

No. 252196

Order By:

AT 5.30pm D/T 6.30pm

Date: 8/10/18

車牌
Vehicle No. YM 8974Y

車型
Model Cargo Trub 10 ton

From: 6 fishery pore rd

To: Tech park cres

Remarks:

Day/Night

Customer Signature & Company Stamp

Authorised Signature

Tow Truck No.:

XE514Z

All business transactions with Yishun Towing Pte Ltd are subject to its Standard Conditions in so far as these Conditions are applicable. Copies of these conditions may be obtained upon request. Note: Please see terms & conditions on the reverse side.



Service Request Details

Claim

S8M00YQG

Reference

None 

Loss Date

October 8, 2018

Request Date

October 12, 2018

Due Date

October 19, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline WorkAccept Work

Vehicle Information

Incident Vehicle Registration #

YM8974Y

Make

TPVD HYUNDAI

12.10.2018 @ 9.45am
Seen veh in.
Rusli

Model

Service Address

...

Primary Contact/Insured

IVY WAREHOUSING & TRANSPORTATION PTE LTD
40 PENJURU LANE, #01-02, 609216, Singapore
65674755

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

 Re:RE: MANDATE IA -SIN SHENG - YM 8974Y

Type

 Question

Message

Hi, the towing receipt did not indicate cost. Kindly confirm with the workshop before offer. For LOU, to offer lower at \$120/day first. Thanks

[Reply](#)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 15/10/2018

Survey Details:

Date of loss	8-Oct-18
Date of appointment	12-Oct-18
Date of survey	12-Oct-18
Location of survey	SIN SHENG ENGINEERING SERVICES

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	YM8974Y
Make and Model	HINO GH8JRKA - 7684cc
Date of registration	24-Jul-08
Excess	
Market Value	\$ 28,000.00
Part Rebate	\$ 15,372.00
Nett Loss	\$ 12,628.00

Repair details:

Initial Estimate	14,387.54
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 10,958.12
Check items (estimate)	\$ -
Labour	\$ 1,980.00
Total	\$ 12,938.12
Lump Sum(if applicable)	\$ 10,300.00

Number of days for repair	7 days
---------------------------	--------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

INSURED CHANGING LANE / NILC; COE EXPIRY 2023 JULY

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 11,021.00	GST
Loss of use	\$ 1,350.00	\$150 x 9 days
LTA search fees	\$ 7.49	
Proposed Total	\$ 12,378.49	



新盛机械工程服务

SIN SHENG ENGINEERING SERVICES

REGISTRATION NO : 312029/00D

No 3, Tech Park Crescent, Tuas Tech Park, Singapore 638129

Tel : 6863 9595 Fax : 6863 6477 Email : sinsheng1981@gmail.com

16-Nov-18

LKK Auto Consultants Pte Ltd
51 Ubi Ave 1, #02-25
Paya Ubi Industrial Park
Singapore 408933

Fax: 6741 4108

Tel: 6256 3561

Our ref: SSES/L2018/0373

Your ref: CC4/ASM18018556/R1ja3

Attn: Ms Joy

Dear Sir,

VEHICLE: YM8974Y (DoA: 08/10/2018)

We refer to the above and append herewith our costings for your perusal: -

Final Repair Bill	:	11,021.00
Loss of Use: 9 days @ S\$ 250/day (including 2 day for PRI)	:	2250.00
Survey Fee	:	N/A
Third Party Vehicle Insurance Search Fee	:	7.49
Total	:	<u><u>13,278.49</u></u>

Thank You

Yours faithfully

Susan Tan

OPERATIONS EXECUTIVE

Encl

Your Insured's vehicle : YN8557M

Our customer's vehicle : YM8974Y

Date : 10-Oct-18

AXA INSURANCE PTE LTD

Dear Sirs,

DATE OF ACCIDENT : 8-Oct-18

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION/SURVEY & SEEK ATTENTION

We have been appointed by C & P Leasing Pte Ltd repair their vehicle no. YM8974Y
Please be informed that the said vehicle can be inspected at :

Workshop : Sin Sheng Engineering Services
Address : 3 Tech Park Crescent, Tuas Tech Park, Singapore 638129
Contact : Ms Susan
Tel / Fax : 6863 9595 / 6863 6477

Pursuant to ePractice Direction No 2 of 2011, we hereby give you notice to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday failing which we will commence repairs thereafter without any further notice or reference to you. Kindly acknowledge upon inspection in the acknowledgement box below, Alternatively kindly inform us in writing if you are waiving your rights to an inspection of our customer's vehicle.

NB. Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damage only and shall not preclude client's driver/passanger from claiming injury-related damage arising from this accident.

Your sincerely,

Susan

Acknowledgement	
This is to confirm that I <i>Rohit</i>	\\[Full Name of Surveyor]
of <i>LKK MRO</i>	\\[Surveyor's Company]
have completed the pre-repair inspection on <i>12/10/18</i>	\\[Date if Inspection]
at <i>1410</i>	\\[Time of Inspection]
<i>[Signature]</i>	<i>Susan</i>
Signature of Appointed Surveyor	Witnessed By:
Company Stamp	Date

Waiver
We waive our rights to an inspection/survey of the above vehicle.
Signature _____
Name :
Date :



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18018556/R1ja3s2		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 17-07-2019		
ATTN: STACEY NG		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 8557M	Veh. Inspected	YM 8974Y	
Policy No.	VCA/P1667496	Coverage (\$)	0.00	
Claim No.	S8M00YQG	Excess (\$)	0.00	
Assign From	STACEY NG	Assign Date	12/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	HINO GH8JRKA	c.c	7684	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	GH8JRK10523	Colour	YELLOW	
Odometer	95666	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	10.00-20	NYLON	8 mm	
L/H Front Tyre	10.00-20	NYLON	8 mm	
R/H Rear Tyre	10.00-20 (D)	NYLON	8/8 mm	
L/H Rear Tyre	10.00-20 (D)	NYLON	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/10/2018	Inspection Date	12/10/2018	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YM 8974Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT PANEL (CONSISTENT)	BENT	2,958.50	2,958.50
2	PANEL BRACKET @ \$298.50 (CONSISTENT)	BENT	597.00	597.00
2	STRIKER, FR PANEL LATCH @ \$95.20 (CONSISTENT)	BENT	190.40	190.40
2	LATCH FR PANEL OPENER @ \$195.20 (CONSISTENT)	BENT	390.40	390.40
1	CABLE ASSY (CONSISTENT)	SERVICEABLE	165.20	-
1	FRONT GRILLE (CONSISTENT)	SCRATCHED	495.20	495.20
1	HINO LOGO (CONSISTENT)	NECESSARY	175.50	175.50
1	WIPER PANEL (CONSISTENT)	CUT	698.50	698.50
1	CORNER PANEL RHS (CONSISTENT)	BROKEN	468.20	468.20
2	SIGNAL LAMP @ \$265.50 (CONSISTENT)	BROKEN	531.00	531.00
1	BUMPER (CONSISTENT)	BENT	798.20	798.20
1	HEADLAMP RHS (CONSISTENT)	SCRATCHED	765.20	765.20
1	FRONT DOOR RHS (CONSISTENT)	BENT	2,945.50	2,945.50
1	FRONT DOOR LOCK INR (CONSISTENT)	BENT	288.20	288.20
2	DOOR HINGE @ \$220.20 (CONSISTENT)	LOWER BENT / TOP SERVICEABLE	440.40	220.20
1	PILLAR, RHS (CONSISTENT)	BENT	695.50	695.50
1	WASHER TANK (CONSISTENT)	DEFORMED	278.20	278.20
1	WEATHERSTRIP, WINDSHIELD (CONSISTENT)	NECESSARY	396.20	396.20
2	HOSE HEATER PIPING @ \$195.20 (CONSISTENT)	SERVICEABLE	390.40	-
	LESS 15% DISCOUNT		-2,050.16	-1,933.79
			11,617.54	10,958.11
LABOUR				
	TO REMOVE / REFIT FRONT WINDSCREEN TO FACILITATE REPAIRS.	NOT NECESSARY	150.00	-
	TO PANEL BEAT / REPAIR RH BODY. TO DISMANTLE / REPLACE ABOVE MENTIONED PARTS.		1,200.00	900.00
	SPRAY PAINTING.		950.00	750.00
	TO APPLY NEW LOGO.		250.00	150.00
	TO APPLY TUFF KOTE.		100.00	60.00

Report Ref No. CC4/ASM18018556/R1ja3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING CHARGES.		120.00	120.00
			2,770.00	1,980.00
	GRAND TOTAL		14,387.54	12,938.11
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,300.00

Report Ref No. CC4/ASM18018556/R1ja3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.