

INS. CASE OWNER:

LKK:

LDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

30/10

SLM 17105 - CS/MSGL 7022490/6662:00A. 18/11/18

SGV 3777Y - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(

Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

450.00 (\$ 50 x 9 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$: 8450.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

EM - 1 Auto Pte Ltd.

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$350.00

COPY SENT 11/11/19

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLM 1710S
Vehicle Model : HONDA VEZEL
Accident Date : 09.10.2018
Original Reg Date : 22.03.2017

Date : 11.10.2018
Chassis : RU31215129
TP Ins. AXA

ESTIMATE

1	1 pc	Front Door RH	✓		\$ 980.00	bt
2	1 pc	Front Door Black Sticker RH	✓		\$ 41.20	nei
3	1 pc	Front Door Outer Moulding RH	✓		\$ 92.00	? / de
4	1 pc	Front Door Inner Lock RH	X		\$ 241.30	x un
5	1 pc	Front Door Lock Catch RH	X		\$ 46.20	x un
6	1 pc	Front Door Weatherstrip RH	✓		\$ 96.20	nei
7	1 pc	Front Door Side Rubber RH	✓		\$ 87.20	? / de
8	1 pc	Front Door Bottom Rubber RH	✓		\$ 62.30	? / de
9	1 pc	Rear Door RH	✓		\$ 980.00	bt
10	1 pc	Rear Door Black Sticker RH	✓		\$ 41.20	nei
11	1 pc	Rear Door Outer Moulding RH	✓		\$ 92.00	? / de
12	1 pc	Rear Door Inner Lock RH	✓		\$ 250.00	? / bt
13	1 pc	Rear Door Lock Catch RH	X		\$ 46.20	x un
14	1 pc	Rear Door Weatherstrip RH	✓		\$ 96.20	nei
15	1 pc	Rear Door Side Rubber RH	✓		\$ 87.20	? / de
16	1 pc	Rear Door Bottom Rubber RH	✓		\$ 62.30	? / de
17	2 pcs	Rear Door Hinge RH	✓	62	\$ 124.00	bt
18	1 pc	Rear Door Checker RH	X		\$ 78.00	x un
19	1 pc	Rear Door Channel RH	✓		\$ 102.00	? / de
20	1 pc	Rear Door Channel Seal RH	✓		\$ 92.10	? / de
21	1 pc	Rear Door Regulator Motor RH	?	✓	\$ 395.00	? / bt
22	1 pc	Rear Door Regulator Gear RH	✓		—	?
23	1 pc	Rear Door Inner Trim RH	✓		\$ 640.00	? / de
24	1 set	Rear Door Inner Trim Clip RH	X		\$ 40.00	x un
25	1 pc	Side Skirt RH	✓		\$ 67.00	nei
26	1 set	Side Skirt Clips	✓		\$ 40.00	? / nei
27	1 pc	Rear Fender RH	✓		\$ 884.40	bt
28	1 pc	Rear Fender Arch Garnish RH	✓		\$ 195.00	nei
29	1 set	Rear Fender Arch Garnish Clips	✓		\$ 30.00	nei
30	1 pc	Rear Fender Inner Shield RH	X		\$ 133.00	x un
31	1 set	Rear Fender Inner Shield Clips	X		\$ 30.00	x un

C/F

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autoteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLM 1710S

B/F

1	1 pc	Rear Bumper	✓	\$ 950.00
2	1 pc	Rear Bumper Side Pad RH	X	\$ 250.00
3	1 pc	Rear Bumper Side Pad Retainer RH	✓	\$ 46.00
4	1 set	Rear Bumper Clip	✓	\$ 20.00
5	1 pc	Rear Axle Beam	X	\$ 1650.40
6	1 pc	Rear Absorber RH	✓	\$ 340.00
7	1 pc	Rear Wheel Bearing RH	✓	\$ 285.00

photo? de
Rp
re ✓
re ✓
X n
? ✓
? ✓

Special Nett

1	1 pc	Rear Tyre 16" RH	X	X	380.00
2	1 pc	Rear Sport Rim 16" RH	✓	300	500.00

X RM
ent 300

Labour charge

Panel Beating	1000	1,500.00
Spray painting	1200	1,500.00
Anti rust	60	100.00
Check Wiring	30	50.00
Remove and install front and rear door part.	160	180.00
Remove and install carpet and seat.	60	120.00
Remove and install rear under carriage.	100	280.00
To check four wheel alignment	80	90.00
To reset and check fault code	100	180.00

1000
1200
60.
30
100.
60.
100? photo ✓
80.
100

15362.20

Tanpin 97495449
wp

12/10/18 01540

Resurvey before After repair.

8 days.

surp lkk auto.com.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLM 1710S
Vehicle Model : HONDA VEZEL
Accident Date : 09.10.2018
Original Reg Date : 22.03.2017

Date : 11.10.2018
Chassis : RU31215129
TP Ins. : AXA

ESTIMATE

1	1 pc	Front Door RH		\$ 980.00	bt
2	1 pc	Front Door Black Sticker RH		\$ 47.20	nei
3	1 pc	Front Door Outer Moulding RH		\$ 92.00	?
4	1 pc	Front Door Inner Lock RH		\$ 291.30	x
5	1 pc	Front Door Lock Catch RH		\$ 46.20	x
6	1 pc	Front Door Weatherstrip RH		\$ 96.50	nei
7	1 pc	Front Door Side Rubber RH		\$ 87.20	?
8	1 pc	Front Door Bottom Rubber RH		\$ 62.30	?
9	1 pc	Rear Door RH		\$ 980.00	bt
10	1 pc	Rear Door Black Sticker RH		\$ 47.20	nei
11	1 pc	Rear Door Outer Moulding RH		\$ 92.00	?
12	1 pc	Rear Door Inner Lock RH		\$ 252.00	?
13	1 pc	Rear Door Lock Catch RH		\$ 46.20	x
14	1 pc	Rear Door Weatherstrip RH		\$ 96.50	nei
15	1 pc	Rear Door Side Rubber RH		\$ 87.20	?
16	1 pc	Rear Door Bottom Rubber RH		\$ 62.30	?
17	2 pcs	Rear Door Hinge RH	62	\$ 124.00	?
18	1 pc	Rear Door Checker RH		\$ 78.00	x
19	1 pc	Rear Door Channel RH		\$ 102.00	?
20	1 pc	Rear Door Channel Seal RH		\$ 92.10	?
21	1 pc	Rear Door Regulator Motor RH	?	\$ 395.00	?
22	1 pc	Rear Door Regulator Gear RH	1	—	?
23	1 pc	Rear Door Inner Trim RH		\$ 690.00	?
24	1 set	Rear Door Inner Trim Clip RH		\$ 40.00	x
25	1 pc	Side Skirt RH		\$ 67.00	nei
26	1 set	Side Skirt Clips		\$ 40.00	?
27	1 pc	Rear Fender RH		\$ 884.40	dei
28	1 pc	Rear Fender Arch Garnish RH		\$ 195.00	nei
29	1 set	Rear Fender Arch Garnish Clips		\$ 30.00	nei
30	1 pc	Rear Fender Inner Shield RH		\$ 133.00	x
31	1 set	Rear Fender Inner Shield Clips		\$ 30.00	x

C/F

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLM 1710S

B/F

1	1 pc	Rear Bumper		\$ 920.00	photo?
2	1 pc	Rear Bumper Side Pad RH		\$ 250.00	Rx
3	1 pc	Rear Bumper Side Pad Retainer RH		\$ 46.00	Rs ✓
4	1 set	Rear Bumper Clip		\$ 20.00	Rs ✓
5	1 pc	Rear Axle Beam		\$ 1650.40	X
6	1 pc	Rear Absorber RH		\$ 390.00	W?
7	1 pc	Rear Wheel Bearing RH		\$ 285.00	W?

10472.20

Special Nett

1	1 pc	Rear Tyre 16" RH		380.00	X
2	1 pc	Rear Sport Rim 16" RH		500.00	cut - 300.

Labour charge

Panel Beating		1,500.00	1000
Spray painting		1,500.00	1200
Anti rust		100.00	60.
Check Wiring		50.00	30.
Remove and install front and rear door part.		180.00	100.
Remove and install carpet and seat.		120.00	60.
Remove and install rear under carriage.		280.00	100? photo
To check four wheel alignment		90.00	80.
To reset and check fault code		180.00	100

15,302.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495449
-wp-

12/10/18 01540

Resurvey before After repair.

8 days.

sur @ lkk auto.com.

R- 4380

? 3875.00

L- 2630



Service Request Details

Claim

S8M00YQ1

Reference

None 

Loss Date

October 9, 2018

Request Date

October 11, 2018

Due Date

October 18, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

EM-1 Auto
12/10/2018 @ 9:20am
Mr. Chiu veh in.
Taufik.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration

SLM1710S

Make

TPVD HONDA

Model

VEZEL

Service Address

...

Primary Contact/Insured

SOH CHEI YONG

39 JALAN LIMAU KASTURI, 468436, Singapore

96178944

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



<MANDATE IA> - S8M00YQ1 [ACCIDENT INVOLVING SGV 3717Y(OI) & SLM 1710S(TP) ON 09/10/2018]

Type

🔗 Question

Message

Liability: 100%. Insured driver changed land and collided with third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$8,638.99(if claim LOU) - \$9,155.99(if claim LOR). Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 11 Jan 2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 11/1/2019

Survey Details:

Date of loss	9-Oct-18
Date of appointment	11-Oct-18
Date of survey	12-Oct-18
Location of survey	EM-1 AUTO PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLM1710S
Make and Model	HONDA VEZEL 1.5X - 1496cc
Date of registration	22-Mar-17
Excess	
Market Value	\$ 80,000.00
Parf Rebate	\$ 46,150.00
Nett Loss	\$ 33,850.00

Repair details:

Initial Estimate	15,302.20
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 6,584.08
Check items (estimate)	NIL
Labour	\$ 2,730.00
Total	\$ 9,314.08
Lump Sum(if applicable)	\$ 7,450.00

Number of days for repair	<u>8 days</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 7,971.50	\$ 7,971.50
Loss of use (11days x \$60.00)	\$ 660.00	NIL
Loss of rental (11days x \$100.00)(w/GST)	NIL	\$ 1,177.00
Loss of income	NIL	NIL
LTA search fees	\$ 7.49	\$ 7.49
Others	NIL	NIL
Proposed Total	\$ 8,638.99	\$ 9,155.99

Hsiao Tong (LKKAUTO)

From: Chia Sin Muk <em1autopteltd@gmail.com>
Sent: Wednesday, 27 February 2019 2:38 PM
To: Taufikh (LKKAUTO)
Cc: Vivian Lau (LKKAUTO); Asher Sng (LKKAUTO); Hsiao Tong (LKKAUTO); Simon Ho (LKKAUTO)
Subject: Re: EM-1 AUTO OUTSTANDING CASES

WITHOUT PREJUDICE

Dear Taufikh,

Confirmed COR \$7,450.00 + 8days.

Thanks & Best Regards,

Karen, on behalf of,

Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

On Wed, 27 Feb 2019 at 13:14, Taufikh (LKKAUTO) <Taufikh@lkkauto.com> wrote:

Hi Mr Chia,

SLM1710S COR I/s\$7450 , 8 days.

Regards

Taufikh

Lkk AUTO

From: Chia Sin Muk [<mailto:em1autopteltd@gmail.com>]
Sent: Wednesday, 23 January 2019 3:27 PM
To: Olivia Lau (LKKAUTO)
Cc: Naz (LKKAUTO); Taufikh (LKKAUTO); Simon Ho (LKKAUTO); SUR; Admin A; Hsiao Tong (LKKAUTO)
Subject: Re: EM-1 AUTO OUTSTANDING CASES

WITHOUT PREJUDICE

Dear All,

SLM 1710s survey by Mr taufikh

Kindly finalize with us asap.

Thanks & Best Regards,
Nicole, on behalf of,
Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

On Wed, 9 Jan 2019 at 13:25, Olivia Lau (LKKAuto) <olivialau@lkkauto.com> wrote:

Hi Nicole,

Thank you for your email.

LKK Ref: CC4/ASM18011575/Nwa3 - NAZ

LKK Ref: CC4/ASM18018557/T1wa3 - TAUFIKH

NAZ / TAUFIKH – Please follow up.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Make
good
use of
Today

From: Chia Sin Muk [<mailto:em1autopteltd@gmail.com>]

Sent: Thursday, 3 January, 2019 12:42 PM

To: SUR <sur@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Simon Ho (LKKAuto) <SimonHo@lkkauto.com>; Naz (LKKAuto) <Naz@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Subject: EM-1 AUTO OUTSTANDING CASES

WITHOUT PREJUDICE

Dear All,

Kindly finalize with us for the above cases.

Refer to the attached files.

SLX 6598J

SLM 1710S

Thanks & Best Regards,

Nicole, on behalf of,
Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.



Pls proceed DS with quantum as proposed

Type

🔗 Question

Message

LOR is subject to rental receipt.

Reply

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY/ GST REG. NO: 201316380R

M/S FAVRODRIVE CAR RENTAL

Proforma Invoice : 19/PI00049/5341TP

Date : 18-Mar-2019

AXA Insurance Singapore Pte Ltd

Motor Claim Department

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Without Prejudice

Date of Accident : 09-Oct-2018
Our Client's Vehicle Number : SLM 1710S
Vehicle Make/ Model : HONDA VEZEL
Your Insurer : SGB 3717Y

DESCRIPTION	SUB-AMOUNT	GST 7%	AMOUNT (SGD)
Lump Sum Repair Cost (Recommended LKK Taufik)	7,450.00	521.50	7,971.50 SR
LTA Fee	6.96	0.49	7.45 SR
GIA Fee	27.10	1.90	29.00 SR
Loss of (Rental/Use) (9 days x \$ 150) car leasing	1,347.00		1,347.00 ES

SGD (Nine Thousand Three Hundred Fifty-Four And Cents
Ninety-Four only)

GRAND TOTAL

9,354.94

Subject to 7% GST

523.88

Authorised Signature and Company Stamp

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGV 3717Y (Insd veh)	Model:	HONDA VEZEL 1.5 HYBRID
	SLM 1710S (TP veh)		
Date of Accident:	09/10/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	16,373.35
Final Repair Cost	:	\$	7,971.50
Loss of Use	:	\$	450.00
Rental (if any)	:	\$	9 days at \$50.00 per day
LTA / GIA Search Fee	:	\$	36.45

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum (GLOBAL SUM)	:	\$ 8,450.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability ____ 100 ____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: ____
BOLA Liability: ____ (%)	Assessed Liability (*): ____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown		
1)	EM-1 AUTO PTE LTD	\$ 8,450.00

NUR SHAQILAH BTE ABDOL
WAHAB

03/07/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18018557/T1ga3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: PETER WANG		Date : 03-07-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGV 3717Y	Veh. Inspected	SLM 1710S	
Policy No.	P0648242	Coverage (\$)	0.00	
Claim No.	S8M00YQ1	Excess (\$)	0.00	
Assign From	PETER WANG	Assign Date	11/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL 1.5 HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31215129	Colour	BLACK	
Odometer	092300	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60R16	DUNLOP	6 mm	
L/H Front Tyre	215/60R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/10/2018	Inspection Date	12/10/2018	
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 1710S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR RH (CONSISTENT)	BENT	980.00	980.00
1	FRONT DOOR BLACK STICKER RH (CONSISTENT)	NECESSARY	47.20	47.20
1	FRONT DOOR OUTER MOULDING RH (CONSISTENT)	DEFORMED	92.00	92.00
1	FRONT DOOR INNER LOCK RH (CONSISTENT)	NOT NECESSARY	291.30	-
1	FRONT DOOR LOCK CATCH RH (CONSISTENT)	NOT NECESSARY	46.20	-
1	FRONT DOOR WEATHERSTRIP RH (CONSISTENT)	NECESSARY	96.50	96.50
1	FRONT DOOR SIDE RUBBER RH (CONSISTENT)	DEFORMED	87.20	87.20
1	FRONT DOOR BOTTOM RUBBER RH (CONSISTENT)	DEFORMED	62.30	62.30
1	REAR DOOR RH (CONSISTENT)	BENT	980.00	980.00
1	REAR DOOR BLACK STICKER RH (CONSISTENT)	NECESSARY	47.20	47.20
1	REAR DOOR OUTER MOULDING RH (CONSISTENT)	DEFORMED	92.00	92.00
1	REAR DOOR INNER LOCK RH (CONSISTENT)	BENT	252.00	252.00
1	REAR DOOR LOCK CATCH RH (CONSISTENT)	NOT NECESSARY	46.20	-
1	REAR DOOR WEATHERSTRIP RH (CONSISTENT)	NECESSARY	96.50	96.50
1	REAR DOOR SIDE RUBBER RH (CONSISTENT)	DEFORMED	87.20	87.20
1	REAR DOOR BOTTOM RUBBER RH (CONSISTENT)	DEFORMED	62.30	62.30
2	REAR DOOR HINGE RH @ \$62.00 (CONSISTENT)	BENT	124.00	124.00
1	REAR DOOR CHECKER RH (CONSISTENT)	NOT NECESSARY	78.00	-
1	REAR DOOR CHANNEL RH (CONSISTENT)	DEFORMED	102.00	102.00
1	REAR DOOR CHANNEL SEAL RH (CONSISTENT)	DEFORMED	92.10	92.10
1	REAR DOOR REGULATOR MOTOR RH (CONSISTENT) }	BENT	395.00	395.00
1	REAR DOOR REGULATOR GEAR RH (CONSISTENT) }		-	-
1	REAR DOOR INNER TRIM RH (CONSISTENT)	DEFORMED	690.00	690.00
1	SET REAR DOOR INNER TRIM CLIP RH (CONSISTENT)	NOT NECESSARY	40.00	-
1	SIDE SKIRT RH (CONSISTENT)	DISTORTED	627.00	627.00
1	SET SIDE SKIRT CLIPS (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR FENDER RH (CONSISTENT)	DENTED	884.40	884.40
1	REAR FENDER ARCH GARNISH RH (CONSISTENT)	CUT	195.00	195.00
1	SET REAR FENDER ARCH GARNISH CLIPS (CONSISTENT)	NECESSARY	30.00	30.00
1	REAR FENDER INNER SHIELD RH (CONSISTENT)	NOT NECESSARY	133.00	-

Report Ref No. CC4/ASM18018557/T1ga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR FENDER INNER SHIELD CLIPS (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	920.00	920.00
1	REAR BUMPER SIDE PAD RH (CONSISTENT)	TO REPAIR SEE LABOUR	252.00	-
1	REAR BUMPER SIDE PAD RETAINER RH (CONSISTENT)	NECESSARY	46.20	46.20
1	SET REAR BUMPER CLIP (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR AXLE BEAM (CONSISTENT)	NOT NECESSARY	1,650.40	-
1	REAR ABSORBER RH (CONSISTENT)	BENT	392.00	392.00
1	REAR WHEEL BEARING RH (CONSISTENT)	BENT	285.00	285.00
	LESS 20% DISCOUNT		-	-1,571.02
			10,422.20	6,284.08
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TYRE 16" RH (SN) (CONSISTENT)	NOT NECESSARY	380.00	-
1	REAR SPORT RIM 16" RH (SN) (CONSISTENT)	CUT	500.00	300.00
			880.00	300.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER SIDE PAD RH.		1,500.00	1,000.00
	SPRAY PAINTING.		1,500.00	1,200.00
	ANTI RUST.		100.00	60.00
	CHECK WIRING.		50.00	30.00
	REMOVE AND INSTALL FRONT AND REAR DOOR PART.		180.00	100.00
	REMOVE AND INSTALL CARPET AND SEAT.		120.00	60.00
	REMOVE AND INSTALL REAR UNDER CARRIAGE.		280.00	100.00
	TO CHECK FOUR WHEEL ALIGNMENT.		90.00	80.00
	TO RESET AND CHECK FULL CODE.		180.00	100.00
			-	-
			-	-
			-	-
			4,000.00	2,730.00
	GRAND TOTAL		15,302.20	9,314.08

Report Ref No. CC4/ASM18018557/T1ga3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,450.00
---	--	--	----------

Report Ref No. CC4/ASM18018557/T1ga3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.