

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autoteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLM 1710S
Vehicle Model : HONDA VEZEL
Accident Date : 09.10.2018
Original Reg Date : 22.03.2017

Date : 11.10.2018
Chassis : RU31215129
TP Ins. AXA

ESTIMATE

1	1 pc	Front Door RH		\$ 980.00	bt
2	1 pc	Front Door Black Sticker RH		\$ 47.20	nei
3	1 pc	Front Door Outer Moulding RH		\$ 92.00	?
4	1 pc	Front Door Inner Lock RH		\$ 291.30	x
5	1 pc	Front Door Lock Catch RH		\$ 46.20	x
6	1 pc	Front Door Weatherstrip RH		\$ 96.50	nei
7	1 pc	Front Door Side Rubber RH		\$ 87.20	?
8	1 pc	Front Door Bottom Rubber RH		\$ 62.30	?
9	1 pc	Rear Door RH		\$ 980.00	bt
10	1 pc	Rear Door Black Sticker RH		\$ 47.20	nei
11	1 pc	Rear Door Outer Moulding RH		\$ 92.00	?
12	1 pc	Rear Door Inner Lock RH		\$ 250.00	?
13	1 pc	Rear Door Lock Catch RH		\$ 46.20	x
14	1 pc	Rear Door Weatherstrip RH		\$ 96.50	nei
15	1 pc	Rear Door Side Rubber RH		\$ 87.20	?
16	1 pc	Rear Door Bottom Rubber RH		\$ 62.30	?
17	2 pcs	Rear Door Hinge RH	Ⓟ 62	\$ 124.00	?
18	1 pc	Rear Door Checker RH		\$ 78.00	x
19	1 pc	Rear Door Channel RH		\$ 102.00	?
20	1 pc	Rear Door Channel Seal RH		\$ 92.10	?
21	1 pc	Rear Door Regulator Motor RH	?	\$ 395.00	?
22	1 pc	Rear Door Regulator Gear RH	?	-	?
23	1 pc	Rear Door Inner Trim RH		\$ 690.00	?
24	1 set	Rear Door Inner Trim Clip RH		\$ 40.00	x
25	1 pc	Side Skirt RH		\$ 67.00	nei
26	1 set	Side Skirt Clips		\$ 40.00	?
27	1 pc	Rear Fender RH		\$ 884.40	del
28	1 pc	Rear Fender Arch Garnish RH		\$ 195.00	nei
29	1 set	Rear Fender Arch Garnish Clips		\$ 30.00	nei
30	1 pc	Rear Fender Inner Shield RH		\$ 133.00	x
31	1 set	Rear Fender Inner Shield Clips		\$ 30.00	x

C/F

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SLM 1710S

B/F

1	1 pc	Rear Bumper		\$ 950.00	photo?
2	1 pc	Rear Bumper Side Pad RH		\$ 250.00	Rx
3	1 pc	Rear Bumper Side Pad Retainer RH		\$ 46.00	Re ✓
4	1 set	Rear Bumper Clip		\$ 50.00	Re ✓
5	1 pc	Rear Axle Beam		\$ 1650.40	X
6	1 pc	Rear Absorber RH		\$ 390.00	W?
7	1 pc	Rear Wheel Bearing RH		\$ 225.00	W?

Special Nett

1	1 pc	Rear Tyre 16" RH		380.00	X
2	1 pc	Rear Sport Rim 16" RH		500.00	cut ✓ 300.

Labour charge

Panel Beating		1,500.00	1000
Spray painting		1,500.00	1200
Anti rust		100.00	60.
Check Wiring		50.00	30.
Remove and install front and rear door part.		180.00	100.
Remove and install carpet and seat.		120.00	60.
Remove and install rear under carriage.		280.00	100? photo
To check four wheel alignment		90.00	80.
To reset and check fault code		180.00	100

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Tanpin 97495749
-wp-

12/10/18 01540

Resurvey before After repair.

8 days.

sur @ lkk auto.com.