

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 11/10/2018

AXA

ATTN: MOTOR CLAIMS DEPT

ACCIDENT DATE : 09/10/2018 @ 17:35
 VRN : GBD6138C
 MODEL : NISSAN NV200 1.5
 TP VRN : GT7363T

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 REAR BUMPER	1	\$ 624.80	\$ 624.80	de
2 REAR BUMPER CLIP	10	\$ 5.00	\$ 50.00	ue
3 REAR BUMPER RETAINER R/L	2	\$ 63.30	\$ 126.60	ue
4 REAR BUMPER REFLECTOR R/L	2	\$ 55.00	\$ 110.00	x
5 REAR RH DOOR PANEL	1	\$ 1,153.20	\$ 1,153.20	bf
6 TAILLAMP RH	1	\$ 252.10	\$ 252.10	cut
7 REAR RH DOOR HINGE UPPER	1	\$ 115.00	\$ 115.00	Ry
8 REAR RH DOOR HINGE LOWER	1	\$ 115.00	\$ 115.00	Ry
9 REAR LH DOOR PANEL	1	\$ 1,537.30	\$ 1,537.30	Ry
10 REAR LH DOOR HINGE UPPER	1	\$ 115.00	\$ 115.00	Ry
11 REAR LH DOOR HINGE LOWER	1	\$ 115.00	\$ 115.00	Ry
12 REAR LH DOOR LOCK	1	\$ 150.00	\$ 150.00	?
13 REAR END PANEL OUTER	1	\$ 201.60	\$ 201.60	Ry
14 REAR END PANEL GARNISH	1	\$ 77.00	\$ 77.00	?
15 LOGO "NV200"	1	\$ 79.90	\$ 79.90	ue
16 LOGO "DCI"	1	\$ 88.90	\$ 88.90	ue
17 LOGO "NISSAN"	1	\$ 145.60	\$ 145.60	ue
			\$ 5,057.00	
All Nett Items Discount -10%			\$ 505.70	
			\$ 4,551.30	
<u>Special Nett</u>				
18 RR RH DOOR WINDSCREEN SEALANT	1	\$ 45.00	\$ 45.00	ue
19 RR LH DOOR WINDSCREEN SEALANT	1	\$ 45.00	\$ 45.00	x
20 STICKER "6 PAX"	1	\$ 15.00	\$ 15.00	ue
21 STICKER "70 KM/H"	1	\$ 15.00	\$ 15.00	ue
22 STICKER FULL SET	1	\$ 500.00	\$ 500.00	ue - 300
23 REVERSE SENSOR	1	\$ 200.00	\$ 200.00	ue
			\$ 820.00	

PARTS TOTAL \$ 5,371.30

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of Affected Area	\$ 1,500.00
Putty, Blend And Spray Paint on Affected Area	\$ 1,500.00
Check Wiring, Re-align Taillamps, Ensure Proper Functioning	\$ 80.00
Remove and Replace Rear RH Door Window Glass to Facilitate Repair	\$ 100.00
Remove and Replace Rear LH Door Window Glass to Facilitate Repair	\$ 100.00
Remove and Refit Rear End Panel Lining and Garnish to Facilitate Repair	\$ 150.00
Remove and Reinstall Rear Trim Compartment to Facilitate Cutting and Repairing Work	\$ 150.00
Dismantle and Transfer Rear RH Door Fittings & Mechanisms to New Tailgate	\$ 180.00
Dismantle and Transfer Rear LH Door Fittings & Mechanisms to New Tailgate	\$ 180.00
Remove and Reinstall Reverse Sensors	\$ 120.00
Conduct Water Seepage Test	\$ 120.00

LABOURS TOTAL \$ 4,180.00

Grand Total : \$ 9,551.30

Add 7% GST : \$ 668.59

Nett Total : \$ 10,219.89

No. of repair days: 12



CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufan 97495749
- WP'
16/10/18 @ 11am
* Resurvey before paint.
sur @ 11am - 12pm
6 days.