

ASS. REC. BY:

REF: CS3/SPF18003751/11vd3-1

Special Instruction:

Surveyor: Taulikh

ASSIGNMENT (Office)

From (Person): Frankie they of SPF Date/Time: 30/08/2018

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLF 27984 Insured: Qx 61X

at Workshop m/s Han Car Repairs Tel: 62710275

of Blk 100L, Blk Merah Lane 3 # 01-49

Policy No: Claim No: AEMD/105/009/2018/017

Sum Insured: Excess:

Make of Veh: D.O.A. 31/01/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 1up? H.O.D. Endorsement:

Date/Time: 11/09/2018 Person Contacted: Tina Vehicle: IN OUT

Date/Time	Action/Instruction (X) Estimate
	SLF 27984 - X
	Qx 61X - X
14/6/18	Submit LS \$ 3300, 4 days
12/10/18	- pending photographs from Frankie.


15/10/18 Submit LS \$ 4200 (Red 2900, 410), 4 days

RECEIVED 15 OCT 2018

Repair days 84

Tarim Lin

12/10/18



NG SHI WEI
 BLK 455A ANG MO KIO ST 44 #29-07
 561455

Attention : THE OWNER

Contact : 9750 3949

Tax Invoice : TP000248

Date : 22/03/2018
 Vehicle Num : SLF 2798 U
 Make/Model : HONDA VEZEL-2016
 Chassis/Eng# : RU31203879/LEB5903889
 Accident Date : 31/01/2018
 Claim No. :
 Reference :
 Policy No. : GA243617/1

	Amount S\$
LUMP SUM REPAIRS	7,100.00



for HAN CAR REPAIRS

E. & O.E.	Total S\$:	7,100.00
	GST @ 7% S\$:	497.00
	Amount Due S\$:	7,597.00

=====

Autocar Leasing Pte Ltd

Company Regn. No. 200806807W
160 Sin Ming Drive #04-06
Sin Ming Auto City Singapore 575722
Tel: 6451 6602 Handphone: 9363 3186 Facsimile: 6451 6902

HIRING AGREEMENT cum INVOICE

No. : 00397

Vehicle Number : SJK 9766 M
Make & Model : MITSUBISHI L200 (ER 1.5 (A))

HIRER'S PARTICULARS

Name of Hirer : Ng Shi Wei
Address : BLK 455A Ang Mo Kio St. 24 # 29-07
(S) 561455
Contact Number : (Off) _____ Licence Number : _____
(Res) _____ Licence Expiry : _____
(H/p) 9750 3949
Nationality : Singaporean
NRIC No. : S 8323200 | 2 Date of Birth. : 25 Oct 1983

Name of Driver : _____
Address : _____
Contact Number : (Off) _____ Licence Number : _____
(Res) _____ Licence Expiry : _____
(H/p) _____
Nationality : _____
NRIC No. : _____ Date of Birth. : _____

RENTAL PRICING

Daily Rental Rate	: S\$ <u>120.00</u>	Date Out	: <u>26-2-18</u>
Days on Rental	: <u>8</u>	Time Out	: <u>2 pm</u>
Sub-total	: S\$ <u>960.00</u>	Date Return	: <u>06-3-18</u>
Misc. charges	: S\$ <u>-</u>	Time Return	: <u>12.55 pm.</u>
TOTAL	: S\$ <u>960.00</u>		

- *** RENTER's Liability for Vehicle Damage EXCESS is S\$1,500.00 ON ALL CLAIMS.
- ** Applicable to Driver below 23 YRS old OR with less than 2 YRS driving experience EXCESS is S\$3,500.00
- * The Vehicle is strictly for Singapore use only.

Remark

HIRER'S DECLARATION

I agree to the terms and conditions above and as set out overleaf. If I opt to pay by Credit / Charge Card, my signature here is deemed to have made on application credit card charge slip. I have removed all valuables from the car.

Authorised Signatory and Company Stamp

Date :

Autocar Leasing Pte Ltd

Prepared by

Date :

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 20100268D

Report Reference : TP / 02-18040/DY / 2018
Date of Report : 8 Mar 2018

Ng, Shi Wei
Blk 8 Tanjong Pagar Plaza
#18-105
Singapore 080008

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 31 Jan 2018

As per your instruction dated **26 Feb 2018** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SLF 2798 U**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SLF 2798 U
Model : Honda Vezel
Year / Capacity : 2016/1496
Chassis No : RU31203879
Engine No : LEB5903889
Mileage : 20686
Colour : Black

2. TYRES CONDITION

			<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	:	225/45 R18	Goodyear	7.00	mm	Sport
REAR	O/S	:	225/45 R18	Goodyear	7.00	mm	Sport
FRONT	N/S	:	225/45 R18	Goodyear	7.00	mm	Sport
REAR	N/S	:	225/45 R18	Goodyear	7.00	mm	Sport

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417893
Tel: 81818302 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Han Car Repairs
Blk 1001 Bukit Merah Lane 3
#01-49 Alexandra Village
Singapore 159718
5. Estimated normal period of repair : 8 working days and including lead time to complete.
6. Enclosed number of photograph : 101 copies.
7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SLF 2798 U
 Report No: TP/ 02-18040/DY / 2018

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Rear windscreen moulding	Necessary	\$ 140.00	\$ 140.00 NECV ✓
1	Rear tailgate	Damage	\$ 1583.50	\$ 1583.50 953.30 DD ✓
2	Rear tailgate dampers	Damage	\$ 420.00	\$ 420.00 NNX
2	Rear tailgate hinges	Intact	\$ 110.00	\$
1	Rear tailgate inner board	Intact	\$ 638.00	\$
2	Rear tailgate lamps	Damage	\$ 560.00	\$ 560.00 CUT ✓
1	Rear tailgate lock	Damage	\$ 210.00	\$ 210.00 BT ✓
1	Rear tailgate logo	Necessary	\$ 32.00	\$ 32.00 NECV ✓
1	Rear tailgate outer garnish	Damage	\$ 187.00	\$ 187.00 CUT XNN
1	Rear tailgate rubber	Necessary	\$ 195.00	\$ 195.00 NNX
1	Rear tailgate 'VEZEL' emblem	Necessary	\$ 75.00	\$ 75.00 } NEC
1	Rear tailgate 'HYBRID' emblem	Necessary	\$ 76.00	\$ 76.00 } NEC
2	Rear taillamps @ 456.80	Damage	\$ 1500.00	\$ 1500.00 913.60 CRAV ✓
1	Rear end panel	Damage	\$ 675.90	\$ 675.90 580.00 DD XR
1	Rear end panel inner garnish	Damage	\$ 128.90	\$ 128.90 CUT ✓
2	Rear side bumpers	Damage	\$ 518.00	\$ 518.00 R X
1	Rear bumper	Damage	\$ 936.10	\$ 936.10 810.00 DD ✓
2	Rear bumper reflectors	Damage	\$ 362.00	\$ 362.00 CRA ✓
2	Rear bumper side retainers	Necessary	\$ 88.00	\$ 88.00 72.00 NEC
			\$ 8435.40	\$ 7687.40
	Discount 20.0%		\$ 1687.08	\$ 1537.48
			\$ 6748.32	\$ 6149.92
<u>Special Nett Items</u>				
1	Rear quarter glass sealant	Necessary	\$ 60.00	\$ 60.00
1	Rear reverse sensor (1 set) 2 pcs	Damage	\$ 480.00	\$ 480.00 200 Short
			\$ 540.00	\$ 540.00

Spare Parts Total \$ 7288.32 \$ 6689.92

Vehicle No: SLF 2798 U
 Report No: TP/ 02-18040/DY / 2018


LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 7288.32	\$ 6689.92
1	To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts.	\$ 50.00	\$ 40.00
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 200.00	\$ 120.00 ^{80.00}
3	To remove and refit rear bumper sensor.	\$ 200.00	\$ 120.00 ^{60.00}
4	To remove and refit rear windscreen glass.	\$ 180.00	\$ 120.00 ^{80.00}
5	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1050.00	\$ 880.00 ^{600.00}
6	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1050.00	\$ 880.00 ^{600.00}
7	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00	\$ 60.00
Total		\$ 10118.32	\$ 8909.92

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 7100.00

SDLS: SEVEN THOUSAND ONE HUNDRED ONLY


 Qualified Appraiser

Repair days 34

TG Lim

 12/10/18



GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-18-047262
Date of Request: 28/03/2018
Your Ref No: GS/18/2739/HC/SY/MS

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 31/01/2018
Place of Accident: BLK 28 OLD POLICE ACADEMY
Client Vehicle No: SLF2798U

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
QX61X	No match found.	

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-047262
Date of Request: 28/03/2018

Your Ref No: GS/18/2739/HC/SY/MS

KSCGP JURIS LLP
10 Hoe Chiang Road #13-03A
Keppel Tower
Singapore 089315

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 31/01/2018
Place of Accident: BLK 28 OLD POLICE ACADEMY
Client Vehicle No: SLF2798U

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque

Enquire Vehicle & Owner Information (Vehicle No. QX61X As At 31 Jan 2018 / 15:10:00)

Vehicle No. QX61X

Search Reason: Insurance claim in relation to traffic accident

Law/Plan Case No.: GS/18/2739/HC/SY/MS

Current Owner Details:

Owner ID Type: Government

Owner ID: T08GA0036C

Owner Name: SINGAPORE POLICE FORCE

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 28

Registered Street Name: IRRAWADDY ROAD

Registered Unit No.: -

Registered Building Name: NEW PHOENIX PARK

Registered Postal Code: 329560

Current Vehicle Details

Vehicle No.: QX61X

Make Description/Model: SUBARU / IMPREZA SMT

Insurance Company Name: -



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref :	CS3/SPF18003751/T1vd3e2-1
CONTRACT MANAGEMENT SECTION (SINGAPORE POLICE FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date :	15-10-2018
ATTN : FRANKIE THAY		Code :	SPF3
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 61X	Veh. Inspected	SLF 2798U
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/017	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	30/08/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL 1.5X HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU31203879	Colour	BLACK
Odometer	20686	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R18	GOODYEAR	6 mm
L/H Front Tyre	225/45 R18	GOODYEAR	6 mm
R/H Rear Tyre	225/45 R18	GOODYEAR	6 mm
L/H Rear Tyre	225/45 R18	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/01/2018	Inspection Date	27/02/2018
Survey held at	HAN CAR REPAIRS BLK 1001 #01-49 BUKIT MERAH LANE 3 ALEXANDRA VILLAGE SINGAPORE 159718		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 2798U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR WINDSCREEN MOULDING	NECESSARY	140.00	140.00
1	REAR TAILGATE	DENTED	1,583.50	953.30
2	REAR TAILGATE DAMPERS	NOT NECESSARY	420.00	-
2	REAR TAILGATE HINGES	NOT NECESSARY	110.00	-
1	REAR TAILGATE INNER BOARD	NOT NECESSARY	638.00	-
2	REAR TAILGATE LAMPS	CUT	560.00	560.00
1	REAR TAILGATE LOCK	BENT	210.00	210.00
1	REAR TAILGATE LOGO	NECESSARY	32.00	32.00
1	REAR TAILGATE OUTER GARNISH	NOT NECESSARY	187.00	-
1	REAR TAILGATE RUBBER	NOT NECESSARY	195.00	-
1	REAR TAILGATE "VEZEL" EMBLEM }	NECESSARY	75.00	56.20
1	REAR TAILGATE "HYBRID" EMBLEM }	NECESSARY	76.00	76.00
2	REAR TAILLAMPS	CRACKED	1,500.00	913.60
1	REAR END PANEL	TO REPAIR SEE LABOUR	675.90	-
1	REAR END PANEL INNER GARNISH	CUT	128.90	128.90
2	REAR SIDE BUMPERS	TO REPAIR SEE LABOUR	518.00	-
1	REAR BUMPER	DENTED	936.10	810.00
2	REAR BUMPER REFLECTORS	CRACKED	362.00	362.00
2	REAR BUMPER SIDE RETAINERS	NECESSARY	88.00	72.00
	LESS 20% DISCOUNT		-1,687.08	-862.80
			6,748.32	3,451.20
<u>SPECIAL NETT ITEMS</u>				
1	REAR QUARTER GLASS SEALANT (SN)	NECESSARY	60.00	60.00
1	SET REAR REVERSE SENSOR (2 PCS)(SN)	SHORTED	480.00	200.00
			540.00	260.00
<u>LABOUR</u>				
	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING,HARNESS WIRES,SOCKETS,REPLACE DAMAGED PARTS.		50.00	40.00
	TO REMOVE AND REFIT INNER TRIMS,INNER GARNISHES,TO FACILITATE THE REPAIRS.		200.00	80.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		200.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		180.00	80.00

Report Ref No. CS3/SPF18003751/T1vd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR SIDE BUMPERS.		1,050.00	600.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,050.00	600.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		100.00	60.00
			2,830.00	1,520.00
	GRAND TOTAL		10,118.32	5,231.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,200.00

Report Ref No. CS3/SPF18003751/T1vd3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.