

AAD1810-118

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 498G**

*Not Authorized*  
*1: B.1*  
*Resonance B4 paint*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :

**SHD 498G**  
VF1ABL15AUC283432  
RENAULT  
LATITUDE  
9.10.2018  
**AIG**

PART		LIST	
1	1 BUMPER COVER REAR	\$	CM 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	CM 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	SL 113.47 X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	DI 135.97 ✓
5	1 BUMEP R RETAINER RH REAR	\$	DI 44.99 ✓
6	1 BUMPER REFLECTOR RH	\$	CM 43.61 ✓
7	1 BUMEP R BRACKET SIDE LH REAR	\$	SL 135.97 X
8	1 BUMEP R RETAINER LH REAR	\$	SL 44.99 X
9	1 BUMPER REFLECTOR LH	\$	SL 43.61 X
10	1 BUMPER BEAM REAR	\$	B 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	R 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	R 225.95 X
13	1 BOOT REAR	\$	B 2,872.68 ✓
14	1 BOOT FINISHER	\$	SL 470.06 X
15	1 BOOT WHEATERSTRIP	\$	DI 323.05 ✓
16	1 BOOT REFLECTOR LAMP LH	\$	SL 493.35 X
17	1 BOOT REFLECTOR LAMP RH	\$	DI 493.35 ✓
18	1 BOOT BADGE 'RENAULT'	\$	SL 225.36 ✓
19	1 BOOT BADGE	\$	SL 225.36 ✓
20	1 BOOT STRUT LH	\$	SL 276.08
21	1 BOOT STRUT RH	\$	SL 276.08
22	1 BOOT HINGE LH	\$	R 367.84
23	1 BOOT HINGE RH	\$	R 367.84
24	1 BOOT INNER TRIM	\$	SL 586.45
25	1 BOOT SWITCH	\$	SL 168.13
26	1 BOOT LOCK	\$	R 202.67
27	1 BOOT LOCK CATCH	\$	R 74.40
28	2 LICENCE PLATE LAMP	\$	SL 50.52
29	2 BOOT RUBBER PLUG	\$	SL 221.81

X

**Trans-cab Auto Services Pte Ltd**

AAD1810-118

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 498G**

30	1 DOOR PANEL REAR LH	\$	R	2,844.66	X
31	1 FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	X
32	1 FENDER PANEL REAR LH	\$	R	3,299.13	X
33	1 WHEELARCH REAR LH	\$	Sn	543.47	X
34	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	X
35	1 FENDER PANEL REAR RH	\$	Bu	3,299.13	✓
36	1 WHEELARCH REAR RH	\$	Sn	543.47	X
37	1 TAILLAMP RH	\$	cmf	552.55	✓
38	1 TAILLAMP PANEL RH	\$	Bu	986.70	✓
39	1 TAILLAMP LH	\$	Sn	552.55	X
40	1 TAILLAMP PANEL LH	\$	R	986.70	X
41	1 OUTER PANEL REAR (End Panel)	\$		1,471.77	?
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56	X
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
44	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
45	1 EXHAUST REAR	\$	R	7,489.05	X
46	1 EXHAUST CAP REAR	\$	R	230.49	X
47	1 FENDER WHEEL HOUSE PANEL REAR RH	\$	R	3,039.04	X
48	1 CHASSIS PANEL REAR RH	\$	R	3,766.43	X

<b>TOTAL</b>	\$	<b>45,519.07</b>
<b>10%</b>	\$	<b>4,551.91</b>
	\$	<b>40,967.16</b>

**Special Nett**

1	1SET PARKING AID	\$	Shot	700.00	Boorn
2	1SET REAR BUMPER CLIP	\$	na	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00	✓
13	1 BOOT STICKER "6555-3333"	\$	na	30.00	✓

**Trans-cab Auto Services Pte Ltd**

AAD1810-118

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 498G**

14	1 BOOT INNER TRIM CLIP	\$	nn	45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
18	1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
19	1 TAILLAMP CLIP RH	\$	nn	5.00	✓
20	1 TAILLAMP CLIP LH	\$	nn	5.00	X
21	2 REAR WINDSCREEN SELANT	\$	nn	80.00	40sn
22	1 WINDSCREEN MOULDING	\$	nn	100.00	✓
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	30sn
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	X
25	1 SPARE TYRE	\$	sn	330.00	X

**TOTAL \$ 2,225.02****TOTAL PARTS \$ 43,192.18****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	800/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	1000/
To Rust-Proofing Of The Affected Areas.	\$	170.00	90/
To reinstall rear bumper parking sensor.	\$	170.00	60/
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60/
To repair and realign rear exhaust pipe.	\$	nn	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn	170.00 X

**Trans-cab Auto Services Pte Ltd**

**AAD1810-118**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 498G**

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 100d
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	120d
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X

**TOTAL \$ 12,540.00**

**Over All Total \$ 55,732.18**

**(LUMP SUM)**

**Repair Days** ~~20 DAYS~~  
*8 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: