

INS. CASE OWNER:

cc 4, FWD 180 18569, Kca34

IKE:

IDAC:

Surveyor:

fsc

DOI:

ASSIGNMENT

11/15/18

Date / Time:

11/15/18

Registered in Merion:

Pre-assign / CCU / FTE

FBM8146



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :\$:

D.O.A: 2/10/18

Place of Accident:

Is driver the owner?

( YES )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No

SJU 15312



INSRS:

WSP:

Tel:

Liability:

RMKS:

BH Auto.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

301-0

on

SJU 15312

FBM8146

cc 4 / FWD 180 18569 (GIA), 11/15/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call GI:

After call ltr to GI:

Documentation Check List: Handler: Typist:

Notification ltr (if non-pickup)

After call ltr to GI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

\* FWD can't received email from BH Auto.  
 \* claiming each other.  
 \* II & III - Amend.

15-10-18 Sales APPROVE TO REJECT TP claim.

MANAGER APPROVE TO REJECT claim.

EMAIL WSP TO SUBJECT TP claim.

Given  
 Yes  
 12/1/18

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

24

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

\*TP can't FROM PROGRESS, see WIT TP

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\* 500

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPIED  
 13/1/18

REF: FWD

## ASSIGNMENT

From: Date: 11/10/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJU 15312

at Workshop n/s

of Blk 1 Sn Ming Ind Est #01-115

Insured

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

1pm - 2pm

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJU 15318 Yr Regn: 11 / 09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai A) Avante C.C. 159,

Colour: M. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 23602, T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KM1H0U418MAU896556

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 4 mm

R/Bal: 8 mm

L/Bal: 4 mm

L/Bal: 8 mm

D.O.A: 2/10/18

D.O.I: 11/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/10 File passed Catherine

1/6: 4700 (BED: 2.549.24 60% EXCISE (CHECK ITEM 46.70))

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ - RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT

FWD SINGAPORE PTE LTD

6 TEMASEK BOULEVARD

#18-01 SUNTEC TOWER FOUR

SINGAPORE 038986

TEL : 6820 8888

DATE : 05/10/2018

PAGE : 1 OF 2

*Not Withheld*

*11 Sep 8?*

*Assess After Paint*

ACCIDENT REPAIR ON : SJU1531Z

MODEL : HYUNDAI AVANTE 1.6

POLICY NO : GA03354/1

CHASSIS NO : KMHU41BMAU896556

YEAR OF MANUFACTURE : 2009

DATE / TIME OF ACCIDENT : 02/10/2018@08:45HRS

LOCATION : BLK 102 HOUGANG AVE CARPARK

THIRD PARTY VEHICLE NO : FBM819M

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT	
1	FRONT HEADLAMP RH	1	\$m	\$ 480.00	X
2	FRONT HEADLAMP LOWER BRACKET RH	1	\$m	\$ 30.00	X
3	FRONT BUMPER	1	By/Bur	\$ 461.40	✓
4	FRONT BUMPER SIDE RETAINER RH	1		\$ m 19.00	X
5	FRONT BUMPER LOWER GRILLE	1	Dis	\$ 47.00	✓
6	FRONT BUMPER FOG LAMP COVER RH	1	Dis	\$ 25.30	✓
7	FRONT BUMPER LOWER GARNISH	1		\$D/I 44.00	✓
8	FRONT BUMPER UNDER COVER	1		\$ 43.20	?
9	FRONT BUMPER INNER SPONGE	1	\$m	\$ 113.40	X
10	FRONT BUMPER REINFORCEMENT	1	m	\$ 254.00	X
11	FRONT FENDER INNER SHIELD RH	1		\$m 48.00	X
		SUB TOTAL		\$ 1,565.30	
		LESS 20%		\$ (313.06)	
		PARTS TOTAL		\$ 1,252.24	

SPECIAL NETT ITEMS		QUANTITY	UNIT PRICE	AMOUNT	
1	FRONT HEADLAMP CLIPS RH	nn 3	\$ 3.00	\$ 9.00	X
2	FRONT BUMPER CLIPS	nn 10	\$ 3.00	\$ 30.00	✓
3	FRONT BUMPER LOWER GARNISH CLIPS	nn 4	\$ 3.00	\$ 12.00	✓
4	FRONT BUMPER UNDER COVER CLIPS	4	\$ 3.00	\$ 12.00	✓
5	FRONT FENDER INNER SHIELD CLIPS RH	nn 4	\$ 3.00	\$ 12.00	X
		PARTS TOTAL		\$ 75.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**ACCIDENT REPAIR ON : SJU1531Z**  
**MODEL : HYUNDAI AVANTE 1.6**  
**POLICY NO : GA03354/1**  
**CHASSIS NO : KMHU41BMAU896556**  
**YEAR OF MANUFACTURE : 2009**  
**DATE / TIME OF ACCIDENT : 02/10/2018@08:45HRS**  
**LOCATION : BLK 102 HOUGANG AVE CARPARK**  
**THIRD PARTY VEHICLE NO : FBM819M**

**DATE : 05/10/2018**  
**PAGE : 2 OF 2**

LABOUR CHARGES FOR FRONT RIGHT PORTION		AMOUNT
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ 400.00
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ 300.00
3	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS. <i>an</i>	\$ 80.00
4	PROVIDE SKILL LABOUR AND WATER PROOF SEALANT FOR ALL REPLACE AND REPAIR PARTS. <i>San</i>	\$ 80.00
5	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 60.00
LABOUR TOTAL		\$ 920.00

2001  
 2001  
 X  
 X  
 15/

TOTAL PARTS & LABOUR	\$ 2,247.24
GST 7%	\$ 157.31
<b>GRAND TOTAL</b>	<b>\$ 2,404.55</b>
ESTIMATE REPAIR DURATION	<del>4</del> DAYS

2 days

YOURS SINCERELY



ESTIMATOR : KIT  
 TEL : 8405 4058  
 FAX : 6269 2404  
 EMAIL : karkit.ngai@bhauto.com.sg

**SURVEY ATTENDED BY :**

NAME	<i>Meneth</i>
COMPANY	<i>CLK</i>
DATE	<i>11/10/18</i>
TIME	<i>1.35pm</i>
TEL	<i>96910663</i>
EMAIL	

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Josey Loh

Date: 23 Oct 2018

**Preliminary Advice**

Insured Vehicle No	: FBM814B	Accident Date	: 02/10/2018
TP Vehicle No	: SJU1531Z	Assignment Date	: 12/10/2018
Make	: HYUNDAI AVANTE	Est. Duration of Repair	: 2 days
Date of Inspection	: 11/10/2018		
Inspection At	: BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117 Singapore 575636		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ....front O/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,247.24
Revised Amount	:S\$	919.16
Check Items (Estimated)	:S\$	46.56
Total	:S\$	965.72

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.

## Asher Sng (LKKAuto)

---

**From:** josey.loh@fwd.com  
**Sent:** Monday, 15 October 2018 5:16 PM  
**To:** Asher Sng (LKKAuto)  
**Cc:** motorclaims.sg@fwd.com  
**Subject:** RE: Accident involving FBM814B & SJU1531Z on 02/10/2018 (Our Ref: 1201800012661)

Hi Asher,

Please proceed. Thank you.

Kind Regards

Josey Loh  
Executive, Claims

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872  
E [josey.loh@fwd.com](mailto:josey.loh@fwd.com)  
W [fwd.com.sg](http://fwd.com.sg)

**FWD**  
insurance



**From:** Asher Sng (LKKAuto) [mailto:[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)]  
**Sent:** Monday, 15 October, 2018 4:55 PM  
**To:** Josey Loh Kah Wai - SGUser  
**Cc:** Motor Claims SG - SG Common  
**Subject:** RE: Accident involving FBM814B & SJU1531Z on 02/10/2018 (Our Ref: 1201800012661)

Hi Josey,

We refer to the above matter.

Both party reported third party exit from parking lot and collided with our insured vehicle.

We are of the opinion that BOLA 24 shall be applied and liability is not in third party favour.

In view of the above, we are intending to reject TP claim.

For your approval/ comments/ instruction.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Mei Kwan (LKKAuto)

**Sent:** Friday, 12 October, 2018 3:51 PM

**To:** [josey.loh@fwd.com](mailto:josey.loh@fwd.com)

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

**Subject:** RE: Accident involving FBM814B & SJU1531Z on 02/10/2018 (Our Ref: 1201800012661)

Dear Sir / Madam,

Thank you for your assignment.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** [josey.loh@fwd.com](mailto:josey.loh@fwd.com) <[josey.loh@fwd.com](mailto:josey.loh@fwd.com)>

**Sent:** Friday, 12 October, 2018 10:15 AM

**To:** Mei Kwan (LKKAuto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com)

**Subject:** Accident involving FBM814B & SJU1531Z on 02/10/2018 (Our Ref: 1201800012661)

Hi Mei Kwan,

We refer to the above matter and our telephone conversation earlier on.

Please liaise with TP repairer for survey arrangement and create the case in Merimen.

Thank you.

Kind Regards


Josey Loh

Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872  
E [josey.loh@fwd.com](mailto:josey.loh@fwd.com)  
W [fwd.com.sg](http://fwd.com.sg)



**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.



**Asher Sng (LKKAuto)**

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Monday, 15 October 2018 5:30 PM  
**To:** BHAS - Jacelyn Loh  
**Subject:** ACCIDENT INVOLVING FBM 814B AND SJU 1531Z ON 02/10/2018  
**Attachments:** OI SKETCH PLAN.pdf

Your Ref: SJU 1531Z  
Our Ref: CC4/FWD18018569/Kea3

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Hi Sir/Mdm,

We refer to the above matter.

**ACCIDENT INVOLVING FBM 814B AND SJU 1531Z ON 02/10/2018**

We attached here with a copy of our insured's accident statement for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client exit from the parking lot and collided into our insured vehicle.

We are of the opinion that BOLA S24 applied and liability is not in your client's favor.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Oct 2018 <a href="#">Edit Reg</a>		11 Oct 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$5700.00</b> <a href="#">Edit Estimates</a>	<b>\$5700.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>William Grover Ashlock</b> , ID: S2767109H									
Main Claimant: <b>TAN SHOU WEI ALLEN</b> , ID: S1167185C									
Vehicle Reg. No.: <b>SJU1531Z</b>		Date of Loss: 02/10/2018 08:00 - :59 <b>[106 Months and 12 Days From LTA Reg Date (Man Yr)]</b>							
Claim Type: <b>TP / 1201800012661</b>		Policy/Cover Note No.: <b>PNMC2018-00002502 (Comprehensive)</b>							
Vehicle Reg. No. (Insured): <b>FBM814B</b>		Policy No. (Claimant): <b>GA03354/1</b>							
		Excess:							
Repairer: <b>BH Auto Services Pte Ltd (Sin Ming)</b> Bldg 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944									
Handling Insurer: <b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700 ... [Handled by <b>Josey Loh</b> ]									
Claimant's Insurer: <b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 23/10/2018]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJU1531Z (1201800012661)  
[FBM814B]  
TP  
TAN SHOU WEI ALLEN  
Oct 2 2018 8:00AM  
[William Grover Ashlock]  
BH Auto Services Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 11:35	Adjuster Immediate Advice	Load HTML	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/11/18 13:48	General View	Load JPG	<input checked="" type="checkbox"/>
2	13/11/18 13:48	General View	Load JPG	<input checked="" type="checkbox"/>
3	13/11/18 13:48	General View	Load JPG	<input checked="" type="checkbox"/>
4	13/11/18 13:48	General View	Load JPG	<input checked="" type="checkbox"/>
5	13/11/18 13:48	General View	Load JPG	<input checked="" type="checkbox"/>
6	13/11/18 13:48	General View	Load JPG	<input checked="" type="checkbox"/>
7	13/11/18 13:48	General View	Load JPG	<input checked="" type="checkbox"/>
8	13/11/18 13:48	General View	Load JPG	<input checked="" type="checkbox"/>
9	13/11/18 13:48	General View	Load JPG	<input checked="" type="checkbox"/>
10	13/11/18 13:48	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
11	13/11/18 13:48	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/10/18 15:58	ACKNOWLEDGEMENT EMAIL TO FWD DD 12.10.2018.	Load PDF	
2	12/10/18 15:58	TP GIA REPORT	Load PDF	
3	15/10/18 16:43	OI GIA REPORT	Load PDF	
4	15/10/18 17:28	MANDATE TO REJECT TP CLAIM	Load PDF	
5	15/10/18 17:28	EMAIL WSP TO REJECT TP CLAIM	Load PDF	
6	23/10/18 11:30	EMAIL FROM TP TO WKSP	Load PDF	
7	23/10/18 11:30	TP ESTIMATE - MARKED	Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		<a href="#">Reset</a>   <a href="#">Save</a>   <a href="#">Print</a>
There are no document checklists configured.		
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%; margin-top: 5px;"></div>		
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

# LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18018569/KEA3Q2

Date: 14/11/2018

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2018-00002502

Claimant Vehicle No: SJU1531Z Insured Vehicle No: FBM814B

Date of Loss: 02/10/2018 Nature of Claim: TP Claim No: 1201800012661

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU1531Z**  
 Make & Model: **HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A)** Engine No: **G4FC9U749193**  
 Reg. Date: **20/11/2009 (Man. Year: 2009)** Chassis No: **KMH DU41BMAU896556**  
 Colour: **Metallic Blue** Odometer: **236021 km**  
 Engine Capacity: **1591 cc**  
 Market Value/New Car Price: **N/A**  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: **195/60 R15** Rear Tyre Size: **195/60 R15**  
 Front Left Side: **Yokohama 4 mm** Rear Left Side: **Yokohama 8 mm**  
 Front Right Side: **Yokohama 4 mm** Rear Right Side: **Yokohama 8 mm**

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,327.24	504.16	823.08	62.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	920.00	415.00	505.00	54.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,247.24</b>	<b>919.16</b>	<b>1,328.08</b>	<b>59.10</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>700.00</b>		
<b>(S\$)</b>	<b>2,247.24</b>	<b>700.00</b>	<b>1,547.24</b>	<b>68.85</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>157.31</b>	<b>49.00</b>	<b>108.31</b>	<b>68.85</b>
<b>Nett Amount (S\$)</b>	<b>2,404.55</b>	<b>749.00</b>	<b>1,655.55</b>	<b>68.85</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 11/10/2018

Date Inspected: 11/10/2018 Inspected At:

BH Auto Services Pte Ltd (Sin Ming)  
 Blk 1 Sin Ming Industrial Estate Sector C,  
 #01/111/113/115/117  
 Singapore 575636

Estimated Period of Repair: 2.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2018)
<b>Parts:</b> 143	HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJU1531Z)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP RH	Serviceable	480.00 FL	*- FL
2	1		*FRONT HEADLAMP LOWER BRACKET RH	Serviceable	30.00 FL	*- FL
3	1		*FRONT BUMPER	Bent / Buckled	461.40 FL	*461.40 FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	19.00 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Distorted	47.00 FL	*47.00 FL
6	1		*FRONT BUMPER FOG LAMP COVER RH	Dented	25.30 FL	*25.30 FL
7	1		*FRONT BUMPER LOWER GARNISH	Distorted	44.00 FL	*44.00 FL
8	1		*FRONT BUMPER UNDER COVER	*Check	43.20 FL	*- FL
9	1		*FRONT BUMPER INNER SPONGE	Serviceable	113.40 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Repair	254.00 FL	*- FL
11	1		*FRONT FENDER INNER SHIELD RH	Serviceable	48.00 FL	*- FL
12	3		*FRONT HEADLAMP CLIPS RH	Not Necessary	9.00 FS	*- FS
13	10		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
14	4		*FRONT BUMPER LOWER GARNISH CLIPS	Necessary	12.00 FS	*12.00 FS
15	4		*FRONT BUMPER UNDER COVER CLIPS	*Check	12.00 FS	*- FS
16	4		*FRONT FENDER INNER SHIELD CLIPS RH	Not Necessary	12.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,640.30</b>	<b>619.70</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>313.06</b>	<b>115.54</b>
<b>Total Parts (\$\$)</b>	<b>1,327.24</b>	<b>504.16</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS ,PANEL BEAT ,CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	400.00	200.00
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITATES	New	300.00	200.00
3	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS	New	80.00	0.00
4	PROVIDE SKILL LABOUR AND WATER PROOF SEALANT FOR ALL REPLACE AND REPAIR WORKS	New	80.00	0.00
5	DISCONNECT ,CHECK ,RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING ,HARNESS ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED PARTS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	60.00	15.00
<b>Gross Labour Cost (\$\$)</b>			<b>920.00</b>	<b>415.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >