

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 | Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: YP6237P181010

Estimate

Customer

Name: AXA Insurance Singapore Pte Ltd

Address: Motor Claims Department

8 Shenton Way #27-01

AXA Tower

Singapore 068811

Date:

11-10-18

Vehicle No: YP6237P

Model/Make: Mitsubishi Fuso

FM65FM2RDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Rh Windscreen Glass <i>one</i>	\$ 1,526.00	
2	Windscreen Weatherstrip <i>cut</i>	\$ 691.50	
3	Wiper Panel	\$ 2,436.60	
4	Corner Panel <i>o/s</i> <i>100/100</i>	\$ 383.60	
5	"FUSO" Mark <i>rec</i>	\$ 280.10	
6	Grille <i>one</i>	\$ 978.10	
7	Grille "Mitsubishi Logo" Motif <i>11</i>	\$ 155.30	
8	Panel <i>2</i>	\$ 3,263.20	
9	"Corporate" Advertisement & Artwork <i>rec</i>	\$ 350.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,000.00	
	To putty & spray painting & including touch up paint on accident affected	\$ 600.00	
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 200.00	
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 11,944.40

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

Not Acknowledged
LH
before ph. before painting
12/10/18
4 day.

Liu's Auto Consultants hence notify the insurer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: