

# **ESTIMATE TO REPAIR**

VEHICLE NO. : SKW 3272 K  
 MAKE : MAZDA  
 MODEL : 2 5-DOOR HATCHBACK 1.5L SP.6EAT  
 YEAR : 2015  
 CHASSIS NO : JM6DJ2HAA01100508

|                |   |
|----------------|---|
| SURVEYOR NAME  | : |
| DATE OF SURVEY | : |
| TIME OF SURVEY | : |

DATE : 10-Oct-18  
 DATE OF ACCIDENT : 8-Oct-18  
 THIRD PARTY REF : SLJ 905 U / AIG

| Qty     | Parts Description/ Labour                  | Type   | Unit Price | Nett Item Amt | Amount             |
|---------|--------------------------------------------|--------|------------|---------------|--------------------|
| 1 pc    | Rear Bumper                                |        |            |               | \$ 850.80          |
| 2 pcs   | Rear Bumper Side Retainer                  |        | \$ 25.90   |               | \$ 51.80           |
| 1 pc    | Rear End Panel                             |        |            |               | \$ 380.20          |
| 1 pc    | Rear End Panel Garnish                     |        |            |               | \$ 73.30           |
| 1 pc    | Tailgate                                   |        |            |               | \$ 911.10          |
| 1 pc    | Tailgate Lock                              |        |            |               | \$ 202.10          |
| 1 pc    | Tailgate Rubber                            |        |            |               | \$ 160.50          |
| 1 pc    | Tailgate Centre Emblem                     |        |            |               | \$ 58.20           |
| 1 pc    | Tailgate MAZDA 2 Emblem                    |        |            |               | \$ 55.50           |
| 1 pc    | Tailgate SKYACTV Emblem                    |        |            |               | \$ 64.70           |
|         |                                            |        |            |               | \$ 2,808.20        |
|         | Less 20%                                   |        |            |               | \$ 561.64          |
|         |                                            |        |            |               | \$ 2,246.56        |
| 1 tube  | Rear Windscreen Sealant                    | S.Nett |            |               | \$ 40.00           |
| 1 pc    | Rear Number Plate                          | S.Nett |            |               | \$ 40.00           |
| 1 set   | Rear Bumper Sensor                         | S.Nett |            |               | \$ 200.00          |
|         | To putty and spray painting.               |        |            |               | \$ 800.00          |
|         | To transfer tailgate fittings.             |        |            |               | \$ 80.00           |
|         | To remove and refix rear windscreen glass. |        |            |               | \$ 120.00          |
|         | To anti-rust.                              |        |            |               | \$ 60.00           |
|         | Labour Charges.                            |        |            |               | \$ 700.00          |
| TG-RA/- | <b>TOTAL</b>                               |        |            |               | <b>\$ 4,286.56</b> |
|         |                                            |        |            |               |                    |

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721  
 Tel:65-64520893 Fax:65-64589127 Website : www.LTM.sg  
 Co.Reg No.199307277D GST Reg No.M2-0019086-0