

ASS. REC. BY:

REF:

CS/CTI18018612/R/qd3et

Special Instruction:

Surveyor:  
Meinen

Peroul

From (Person):

Irene Fay

of

CTI

Date/Time:

12/10/18 @ 3:20pm

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8LH 216 K

Insured:

at Workshop m/s

Cycle & Caminge Ind.  
188 pondch loop

Tel:

9186 5109

of

Policy No:

DMPCSN3094911700

Claim No:

SNM18D04857C01

Sum Insured:

Excess:

\$90000

Make of Veh:

(Client's Record)

D.O.A.

09/10/18

CA / ☒ REV / REP. / REV 24 HRS

15/10/2018

H.O.D. Endorsement:

Date/Time: 12/10/18 @ 5:43pm

Person Contacted:

Yik

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction	( <input checked="" type="checkbox"/> ) Estimate
15/10/18 @ 11:40am	Report to Irene Fay via Meinen.	8LH 216K-CC3/CTI18005826/R/mq3
16/10/18 @ 3:44pm	Alfred informed C/A via Megamer.	Est: 28/3/18
17/10/18 @ 10:27am	Informed Mr Yik C/A & Ex: \$900 by email.	
17/11/18 @ 10:42am	Confirmed with Mr Yik final fix \$16976.30, 5 days.	
	(Red @ 6143.05, 36%)	

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
☒ TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLH 216K  
 at Workshop m/s C8C  
 of Parragon Loop  
 Insured: CTI  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: 900  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: 137K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLH 216K Yr Regn: 2016 / OCT  
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: MERCEDES PANO C180 AVATAR C.C 1595  
 Colour: GREY A/C: Insured / Std / NI / NA  
 Sp.Reading: 30400 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WPD 2050402R 213607  
 Gen. Cond: Good / ☒ Fair / Poor / Burnt  
 Steering: ☒ Inorder / Jammed / Leaked / Burnt or  
 Brake: ☒ Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / 8/Rim / STD A/Rim or  
 Tyre Size: F: 225/50R17  
 R: 17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or CONTINENTAL  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 09/10/18 D.O.I. 15/10/18  
 Survey held at C8C (CPL)  
 Des. of Damages: ☒ Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 25 FEB 2019

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation: \_\_\_\_\_

Photos

Others

TOTAL

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format : ALERTLump Sum / I.B.I: (\$ 1099630)220120

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Oct 2018		12 Oct 2018 15:20 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHUA CHONG PIEN			Date of Loss:	09/10/2018 00:00 - :59
Vehicle Reg. No.:	SLH216K			Policy/Cover Note No.:	DMPCSN3094911700 (Comprehensive)
Claim Type:	OD / SNM18D04857C01			Excess:	S\$900.00
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300				
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/10/2018]				
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT				

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Monday, 25 February 2019 11:42 AM  
**To:** 'Tony Lim'; Yik Chan Hoe; Rasul (LKKAUTO); SUR; Dennis Yap  
**Subject:** RE: SLH216K final bill

Dear Mr Yik,

WITHOUT PREJUDICE

Confirm final fig \$10,976.30 before excess \$900.00 & GST and 5 repair days.

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,  
Shiau Chan (Ms) | Case Handler  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,  
#02-25 | S(408933)

-----Original Message-----

From: Tony Lim <tony.lim@cyclecarriage.com.sg>  
Sent: Monday, 18 February 2019 4:31 PM  
To: Yik Chan Hoe <chanhoe.yik@cyclecarriage.com.sg>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>; Dennis Yap <dennis.yap@cyclecarriage.com.sg>  
Subject: RE: SLH216K final bill

Hi Yik,

As per attached.

Thank you.

Warmest Regards,  
Tony Lim

-----Original Message-----

From: Yik Chan Hoe  
Sent: Friday, 15 February 2019 5:35 PM  
To: 'Rasul@lkkauto.com' <Rasul@lkkauto.com>; 'sur@lkkauto.com' <sur@lkkauto.com>; Dennis Yap <dennis.yap@cyclecarriage.com.sg>  
Cc: Tony Lim <tony.lim@cyclecarriage.com.sg>  
Subject: SLH216K final bill

Hi Rasul,

Fyna.

Aside to Dennis,

Please forward the photos to Rasul.

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 17 October 2018 10:27 AM  
**To:** Yik Chan Hoe  
**Cc:** SUR  
**Subject:** VEHICLE SLH 216K (DOA: 09/10/2018)

Dear Mr Yik,

As instructed by our client, please proceed to repair the **insured vehicle SLH 216K (Excess \$900/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	12 Oct 2018 15:19	Clim Veh Model Changed	(202036) MERCEDES-BENZ C180 1.6 (A).	Irene Tay Hui Ping
2	12 Oct 2018 15:19	Clim Created	Reg No: SLH216K. Policy No: DMPCSN3094911700. Acct Date: 2018/10/09. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Cycle & Carriage Industries Pte Ltd (Pandan Loop). Ins.Status => Incoming Claim	Irene Tay Hui Ping
3	12 Oct 2018 15:20	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):PLEASE SURVEY AND REVERT	Irene Tay Hui Ping
4	12 Oct 2018 15:20	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/10/23	Irene Tay Hui Ping
5	12 Oct 2018 15:20	Adj Mandate Set	Approved:0.00.	Irene Tay Hui Ping
6	12 Oct 2018 17:28	Clim Registration Modified	Excess: 0.00 -> 900.00.	Irene Tay Hui Ping
7	12 Oct 2018 17:29	Assignment 1st Accessed		[A] SHIAU CHAN
8	15 Oct 2018 11:15	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] SHIAU CHAN
9	15 Oct 2018 11:18	Adj Rpt Initiated		[A] SHIAU CHAN
10	15 Oct 2018 11:18	Clim Dtl Modified	Driver Name: -> CHUA CHONG PIEN. Circumstances of Loss: -> 24.	[A] SHIAU CHAN
11	15 Oct 2018 11:18	Clim Dtl Modified	Claimant's ID: -> S1420200E.	[A] SHIAU CHAN
12	15 Oct 2018 11:18	Clim Dtl Modified	JPJ Reg. Date: -> 2016/10/21.	[A] SHIAU CHAN
13	15 Oct 2018 11:18	Clim Details Notified		[A] SHIAU CHAN
14	15 Oct 2018 11:39	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/10/23	[A] SHIAU CHAN
15	15 Oct 2018 11:40	Adj Mandate Request	Cur.Reg:14857.61:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
16	16 Oct 2018 15:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/10/23. Mandate Remarks: Proceed to authorize repairs UP TO \$14,857.61 BEFORE Excess of \$900.00. RE-INSPECTION OF VEHICLE REQUIRED.	[I] Alfred Toh
17	16 Oct 2018 15:44	Adj Mandate Set	Approved:14857.61:Proceed to authorize repairs UP TO \$14,857.61 BEFORE Excess of \$900.00. RE-INSPECTION OF VEHICLE REQUIRED.Reinsp:Adj decides.	[I] Alfred Toh

Date From



Date To



Audit Type None

Go

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1945260	15/10/2018 11:18	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLH216K		10.70

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 15 Oct 2018

**Preliminary Advice**

Vehicle No	: SLH216K	Accident Date	: 09/10/2018
Make	: MERCEDES-BENZ C180	Policy No.	: DMPCSN3094911700
Assignment Date	: 12/10/2018	Excess	: S\$900.00
Date of Inspection	: 15/10/2018	Est. Duration of Repair	: 5.00
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,538.47
Revised Amount	:S\$	8,728.20
Check Items (Estimated)	:S\$	6,129.41
Total	:S\$	14,857.61

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	137,000.00
COE / PARF Rebate	:S\$	74,096.00
Salvage Value	:S\$	
Margin for Repair	:S\$	62,906.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0200E
Vehicle Details	
Vehicle No.:	SLH216K
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180 AVANTGARDE (R17 LED)
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	27491030729140
Chassis No.:	WDD2050402R213607
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$35,663.00
Original Registration Date:	21 Oct 2016
First Registration Date:	21 Oct 2016
Transfer Count:	1
Actual ARF Paid:	\$36,929.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Oct 2026
PARF Rebate Amount:	\$27,696.00
Intended COE Rebate Details	
COE Expiry Date:	20 Oct 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,903.00
COE Rebate Amount:	\$46,400.00
<b>Total Rebate Amount:</b>	<b>\$74,096.00</b>

The information contained herein is correct as at 15 Oct 2018

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	10/10/2018 13:24
Date Of Accident	09/10/2018 08:30
Exact Location Of Accident	356 ALEXANDRA RD CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH216K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHUA CHONG PIEN
NRIC No	S1420200E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94557568
Alternative Phone No	OFFICE-94557568

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3094911700
Cover Note Number	

### Driver

Name of Driver	CHUA CHONG PIEN
NRIC No	S1420200E
Date Of Birth	28/10/1960
Occupation	INDOOR
Date Of Driving Pass	02/11/1982
Driving Experience	35 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94557568
Fax Number	
Contact Number	OFFICE-94557568
EMail Address	NOEMAIL

Address	BLK 3 MARINE TERRACE #08-286
Postcode	440003
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

WHILE TURNING LEFT IN THE CARPARK, MY CAR SKIDDED SLIGHTLY DUE TO THE WET SURFACE AND KNOCKED INTO THE PILLAR.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REFER CSE YIK
Was there any audio recorded?	NO

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, <sup>regulators</sup> law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

**Yik Chan Ho**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272  
Email: chanhoe.yik@cyclocarriage.com.sg

Reporting Centre Personnel's  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While turning left in the carpark,  
my car skidded slightly due to  
the wet surface and knocked  
into the pillar.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

**Yik Chan Hoo**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272  
Email: chanhoe.yik@cyclocarriage.com.sg

Reporting Centre Personnel's  
Name:  
NRIC/FIN No.:

**CERTIFICATE OF INSURANCE**

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.

DMPCSN3094911700

Engine No : 27491030729140

Chassis No: WDD2050402R213607

1. Index Mark and Registration  
Number of Vehicle

SLH216K

2. Name of Policy Holder

MR CHUA CHONG PIEN

3. Effective date of the Commencement of Insurance for  
the purposes of the Regulations, Ordinance or Enactment

13 DECEMBER 2017  
(10:58 HOURS)  
20 APRIL 2019

NAMED DRIVERS EX SECT. I.....S\$900.00  
IN ADDITION TO NAMED DRIVERS EX:  
EX SECT. I - AGE <= 25.....S\$3,000.00  
EX SECT. I - AGE >= 26.....S\$500.00  
\* AGE AS AT DATE OF ACCIDENT  
EX ON WINDSCREEN.....S\$100.00

4. Date of Expiry of Insurance

5. Persons or Classes of Persons entitled to drive \*

(A) THE POLICYHOLDER.

(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR  
REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A  
COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use: \*

USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS.  
THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD TUITION DRIVING TEST RACING PACE-MAKING, RELIABILITY  
TRIAL, SPEED-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS  
OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

EXCESS WHICHEVER IS APPLICABLE FOR LOSSES OCCURRING OUTSIDE SINGAPORE (CONSTRUCTIVE TOTAL LOSS / THEFT)  
WILL BE DOUBLED.

ONE TIME WAIVER OF EXCESS FOR THE FIRST S\$1,000 WILL APPLY TO THE INSURED AND NAMED DRIVERS IN THE EVENT  
OF OWN DAMAGE CLAIM AT OUR AUTHORISED WORKSHOPS FOR EACH POLICY YEAR.

HIRE PURCHASE CO. : SING INVESTMENTS & FINANCE LTD AS HP OWNER


\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)  
and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

**I/We hereby Certify** that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles  
(Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia). Please see reverse  
For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.



undersigned By:

Authorised Officer



Authorised Signatory

REPUBLIC OF SINGAPORE DRIVING LICENCE

Picture Number: S1420200E

Name: CHUA CHONG PIEN

Birth Date: 28 Oct 1960

Issue Date: 02 Jan 2003

000080805G

REPUBLIC OF SINGAPORE

IDENTITY CARD NO: S1420200E

Name: CHUA CHONG PIEN

蔡崇平

Race: CHINESE

Date of Birth: 28-10-1960

Country of Birth: SINGAPORE

Sex: M

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: 02 Nov 1982

NP 428A

Licence No: S1420200E

WCE

0217982

NRIC No: S1420200E

Blood Group: O+

Date of Issue: 08-01-1992

APT BLK 3 MARINE TERRACE #08-286

SINGAPORE 440003

NRIC No: S1420200E

Date: 19-08-1999

No: 3040636

FOR C&C USE ONLY



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SLH216K

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

WIP No  
Reg No/Reg Date  
Date In/Mileage  
Chassis No  
Engine No  
Make/Model  
Colour/Trim

## Vehicle &amp; Document Information

27508  
SLH216K / 21/10/2016  
/ 30223  
WDD2050402R213607  
27491030729140  
MB/MB C 180 SEDAN (W205) "AVANTGARDE / A  
027 775 Iridium Sil/ 041 101 Black ARTIC

Account No	Terms	Date/Time Printed	CSE	Operator					
WC000668	Credit	10/10/2018/ 16:04	YK	395 / Yik Chan Hoe					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
Z REQUEST									
Customer Request									
M BPNSUN									
POLICY NO/ACC DATE : DMPASN3094911760 // 09/10/2018 DRIVE IN/EXCESS									
: 10/10/2018 // TBA DATE IN/DATE SURVEY: BY/AUTHORIZED ON : PLS									
SELECT MECH NO "699" AND KEY									
S BPNSUB									
1 PC FRONT NO PLATE									
A BPILAB									
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW									
BODY PANELS WITH REFINISH.									
A BPIRES									
RESPRAY FRONT BUMPER AND RIGHT FRONT FENDER									
A BPILAB									
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO									
STANDARD SETTINGS.							0.10	380.00	
A BPILAB									
CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT									
M RIGHT FRONT FENDER									
M FRONT BUMPER									
M LEFT FRONT BASIC MOUNTING FOR BUMPER									
M RIGHT FRONT BASIC MOUNTING FOR BUMPER									
M FRONT IMPACT ABSORBER									
M FRONT BOTTOM BASIC MOUNTING FOR BUMPER									
M FRONT TOP BASIC MOUNTING FOR BUMPER									
M LEFT FRONT BUMPER MOUNTING RAIL									
M RIGHT FRONT BUMPER MOUNTING RAIL									
M FRONT BUMPER GRILLE									
M RIGHT FRONT BUMPER GRILLE									
M FRONT CPA RADAR SENSOR									
M FRONT DISTANCE SENSOR									
M [STR] BLIND RIVET									
M FRONT LICENSE PLATE MOLDING									

Confirmed &amp; accepted by

Yik Chan Hoe  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4353 HP: 9186 5100 Fax: 6872 1272  
Email: chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SLH216K

CHINA TAIPIING INSURANCE (S) PTE LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

WIP No 27508  
Reg No/Reg Date SLH216K / 21/10/2016  
Date In/Mileage / 30223  
Chassis No WDD2050402R213607  
Engine No 27491030729140  
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A  
Colour/Trim 027 775 Iridium Sil/ 041 101 Black ARTIC

### Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	10/10/2018/ 16:04	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M FRONT BUMPER COVER, TOWING EYE	1.00	63.10	00.00	63.10
M FRONT SRS PRESSURE SENSOR	1.00	182.62	00.00	182.62
M FRONT RADIATOR GRILLE AIR DUCT	1.00	125.66	00.00	125.66
M RADIATOR GRILLE	1.00	130.01	00.00	130.01
M LEFT HEADLAMP UNIT	1.00	3126.25	00.00	3126.25
M RIGHT HEADLAMP UNIT	1.00	3126.25	00.00	3126.25

Resue  
Hp 90010068  
5 days

15/10/18 @ 1045  
EXCESS: 900

Resue  
Resurvey by paint

17/10/18

17173.35

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Confirmed & accepted by

Authorized signatory and company stamp

Nett 16,538.47  
7% GST on 16538.47 1157.69  
Total Payable 17,696.16

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg

17119.35





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## Finalization

## ESTIMATE FOR SLH216K

CHINA TAIPING INSURANCE (S) PTE LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

### Vehicle & Document Information

WIP No 27508  
Reg No/Reg Date SLH216K / 21/10/2016  
Date In/Mileage 22/10/2018 / 30876  
Chassis No WDD2050402R213607  
Engine No 27491030729140  
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A  
Colour/Trim 027 775 Iridium Sil/ 041 101 Black ARTIC

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	15/02/2019/ 17:25		395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPN5UN POLICY NO/ACC DATE : DMPCSN3094911760 // 09/10/2018 DRIVE IN/EXCESS : 10/10/2018 // \$900.00 DATE IN/DATE SURVEY: 15/10/2018 // RASUL LKK BY/AUTHORIZED ON : 17/10/2018 // VERON LKK				
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				1440.00
A BPIRES RESPRAY FRONT BUMPER AND RIGHT FRONT FENDER				1200.00
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.			0.10	380.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT NETT				120.00
X RIGHT FRONT FENDER	1.00	899.51	00.00	899.51
X FRONT BUMPER	1.00	1536.50	00.00	1536.50
X RIGHT FRONT BASIC MOUNTING FOR BUMPER	1.00	70.92	00.00	70.92
X FRONT IMPACT ABSORBER	1.00	154.81	00.00	154.81
X FRONT TOP BASIC MOUNTING FOR BUMPER	1.00	65.64	00.00	65.64
X FRONT CPA RADAR SENSOR	1.00	1145.00	00.00	1145.00
X [STR] BLIND RIVET	4.00	4.07	00.00	16.28
X RIGHT HEADLAMP UNIT	1.00	3188.78	00.00	3188.78
X FRONT BOTTOM BASIC MOUNTING FOR BUMPER	1.00	106.39	00.00	106.39
X BPNEXC INSURANCE EXCESS				-900.00
X FRONT SUPPORT PANEL CONSOLE	1.00	208.24	00.00	208.24
X LEFT FRONT CROSSMEMBER BRACKET	1.00	67.61	00.00	67.61
X COVER F ENGINE COMP. BM	1.00	187.61	00.00	187.61
X FRONT SRS PRESSURE SENSOR	1.00	189.01	00.00	189.01

Confirmed & accepted by

Yik Chan Hoe  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272  
Email: chanhoe.yik@cyclecarriage.com.sg

7% GST on 10076.30  
Nett 10,076.30  
705.34

Total Payable 10,781.64

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

# ESTIMATE FOR SLH216K

## SUPPLEMENTARY

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information  
WIP No 27508  
Reg No/Reg Date SLH216K / 21/10/2016  
Date In/Mileage 22/10/2018 / 30876  
Chassis No WDD2050402R213607  
Engine No 27491030729140  
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A  
Colour/Trim 027 775 Iridium Sil / 041 101 Black ARTIC

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	15/02/2019/ 17:25		395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X FRONT SUPPORT PANEL CONSOLE	1.00	208.24	00.00	208.24
X LEFT FRONT CROSSMEMBER BRACKET	1.00	67.61	00.00	67.61
X COVER ENGINE COMP. BM	1.00	187.61	00.00	187.61

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

**Yik Chan Hoe**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272  
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

	Nett	463.46
7% GST on	463.46	32.44

**Total Payable 495.90**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Oct 2018		12 Oct 2018 15:20 <a href="#">Edit Adj Rpt</a>	<b>\$10,976.30</b> <a href="#">Edit Estimates</a>	<b>\$10,976.30</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	CHUA CHONG PIEN, ID: S1420200E								
Vehicle Reg. No.:	SLH216K	Date of Loss:	09/10/2018 00:00 - :59 [23 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM18D04857C01	Policy/Cover Note No.:	DMPCSN3094911700 (Comprehensive)						
		Excess:	S\$900.00						
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 23/10/2018]								
Driver/Custodian:	CHUA CHONG PIEN ( / Male) , NRIC: S1420200E Email:								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
<ul style="list-style-type: none"> <li>CHINA_TAIPIING (16/10/2018): Alert - Adj Mandate Approved (S\$14857.61) - SLH216K - Claim Handler: Irene Tay H...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLH216K (SNM18D04857C01)  
 OD  
 Oct 9 2018 12:00AM  
 [CHUA CHONG PIEN]  
 Cycle & Carriage Industries Pte Ltd
















































[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/10/18 11:39	Adjuster Immediate Advice	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/10/18 13:26	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
2	16/10/18 13:26	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
4	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
5	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
6	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
7	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
8	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
9	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
10	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
11	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
12	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
13	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
14	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
15	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
16	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
17	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
18	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
19	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
20	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
21	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
22	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
23	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
24	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
25	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
26	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
27	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
28	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
29	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
30	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
31	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
32	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
33	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
34	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>
35	16/10/18 13:26	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
36	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
37	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
38	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
39	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
40	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
41	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
42	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
43	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
44	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
45	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
46	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
47	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
48	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
49	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
50	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
51	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
52	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
53	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
54	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
55	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
56	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
57	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
58	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
59	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
60	16/10/18 13:26	General View	 Load JPG	<input checked="" type="checkbox"/>	
61	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
62	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
63	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
64	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
65	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
66	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
67	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
68	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
69	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
70	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
71	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
72	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
73	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
74	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
75	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
76	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
77	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
78	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
79	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
80	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
81	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
82	25/02/19 11:45	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	15/10/18 11:39	ESTIMATE	Load PDF		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
2	26/02/19 11:06	Supplementary	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>	
<div></div>	
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer	
<small>Note: Remarks are private unless you show it to other parties.</small>	

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909**Our File No:** CS/CTI18018612/R1QD3E2**Date:** 26/02/2019REFERENCE

Insured/Claimant:	CHUA CHONG PIEN	Policy No:	DMPCSN3094911700
Date of Loss:	09/10/2018	Nature of Claim:	OD
		Claim No:	SNM18D04857C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH216K	Engine No:	27491030729140
Make & Model:	MERCEDES-BENZ C180, 1.6 (A)	Chassis No:	WDD2050402R213607
Reg. Date:	21/10/2016 (Man. Year: 2016)	Odometer:	30400 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$137,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,473.35	7,836.30	4,637.05	37.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	3,140.00	1,560.00	33.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,173.35</b>	<b>10,976.30</b>	<b>6,197.05</b>	<b>36.09</b>
<b>- Excess (S\$)</b>	<b>900.00</b>	<b>900.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>16,273.35</b>	<b>10,076.30</b>	<b>6,197.05</b>	<b>38.08</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,139.13</b>	<b>705.34</b>	<b>433.79</b>	<b>38.08</b>
<b>Nett Amount (S\$)</b>	<b>17,412.48</b>	<b>10,781.64</b>	<b>6,630.84</b>	<b>38.08</b>

INSPECTION

Date of Assignment:	12/10/2018
Date Inspected:	15/10/2018 Inspected At:

Cycle & Carriage Industries Pte Ltd  
(Pandan Loop)  
188 Pandan Loop  
Singapore 128378

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD RASUL

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2019)
<b>Parts:</b>	143	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLH216K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NO PLATE	Serviceable	60.00 FS	*- FS
2	1		*RIGHT FRONT FENDER	Bent	899.51 FS	*899.51 FS
3	1		*FRONT BUMPER	Deformed	1,536.50 FS	*1,536.50 FS
4	1		*LEFT FRONT BASIC MOUNTING FOR BUMPER	Necessary	70.92 FS	*70.92 FS
5	1		*RIGHT FRONT BASIC MOUNTING FOR BUMPER	Serviceable	68.53 FS	*- FS
6	1		*FRONT IMPACT ABSORBER	Cracked	154.81 FS	*154.81 FS
7	1		*FRONT BOTTOM BASIC MOUNTING FOR BUMPER	Cracked	106.39 FS	*106.39 FS
8	1		*FRONT TOP BASIC MOUNTING FOR BUMPER	Cracked	65.64 FS	*65.64 FS
9	1		*LEFT FRONT BUMPER MOUNTING RAIL	Serviceable	11.22 FS	*- FS
10	1		*RIGHT FRONT BUMPER MOUNTING RAIL	Serviceable	11.22 FS	*- FS
11	1		*FRONT BUMPER GRILLE	Serviceable	172.64 FS	*- FS
12	1		*RIGHT FRONT BUMPER GRILLE	Serviceable	59.28 FS	*- FS
13	1		*FRONT CPA RADAR SENSOR	Cracked	1,145.00 FS	*1,145.00 FS
14	4		*FRONT DISTANCE SENSOR	Serviceable	688.28 FS	*- FS
15	4		*[STR] BLIND RIVET	Necessary	16.28 FS	*16.28 FS
16	1		*FRONT LICENSE PLATE MOLDING	Serviceable	120.86 FS	*- FS
17	1		*FRONT BUMPER COVER, TOWING EYE	Serviceable	63.10 FS	*- FS
18	1		*FRONT SRS PRESSURE SENSOR	Not Working	189.01 FS	*189.01 FS
19	1		*FRONT RADIATOR GRILLE AIR DUCT	Serviceable	125.66 FS	*- FS
20	1		*RADIATOR GRILLE	Serviceable	130.01 FS	*- FS
21	1		*LEFT HEADLAMP UNIT	Serviceable	3,126.25 FS	*- FS
22	1		*RIGHT HEADLAMP UNIT	Cracked	3,188.78 FS	*3,188.78 FS
23	1		*FRONT SUPPORT PANEL CONSOLE	Cracked	208.24 FS	*208.24 FS
24	1		*LEFT FRONT CROSSMEMBER BRACKET	Bent	67.61 FS	*67.61 FS
25	1		*COVER F ENGINE COMP. BM	Cracked	187.61 FS	*187.61 FS
					<b>Total Parts (\$\$)</b>	<b>12,473.35      7,836.30</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	2,400.00	1,440.00
2	RESPRAY FRONT BUMPER AND RIGHT FRONT FENDER	New	1,800.00	1,200.00
3	USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
4	CHECK HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	120.00
Gross Labour Cost (\$\$)			<b>4,700.00</b>	<b>3,140.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >