

12/03/2003

ASS. REC. BY:

REF: OS/MSG18018622/Kvd3¹²

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSG

Date/Time: 15/10/18 @ 11:25am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJA 5969Z

Insured:

XE 2722B

at Workshop m/s

eheng Hoe Motor

Tel:

6481 2001

of

Blk 1019, Yishun Ind. Park A #01-374

Policy No:

B28912702 MCC

Claim No:

573010

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

11/10/2018

Insp: eheng hoe (AMK)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS 'up'

Date/Time:

12:02pm @ 15/10/18

Person Contacted:

Donylyn

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJA 5969Z-CC4/AIG11009826/A/a3/c2

D.O.A: 20/5/2011

XE 2722B - X.

16/10/18

Send preli revised via merimen, pending parts prices from repairer

3/11

11487.00 Confirm E fudg (Red 2754.05, 1990)

ASS. REC. BY:

REF: *msg-1*

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$ 79k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.: Yes or No

Lum Sum:

1-B/26 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STA 59692

Yr Regn:

05, 13

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

BMW 320i

c.c

1997

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

141602

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA3B16060NP 55142

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD / ☐ RIm or

Tyre Size:

F:

225/50R17

R:

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /
TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

11/10/18

D.O.I.

15/10/18

Survey held at

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/10 File pass to Catherine

RECEIVED 04 JAN 2019

3/1/2019

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 3/1 - typist

Days Of Repair:

14

Resurvey No. of Trip:

2

Survey Fee:

200

Transportation:

10

S - RS, SI

Fixtures

Others

TOTAL

210

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

mer, men

Lump Sum / I.B.I. (\$

11,497

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 16 Oct 2018

Preliminary Advice

Insured Vehicle No	: XE2722B	Accident Date	: 11/10/2018
TP Vehicle No	: SJA5969Z	Assignment Date	: 15/10/2018
Make	: BMW 320I	Est. Duration of Repair	: 14.00
Date of Inspection	: 15/10/2018		
Inspection At	: CHENG HOE MOTOR SERVICE (HQ) BLK 1019, YISHUN IND. PARK A, #01-374 SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,920.00 (LABOUR ONLY)
Revised Amount	:S\$	3,230.00 (LABOUR ONLY)
Check Items (Estimated)	:S\$	250.00
Total	:S\$	3,480.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.
Pending parts prices from repairer.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Oct 2018		15 Oct 2018 11:25 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SAMWOH CORPORATION PTE LTD, Co. Reg. No.: 198502202Z		
Main Claimant:	SEE CHIN YONG MILTON (SHI ZHENRONG MILTON)		
Vehicle Reg. No.:	SJA5969Z	Date of Loss:	11/10/2018 15:00 - :59 [64 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 573010	Policy/Cover Note No.:	B28912702MKC (Comprehensive) Coverage: 08/03/2018 - 07/03/2019
Vehicle Reg. No. (Insured):	XE2722B	Policy No. (Claimant):	
		Excess:	
Repairer:	Cheng Hoe Motor Service (HQ) BLK 1019, YISHUN IND. PARK A, #01-374, 768761 Yishun - Tel: 67556142		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/10/2018]		
Driver/Custodian (Insured):	WANG JIA AN (), NRIC: G2149424R, Tel: +6583573817		
Adj Asg. Remarks:	Third Party Pre-Repair Survey. TP selected LKK (Kenneth Kong) to be SJE. Please arrange at AMK Branch. Liability : Against OI Contact : Ms Dorlyn Li @ 6481 2001.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

500+ dealers
competed to
buy my car!

Sell ur Car for More Cash
Highest Price or Get \$100 Free
Get Paid Now, Handover Later

SELL YOUR CAR

BMW 320

Price Range

Depreciation

2013

Vehicle Type

Submit

Advanced
Search

Used Car Comparison

--- Comparing 2 Vehicles ---

BMW 3 Series 320i

BMW 3 Series 320i Sport



NO IMAGE AVAILABLE



NO IMAGE AV

Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Use search bar above to select another car to compare.

Use search bar above to select another car to compare.

CAR DETAILS

Price	\$78,800	\$86,800
Instalment	\$1,178	\$1,198
Registration Date	29-Mar-2013	20-Aug-2013
Manufactured	2012	2013
Mileage	75,000 km	68,000 km
Transmission	Auto	Auto
Engine Cap	1,997 cc	1,997 cc
Road Tax	\$1,210 /yr	\$1,210 /yr
Power	135.0 kW (181 bhp)	135.0 kW (181 bhp)
Curb Weight	1,420 kg	1,420 kg
Features	2.0L TwinPower Turbocharged Engine, Automatic 8 Speed Step-Tronic Sport Transmission, ABS, Experience Driving ECO Pro/Sports Mode, Paddle Shifts.	BMW 2.0L Twin Power Turbocharged Engine, Automatic 8 Speed Step Tronic Sport Transmission, ABS, Experience Driving ECO Pro/Sports Mode, Paddle Shift.
Accessories	17" Sports Rims, Factory Fitted Audio/GPS/, 2x Electric Sport Seats/Memory, Cruise Control, Parking Assist, Climate Aircon, Rear Knockdown Seats.	17" Sports Rims, Factory Fitted Audio/GPS/, 2 x Electric Sport Seats And Memory, Cruise Control, Parking Assist, Climate Aircon, Rear Knockdown Seats.
Description	High/Flexible Loan Available! Well Maintained By 1 Previous Owner Only! Awesome Drive And Easy To Handle! Superb Fuel Efficiency! A No Headache And Spacious Car! Call Our Friendly Sales Team Now For More Info!	Immaculate Condition, Well Kept And Maintained By Single Owner With Low Mileage Clocked, Always Sheltered Park, Trade In And Loan Available, Hurry Make An Appointment To View This Unit Now.
COE	\$73,301	\$77,989
OMV	\$36,602	\$40,196
ARF	\$38,243	\$43,275
Depreciation	\$13,380 /yr	\$13,420 /yr
No. of Owners	1	1
Type of Vehicle	Luxury	Luxury
Category		

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0098A

Vehicle Details

Vehicle No.: SJA5969Z
Vehicle to be Exported: No
Intended Deregistration Date: 11 Oct 2018
Vehicle Make: B.M.W.
Vehicle Model: 320I AT D/AB 4DR ABS HID NAV
Primary Colour: Grey
Manufacturing Year: 2013
Engine No.: A7550450N20B20B
Chassis No.: WBA3B16060NP55142
Maximum Power Output: 135.0 kW (181 bhp)
Open Market Value: \$39,015.00
Original Registration Date: 31 May 2013
First Registration Date: 31 May 2013
Transfer Count: 0
Actual ARF Paid: \$41,621.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 30 May 2023
PARF Rebate Amount: \$29,134.00

Intended COE Rebate Details

COE Expiry Date: 30 May 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$67,304.00
COE Rebate Amount: \$31,191.00
Total Rebate Amount: \$60,325.00

The information contained herein is correct as at 11 Oct 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 11/10/2018

TP Veh Reg No: XE2722B

Estimate No: ES1891175/AMK

Date: 12 Oct 2018

Policy No: D18MTPV01008447

Veh Reg No: SJA5969Z

Make/Model: BMW 320I AUTO

Chassis No: WBA3B16060NP55142

Engine No: A7550450N20B20B

Reg. Date: 31/05/2013

Estimate Repair Cost to Vehicle No :SJA5969Z

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR BUMPER (PRICE PENDING)	0.00	1 PC	0.00	✓
2 REAR BUMPER REINFORCEMENT (PRICE PENDING)	0.00	1 PC	0.00	✓
3 REAR BUMPER REINFORCEMENT COVER (PRICE PENDING)	0.00	1 PC	0.00	✓
4 REAR BUMPER TOW HOOK COVER (PRICE PENDING)	0.00	1 PC	0.00	✓
5 REAR BUMPER RH REFLECTOR (PRICE PENDING)	0.00	1 PC	0.00	✓
6 REAR BUMPER CENTRE TRIM STRIP (PRICE PENDING)	0.00	1 PC	0.00	✓
7 REAR BUMPER PARKING SENSOR (4PCS) (PRICE PENDING)	0.00	2 SET	0.00	✓
8 REAR BUMPER PDC SENSOR WIRE HARNESS (PRICE PENDING)	0.00	1 SET	0.00	✓
9 REAR BUMPER CENTRE GUIDE (PRICE PENDING)	0.00	1 PC	0.00	✓
10 REAR BUMPER SIDE GUIDE (PRICE PENDING)	0.00	2 PC	0.00	✓
11 REAR BOOT (PRICE PENDING)	0.00	1 PC	0.00	✓
12 REAR BOOT HINGE (PRICE PENDING)	0.00	2 PC	0.00	✓
13 REAR BOOT INNER LOCK (PRICE PENDING)	0.00	1 PC	0.00	✓
14 REAR BOOT INNER RUBBER (PRICE PENDING)	0.00	1 PC	0.00	50gsm
15 REAR BOOT LOGO (PRICE PENDING)	0.00	1 PC	0.00	✓
16 REAR BOOT EMBLEM '320I' (PRICE PENDING)	0.00	1 PC	0.00	✓
17 REAR BOOT INSULATOR (PRICE PENDING)	0.00	1 PC	0.00	✓
18 REAR BOOT REFLECTOR (PRICE PENDING)	0.00	2 PC	0.00	✓
19 REAR BOOT NUMBER PLATE LAMP (PRICE PENDING)	0.00	2 PC	0.00	✓
20 REAR BOOT CONTROL UNIT (SMART OPENER) (PRICE PENDING)	0.00	1 PC	0.00	✓
21 REAR BOOT PUSH BUTTON (PRICE PENDING)	0.00	1 PC	0.00	✓
22 REAR BOOT STRIKER (PRICE PENDING)	0.00	1 PC	0.00	✓
23 REAR BOOT RH HINGE OUTER COVER (PRICE PENDING)	0.00	1 PC	0.00	✓
24 RH TAILLAMP (PRICE PENDING)	0.00	1 PC	0.00	✓
25 RH TAILLAMP PANEL (PRICE PENDING)	0.00	1 PC	0.00	✓
26 REAR END PANEL (PRICE PENDING)	0.00	1 PC	0.00	✓
27 REAR END PANEL INNER TOP GARNISH (PRICE PENDING)	0.00	1 PC	0.00	✓
28 REAR RH FENDER (PRICE PENDING)	0.00	1 PC	0.00	✓
29 REAR RH FENDER INNER TRIM (PRICE PENDING)	0.00	1 PC	0.00	✓
30 REAR RH FENDER INNER TRIM COVER (PRICE PENDING)	0.00	1 PC	0.00	✓
31 REAR RH FENDER LOCK (PRICE PENDING)	0.00	1 PC	0.00	✓
32 REAR RH FENDER TOOL SPONGE (PRICE PENDING)	0.00	1 PC	0.00	✓
33 REAR RH FENDER TOOL SPONGE COVER (PRICE PENDING)	0.00	1 PC	0.00	✓
34 REAR RH FENDER PANEL (PRICE PENDING)	0.00	1 PC	0.00	✓
35 REAR WINDSCREEN GLASS (PRICE PENDING)	0.00	1 PC	0.00	✓
36 REAR WINDSCREEN GLASS MOULDING (PRICE PENDING)	0.00	1 PC	0.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO 201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581
TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department
WS Ref: TP/MSIG/AMK
Claim Type: Third Party
Accident Date: 11/10/2018
TP Veh Reg No: XE2722B

Estimate No: ES1891175/AMK
Date: 12 Oct 2018
Policy No: D18MTPV01008447
Veh Reg No: SJA5969Z
Make/Model: BMW 320I AUTO
Chassis No: WBA3B16060NP55142
Engine No: A7550450N20B20B
Reg. Date: 31/05/2013

Estimate Repair Cost to Vehicle No :SJA5969Z

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 3,920.00
			Add GST @ 7%	274.40
			Total Amount Payable	S\$ 4,194.40

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental charges must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO 201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 11/10/2018

TP Veh Reg No: XE2722B

Estimate No: ES1891175/AMK

Date: 12 Oct 2018

Policy No: D18MTPV01008447

Veh Reg No: SJA5969Z

Make/Model: BMW 320I AUTO

Chassis No: WBA3B16060NP55142

Engine No: A7550450N20B20B

Reg. Date: 31/05/2013

Estimate Repair Cost to Vehicle No :SJA5969Z

Description	U/Price	Quantity	List Price	Amount
			SS	SS
* AMENDMENT *				
Net Price				
1 REAR BUMPER	1,120.00	1 PC	1,120.00	✓
2 REAR BUMPER REINFORCEMENT	432.00	1 PC	432.00	✓
3 REAR BUMPER REINFORCEMENT COVER	72.00	1 PC	72.00	✓
4 REAR BUMPER TOW HOOK COVER	45.00	1 PC	45.00	✓
5 REAR BUMPER RH REFLECTOR	35.00	1 PC	35.00	✓
6 REAR BUMPER CENTRE TRIM STRIP	78.00	1 PC	78.00	✓
7 REAR BUMPER PARKING SENSOR (4PCS)	328.00 X4	1 PC	328.00	✓ 656.00
8 REAR BUMPER PDC SENSOR WIRE HARNESS	357.00	1 SET	357.00	✓
9 REAR BUMPER CENTRE GUIDE	42.00	1 PC	42.00	✓
10 REAR BUMPER SIDE GUIDE	54.00	2 PC	108.00	✓
11 REAR BOOT	1,210.00	1 PC	1,210.00	✓
12 REAR BOOT HINGE	88.00	2 PC	176.00	✓
13 REAR BOOT INNER LOCK	213.00	1 PC	213.00	✓
14 REAR BOOT INNER RUBBER	92.00	1 PC	92.00	✓ 501.00 468.00
15 REAR BOOT LOGO	69.00	1 PC	69.00	✓
16 REAR BOOT EMBLEM '320I'	69.00	1 PC	69.00	✓
17 REAR BOOT INSULATOR	115.00	1 PC	115.00	✓
18 REAR BOOT REFLECTOR	250.00	2 PC	500.00	✓
19 REAR BOOT NUMBER PLATE LAMP	28.00	2 PC	56.00	✓
20 REAR BOOT CONTROL UNIT (SMART OPENER) (PRICE PENDING)	0.00	1 PC	0.00	✓
21 REAR BOOT PUSH BUTTON	47.00	1 PC	47.00	✓
22 REAR BOOT STRIKER	56.00	1 PC	56.00	✓
23 REAR BOOT RH HINGE OUTER COVER	38.00	1 PC	38.00	✓
24 RH TAILLAMP	357.00	1 PC	357.00	✓
25 REAR END PANEL	595.00	1 PC	595.00	✓
26 REAR END PANEL INNER TOP GARNISH	85.00	1 PC	85.00	✓
27 REAR RH FENDER	1,625.00	1 PC	1,625.00	✓
28 REAR RH FENDER INNER TRIM	188.00	1 PC	188.00	✓
29 REAR RH FENDER INNER TRIM COVER	46.00	1 PC	46.00	✓
30 REAR RH FENDER LOCK	18.00	1 PC	18.00	✓
31 REAR RH FENDER TOOL SPONGE	43.00	1 PC	43.00	✓
32 REAR RH FENDER TOOL SPONGE COVER	31.00	1 PC	31.00	✓
33 REAR RH FENDER PANEL	472.00	1 PC	472.00	✓
34 REAR WINDSCREEN GLASS	715.00	1 PC	715.00	✓
35 REAR RH CONTROL MODULE	456.05	1 PC	456.05	✓

1821
7903

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST 201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581
 TEL: 68277660 FAX: 62257402
 ATTN: Motor Claim Department
 WS Ref: TP/MSIG/AMK
 Claim Type: Third Party
 Accident Date: 11/10/2018
 TP Veh Reg No: XE2722B

Estimate No: ES1891175/AMK
 Date: 12 Oct 2018
 Policy No: D18MTPV01008447
 Veh Reg No: SJA5969Z
 Make/Model: BMW 320I AUTO
 Chassis No: WBA3B16060NP55142
 Engine No: A7550450N20B20B
 Reg. Date: 31/05/2013

Estimate Repair Cost to Vehicle No :SJA5969Z

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			9,889.05	9,889.05
Special Net				
36 REAR NUMBER PLATE	80.00	1 PC	80.00	80.00
37 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	40.00
			120.00	120.00
Labour				
38 TOWING	120.00	1 LA	120.00	120.00
39 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	120.00
40 REMOVE & REFIX REAR BUMPER,BOOTLID & ATTACHMENTS,TAILLAMPS,TO CUT,WELD & RENEW REAR END PANEL,REAR RH FENDER,TAILLAMP PANEL,KNOCKING & REPAIR REAR SPARE TYRE PANEL,REAR RH WHEEL HOUSE,LH FENDER ,REAR DOOR & REALIGN THE SAME	1,600.00	1 LA	1,600.00	1,600.00
41 PUTTY & RESPRAY REAR BUMPER,REAR BOOT,BOTH FENDERS,REAR END PANEL,REAR SPARE TYRE PANEL, RH WHEELHOUSE & ALL AFFECTED AREAS	1,400.00	1 LA	1,400.00	1,400.00
42 REMOVE & REFIX REAR SEAT,CARPET,ROOF LINING TO FACILITATE REPAIR	120.00	1 LA	120.00	120.00
43 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN CHASSIS	250.00	1 LA	250.00	250.00
44 REMOVE & REFIX FUEL TANK ASSY TO FACILITATE REPAIR	100.00	1 LA	100.00	100.00
45 RUSTPROOFING	90.00	1 LA	90.00	90.00
			3,800.00	3,800.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581
TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department
WS Ref: TP/MSIG/AMK
Claim Type: Third Party
Accident Date: 11/10/2018
TP Veh Reg No: XE2722B

Estimate No: ES1891175/AMK
Date: 12 Oct 2018
Policy No: D18MTPV01008447
Veh Reg No: SJA5969Z
Make/Model: BMW 320I AUTO
Chassis No: WBA3B16060NP55142
Engine No: A7550450N20B20B
Reg. Date: 31/05/2013

Estimate Repair Cost to Vehicle No :SJA5969Z

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
	14,251.05		Total	S\$ 13,809.05
			Add GST @ 7%	966.63
			Total Amount Payable	S\$ 14,775.68

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

14907.05

* INPUT OF PARTS PRICE

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

~~CASH SALE / WORK ORDER~~
SPEEDO TOWING SERVICE

Bus. Reg. No: 53217861X
H/P: 9767 6774

Nº 9867

Date: 11/05/18

Name / Company CASH.
Vehicle No. SJA 5969 Z BMW
Contact No. 9691 9700
From Town square Ave 3
To Airport (Hawthorn)
Amount \$120/- Remarks (K-Run) (Scam)

- 1) Jump Start
- 2) Tyre Replacement
- 3) Accident / Breakdown
- 4) Multi / Basement
- 5) With Load / Cargo Box
- 6) King Dolly
- 7) Transport Charge
- 8) Low Body Kit
- 9) Door Opening Service
- 10) Crane Up / Winch Out
- 11) Collect Doc / Key
- 12) Petrol Charge

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

**24 HRS
TOWING SERVICE**

Tow Truck Driver

Received By

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO 201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 11/10/2018

TP Veh Reg No: XE2722B

Estimate No: ES1891175/AMK

Date: 24 Oct 2018

Policy No: D18MTPV01008447

Veh Reg No: SJA5969Z

Make/Model: BMW 320I AUTO

Chassis No: WBA3B16060NP55142

Engine No: A7550450N20B20B

Reg. Date: 31/05/2013

Estimate Repair Cost to Vehicle No :SJA5969Z

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
* AMENDMENT *				
Supplementary 1				
List Price				
1 REAR BOOT LH HINGE OUTER COVER	38.00	1 PC	38.00	
2 REAR BOOT LH REFLECTOR BULB HOLDER	76.00	1 PC	76.00	
			114.00	114.00
Total				S\$ 114.00
GST Amount				S\$ 7.98
Total Amount Payable				S\$ 121.98

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18018622/KVD3N2

Date: 07/01/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B28912702MKC
Claimant Vehicle No :	SJA5969Z	Insured Vehicle No :	XE2722B
Date of Loss:	11/10/2018	Nature of Claim:	TP
		Claim No:	573010

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJA5969Z	Engine No:	A7550450N20B20B
Make & Model:	BMW 320I, 2.0 (A)	Chassis No:	WBA3B16060NP55142
Reg. Date:	31/05/2013 (Man. Year: 2013)	Odometer:	141602 km
Colour:	Metallic Grey		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,107.05	8,117.00	2,990.05	26.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	3,380.00	420.00	11.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,907.05	11,497.00	3,410.05	22.88
+ GST 7.00/7.00% (S\$)	1,043.49	804.79	238.70	22.88
Nett Amount (S\$)	15,950.54	12,301.79	3,648.75	22.88

INSPECTION

Date of Assignment:	15/10/2018	
Date Inspected:	15/10/2018 Inspected At:	10 Ang Mo Kio Ind Park 2A #01-04 Repairer: Cheng Hoe Motor Service (HQ) BLK 1019, YISHUN IND. PARK A, #01-374 Singapore 768761

Estimated Period of Repair: 14.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Jan 2019)
Parts:	N/A BMW 320I 2.0 (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJA5969Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent/Cracked	1,120.00 FS	*1,120.00 FS
2	1		*REAR BUMPER REINFORCEMENT	Bent	432.00 FS	*432.00 FS
3	1		*REAR BUMPER REINFORCEMENT COVER	Cracked	72.00 FS	*72.00 FS
4	1		*REAR BUMPER TOW HOOK COVER	Dented	45.00 FS	*45.00 FS
5	1		*REAR BUMPER RH REFLECTOR	Mtg Cracked	35.00 FS	*35.00 FS
6	1		*REAR BUMPER CENTRE TRIM CTRIP	Distorted	78.00 FS	*78.00 FS
7	1		*REAR BUMPER PARKING SENSOR (4 PCS)	Shorted (2 Pcs only)	1,312.00 FS	*656.00 FS
8	1		*REAR BUMPER PDC SENSOR WIRE HARNESS (Set)	Serviceable	357.00 FS	*- FS
9	1		*REAR BUMPER CENTRE GUIDE	Cracked	42.00 FS	*42.00 FS
10	2		*REAR BUMPER SIDE GUIDE	Cracked	108.00 FS	*108.00 FS
11	1		*REAR BOOT	Bent	1,210.00 FS	*1,210.00 FS
12	2		*REAR BOOT HINGE	Bent	176.00 FS	*176.00 FS
13	1		*REAR BOOT INNER LOCK	Dented	213.00 FS	*213.00 FS
14	1		*REAR BOOT LOGO	Necessary	69.00 FS	*69.00 FS
15	1		*REAR BOOT EMBLEM 320I	Necessary	69.00 FS	*69.00 FS
16	1		*REAR BOOT INSULATOR	Deformed	115.00 FS	*115.00 FS
17	1		*REAR BOOT REFLECTOR	O/s Cracked	500.00 FS	*250.00 FS
18	2		*REAR BOOT NUMBER PLATE LAMP	N/s Cracked/O/s Dented	56.00 FS	*56.00 FS
19	1		*REAR BOOT CONTROL UNIT (SMART OPENER)(NPA)	Serviceable	0.00 FS	*- FS
20	1		*REAR BOOT PUSH BUTTON	Buckled	47.00 FS	*47.00 FS
21	1		*REAR BOOT STRIKER	Distorted	56.00 FS	*56.00 FS
22	1		*REAR BOOT RH HINGE OUTER COVER	Dented	38.00 FS	*38.00 FS
23	1		*RH TAILLAMP	Broken	357.00 FS	*357.00 FS
24	1		*REAR END PANEL	Bent	595.00 FS	*595.00 FS
25	1		*REAR END PANEL INNER TOP GARNISH	Dented	85.00 FS	*85.00 FS
26	1		*REAR RH FENDER	Cut	1,625.00 FS	*1,625.00 FS
27	1		*REAR RH FENDER INNER TRIM	Deformed	188.00 FS	*188.00 FS
28	1		*REAR RH FENDER INNER TRIM COVER	Deformed	46.00 FS	*46.00 FS
29	1		*REAR RH FENDER LOCK	Serviceable	18.00 FS	*- FS
30	1		*REAR RH FENDER TOOL SPONGE	Dented	43.00 FS	*43.00 FS
31	1		*REAR RH FENDER TOOL SPONGE COVER	Deformed	31.00 FS	*31.00 FS
32	1		*REAR RH FENDER PANEL	Repair	472.00 FS	*- FS
33	1		*REAR WINDSCREEN GLASS	Serviceable	715.00 FS	*- FS
34	1		*REAR RH CONTROL MODULE	Serviceable	456.05 FS	*- FS
35	1		*REAR BOOT LH HINGE OUTER COVER	Dented	38.00 FS	*38.00 FS
36	1		*REAR BOOT LH REFLECTOR BULB HOLDER	Dented	76.00 FS	*76.00 FS
37	1		*REAR BOOT INNER RUBBER (50%)	Distorted/Cut	92.00 FS	*46.00 FS
38	1		*REAR NUMBER PLATE	Dented	80.00 FS	*60.00 FS
39	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	11,107.05
						8,117.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	120.00	120.00
2	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
3	REMOVE & REFIX REAR BUMPER,BOOTLID & ATTACHMENTS,TAILLAMPS.TO CUT,WELD & RENEW REAR END PANEL,REAR RH FENDER,TAILLAMP PANEL,KNOCKING & REPAIR REAR SPARE TYRE PANEL,REAR RH WHEEL HOUSE,LH FENDER,REAR DOOR & REALIGN THE SAME	New	1,600.00	1,400.00
4	PUTTY & RESPRAY REAR BUMPER,REAR BOOT,BOTH FENDERS,REAR END PANEL,REAR SPARE TYRE PANEL,RH WHEELHOUSE & ALL AFFECTED AREAS	New	1,400.00	1,200.00
5	REMOVE & REFIX REAR SEAT,CARPET,ROOF LINING TO FACILITATE REPAIR	New	120.00	120.00
6	TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN CHASSIS	New	250.00	250.00
7	REMOVE & REFIX FUEL TANK ASSY TO FACILITATE REPAIR	New	100.00	80.00
8	RUSTPROOFING	New	90.00	90.00
Gross Labour Cost (S\$)			3,800.00	3,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >