



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Ms Siti Rosmawati Binte Mohamed
	Reg No/Reg Date	SLV9311K / 23/01/2018
	Date In/Mileage	11/10/2018/ 0
	Chassis No	MMBSTA13AJH000881
	Engine No	3A92UGN8819
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	P57 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	22/11/2018/ 08:05	DS	323 / ChrisBulaciac	11628

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 TO TRANSFER RHF & RHR DOOR COMPONENT AND MECHANISM PARTS				300.00
S MIPNT88088 TO REPLACE RHR DOOR PANEL,ETC -TO REPAIR ON RH SIDE CENTER PILLAR STRAIGHTEN,REFORM,ALIGN ON RH SIDE ACCIDENT AFFECTED AREAS				600.00
S MIPNT88088 TO APPLT SEALANT KIT ON NEW PANEL				100.00
S MIPNT98088 SPRAY PAINTING ON RH SIDE ACCIDENT AFFECTED AREAS				420.00
X JJ5730B792 RR DR,RH PANEL ASSY	1.00	791.00	0.00	791.00
X JJ7410A944XA TAPEL RR DOOR SASH	1.00	29.00	0.00	29.00
Z NOTES ACCIDENT ON 08/10/2018 ALONG CARPARK INFRONT OF TANJONG KATONG PRI OWNER CLAIMING THIRD PARTY LOSS OF USE 03DAYS x S\$80.00 = S\$240.00 TP # GV39R TP INS : CHINA TAIPING				

Confirm & accepted by

Parts	820.00
Labour	0.00
Standard Menu	0.00
Specialist Job	1,420.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	2,240.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.