



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Ms Siti Rosmawati Binte Mohamed
	Reg No/Reg Date	SLV9311K / 23/01/2018
	Date In/Mileage	11/10/2018/ 0
	Chassis No	MMBSTA13AJH000881
	Engine No	3A92UGN8819
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	P57 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000018	Credit	12/10/2018/ 19:17	DS	218 / MarsLer	11628				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
S	MIPNT88088								300 600.00
TO TRANSFER RHF & RHR DOOR COMPONENT AND MECHANISM PARTS								x 250.00	
S	MIPNT88088								x 1200.00
DIAGNOSTIC / SCANNING									
S	MIPNT88088								600 3000.00
TO REMOVE AND RE-INSTALL ROOF LINING & CAPERTING & SEAT									
TO GIVE WAY ACCESS REPAIR ON RH SIDE CENTER PILLAR (NETT)									
S	MIPNT88088								100 200.00
TO REPLACE RHF & RHR DOOR PANEL,ETC									
-TO REPAIR ON RH SIDE CENTER PILLAR									
STRAIGHTEN,REFORM,ALIGN ON RH SIDE ACCIDENT AFFECTED AREAS									
S	MIPNT88088								+ 600.00
TO APPLT SEALANT KIT ON NEW PANEL									
S	MIPNT88088								420 2520.00
TO REPLACE RH SIDE SEAT BELT									
S	MIPNT98088								
SPRAY PAINTING ON RH SIDE ACCIDENT AFFECTED AREAS									
M	JJ5700B682	FR DOOR,RH PANEL ASS	new	1.00	986.00	0.00	+ 986.00		
M	JJ7410A940XA	TAPE,FR DR SASH,RH	new	1.00	29.00	0.00	+ 29.00		
M	JJ5730B792	RR DR,RH PANEL ASSY	renewed	1.00	791.00	0.00	✓ 791.00		
M	JJ5702A161	HINGE,FR DOOR,UPR LH	new	1.00	54.00	0.00	+ 54.00		
M	JJ5732A110	RR DR,UPR RH HINGE	new	1.00	54.00	0.00	+ 54.00		
M	JJ5757A312	MOULDING, RR DOOR WI	new	1.00	66.00	0.00	+ 66.00		
M	JJ5755A280	WEATHERSTRIP,RR DR O	new	1.00	135.00	0.00	+ 135.00		
M	JJ5743A224	REGULATOR,RR DOOR WI	new	1.00	130.00	0.00	+ 130.00		
M	JJ5713A323	MOTOR,RR DOOR POWER	new	1.00	387.00	0.00	+ 387.00		
M	JJ5745A426	LATCH,RR DOOR,RH	new	1.00	318.00	0.00	+ 318.00		
M	JJ5732A101	CHECKER,RR DR	new	1.00	46.00	0.00	+ 46.00		
M	JJ7410A944XA	TAPE, RR DOOR SASH,	new	1.00	29.00	0.00	✓ 29.00		
M	JJ7000F740XA	SEAT BELT,FR SEAT PR		1.00	581.00	0.00	+ 581.00		
M	JJ7211A298HA	TRIM,CTR PILLAR,UPR		1.00	49.00	0.00	+ 49.00		
M	JJ7211A272XA	TRIM,CTR PILLAR,LWR		1.00	142.00	0.00	+ 142.00		
M	JJ7656A188XA	SCUFF PLATE,RR RH		1.00	50.00	0.00	+ 50.00		

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Ms Siti Rosmawati Binte Mohamed
	Reg No/Reg Date	SLV9311K / 23/01/2018
	Date In/Mileage	11/10/2018/ 0
	Chassis No	MMBSTA13AJH000881
	Engine No	3A92UGN8819
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	P57 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	12/10/2018/ 19:17	DS	218 / MarsLer	11628

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
<p>Z NOTES ACCIDENT ON 08/10/2018 ALONG CARPARK INFRONT OF TANJONG KATONG PRI OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # GV39R TP INS : CHINA TAIPING</p> <p style="text-align: center; font-size: 48px; opacity: 0.3;">Estimate</p> <p style="text-align: right; font-style: italic;">Addn liny. 9/12 22/10/18. 03 days</p>				

Confirm & accepted by

Parts	3,847.00
Labour	0.00
Standard Menu	0.00
Specialist Job	8,370.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	12,217.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.