

ASS. REC. BY:

REF:

CS/FWD18018636/G4b<sup>3</sup>

Special Instruction:

SURVIVOR

## ASSIGNMENT (Office)

From (Person):

Josey Loh

of

FWD

Date/Time:

15/10/2018 11:12am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA 470R

Insured:

at Workshop m/s

Trans Eurokars

Tel:

9127 7928

of

5 ubi close

Policy No:

Claim No:

1201800013089 / CL

Sum Insured:

Excess:

\$1000.00

Make of Veh:

D.O.A.

10.10.2018

(Client's Record)

CA / KEY / REP. / REV 24 HRS

16.10.2018 @ 1pm

H.O.D. Endorsement:

Date/Time:

15/10/2018 11:13am

Person Contacted:

Ronald

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKA 470R - CS3/FWD18018636 / Ucd3

DOF: 10/10/2018

17/10/18 @ 5:35pm revert to Josey Loh via Merimen.

18/10/18 @ 9:49am - authorise repair by Josey Loh

18/10/2018 @ 10:18am - email to Ronald authorise repair excess \$1000

Part by part \$11,1A.57 (Red: 3498.57; 23%)

Surveyor

XHL

REF: FWD

21851

# ASSIGNMENT

From: Date: 16/10/2018

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 9KA 470R

at Workshop m/s Trans Eurocars

of Subi Rose

Insured:

Policy No:

Claims No:

Sum Insured: Excess:


(Client's Record)

Make of Veh: Ronald

(Policy Condition)

1pm

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$81K

[81K noted by XHL]

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: 5KA 470R Yr Regn: 28 Sep 2016

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda CX-3 C.C. 1998

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 22527 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 215/50 R18

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

☒ TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at

Des. of Damages ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 16-10-18

1pm

Date / Time Action / Instruction

RECEIVED 21 DEC 2018

Date/Time, File Pass to?

21/12 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / (B): (\$ 11,117.58

☐ : Preli. Report  
☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS. 51

) Photos

) Others

TOTAL

250
50
30+50
10
410

## Catherine Chong (LKK Auto)

---

**From:** josey.loh@fwd.com  
**Sent:** Monday, 15 October, 2018 11:12 AM  
**To:** assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com  
**Cc:** motorclaims.sg@fwd.com; clara.li@fwd.com  
**Subject:** FW: ARRANGE FOR SURVEY-OD / YOUR REF: SKA470R (Our Ref: 1201800013089/CL)  
**Attachments:** 0337\_181015104413\_001.pdf

Hi LKK team,

Please refer to the email below and liaise with the repairer for OD survey arrangement. Policy excess \$1,000.00.

Attached is the repair estimate & OI GIA report.

Please create the case in Merimen and revert to us with your preliminary report.

Thank you.

Kind Regards

Josey Loh

Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E [josey.loh@fwd.com](mailto:josey.loh@fwd.com)

W [fwd.com.sg](http://fwd.com.sg)



**From:** ronald.yap@eurokars.com.sg [mailto:[ronald.yap@eurokars.com.sg](mailto:ronald.yap@eurokars.com.sg)]

**Sent:** Monday, 15 October, 2018 10:36 AM

**To:** Josey Loh Kah Wai - SGUser

**Cc:** jess.francis@eurokars.com.sg; samuel.ng@eurokars.com.sg

**Subject:** ARRANGE FOR SURVEY-OD / YOUR REF: SKA470R

Dear Josey,

Kindly assist us to arrange the survey of your client's car as attached.

Let us have your appointed surveyor please.

Thank You,

Ronald Yap  
Insurance Claims

**Trans Eurokars Pte Ltd**

5 Ubi Close, Singapore 408605  
T: 6395 8899 H: 9127 7928  
[ronald.yap@eurokars.com.sg](mailto:ronald.yap@eurokars.com.sg)

*This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Thursday, 18 October 2018 10:18 AM  
**To:** ronald.yap@eurokars.com.sg  
**Cc:** SUR  
**Subject:** SKA 470R / OD / FWD

Dear Ronald,

As instructed by our client, please proceed to repair the insured vehicle **SKA470R (Excess \$1000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Received Message

This mail is associated with :

**\*SKA470R (1201800013089)**

OD

Oct 10 2018 12:00AM

[VICTOR LOW SUE KHAI]

Trans Eurokars Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** FWD Singapore Pte. Ltd. (HQ) (FWD\_SG), sent on 18/10/2018 09:49 AM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$5757.53) - SKA470R - Claim Handler: Clara Li Zi Rong

Approved:5757.53.

### DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Clara Li Zi Rong

Date: 17 Oct 2018

**Preliminary Advice**

Vehicle No	: SKA470R	Accident Date	: 10/10/2018
Make	: MAZDA CX-3 SKYACTIV-G	Policy No.	: PNPV2018-00010248
Assignment Date	: 15/10/2018	Excess	: S\$1,000.00
Date of Inspection	: 16/10/2018	Est. Duration of Repair	: 4.00
Inspection At	: TRANS EUROKARS PTE LTD (HQ) 5 UBI CLOSE SINGAPORE 408605		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,600.90
Revised Amount	:S\$	5,102.33
Check Items (Estimated)	:S\$	655.20
Total	:S\$	5,757.53

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	65,672.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,328.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/10/2018 19:46
Date Of Accident	10/10/2018 07:30
Exact Location Of Accident	PIE TOWARDS CHANGI AT SIMEI EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA470R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	VICTOR LOW SUE KHAI
NRIC No	S7402185I
Email Address	VICLOW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98532274
Alternative Phone No	OFFICE-98532274

### Vehicle Particulars

Manufacturer	MAZDA
Model	CX-3 SKYACTIV-G
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00010248
Cover Note Number	

### Driver

Name of Driver	VICTOR LOW SUE KHAI
NRIC No	S7402185I
Date Of Birth	14/01/1974
Occupation	INDOOR
Date Of Driving Pass	08/04/1998
Driving Experience	20 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98532274
Fax Number	
Contact Number	OFFICE-98532274
Email Address	VICLOW@GMAIL.COM

Address	BLK 613 BEDOK RESERVOIR ROAD #08-1174
Postcode	470613
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS DRIVING ALONG PIE TOWARDS CHANGI. SUDDENLY TRAFFIC IN FRONT WAS JAM AND VEHICLE B IN FRONT OF ME MAKE A JAM BRAKE. I CAN'T STOP IN TIME AND COLLIDED ONTO REAR OF VEHICLE B . NO INJURIES INVOLVED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING VIDEO FROM INSURED
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMC586G
Vehicle Make/Model/Colour	TOYOTA/WISH 1.8XE A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SARAH WONG YEE LING
NRIC/Passport Number	S8200782B
Contact Number	97918155
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

# Sketch Plan

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 

I understand, acknowledge, agree and consent that:

  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS  
REPORTING OFFICER  
Jun Keat

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel

## Sketch Plan



Common Statement Pg. 1

ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG PIE TOWARDS CHANGI. SUDDENLY TRAFFIC IN FRONT WAS JAM AND VEHICLE B IN FRONT OF ME MAKE A JAM BRAKE. I CAN'T STOP IN TIME AND COLLIDED ONTO REAR OF VEHICLE B . NO INJURIES INVOLVED.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
WONG JUN KEAT

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

11 October 2018 at 5:33 PM

Date/Time:

11 October 2018 at 5:33 PM



## CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance  
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

**POLICY NUMBER:** PNPV2018-00010248 (Comprehensive - Executive Plan)

**Car plate number:** SKA470R

**Your name (As the policyholder):** Victor Low Sue Khai

**Coverage start date:** 28/09/2018

**Coverage end date:** 27/09/2019

**Covered geographical area:** Singapore, West Malaysia and Southern Thailand

**Who is insured to drive:**

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

**Important things to know:**

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

**Finance company:** Hong Leong Finance Limited

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

**Issued on:** 06/08/2018

**Abhishek Bhatia**  
Chief Executive Officer  
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888  
or email us at [contact.sg@fwd.com](mailto:contact.sg@fwd.com) if any details  
in this Certificate of Insurance need to be changed.



## YOUR EXECUTIVE CAR INSURANCE SUMMARY

Please call +65-6322-2072 for FWD Emergency Assistance  
if Your Car breaks down or is involved in an accident.  
All accidents must be reported within 24 hours or the next working day of the incident  
regardless of whether it will lead to a claim.

POLICY NUMBER : PNPV2018-00010248

### About this policy

Premium paid : S\$881.59 Coverage start date : 28/09/2018  
(Inclusive of GST) Coverage end date : 27/09/2019  
Who is insured to drive: : You and any Authorised Driver  
Policy Type : EXECUTIVE

### About you (As the policyholder)

Your name : Victor Low Sue Khai  
Address : 613 Bedok Reservoir Road #08-1174 Eunos Grove Singapore 470613  
Email : viclow@gmail.com  
NRIC/FIN : S7402185I Date of birth : 14/01/1974  
Marital status : Married Gender : Male  
Current no claims discount : 50% Mobile Number : 98532274  
Years of driving experience : Three or more Certificate of merit : Yes

### About your car

Car make and model : MAZDA CX-3 2.0  
Year of first registration : 2016  
Car plate number : SKA470R  
Issued on: : 06/08/2018

**Abhishek Bhatia**  
Chief Executive Officer  
FWD Singapore Pte Ltd

Please refer to contract for specific terms, conditions  
and exclusions of this policy.

Please immediately inform us at +65-6820-8888  
or email us to [contact.sg@fwd.com](mailto:contact.sg@fwd.com) if any details in  
this Car Insurance Summary need to be changed.

> Back to OneMotoring

D.O.A. 10/10/2018  
Bel: 7yrs 11:6mths

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2185I M.V. \$81,000
Vehicle Details	
Vehicle No.:	SKA470R
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Oct 2018
Vehicle Make:	MAZDA
Vehicle Model:	CX-3 SKYACTIV-G 2.0 6AT 2WD SR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	PE30965864
Chassis No.:	JM6DK2W7AH0125669
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$24,450.00
Original Registration Date:	28 Sep 2016
First Registration Date:	28 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$26,230.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2026
PARF Rebate Amount:	\$19,672.00 13,115
Intended COE Rebate Details	
COE Expiry Date:	27 Sep 2026 ✓
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,903.00
COE Rebate Amount:	\$46,000.00
<b>Total Rebate Amount:</b>	<b>\$65,672.00</b>

The information contained herein is correct as at 17 Oct 2018

OK



TRANS EUROKARS PTE LTD  
NO:5 UBI CLOSE, SINGAPORE 408605  
ESTIMATE COST OF REPAIRS



FWD Singapore Pte Ltd 6 Temasek Boulevard, #18-01 Suntec Tower 4, Singapore 038986 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Victor Low Sue Khai ADDRESS : Blk 613 Bedok Reservoir Road #08-1174 Singapore 470613 TEL : 98532274		WIP : 31679 EXCESS : DATE: 13-Oct-18	
VEH NO :	SKA470R	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6DK2W7AH0125669	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	CX3	DATE REG.:	28-Sep-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	FRONT BUMPER	1	MDD1G-50-031FBB		\$ 915.40
2	CHROME LHS	1	MD10J-50-7K0C		\$ 189.60
3	CHROME RHS	1	MD10J-50-7J0C		\$ 189.60
4	FOAM, FRONT REINFORCEMENT	1	MD10E-50-111		\$ 65.50
5	FASTENER, FOAM	2	MFD01-68-AC3		\$ 11.80
6	FRONT REINFORCEMENT	1	MD10E-50-070		\$ 440.50
7	PLATE SET, FRONT REINFORCEMENT	1	MD10J-50-1C0A		\$ 139.60
8	FASTENER, PLATE SET	5	MGD7A-50-EA1		\$ 15.00
9	FASTENER, FRONT BUMPER	5	MB45A-56-146A		\$ 14.00
10	RIVET, FRONT BUMPER	6	MTK21-50-355		\$ 52.20
11	RIVET, FRONT BUMPER	3	MS51S-51-833		\$ 11.40
12	RIVET, FRONT BUMPER	2	MB33J-51-833		\$ 14.40
13	CLIP, FRONT BUMPER	9	MC274-50-133		\$ 31.50
14	CLIP, FRONT BUMPER	2	MG51E-56-496A		\$ 19.40
15	MASCOT, FRONT	1	MD10J-51-730		\$ 58.50
16	BRACKET, FRONT GRILLE	1	MD10J-50-716B		\$ 55.60
17	FRONT GRILLE ASSY	1	MD10L-50-710J		\$ 883.10
18	FASTENER, FRONT GRILLE	5	MGD7A-50-EA1		\$ 15.00
19	PIN LOCATOR, FRONT GRILLE	2	MKD45-50-1K5A		\$ 5.40
20	GROMMET, FRONT GRILLE	2	MKD45-50-ES1		\$ 5.40
21	CLIP, FRONT GRILLE	2	MG46L-50-EB1		\$ 8.80
22	STAY LOCK	1	MD10E-52-15Y		\$ 38.50
23	BONNET	1	MDKY0-52-31XA		\$ 863.80
24	WEATHERSTRIP, BONNET	1	MD10E-56-770A		\$ 65.00
25	FASTENER, GARNISH FENDER	8	MKD53-51-W24		\$ 31.20
26	FASTENER, GARNISH FENDER	8	MKD51-51-W24		\$ 60.80
Grille Top - X			TOTAL PARTS		\$ 4,201.00
			LESS 10%		\$ 420.10
			TOTAL PARTS COST		\$ 3,780.90

Labour Description			
		1220	
1	MZ-BR-FRONT4	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND BONNET. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,980.00
2	MZ-SP-SFRT04	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT AND BONNET.	\$ 1,890.00
3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 250.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	\$ 100.00
		NETT	
		TOTAL LABOUR	\$ - \$ 4,820.00
		TOTAL PARTS	\$ - \$ 3,780.90
		TOTAL	\$ - \$ 8,600.90
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

**REMARKS:**

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

1461644

Authorised Signature

Quo Qiao - 82880282

4 Days.

before paint photos.

16/10/18.

18/10/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD  
NO:5 UBI CLOSE, SINGAPORE 408605  
SUPPLEMENTARY ESTIMATE COST OF REPAIR



FWD Singapore Pte Ltd 6 Temasek Boulevard, #18-01 Suntec Tower 4, Singapore 038986 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Victor Low Sue Khai ADDRESS : Blk 613 Bedok Reservoir Road #08-1174 Singapore 470613 TEL : 98532274		WIP : 31679 EXCESS : DATE: 12-Nov-18	
VEH NO :	SKA470R	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6DK2W7AH0125669	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	CX3	DATE REG.:	28-Sep-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	HEADLAMP RH	1	MDB3F-51-030E		\$ 3,338.50
2	HEADLAMP LH	1	MDB3F-51-040E		\$ 3,338.50
3	RIVET	2	MB092-51-833		\$ 6.60
TOTAL PARTS					\$ 6,683.60
LESS 10%					\$ 668.36
TOTAL PARTS COST					\$ 6,015.24
Labour Description					
1					
TOTAL LABOUR				\$ -	\$ -
TOTAL PARTS				\$ -	\$ 6,015.24
TOTAL				\$ -	\$ 6,015.24
LESS EXCESS				\$ -	\$ -
TOTAL AFTER EXCESS				\$ -	
GST 7%				\$ -	\$ -
GRAND TOTAL				\$ -	\$ -

REMARKS:  
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

\_\_\_\_\_  
Authorised Signature



**TRANS EUROKARS PTE LTD**  
**NO:5 UBI CLOSE, SINGAPORE 408605**  
**FINALISED COST OF REPAIRS**



<b>FWD Singapore Pte Ltd</b> 6 Temasek Boulevard, #18-01 Suntec Tower 4, Singapore 038986 <b>ATTN. :</b> MOTOR CLAIMS <b>FAX :</b>		<b>NAME :</b> Mr Victor Low Sue Khai <b>ADDRESS :</b> Blk 613 Bedok Reservoir Road #08-1174 Singapore 470613 <b>TEL :</b> 98532274		<b>WIP :</b> 31679 <b>EXCESS :</b> \$ 1,000.00 <b>DATE:</b> 13-Oct-18	
<b>VEH NO :</b>	<b>SKA470R</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	Ronald 63957875
<b>CHASSIS NO :</b>	JM6DK2W7AH0125669	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	OWN DAMAGED CLAIM
<b>MODEL :</b>	CX3	<b>DATE REG.:</b>	28-Sep-16	<b>POLICY NO. :</b>	
<b>NATURE OF WORKS</b>					
<b>Parts Description</b>					
NO	QTY		REVISED	PRICES	
1	1	MDD1G-50-031FBB	\$ 915.40	\$ 915.40	
2	1	MD10J-50-7K0C	\$ 189.60	\$ 189.60	
3	1	MD10J-50-7J0C	\$ 189.60	\$ 189.60	
4	1	MD10E-50-111		\$ 65.50	
5	2	MFD01-68-AC3		\$ 11.80	
6	1	MD10E-50-070		\$ 440.50	
7	1	MD10J-50-1C0A		\$ 139.60	
8	5	MGD7A-50-EA1		\$ 15.00	
9	5	MB45A-56-146A	\$ 14.00	\$ 14.00	
10	6	MTK21-50-355	\$ 52.20	\$ 52.20	
11	3	MS51S-51-833	\$ 11.40	\$ 11.40	
12	2	MB33J-51-833	\$ 14.40	\$ 14.40	
13	9	MC274-50-133	\$ 31.50	\$ 31.50	
14	2	MGS1E-56-496A	\$ 19.40	\$ 19.40	
15	1	MD10J-51-730	\$ 58.50	\$ 58.50	
16	1	MD10J-50-716B		\$ 55.60	
17	1	MD10L-50-710J	\$ 883.10	\$ 883.10	
18	5	MGD7A-50-EA1	\$ 15.00	\$ 15.00	
19	2	MKD45-50-1K5A	\$ 5.40	\$ 5.40	
20	2	MKD45-50-ES1	\$ 5.40	\$ 5.40	
21	2	MG46L-50-EB1	\$ 8.80	\$ 8.80	
22	1	MD10E-52-15Y		\$ 38.50	
23	1	MDKY0-52-31XA		\$ 863.80	
24	1	MD10E-56-770A		\$ 65.00	
25	8	MKD53-51-W24		\$ 31.20	
26	8	MKD51-51-W24		\$ 60.80	
<b>SUPPLEMENTARY ITEMS</b>					
1	1	MDB3F-51-030E	\$ 3,338.50	\$ 3,338.50	
2	1	MDB3F-51-040E	\$ 3,338.50	\$ 3,338.50	
3	2	MB092-51-833	\$ 6.60	\$ 6.60	

		<b>TOTAL PARTS</b>	\$ 9,097.30	\$ 10,884.60
		<b>LESS 10%</b>	\$ 909.73	\$ 1,088.46
		<b>TOTAL PARTS COST</b>	\$ 8,187.57	\$ 9,796.14
<b>Labour Description</b>				
1	MZ-BR-FRONT4	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND BONNET. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,320.00	\$ 1,980.00
2	MZ-SP-SFRT04	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT AND BONNET.	\$ 1,260.00	\$ 1,890.00
3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
<b>TOTAL LABOUR</b>			\$ 2,930.00	\$ 4,820.00
<b>TOTAL PARTS</b>			\$ 8,187.57	\$ 9,796.14
<b>TOTAL</b>			\$ 11,117.57	\$ 14,616.14
<b>LESS EXCESS</b>			\$ 1,000.00	\$ -
<b>TOTAL AFTER EXCESS</b>			\$ 10,117.57	
<b>GST 7%</b>			\$ 708.23	\$ -
<b>GRAND TOTAL</b>			\$ 10,825.80	\$ -

**REMARKS:**

**4 REPAIR DAYS** (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Oct 2018 <a href="#">Edit Reg</a>		15 Oct 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$11,117.57</b> <a href="#">Edit Estimates</a>	<b>S\$11,117.57</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	VICTOR LOW SUE KHAI, ID: S7402185I		
Vehicle Reg. No.:	SKA470R	Date of Loss:	10/10/2018 00:00 - :59 [24 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800013089	Policy/Cover Note No.:	PNPV2018-00010248 (Comprehensive)
		Excess:	S\$1,000.00
Repairer:	Trans Eurokars Pte Ltd (HQ) 5 Ubi Close, 408605 Ubi - Tel:		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 24/10/2018]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- FWD\_SG (30/11/2018): Alert - Adj Mandate Approved (S\$12441.13) - SKA470R - Claim Handler: Clara Li Zi...
- FWD\_SG (18/10/2018): Alert - Adj Mandate Approved (S\$5757.53) - SKA470R - Claim Handler: Clara Li Zi ...

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





## Claim Documents

**\*SKA470R (1201800013089)**  
**OD**  
**Oct 10 2018 12:00AM**  
**[VICTOR LOW SUE KHAI]**  
**Trans Eurokars Pte Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/10/18 17:34	<b>Adjuster Immediate Advice</b>	 Load HTM	<input checked="" type="checkbox"/>
2	30/11/18 10:16	<b>Adjuster Immediate Advice</b>	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	17/10/18 16:10	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	17/10/18 16:10	<b>Odometer Reading</b>	 Load JPG	<input checked="" type="checkbox"/>
21	17/10/18 16:10	<b>Chassis Number</b>	 Load JPG	<input checked="" type="checkbox"/>
22	30/11/18 10:17	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
23	30/11/18 10:17	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
24	30/11/18 10:17	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
25	30/11/18 10:17	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
26	30/11/18 10:17	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
27	30/11/18 10:17	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
28	30/11/18 10:17	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
29	30/11/18 10:17	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
30	30/11/18 10:17	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
31	30/11/18 10:17	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
32	30/11/18 10:17	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▾	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	30/11/18 10:17	Reinspection Photo	Load JPG	✓
34	30/11/18 10:17	Reinspection Photo	Load JPG	✓
35	21/12/18 09:55	Reinspection Photo	Load JPG	✓
36	21/12/18 09:55	Reinspection Photo	Load JPG	✓
37	21/12/18 09:55	Reinspection Photo	Load JPG	✓
Documentation			1 per page ▾	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/10/18 16:09	ESTIMATE	Load PDF	
2	30/11/18 10:14	SUPPLEMENTARY	Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	16/10/18 20:15	OI GIA Report	Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower 4  
Singapore 038986

Our File No: CS/FWD18018636/GTBS2

Date: 26/12/2018

## REFERENCE

Insured/Claimant: VICTOR LOW SUE KHAI Policy No: PNPV2018-00010248  
Date of Loss: 10/10/2018 Nature of Claim: OD Claim No: 1201800013089

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKA470R  
Make & Model: MAZDA CX-3 SKYACTIV-G, 2.0 6AT 2WD (A) Engine No: PE30965864  
Reg. Date: 28/09/2016 (Man. Year: 2016) Chassis No: JM6DK2W7AH0125669  
Colour: White Odometer: 22527 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: S\$85,000.00  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/50 R18 Rear Tyre Size: 215/50 R18  
Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm  
Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,896.14	8,207.57	1,688.57	17.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,720.00	2,910.00	1,810.00	38.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,616.14</b>	<b>11,117.57</b>	<b>3,498.57</b>	<b>23.94</b>
<b>- Excess (S\$)</b>	<b>1,000.00</b>	<b>1,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>13,616.14</b>	<b>10,117.57</b>	<b>3,498.57</b>	<b>25.69</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>953.13</b>	<b>708.23</b>	<b>244.90</b>	<b>25.69</b>
<b>Nett Amount (S\$)</b>	<b>14,569.27</b>	<b>10,825.80</b>	<b>3,743.47</b>	<b>25.69</b>

## INSPECTION

Date of Assignment: 15/10/2018  
Date Inspected: 16/10/2018 Inspected At: Trans Eurokars Pte Ltd (HQ)  
5 Ubi Close  
Singapore 408605  
Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 26 Dec 2018)
<b>Parts:</b>	M1-SUV	MAZDA CX-3 SKYACTIV-G 2.0 6AT 2WD (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKA470R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	915.40 FL	*915.40 FL
2	1		*CHROME LHS	Broken	189.60 FL	*189.60 FL
3	1		*CHROME RHS	Broken	189.60 FL	*189.60 FL
4	1		*FOAM, FRONT REINFORCEMENT	Not Necessary	65.50 FL	*- FL
5	2		*FASTENER, FOAM	Not Necessary	11.80 FL	*- FL
6	1		*FRONT REINFORCEMENT	Not Necessary	440.50 FL	*- FL
7	1		*PLATE SET, FRONT REINFORCEMENT	Not Necessary	139.60 FL	*- FL
8	5		*FASTENER, PLATE SET	Not Necessary	15.00 FL	*- FL
9	5		*FASTENER, FRONT BUMPER	Necessary	14.00 FL	*14.00 FL
10	6		*RIVET, FRONT BUMPER	Necessary	52.20 FL	*52.20 FL
11	3		*RIVET, FRONT BUMPER	Necessary	11.40 FL	*11.40 FL
12	2		*RIVET, FRONT BUMPER	Necessary	14.40 FL	*14.40 FL
13	9		*CLIP, FRONT BUMPER	Necessary	31.50 FL	*31.50 FL
14	2		*CLIP, FRONT BUMPER	Necessary	19.40 FL	*19.40 FL
15	1		*MASCOT, FRONT	Necessary	58.50 FL	*58.50 FL
16	1		*BRACKET, FRONT GRILLE	Not Necessary	55.60 FL	*- FL
17	1		*FRONT GRILLE ASSY	Broken	883.10 FL	*883.10 FL
18	5		*FASTENER, FRONT GRILLE	Necessary	15.00 FL	*15.00 FL
19	2		*PIN LOCATOR, FRONT GRILLE	Necessary	5.40 FL	*5.40 FL
20	2		*GROMMET, FRONT GRILLE	Necessary	5.40 FL	*5.40 FL
21	2		*CLIP, FRONT GRILLE	Necessary	8.80 FL	*8.80 FL
22	1		*STAY LOCK	Not Necessary	38.50 FL	*- FL
23	1		*BONNET	Repair	863.80 FL	*- FL
24	1		*WEATHERSTRIP, BONNET	Not Necessary	65.00 FL	*- FL
25	8		*FASTENER, GARNISH FENDER	Not Necessary	31.20 FL	*- FL
26	8		*FASTENER, GARNISH FENDER	Not Necessary	60.80 FL	*- FL
27	1		*GRILLE TOP (NPA)	Not Necessary	0.00 FL	*- FL
28	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
29	1		*HEADLAMP RH	Broken	3,338.50 FL	*3,338.50 FL
30	1		*HEADLAMP LH	Broken	3,338.50 FL	*3,338.50 FL
31	1		*RIVET	Necessary	6.60 FL	*6.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,984.60</b>	<b>9,117.30</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,088.46	909.73
<b>Total Parts (\$\$)</b>	<b>9,896.14</b>	<b>8,207.57</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND BONNET. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	New	1,980.00	1,320.00
2	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT AND BONNET.	New	1,890.00	1,260.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	New	250.00	0.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTION.	New	250.00	150.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	New	350.00	180.00
Gross Labour Cost (\$\$)			4,720.00	2,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >