

ASS. REC. BY:

REF: CS/CTI/8018641/R/sd307

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Catherine Chia

of

CTI

Date/Time:

12/10/18 @ 5:01pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8KP 8805 C

Insured:

SKK 1212 K

at Workshop m/s

vantage Automotive

Tel:

6477 7364

of

305 Alexandra Road

Policy No:

DMPCSN 30369 81503

Claim No:

8NM18D04687C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/09/2018

CA / REV / REP. / REV 24 HRS

Cup

Katherine

H.O.D. Endorsement:

Date/Time: 1013am @ 15/10/18

Person Contacted:

Kavitha

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction (✓) Estimate
	8KP 8805 C - X
	SKK 1212 K - CS/CTI/8017819/Gad3
11/01/19	checked with Katherine Chong (owner), owner withdrawn claim.

D.O.A: 27/09/2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **GO AHEAD LOYANG PTE LTD**,

ADDRESS

: 2 LOYANG WAY

GO AHEAD LOYANG DEPOT

PERSON TO CONTACT

: CLARISSA KOH @ 6387 7169 EXT 522

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.


Thank you.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SKP 8805 C**
 at Workshop m/s **VANTAGE AUTOMOTIVE**
 of **305, ALGAMARA ROAD**
 Insured: **CT**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition) **Karionta**

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SKP 8805 C** Yr Regn: **2014 / OCT**
 Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: **B.M.W 520i AT** c.c. **1997**
 Colour: **Black** A/C: Insured / Std / NI / NA
 Sp.Reading: **43802** T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: **WBA 5A320600334847**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **225/55 R17**
 R: **225/55 R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **CONTINENTAL**

Front: _____ Rear: _____
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. **27/09/18** D.O.I. **15/10/18**

Survey held at **VANTAGE**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 14 JAN 2019

Date/Time, File Pass to?

14/01/19

1) **Typ. ST**

Date/Time, File Return to?

2) **1**

☒ : Preli. Report
☐ : Final Report

Days Of Repair: **4**

Resurvey No. of Trip: **4**

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: **Preli**

Lump Sum / I.B.I: (\$ _____)

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Oct 2018		12 Oct 2018 17:01 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:		RICHARD WEE KENG KWOK, ID: S1650331B		[Created by insurer]	
Main Claimant:		SIME DARBY SERVICES, Co. Reg. No.: 19750106SW			
Vehicle Reg. No.:		SKP8805C	Date of Loss:	27/09/2018 16:00 - :59	
Claim Type:		TP / SNM18D04687C02	Policy/Cover Note No.:	DMPCSN3036981803 (Comprehensive)	
Vehicle Reg. No. (Insured):		SKK1212K	Policy No. (Claimant):	B29040568MCY	
			Excess:	S\$0.00	
Repairer:		Vantage Automotive Limited (Alexandra) 305 Alexandra Road #02-01, Vantage Automotive Centre, 159942 Alexandra - Tel:			
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]			
Claimant's Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888			
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/10/2018]			
Driver/Custodian (Insured):		MOHAMED KALID BIN MOHAMAD SAID (61 / Male), NRIC: S1252487J, Tel: +6597680143			
Adj Asg. Remarks:		EST \$12,523.87 , CASE WITH SJE.			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Katherine Chong <katherine.chong@simedarby.com.sg>
Sent: Friday, 11 January 2019 3:58 PM
To: Shirley Hiew (LKK Auto); Adam Ng Chun Wei
Cc: Admin A; Shu Pei (LKKAuto); Admin-D (LKKAuto); Liu Chun Cheong
Subject: RE: VANTAGE/ REQ FOR DIRECT SETTLEMENT - SKP8805C AND SKK1212K ON 27/09/2018 -TP CHINA

Hi Shirley,

I did check with the client and client mention cancel to make an accident claim.

Thank You.

Regards,
Katherine Chong
Senior Admin
Vantage Automotive Limited
305 Alexandra Road
#02-01 Vantage Automotive Limited
Singapore 159942
Email: katherine.chong@simedarby.com.sg
DID:+65 6477 7364

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, October 24, 2018 9:26 AM
To: Adam Ng Chun Wei
Cc: 甯琚 ©; Shu Pei (LKKAuto); Admin-D (LKKAuto); shabir.abdul.hamid@simedarby.com; sgchong.kean.yap@simedarby.com.sg; Natarajan Kavidha Rajan
Subject: RE: VANTAGE/ REQ FOR DIRECT SETTLEMENT - SKP8805C AND SKK1212K ON 27/09/2018 -TP CHINA

Dear Adam,

kindly check with claims officer Catherine Thia as email address :
catherine.thia@sg.cntaiping.com

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 23 October 2018 7:35 PM
To: Admin-D (LKKAuto)
Cc: Admin A
Subject: FW: VANTAGE/ REQ FOR DIRECT SETTLEMENT - SKP8805C AND SKK1212K ON 27/09/2018 -TP CHINA

CS/CTI18018641/R1sd3

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SDZ7499P

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Adam Ng Chun Wei <adam.ng.chunwei@sime-darby.com.sg>

Sent: Tuesday, 23 October 2018 8:44 AM

To: Admin A <admin-a@lkkauto.com>

Cc: Mohamed Shabir Abdul Hamid <shabir.abdul.hamid@sime-darby.com.sg>; Chong Kean Yap <chong.kean.yap@sime-darby.com.sg>; Natarajan Kavidha Rajan <natarajan.k.rajan@sime-darby.com.sg>

Subject: Re: VANTAGE/ REQ FOR DIRECT SETTLEMENT - SKP8805C AND SKK1212K ON 27/09/2018 -TP CHINA

Dear LKK Team,

Any updates on liability for this case?

Thank you

Regards,

Adam Ng

Customer Service Advisor

AutoFrance (**PEUGEOT**) / Regent Motors (**FORD**)

VANTAGE AUTOMOTIVE



IMPORTANT NOTICE

SKETCH PLAN.

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the judgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.
- Sketch Plan

Sketch Plan

1017
 A
 102 4247
 103 1612
 104 1711
 105 1711
 106 1711
 107 1711
 108 1711
 109 1711
 110 1711
 111 1711
 112 1711
 113 1711
 114 1711
 115 1711
 116 1711
 117 1711
 118 1711
 119 1711
 120 1711
 121 1711
 122 1711
 123 1711
 124 1711
 125 1711
 126 1711
 127 1711
 128 1711
 129 1711
 130 1711
 131 1711
 132 1711
 133 1711
 134 1711
 135 1711
 136 1711
 137 1711
 138 1711
 139 1711
 140 1711
 141 1711
 142 1711
 143 1711
 144 1711
 145 1711
 146 1711
 147 1711
 148 1711
 149 1711
 150 1711
 151 1711
 152 1711
 153 1711
 154 1711
 155 1711
 156 1711
 157 1711
 158 1711
 159 1711
 160 1711
 161 1711
 162 1711
 163 1711
 164 1711
 165 1711
 166 1711
 167 1711
 168 1711
 169 1711
 170 1711
 171 1711
 172 1711
 173 1711
 174 1711
 175 1711
 176 1711
 177 1711
 178 1711
 179 1711
 180 1711
 181 1711
 182 1711
 183 1711
 184 1711
 185 1711
 186 1711
 187 1711
 188 1711
 189 1711
 190 1711
 191 1711
 192 1711
 193 1711
 194 1711
 195 1711
 196 1711
 197 1711
 198 1711
 199 1711
 200 1711
 201 1711
 202 1711
 203 1711
 204 1711
 205 1711
 206 1711
 207 1711
 208 1711
 209 1711
 210 1711
 211 1711
 212 1711
 213 1711
 214 1711
 215 1711
 216 1711
 217 1711
 218 1711
 219 1711
 220 1711
 221 1711
 222 1711
 223 1711
 224 1711
 225 1711
 226 1711
 227 1711
 228 1711
 229 1711
 230 1711
 231 1711
 232 1711
 233 1711
 234 1711
 235 1711
 236 1711
 237 1711
 238 1711
 239 1711
 240 1711
 241 1711
 242 1711
 243 1711
 244 1711
 245 1711
 246 1711
 247 1711
 248 1711
 249 1711
 250 1711
 251 1711
 252 1711
 253 1711
 254 1711
 255 1711
 256 1711
 257 1711
 258 1711
 259 1711
 260 1711
 261 1711
 262 1711
 263 1711
 264 1711
 265 1711
 266 1711
 267 1711
 268 1711
 269 1711
 270 1711
 271 1711
 272 1711
 273 1711
 274 1711
 275 1711
 276 1711
 277 1711
 278 1711
 279 1711
 280 1711
 281 1711
 282 1711
 283 1711
 284 1711
 285 1711
 286 1711
 287 1711
 288 1711
 289 1711
 290 1711
 291 1711
 292 1711
 293 1711
 294 1711
 295 1711
 296 1711
 297 1711
 298 1711
 299 1711
 300 1711
 301 1711
 302 1711
 303 1711
 304 1711
 305 1711
 306 1711
 307 1711
 308 1711
 309 1711
 310 1711
 311 1711
 312 1711
 313 1711
 314 1711
 315 1711
 316 1711
 317 1711
 318 1711
 319 1711
 320 1711
 321 1711
 322 1711
 323 1711
 324 1711
 325 1711
 326 1711
 327 1711
 328 1711
 329 1711
 330 1711
 331 1711
 332 1711
 333 1711
 334 1711
 335 1711
 336 1711
 337 1711
 338 1711
 339 1711
 340 1711
 341 1711
 342 1711
 343 1711
 344 1711
 345 1711
 346 1711
 347 1711
 348 1711
 349 1711
 350 1711
 351 1711
 352 1711
 353 1711
 354 1711
 355 1711
 356 1711
 357 1711
 358 1711
 359 1711
 360 1711
 361 1711
 362 1711
 363 1711
 364 1711
 365 1711
 366 1711
 367 1711
 368 1711
 369 1711
 370 1711
 371 1711
 372 1711
 373 1711
 374 1711
 375 1711
 376 1711
 377 1711
 378 1711
 379 1711
 380 1711
 381 1711
 382 1711
 383 1711
 384 1711
 385 1711
 386 1711
 387 1711
 388 1711
 389 1711
 390 1711
 391 1711
 392 1711
 393 1711
 394 1711
 395 1711
 396 1711
 397 1711
 398 1711
 399 1711
 400 1711
 401 1711
 402 1711
 403 1711
 404 1711
 405 1711
 406 1711
 407 1711
 408 1711
 409 1711
 410 1711
 411 1711
 412 1711
 413 1711
 414 1711
 415 1711

Describe Circumstances of the Accident

On 3-1-2012, I was driving my car travelling P/E toward City to
St. Joseph's Institution. I
travelling at 1st lane, the front car SGQ 1678R suddenly
brake as I brake I applied emergency brake to avoid collision.
It was so sudden that it caused behind car STA 7641X
hit my car to collision to front car of the same lane.
The collision occurred about 50 m from the end of the
car. No injury occurred in the collision of the car & I was
involved.
All parties took particulars and left. Not as I have
to say.

Declaration

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time 11-22am

Driver's Signature (If driver is not the policyholder) / Date
& Time

Winged by Reporting Centre
Personnel

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/09/2018 12:26
Date Of Accident	27/09/2018 16:20
Exact Location Of Accident	OPHIR RD INTERSECTION WITH JALAN BESAR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP8805C
Insured/Policyholder	
Name Of Registered Owner	SIME DARBY SERVICES
Co Reg No	19750106SW 106SW
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64473388

Vehicle Particulars

Manufacturer	BMW
Model	520I-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	B29040568MCY
Cover Note Number	

Driver

Name of Driver	SEONGHO BAE
Passport No/FIN	N9632465
Date Of Birth	29/10/1984
Occupation	INDOOR
Date Of Driving Pass	14/09/2007
Driving Experience	11 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84547033
Fax Number	
Contact Number	
Email Address	BSH017@GMAIL.COM

Address	25 FLORENCE AVE. KEW, VICTORIA AUSTRALIA
Postcode	3101
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NO INFO GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING BMW SKP8805C AND CHANGING LANE WITH INDICATOR 'ON' AND HEAD CHECKED TO BE SURE SAFETY BEFORE I TURN STEERWHEEL. THERE WAS CLEAR AND NO ANY CARS THE LANE. WHEN MY CAR ALREADY INTO THE LANE, BLACK CAR AUDIO SKK1212K CUT IN FRONT OF MY CAR WITH VERY SPEEDY WITHOUT ANY INDICATOR SIGNAL ON. THERE HAS CONTACT MY CAR LET FRONT SIDE BUMPER BAR WITH AUDI RIGHT REAR DOOR. AUDI WAS BEHIND OF ME BEFORE I CHANGED LANE BUT IT CAME WITH HIGH SPEED AND CUT IN INFRONT OF MY LANE, MY BMW DAMAGED FRONT SIDE, AUDI DAMAGE SIDE REAR DOOR. IT WAS HAPPENED AT 04.20PM 27TH SEP 2018 INTERSECTION OPHIR RD AND JALAN BESAR. P.S AUDI HAS DASHCAM FRONT & REAR SO COULD REQUEST SOME FOOTAGE OF THE VIDEO.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKK1212K
Vehicle Make/Model/Colour	AUDI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

IMPORTANT NOTICE

SKETCH PLAN

1. Please report immediately the results of the accident to speed up the claims process.
2. The information provided must be as truthful and accurate as possible. Any or all misrepresentation is a violation of contract law and may allow the insurer to rescind the policy.
3. The name and occupation of the policy beneficiary is not an admission of policy liability on the part of the insured.

5. THE POLICY IS NOT TO BE USED AS EVIDENCE IN THE POLICY LITIGATION

6. The report is the first step in the process of the CNA Personal Injury Protection (PIP) benefit. The report is the first step in the process of the CNA Personal Injury Protection (PIP) benefit. The report is the first step in the process of the CNA Personal Injury Protection (PIP) benefit.
7. By the signature of the report to the insurer, you hereby consent to the making of the report and to copies of the report being made available to the insurer.

8. Coverage under the Personal Injury Protection Act (PIPA)

9. Coverage under the PIPA is provided to the insured and any other person who is injured in the accident and who is covered by the PIPA. Coverage under the PIPA is provided to the insured and any other person who is injured in the accident and who is covered by the PIPA.
10. Coverage under the PIPA is provided to the insured and any other person who is injured in the accident and who is covered by the PIPA. Coverage under the PIPA is provided to the insured and any other person who is injured in the accident and who is covered by the PIPA.


11. Coverage under the PIPA is provided to the insured and any other person who is injured in the accident and who is covered by the PIPA.

12. Coverage under the PIPA is provided to the insured and any other person who is injured in the accident and who is covered by the PIPA. Coverage under the PIPA is provided to the insured and any other person who is injured in the accident and who is covered by the PIPA.
13. Coverage under the PIPA is provided to the insured and any other person who is injured in the accident and who is covered by the PIPA. Coverage under the PIPA is provided to the insured and any other person who is injured in the accident and who is covered by the PIPA.
14. Coverage under the PIPA is provided to the insured and any other person who is injured in the accident and who is covered by the PIPA. Coverage under the PIPA is provided to the insured and any other person who is injured in the accident and who is covered by the PIPA.



Policyholder's Signature (Date & Time) 28/09/2018 SKRIPAK (KUPD)

Witnessed by Officer G. Omer SKRIPAK (KUPD)



Sketch Plan #2


Describe Circumstances of the Accident

Time Location Reg.

I was driving BMW (5K1212F5) and changing lane with indicator "on" and had checked to be sure safety before I turn the overpass. There were clear and no any cars the lane. When my car already into the lane, back colour Audi (5K1212F5) cut ~~into~~ in front of my car with very speed without any indicator sign on. There has contact my car left front side bumper has scratch Audi. Right rear door. Audi was behind of me before I changed lane but it came with high speed and cut in front of my lane therefore, my (BMW) damaged front side, Audi damaged side rear door.

It was happened at 4:20 pm 23th Sep 2018 Intersection Opht Rd and Jalan Besar.

PS AUDI has installed dashcam front & rear so could request some footage of the video.



Declaration

We declare the foregoing particulars are true to every respect.



Police Officer's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Officer Personnel

Driving License



Vantage Automotive Limited
305 Alexandra Road S'pore 159942

Date : 3.10.2018

RE: VEHICLE REPAIR QUOTATION

Insurance Company	:	China Taping Insurance (Singapore) Pte Ltd
Vehicle Reg No	:	SKP8805C
Name of Insured	:	Sime Darby Services Pte Ltd
Policy Number	:	B29040568MCY
Date of Accident	:	28/9/2018
Tyre of Claim	:	TP CLAIM
Model	:	BMW 520i
Chassis No	:	WBA5A32060D334847

We are please to submit our estimate of repairs to the above mention vehicle.

1	SUNDRIES	\$	150.00	20
2	LABOUR TO REMOVE,REALIGN AND REPLACE DAMAGE AREA, FRONT BUMPER, FRT LH FENDER	\$	1,200.00	450
3	TO PUTTY AND SPRAY PAINT FRONT BUMPER, FRONT LH WING AND ALL AFFECTED AREAS.	\$	900.00	600
4	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING	\$	150.00	20
5	TO REMOVE & REPLACE FRONT PARKING SENSOR & CONDUCT DISTANCE SETTING.	\$	150.00	X
6	TO RE-FOCUS HEADLAMP	\$	120.00	20
7	TUFF KOTE,ANTI RUST PRESERVATIONS,BODY CAVITY PRESERVATIONS.	\$	120.00	X
8	SEALANT FOR BODY PANELS.	\$	120.00	X
9	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE PROGRAMME MODULES.	\$	600.00	300

Total (Labour)	\$	4,890.00
Sub Total :	\$	11,681.17
GST 7%	\$	842.70
Grand Total :	\$	12,523.87

10301.17

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

ADAM NG (64777409)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resur
4p 9001w68
4 days
15/10/18 @ 1550
Resy after repair
16/10/18

Vantage Automotive Limited
305 Alexandra Road S'pore 159942

Date : 3.10.2018

RE: VEHICLE REPAIR QUOTATION

Insurance Company	:	China Taping Insurance (Singapore) Pte Ltd
Vehicle Reg No	:	SKP8805C
Name of Insured	:	Sime Darby Services Pte Ltd
Policy Number	:	B29040568MCY
Date of Accident	:	28/9/2018
Tyre of Claim	:	TP CLAIM
Model	:	BMW 520i
Chassis No	:	WBA5A32060D334847

We are please to submit our estimate of repairs to the above mention vehicle.

	Parts	Labour
1 Frt Bumper Primed (PDC)	1 \$ 1,277.55	repair
2 Frt Towing Lug Cover Primed	1 \$ 46.45	X
3 Set Mounting Bumper Front	1 \$ 33.85	?
4 Rivet	10 \$ 5.00	?
5 Bracket LH PDC	1 \$ 13.90	X
6 Bracket RH PDC	1 \$ 13.90	X
7 LH Fog Light LED	1 \$ 417.15	?
8 LH Headlight LED Technology	1 \$ 4,203.70	?
9 LH Grille Air Inlet Partly Closed	1 \$ 74.25	?
10 Frt LH Fender	1 \$ 863.35	repair
11 Frt LH Wheel Arch Cover	1 \$ 128.20	?
12 LH Cover Bottom	1 \$ 71.30	?

Sub Total Parts = \$7,148.60
Less 5% \$ (357.43)
Total Parts = \$6,791.17

...CLAIM SUBFOLDER...(Pending for Survey Report)



















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Oct 2018		12 Oct 2018 17:01 Edit Adj Rpt	S\$1,410.00 Edit Estimates	S\$1,410.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	RICHARD WEE KENG KWOK , ID: S1650331B								
Main Claimant:	SIME DARBY SERVICES , Co. Reg. No.: 19750106SW								
Vehicle Reg. No.:	SKP8805C	Date of Loss:	27/09/2018 16:00 - :59 [47 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04687C02	Policy/Cover Note No.:	DMPCSN3036981803 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKK1212K	Policy No. (Claimant):	B29040568MCY						
		Excess:	S\$0.00						
Repairer:	Vantage Automotive Limited (Alexandra) 305 Alexandra Road #02-01, Vantage Automotive Centre, 159942 Alexandra - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 23/10/2018]								
Driver/Custodian (Insured):	MOHAMED KALID BIN MOHAMAD SAID (61 / Male), NRIC: S1252487J, Tel: +6597680143								
Adj Asg. Remarks:	EST \$12,523.87 , CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















Claim Documents



*SKP8805C (SNM18D04687C02)
[SKK1212K]
TP
SIME DARBY SERVICES
Sep 27 2018 4:00PM
[RICHARD WEE KENG KWOK]
Vantage Automotive Limited

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Vantage Automotive Limited (Alexandra)					Thumbnail	Print	
1	28/09/18 12:51	Accident Statement					Load HTM		
2	01/10/18 15:11	Addendum Sheet					Load JPG	<input checked="" type="checkbox"/>	
3	01/10/18 15:17	Accident Statement Addm. #1					Load HTM		
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Vantage Automotive Limited (Alexandra)					Thumbnail	Print	
1	28/09/18 12:48	Driving License [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
2	01/10/18 15:15	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
3	01/10/18 15:15	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
4	01/10/18 15:15	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
5	01/10/18 15:15	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
6	01/10/18 15:15	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
7	01/10/18 15:15	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
8	01/10/18 15:15	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
9	01/10/18 15:15	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
10	01/10/18 15:15	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
11	01/10/18 15:15	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
12	01/10/18 15:15	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
13	01/10/18 15:15	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
14	01/10/18 15:15	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
15	01/10/18 15:15	Accident Photo [Linked Accident Report Documents]					Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	14/01/19 09:29	General View					Load JPG	<input checked="" type="checkbox"/>	
2	14/01/19 09:29	General View					Load JPG	<input checked="" type="checkbox"/>	
3	14/01/19 09:29	General View					Load JPG	<input checked="" type="checkbox"/>	
4	14/01/19 09:29	General View					Load JPG	<input checked="" type="checkbox"/>	
5	14/01/19 09:29	General View					Load JPG	<input checked="" type="checkbox"/>	
6	14/01/19 09:29	General View					Load JPG	<input checked="" type="checkbox"/>	
7	14/01/19 09:29	General View					Load JPG	<input checked="" type="checkbox"/>	
8	14/01/19 09:29	General View					Load JPG	<input checked="" type="checkbox"/>	
9	14/01/19 09:29	General View					Load JPG	<input checked="" type="checkbox"/>	
10	14/01/19 09:29	General View					Load JPG	<input checked="" type="checkbox"/>	
11	14/01/19 09:29	General View					Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Alexandra)	Thumbnail	Print
12	14/01/19 09:29	General View	 Load JPG	<input checked="" type="checkbox"/>
13	14/01/19 09:29	General View	 Load JPG	<input checked="" type="checkbox"/>
14	14/01/19 09:29	General View	 Load JPG	<input checked="" type="checkbox"/>
15	14/01/19 09:29	General View	 Load JPG	<input checked="" type="checkbox"/>
16	14/01/19 09:29	General View	 Load JPG	<input checked="" type="checkbox"/>
17	14/01/19 09:29	General View	 Load JPG	<input checked="" type="checkbox"/>
18	14/01/19 09:29	General View	 Load JPG	<input checked="" type="checkbox"/>
19	14/01/19 09:29	General View	 Load JPG	<input checked="" type="checkbox"/>
20	14/01/19 09:29	General View	 Load JPG	<input checked="" type="checkbox"/>
21	14/01/19 09:29	General View	 Load JPG	<input checked="" type="checkbox"/>
22	14/01/19 09:29	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
23	14/01/19 09:29	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/10/18 16:59	EMAIL FM VANTAGE	 Load PDF	
2	12/10/18 17:00	REPAIR EST	 Load PDF	
3	12/10/18 17:00	TP GIA	 Load PDF	
4	12/10/18 17:00	OI GIA	 Load PDF	
No	Finalized On	Vantage Automotive Limited (Alexandra)	Thumbnail	Print
1	28/09/18 12:47	Sketch Plan <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
2	28/09/18 12:47	Sketch Plan #2 <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Alexandra)	Thumbnail	Print
1	28/09/18 12:51	Accident Statement	 Load HTM	
2	01/10/18 15:11	Addendum Sheet	 Load JPG	<input checked="" type="checkbox"/>
3	01/10/18 15:17	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Alexandra)	Thumbnail	Print
1	28/09/18 12:48	Driving License	 Load JPG	<input checked="" type="checkbox"/>
2	01/10/18 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	01/10/18 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	01/10/18 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	01/10/18 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	01/10/18 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	01/10/18 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	01/10/18 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	01/10/18 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	01/10/18 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	01/10/18 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	01/10/18 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	01/10/18 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	01/10/18 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	01/10/18 15:15	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Alexandra)	Thumbnail	Print

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Vantage Automotive Limited (Alexandra)		Thumbnail	Print
1	28/09/18 12:47	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	28/09/18 12:47	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18018641/R1SD3E2

Date: 15/01/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3036981803
Claimant Vehicle No :	SKP8805C	Insured Vehicle No :	SKK1212K
Date of Loss:	27/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04687C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP8805C		
Make & Model:	BMW 520I, 2.0 (A)	Engine No:	B2060655N20B20B
Reg. Date:	17/10/2014 (Man. Year: 2013)	Chassis No:	WBA5A32060D334847
Colour:	Black	Odometer:	43802 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,941.17	20.00	6,921.17	99.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,360.00	1,390.00	1,970.00	58.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,301.17	1,410.00	8,891.17	86.31
+ GST 7.00/7.00% (S\$)	721.08	98.70	622.38	86.31
Nett Amount (S\$)	11,022.25	1,508.70	9,513.55	86.31

INSPECTION

Date of Assignment:	12/10/2018	
Date Inspected:	15/10/2018 Inspected At:	Vantage Automotive Limited (Alexandra) 305 Alexandra Road #02-01, Vantage Automotive Centre Singapore 159942
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$4686.78 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Jan 2019)
Parts: 143	BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKP8805C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*20.00 FS
2	1		*FRT BUMPER PRIMED (PDC)	Repair	1,277.55 FL	*- FL
3	1		*FRT TOWING LUG COVER PRIMED	Not Necessary	46.45 FL	*- FL
4	1		*SET MOUNTING BUMPER FRONT	* Check	33.85 FL	*- FL
5	10		*RIVET	* Check	5.00 FL	*- FL
6	1		*BRACKET LH PDC	Not Necessary	13.90 FL	*- FL
7	1		*BRACKET RH PDC	Not Necessary	13.90 FL	*- FL
8	1		*LH FOG LIGHT LED	* Check	417.15 FL	*- FL
9	1		*LH HEADLIGHT LED TECHNOLOGY	* Check	4,203.70 FL	*- FL
10	1		*LH GRILLE AIR INLET PARTLY CLOSED	* Check	74.25 FL	*- FL
11	1		*FRT LH FENDER	Repair	863.35 FL	*- FL
12	1		*FRT LH FENDER ARCH COVER	* Check	128.20 FL	*- FL
13	1		*LH COVER BOTTOM	* Check	71.30 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,298.60	20.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	357.43	0.00
Total Parts (\$\$)	6,941.17	20.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE, REALIGN AND REPLACE DAMAGE AREA, FRONT BUMPER, FRT LH FENDER	New	1,200.00	450.00
2	TO PUTTY AND SPRAY PAINT FRONT BUMPER, FRONT LH WING AND ALL AFFECTED AREAS	New	900.00	600.00
3	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING	New	150.00	20.00
4	TO REMOVE & REPLACE FRONT PARKING SENSOR & CONDUCT DISTANCE SETTING	New	150.00	0.00
5	TO RE-FOCUS HEADLAMP	New	120.00	20.00
6	TUFF KOTE, ANTI RUST PRESERVATIONS, BODY CAVITY PRESERVATIONS	New	120.00	0.00
7	SEALANT FOR BODY PANELS	New	120.00	0.00
8	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE PROGRAMME MODULES	New	600.00	300.00
Gross Labour Cost (S\$)			3,360.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

