

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG18018644/NCD3E2

**Date:** 12/03/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29013131MKC

**Claimant Vehicle No :** PC2284D

**Insured Vehicle No :** XB9069Z

Date of Loss: 08/10/2018

Nature of Claim: TP

Claim No: 572738

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC2284D**

Make & Model: GOLDEN DRAGON XML6103J98, 6.7 D (M)

Engine No: ISB67E530022051177

Reg. Date: 03/01/2014 (Man. Year: 2013)

Chassis No: LL3BGCDH1DA003603

Colour: White

Odometer: 276410 km

Engine Capacity: 6693 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 11 R22.5

Rear Tyre Size: 11 R22.5

Front Left Side: Double Coin 7 mm

Rear Left Side: Firemax 7 mm

Front Right Side: Double Coin 7 mm

Rear Right Side: Firemax 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,350.00	1,215.00	135.00	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	420.00	320.00	100.00	23.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,770.00</b>	<b>1,535.00</b>	<b>235.00</b>	<b>13.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
<b>(S\$)</b>	1,770.00	1,200.00	570.00	32.20
<b>+ GST 7.00/7.00% (S\$)</b>	123.90	84.00	39.90	32.20
<b>Nett Amount (S\$)</b>	<b>1,893.90</b>	<b>1,284.00</b>	<b>609.90</b>	<b>32.20</b>

### INSPECTION

Date of Assignment: 12/10/2018

Date Inspected: 15/10/2018 Inspected At:

Connect3 (woodlands) (HQ)

566 Woodlands Road

Singapore 728697

Estimated Period of Repair: 1.0 days

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 12 Mar 2019)	
<b>Parts:</b>	N/A	GOLDEN DRAGON XML6103J98 6.7 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PC2284D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH REAR VIEW MIRROR ASSY	Cracked	1,350.00 F	*1,350.00 FL
						F=Franchise part. L=ListItemDisc.
					<b>Sub Total (S\$)</b>	<b>1,350.00</b>
					<b>- List Item Discount on L Items 0.00/10.00% (S\$)</b>	<b>0.00</b>
					<b>Total Parts (S\$)</b>	<b>1,350.00</b>
						<b>1,215.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING	New	20.00	20.00
2	LABOUR CHARGES	New	200.00	150.00
3	SPRAY PAINTING	New	200.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>420.00</b>	<b>320.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >