

ASS. REC. BY:

REF: CS/EG118018649/Kltbnz

Special Instruction:

Survivor: Kalvin**ASSIGNMENT (Office)**From (Person): Yee Pei Li of EGL Date/Time: 15-10-2018 1:04pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 8420M Insured: G88 907JZat Workshop m/s Premier Tel: \_\_\_\_\_of 23 Changi South Ave 2 #01-02Policy No: \_\_\_\_\_ Claim No: G88907JZ/BL/p1

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 13-10-2018  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 15-10-2018 2:22pm Person Contacted: Gang Vehicle IN/OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	SHB 8420M - NBA /MSH16002822 /Y
	G88 907JZ - X
19/10@11:09am	Revised preli advise via email.

D.O.A. 03/02/2016

08/11/13

Surveyor: Kelvin

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHB 8420M Yr Regn: 27 Sep, 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Optima c.c. 1835

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 704358 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNAHMY44ME5446552

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/65R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 13/10/8 D.O.I. 15/10/8

Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/10/13 Check 4547150/542. (Red. 3764, 5406) E13°

4

RECEIVED 29 OCT 2013

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Report Format: TP

Lump Sum Fee: (\$ 3150)

250



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GBB9072Z/SL/pl  
Our Ref: CS/EG118018649/K1tb

Date: 19/10/2018

The Motor Claims Department  
ERGO INSURANCE PTE LTD

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. SHB 8420M.**

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 15/10/2018 at the premises of M/s Premier and have the following to report:

Workshop Estimate Amount	: S\$ 6,914.00
Revised Estimate Amount	: S\$ 3,932.90
"Check" Items Amount	: S\$ 891.90
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

**Description of Damage:**

The vehicle sustained damages  
at rear n/s portion.



Repair days: 4 Days

**Comments/ Present Status:**

Damages Consistent.

Yours faithfully  
Kalvin  
Automotive Assessor

## Nivitha (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Monday, 15 October 2018 1:04 PM  
**To:** 'admin-d@lkkauto.com'  
**Cc:** SUR (sur@lkkauto.com)  
**Subject:** OI : GBB9072Z / TP : SHB8420M/LKK / DOA : 13/10/2018  
**Attachments:** GBB9072Z - SAS.pdf; SHB8420M - PARTIAL SAS.pdf; SHB8420M - PRS FORM.pdf; Pre-inspection SHB8420M & GBB9072Z on 13.10.18 (1.31 MB)

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **PREMIER AUTOMOTIVE SERVICES PTE LTD.**

ADDRESS : 23 CHANGI SOUTH AVE 2  
#01-02  
SINGAPORE 486443

PERSON TO CONTACT : GOH WEE DEK @ 6544 6682 / 6214 8880 EXT 68

ERGO OFFICER-IN-CHARGE : STEVE LIM

***Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,  
Yee Pei Li  
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five  
Singapore 038985  
DID: +65 6829 9194  
Tel: +65 6829 9199  
Fax: +65 6829 9247

[www.ergo.com.sg](http://www.ergo.com.sg)

# ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

# ERGO

Date: 15.10.2018  
Our Reference: GBB 9072Z/SL/pl  
Your Reference: SHB 8420M

Sent via Fax

or

Email

weedek.goh@premiertaxi.com /  
gary.shi@premiertaxi.com /  
vincent.chua@premiertaxi.com

To: **PREMIER AUTOMOTIVE SERVICES PTE LTD**

### Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SHB 8420M  
Insured's Vehicle: GBB 9072Z  
Date Of Accident: 13.10.2018


We acknowledge receipt of your request for PRS on: 15.10.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

\* **LKK**

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us to date.
<input checked="" type="checkbox"/>	Others: <b>We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OFFICIER-IN-CHARGE - STEVE LIM</b>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

#### Assessor use only:

Assignment Date: \_\_\_\_\_  
Assignment Time: \_\_\_\_\_

Remarks:

#### Workshop use only:

##### Assessor attended workshop on:

Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Inspector: \_\_\_\_\_

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Friday, 19 October 2018 11:09 AM  
**To:** Admin-D (LKKAUTO); 'Survey Report (ERGO Insurance Pte. Ltd.)'  
**Cc:** SUR; assignments  
**Subject:** RE: GBB9072Z / TP : SHB8420M/LKK / DOA : 13/10/2018  
**Attachments:** PRELI ADVISED SHB 8420M.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHB 8420M**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Monday, 15 October 2018 2:22 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <[Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** RE: GBB9072Z / TP : SHB8420M/LKK / DOA : 13/10/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Monday, 15 October, 2018 1:04 PM  
**To:** 'admin-d@lkkauto.com' <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** SUR ([sur@lkkauto.com](mailto:sur@lkkauto.com)) <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** OI : GBB9072Z / TP : SHB8420M/LKK / DOA : 13/10/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **PREMIER AUTOMOTIVE SERVICES PTE LTD.**

ADDRESS : 23 CHANGI SOUTH AVE 2

## Enquire Transaction History

### Transaction History Details

Log Date/Time: 27 Sep 2013 / 09:12:07 Receipt No.: AACCK001-AX239-130927-000002

Asset Type: Vehicle Transaction Amount: \$70,976.00

Asset ID: SHB8420M Channel: AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type: 01.02 Register New Vehicle (AA)

Business Transaction Reference No.: 20130927091207354329

Vehicle No.: SHB8420M

Vehicle Type: H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1: Air-Con (Taxi)

Vehicle Attachment 2: -

Vehicle Attachment 3: -

Vehicle Scheme: Taxi (Company)

First Registration Date: 27 Sep 2013

Original Registration Date: 27 Sep 2013

Vehicle Make: KIA

Vehicle Model: OPTIMA 1.7(A) DIESEL

Chassis No.: KNAGM414ME5446552

Engine No.: D4FDDH308048

Motor No.: -

Trailer Chassis No.: -

Propellant: Diesel

Passenger Capacity: 4

Engine Capacity: 1685

Power Rating: -

Unladen Weight: 1584

Maximum Laden Weight: 2050

Primary Color: Silver

Secondary Color: -

Manufacturing Year: 2013

Open Market Value: \$20,137.00

Minimum PARF Benefit: \$7,615.00

PARF Eligibility: Y

No. of Transfer: 0

Effective Ownership Date/Time: 27 Sep 2013 09:12:07

COE No.: 2013092701000780E

COE Expiry Date: 26 Sep 2021

COE Bid Category: -

Actual QP/PQP Paid Amount: \$58,144.00

Lifespan Expiry Date: 26 Sep 2021

Owner ID Type: Company

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

15-Oct-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8420 M

1 pc	Rear n/s air vent <i>Xsu</i>	\$	30.00
1 pc	Rear n/s fender <i>Bumped Buc</i>	\$	1,205.00
1 pc	Rear n/s fender inner shield <i>Xsu</i>	\$	120.00
1 pc	Rear windscreen moulding <i>re</i>	\$	87.00
1 pc	Rear bumper <i>Rehnd</i>	\$	696.00
1 pc	Rear bumper sponge <i>Xsu</i>	\$	116.00
1 pc	Rear bumper reinforcement <i>Xsu</i>	\$	607.00
1 pc	Rear bumper lower cover <i>cm</i>	\$	206.00
1 pc	Rear bumper n/s stay <i>Xsu</i>	\$	53.00
1 pc	Rear bumper n/s reinforcement lower bracket <i>Xsu</i>	\$	18.00
1 pc	Rear bumper n/s reinforcement upper bracket <i>Xsu</i>	\$	18.00
1 pc	Rear bumper side bracket n/s <i>Xsu</i>	\$	29.00
1 pc	n/s tail lamp <i>re</i>	\$	421.00
1 pc	n/s tail lamp panel <i>X n/s</i>	\$	218.00
1 pc	n/s reflector <i>Xsu</i>	\$	350.00
1 pc	Rear bumper n/s reflector <i>cm</i>	\$	46.00
		\$	4,220.00
		Less 10%	\$ 422.00
			\$ 3,798.00

### S/NETT

1 set	Rear bumper clips <i>re</i>	\$	48.00
1 set	Rear fender n/s inner shield clips <i>X n/s</i>	\$	38.00
1 pc	Rear n/s fender sticker <i>re</i>	\$	60.00
1 pc	Sealant <i>re</i>	\$	50.00
1 set	Bootlid sticker <i>X n/s</i>	\$	100.00



15-Oct-18

**ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8420 M**

Towing Fee	\$ 50.00	X 21
Sundry	\$ 50.00	20 net
To dismantle and refit rear windscreen	\$ 120.00	100
To dismantle / refit reverse sensor to new bumper and reset to the same	\$ 120.00	20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00	50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the rear n/s fender, n/s tail lamp panel. Including knock-out, straighten, repair, reshape and adjust of the same	\$ 1,100.00	600
To putty and spray painting on rear bumper, rear n/s fender, rear n/s side panel, n/s tail lamp panel, bootlid	\$ 1,000.00	500
To apply rustproofing on the repaired and replaced panels.	\$ 200.00	50
	<u>\$ 6,914.00</u>	

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT  
INCLUDE ANY UNFORESEEN DAMAGES.**

Kelvin CLK

15/10/18 1600h

1+ 4 Pgs.

4s

After Repair photo

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18018649/K1tbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 02-11-2018		
		Code : EGI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBB 9072Z	Veh. Inspected	SHB 8420M	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBB9072Z/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	15/10/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	KNAGM414ME5446552	Colour	SILVER	
Odometer	704358	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	HANKOOK	7 mm	
L/H Front Tyre	205/65 R16	HANKOOK	7 mm	
R/H Rear Tyre	205/65 R16	HANKOOK	7 mm	
L/H Rear Tyre	205/65 R16	HANKOOK	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	13/10/2018	Inspection Date	15/10/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8420M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR N/S AIR VENT	SERVICEABLE	30.00	-
1	REAR N/S FENDER	BUCKLED	1,205.00	1,205.00
1	REAR N/S FENDER INNER SHIELD	SERVICEABLE	120.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	87.00	87.00
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER SPONGE	SERVICEABLE	116.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	607.00	-
1	REAR BUMPER LOWER COVER	CRACKED	206.00	206.00
1	REAR BUMPER N/S STAY	SERVICEABLE	53.00	-
1	REAR BUMPER N/S REINFORCEMENT LOWER BRACKET	SERVICEABLE	18.00	-
1	REAR BUMPER N/S REINFORCEMENT UPPER BRACKET	SERVICEABLE	18.00	-
1	REAR BUMPER SIDE BRACKET N/S	SERVICEABLE	29.00	-
1	N/S TAIL LAMP	CRACKED	421.00	421.00
1	N/S TAIL LAMP PANEL	TO REPAIR SEE LABOUR	218.00	-
1	N/S REFLECTOR	SERVICEABLE	350.00	-
1	REAR BUMPER N/S REFLECTOR	CRACKED	46.00	46.00
	LESS 10% DISCOUNT		-422.00	-266.10
			3,798.00	2,394.90
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REAR FENDER N/S INNER SHIELD CLIPS (SN)	NOT NECESSARY	38.00	-
1	REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SEALANT (SN)	NECESSARY	50.00	50.00
1	SET BOOTLID STICKER (SN)	NOT NECESSARY	100.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			346.00	178.00
<b>LABOUR</b>				
	TOWING FEE.	NOT NECESSARY	50.00	-
	TO DISMANTLE AND REFIT REAR WINDSCREEN.		120.00	100.00

Report Ref No. CS/EGI18018649/K1tbn2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE/REFIT REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	20.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD, CUT-OFF THE REAR N/S FENDER, N/S TAIL LAMP PANEL. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME.		1,100.00	600.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, REAR N/S FENDER, REAR N/S SIDE PANEL, N/S TAIL LAMP PANEL, BOOTLID.		1,000.00	540.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		200.00	50.00
			2,770.00	1,360.00
<b>GRAND TOTAL</b>			<b>6,914.00</b>	<b>3,932.90</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,150.00</b>

Report Ref No. CS/EGI18018649/K1tbn2

**KALVIN ANG WEI KUN**

Automotive Assessor / Investigator

**ADRIAN LING WAI PING**

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.