

17 May

Point-of-Sale Transaction
RACE WERKS PTE LTD

675.00

Final Details for Order #111-0226323-7444221Print this page for your records.**Order Placed:** May 1, 2018**Amazon.com order number:** 111-0226323-7444221**Order Total: \$40.53****Shipped on May 2, 2018****Items Ordered**1 of: *AHL Starter Clutch One Way Bearing for Ducati Monster 620 695 696 750 800*Sold by: Tong Tong Trade Co.,Ltd ([seller profile](#))

Condition: New

Price

\$32.65

Shipping Address:

Abdul Wali Khan
210 Jalan Eunus, EuHabitat Condo,
Block 19, unit 01-68
Singapore, Singapore 419549
Singapore

Item(s) Subtotal: \$32.65
Shipping & Handling: \$7.88

Total before tax: \$40.53
Sales Tax: \$0.00

Total for This Shipment: \$40.53
-----**Shipping Speed:**

Standard Shipping

Payment information**Payment Method:**

Visa | Last digits: 9762

Item(s) Subtotal: \$32.65
Shipping & Handling: \$7.88

Total before tax: \$40.53
Estimated tax to be collected: \$0.00

Grand Total: \$40.53

SGD \$55.77

Billing address

Abdul Wali Khan
210 Jalan Eunus, EuHabitat Condo,
Block 19, unit 01-68
Singapore, Singapore 419549
Singapore

Credit Card transactions

Visa ending in 9762: May 2, 2018: \$40.53

To view the status of your order, return to [Order Summary](#).



Final Details for Order #111-1583303-7101854

Print this page for your records.

Order Placed: May 22, 2018

Amazon.com order number: 111-1583303-7101854

Order Total: \$227.32

Shipped on May 22, 2018

Items Ordered

1 of: *Barnett Performance Products Clutch Plate Kit 306-25-40002*

Sold by: MotoMummy ([seller profile](#))

Condition: New

Price

\$215.15

Shipping Address:

Abdul Wali Khan
210 Jalan Eunus, EuHabitat Condo,
Block 19, unit 01-68
Singapore, Singapore 419549
Singapore

Item(s) Subtotal: \$215.15

Shipping & Handling: \$12.17

Total before tax: \$227.32

Sales Tax: \$0.00

Total for This Shipment: \$227.32

Shipping Speed:

AmazonGlobal Expedited Shipping

Payment information

Payment Method:

Visa | Last digits: 9762

Item(s) Subtotal: \$215.15

Shipping & Handling: \$12.17

Total before tax: \$227.32

Estimated tax to be collected: \$0.00

Grand Total: \$227.32

SD \$313.55

Billing address

Abdul Wali Khan
210 Jalan Eunus, EuHabitat Condo,
Block 19, unit 01-68
Singapore, Singapore 419549
Singapore

Credit Card transactions

Visa ending in 9762: May 22, 2018: \$227.32

To view the status of your order, return to [Order Summary](#).

SBR TRACKDAYS

Company Reg. No 35203868E
8 Kaki Bukit Avenue 4
#08-15, Premier@Kaki Bukit
Singapore 415875
Tel 63841707

INVOICE

SBRT00211

Date 14-06-2018
Terms CASH
Sales Rep :

Bill To
WALI - DUCATI MONSTER S4 - F8C8574T

Tel H/P No. : 92322044

S/No	Product Code	Description	Quantity	Price	Discount	Amount
		USED CLUTCH PUMP/HOLDER	1 SET	190.00		190.00
	55240201A	CRANK POSITION SENSOR	1 PCS	270.00		270.00
		LABOUR CHARGE - DISMANTLE/ASSEMBLE CLUTCH - CLUTCH BLEEDING/FLUID - FUEL TANK CLEANING - INJECTOR CLEANING - VACUM PUMP O RING - DIAGNOSE CHECK	1	450.00		450.00

Remarks :

SGD	TOTAL	\$	910.00
-----	-------	----	--------

Nine Hundred and Ten only

SBR TRACKDAYS

Customer Chop and Signature

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543

INVOICE

Abdul Wali Khan
23 St. Thomas Walk
#08-01 Sam Kiang Mansion
Singapore 235108

Invoice no:	POS0401/18
Date:	29 November 2018
Report no:	401M1018.SBR
Vehicle :	FT4448P

No	Item Description	Qty	Unit Price	Total Amount
1	Being charges for the inspection of the accident vehicle, transport and photographs.			700.00
SGD(\$): Seven hundred only			Grand Total:	700.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES



Authorised signature

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 401M1018.SBR
Vehicle no : FT4448P

1 REFERENCE

Date of inspection : 13 October 2018
Requested by : Abdul Wali Khan
23 St. Thomas Walk
#08-01 Sam Kiang Mansion
Singapore 235108
Type of survey : Independent
Repairer : SBR Motors Pte Ltd
8 kaki Bukit Avenue 4, #08-15 Premier@Kaki Bukit, Singapore 515875
Date of accident : 18 July 2018

2 VEHICLE DATA

Make/model : Ducati Monster S4
Chassis no : ZDMM400AAYB000336
Engine no : ZDM916W4D000220
Date of registration : 17 May 2001 *Coe Expiry Date: 16 May 2021*
Engine capacity : 916 cc
Colour : Red
Odometer reading : meter damaged

3 STATIC CONDITION CHECK

Steering : Affected
Foot brakes : Serviceable
Hand brakes : affected
Paintwork : Fair
General Condition : Bad

4 TIRE CONDITION CHECK MM/MAKE

	<u>MM/MAKE</u>	<u>SIZE</u>
Front tread	: 5 mm/Pirelli	120/70ZR17
Rear tread	: 5 mm/Pirelli	185/55ZR17

5 BRIEF DESCRIPTION OF DAMAGE

Main chassis frame flattened and bent, headlamp broken, meter broken, RH mirror broken, front fender broken, fuel tank dented/scraped, front forks bent/cut, LH front brake disc bent, ERP borken, radiator broken, radiator fan borken, exhaust muffler dislodged/missing, seat cushion torn, rear LH side board scraped, LH & RH pillion footrest brackets broken, LH & RH pillion footrests missing, LH front signal light broken, LH handle bar broken, front wheel rim dented/fractured, LH handle switch broken, LH mirror missing, LH front footrest bracket broken, LH front footrest missing, gear pedal missing, frame slider abraded, RH front footrest missing, etc. Please see photographs attached for more details.

Report no : 227M0618.DW
Vehicle no : FA555P

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and we have not authorized any repairs. This inspection does not account for the damaged parts/items that were damaged in the accident but were hidden from view and need dismantling to verify their conditions.

The vehicle met with an accident on 18 July 2018 and was badly damaged in the process. Apart from the damage to the body panels, lightings and mechanical components. The main chassis was damaged at the left front side of the vehicle: flattened and bent.

This damaged chassis cannot be structurally repaired to a roadworthy condition as it is unsafe to cold work the frame back to its original strength and integrity. Moreover, the damaged chassis frame cannot be replaced as this is prohibited by the Land Transport Authority. For these reasons, I am of the opinion that the damaged vehicle would have to be declared as a Total Loss.

At the time of the accident, the vehicle was about more than 17 years 2 months old. Hence, effectively the vehicle had about less than 2 years 10 months of statutory life remained.

The workshop: SBR Motors Pte Ltd which deals with high performance bikes had quoted the pre-accident market value of about \$8,000.00 for the vehicle.

We had attempted to obtain a reference pre-accident market value for the vehicle through the internet and print media but to no avail.

Therefore, in the absence of a comparable market value for the vehicle, we believe the quoted pre-accident market value \$8,000.00 is fair and reasonable and it would reflect the existing selling price of a similar make/model and year of vehicle.

The total rebate upon scrapping the vehicle on 13 October 2018 would be about \$1,067.00 (see attachment).

7 RECOMMENDATION

The vehicle is recommended to be treated as a Total Loss due to the damaged main chassis.

The pre-accident market value of the vehicle is estimated be about \$8,000.00 at the time of the accident.

Therefore, the claimable amount for the TOTAL LOSS of the vehicle would be about \$6,933.00.

Yours faithfully


.....
Liaw Leong San
Licensed Automotive Appraiser

Report dated : 29 November 2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type

Singapore NRIC

Owner ID

7800I

Vehicle Details

Vehicle No.

FT4448P

Vehicle to be Exported

Yes

Intended Deregistration Date

13 Oct 2018

Vehicle Make

DUCATI

Vehicle Model

MONSTER S4

Primary Colour

Red

Manufacturing Year

2000

Engine No.

ZDM916W4D000220

Chassis No.

ZDMM400AAYB000336

Maximum Power Output

-

Open Market Value

\$13,185.00

Original Registration Date

17 May 2001

First Registration Date

17 May 2001

Transfer Count

7

Actual ARF Paid

\$1,978.00

Intended PARF Rebate Details

PARF Eligibility

No

PARF Eligibility Expiry Date

-

PARF Rebate Amount

\$0.00

Intended COE Rebate Details

COE Expiry Date

16 May 2021

COE Category

D - Motorcycle

COE Period(Years)

10

PQP Paid

\$2,325.00

COE Rebate Amount

\$1,067.00

Total Rebate Amount

\$1,067.00

09 Nov 2018

TOWING FEE

As at 09 Nov 2018, 12:31 AM


09 Nov 2018

TRF 128-30625-0 : I-BANK
ADV

S\$ -80.00


Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR
Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P




Report no: 401M1018.SBR

Vehicle no: FT4448P




Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR


Vehicle no: FT4448P





Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR
Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR
Vehicle no: FT4448P




Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P



Report no: 401M1018.SBR

Vehicle no: FT4448P

