

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 526Z

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

PART

1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT LH
1	BUMPER SUPPORT FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE LH
1	BUMPER BEAM FRT
1	HEADLAMP LH
1	HEADLAMP PANEL FRT LH
1	FENDER PANEL FRT LH
1	WHEELARCH FRT LH
1	FENDER BRACKET LOWER LH
1	FENDER INSULATOR LH
1	DOOR PANEL FRT LH
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	RADIATOR FAN COWLING
1	RADIATOR FAN MOTOR LH
1	RADIATOR FAN MOTOR RH
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	AIR CLEANER BOX
1	AIR CLEANER HOSE

0.0

810-147

1,184.43 +
1,941.53 =
3,125.96 *

3,125.96 x
90.0%
2,813.364 *

0.0

200.0 +
220.0 +
30.0 +
20.0 +
= 470.0

2,813.36 +
470.0 =
3,283.36 *

452 \$ 2,650

3,283.36 x
80.0%
2,626.688 *

SL 260.80

SL 207.21

N 914.08

GR 1,184.43

N 152.15

N 783.83

SL 278.84

SL 15.79

SL 130.84

N 2,844.66

SL 1,707.78

SL 225.36

SL 1,353.75

SL 820.54

SL 967.36

SL 1,479.46

SL 1,353.75

N 615.90

N 89.79

SL 464.20

SL 175.85