

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 526Z**AAD1810-147***Not Authorised*
LI Sing B

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 526Z

VF1ABL15AUC278274

RENAULT

LATITUDE

11.10.2018

CHINA TAIPING**PART****LIST**

1	BUMPER COVER FRT	\$	S ₂	1,259.42	} X
1	BUMPER SPOILER FRT	\$	S ₂	181.75	
1	BUMPER ABSORBER FRT	\$	S ₂	394.68	
1	BUMPER RETAINER FRT LH	\$	S ₂	151.41	
1	BUMPER SUPPORT FRT	\$	S ₂	123.88	
1	BUMPER RETAINER FRT RH	\$	S ₂	150.77	
1	BUMPER SUPPORT FRT	\$	S ₂	123.88	
1	BUMPER UNDERTRAY FRT	\$	S ₂	472.83	
1	BUMPER GRILLE LOWER FRT	\$	S ₂	266.80	
1	BUMPER FOG LAMP GRILLE LH	\$	S ₂	207.21	
1	BUMPER BEAM FRT	\$	N	914.08	} X
1	HEADLAMP LH	\$	Gr	1,184.43	
1	HEADLAMP PANEL FRT LH	\$	N	152.15	
1	FENDER PANEL FRT LH	\$	N	783.83	
1	WHEELARCH FRT LH	\$	S ₂	278.84	
1	FENDER BRACKET LOWER LH	\$	S ₂	15.79	
1	FENDER INSULATOR LH	\$	S ₂	130.84	
1	DOOR PANEL FRT LH	\$	N	2,844.66	
1	RADIATOR GRILLE	\$	S ₂	1,707.78	
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	S ₂	225.36	
1	RADIATOR GRILLE FRAME	\$	S ₂	1,353.75	} X
1	RADIATOR FAN COWLING	\$	S ₂	820.54	
1	RADIATOR FAN MOTOR LH	\$	S ₂	967.36	
1	RADIATOR FAN MOTOR RH	\$	S ₂	1,479.46	
1	RADIATOR GRILLE FRAME	\$	S ₂	1,353.75	
1	FRAME FULL SUPPORT PANEL	\$	N	615.90	
1	FRAME FULL SUPPORT BRACKET	\$	N	89.79	
1	AIR CLEANER BOX	\$	S ₂	464.20	
1	AIR CLEANER HOSE	\$	S ₂	175.85	

Trans-cab Auto Services Pte Ltd

AAD1810-147

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 526Z

1	LOWER ARM LH L70Y	\$	685.76 X
1	KUNCKLE ARM LH L70Y	\$	846.98 X
1	ABSORBER FRT LH L70Y	\$	360.54 X

177 Bonnet BT ✓

TOTAL	\$	20,784.28
10%	\$	2,078.43
	\$	18,705.85

Special Nett

1SET	BUMPER CLIP FRT	\$	66.00	} X
1	BUMPER BRACKET CLIP FRT LH	\$	12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	
1SET	WHEELARCH CLIP FRT RH	\$	30.50	
1	FRONT LEFT TYRE	\$	300.00	
1	FRONT LEFT TYRE RIM	\$	380.00	
		\$	988.00	

TOTAL PARTS	\$	19,693.85
--------------------	----	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 3,500.00 200

Putty and spray painting of the affected portion.

\$ 3,000.00 220

To rust-proofing of the affected areas.

\$ 170.00 30

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1810-147**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 526Z

To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>2d</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	<i>na</i> 380.00	X
To replace, refix and top up coolant for radiator	\$	<i>na</i> 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>na</i> 170.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	X

TOTAL \$ 9,090.00**Over All Total \$ 28,783.85****LUMP SUM (REPAIR DAY)****10 DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: