

ASS. PEC. BY:

REF:

CS/EG218018659 / Uvb024

Special Instruction:

Surveyor

ASSIGNMENT (Office)From (Person): Yee Pei Li of EG21 Date/Time: 15-10-2018 3:07pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLH 7639C Insured: SGN 1019Sat Workshop m/s: Trans Eurokars Tel: 9127 7978of 5 Ubi ClosePolicy No: _____ Claim No: SGN1019S/SA/pl

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12/10/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

18.10.2018 @ 1.30pm

H.O.D. Endorsement:

Date/Time: 15-10-2018 3:13pm Person Contacted: Ronald Vehicle IN/OUT: OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLH 7639C - X</u>
	<u>SGN 1019S - X</u>
<u>19/10/18</u>	<u>Email preli revised to Pei Li</u>

REF: EGI

ASSIGNMENT

From: Date: 18/10/18

Estimated Cost:

OD/TP WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLH 7639C

at Workshop m/s Trans Eurokars
of 5 ubi close

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 1:30pm
Ronald

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 1.3% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Date: Vehicle: IN / OUT

Person Contacted:

Veh No: SLH 7639C Yr Regn: 1/1/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: mazda 3 c.c 1496

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 37451 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM6BM42A8A0346458

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 205/60R16

R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 7 mm Rear 7 mm

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 12/10/18 D.O.I. 18/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/12/18 21A 54691 Confirmed final by 6018-83 with letter. (Recd 9050.26, 6090)

RECEIVED 10 DEC 2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 7/12 - typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation: \$ + RS \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format: TP

Lump Sum / I.B.I. (\$) 6018-83

350



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE L #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SGV1019S/SA/pl
Our Ref: CS/EG118018659/Uvb

Date: 19/10/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SLH 7639C


We thank you for your instruction on 15/10/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/10/2018 at the premises of M/s TRANS EUROKARS PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$15,069.09
Revised Estimate Amount	: S\$5,468.21
"Check" Items Amount	: S\$5,197.99
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 15 October, 2018 3:07 PM
To: 'admin-d@lkkauto.com'
Subject: OI : SGV1019S / TP : SLH7639C/LKK / DOA : 12/10/2018
Attachments: SGV1019S - SAS.pdf; SLH7639C - SAS.pdf; SLH7639C - ESTIMATE.pdf; SLH7639C - PRS FORM.pdf; RE: ARRANGE FOR SURVEY-TP / YOUR REF: SGV1019S / OUR REF: SLH7639C (21.2 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **TRANS EUROKARS PTE LTD**,

ADDRESS : 5 UBI CLOSE
SINGAPORE 408605

PERSON TO CONTACT : RONALD YAP @ 6395 8899 / 9127 7928

ERGO OFFICER-IN-CHARGE : SITI

Note: To survey on DIRECT SETTLEMENT basis. Please inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured & Third Parties SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
Tel: +65 6829 9199
Fax: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 15.10.2018
Our Reference: SGV 1019S/SA/pl
Your Reference: SLH 7639C

Sent via Fax

or

Email

ronald.yap@eurokars.com.sg

To: TRANS EUROKARS PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLH 7639C
Insured's Vehicle: SGV 1019S
Date Of Accident: 12.10.2018

We acknowledge receipt of your request for PRS on: 15.10.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

☐	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐	Our Insured's driver has not reported the accident to us to date.
☒	Others: <u>We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OFFICER-IN-CHARGE - SIT1</u>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 19 October 2018 2:22 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: SGV1019S / TP : SLH7639C/LKK / DOA : 12/10/2018
Attachments: SLH 7639C PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SLH 7639C
Date of survey: 18/10/2018
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 15 October 2018 3:13 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: SGV1019S / TP : SLH7639C/LKK / DOA : 12/10/2018

Dear Pei Li,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Monday, 15 October, 2018 3:07 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : SGV1019S / TP : SLH7639C/LKK / DOA : 12/10/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **TRANS EUROKARS PTE LTD,**

ADDRESS : 5 UBI CLOSE
SINGAPORE 408605

PERSON TO CONTACT : RONALD YAP @ 6395 8899 / 9127 7928

ERGO OFFICER-IN-CHARGE : SITI

Note: To survey on DIRECT SETTLEMENT basis. Please inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured & Third Parties SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel. : +65 6829 9199
Fax : +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 8955B

Vehicle Details

Vehicle No.: SLH7639C

Vehicle to be Exported: No

Intended Deregistration Date: 18 Oct 2018

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Primary Colour: Red

Manufacturing Year: 2016

Engine No.: P520375358

Chassis No.: JM6BM42A8G0346458

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$20,847.00

Original Registration Date: 17 Nov 2016

First Registration Date: 17 Nov 2016

Transfer Count: 0

Actual ARF Paid: \$16,186.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 16 Nov 2026

PARF Rebate Amount: \$12,139.00

Intended COE Rebate Details

COE Expiry Date: 16 Nov 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$52,668.00

COE Rebate Amount: \$42,552.00

Total Rebate Amount: \$54,691.00

The information contained herein is correct as at 18 Oct 2018

OK



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

not authorised 18/10/18
Wahyuh before peng.
5' dry.

ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Teo Chek Wei ADDRESS : Blk 5 Lorong Lew Lian #10-108 Singapore 530005 TEL : 83220244		WIP : 31633 EXCESS : DATE: 13-Oct-18	
VEH NO :	SLH7639C	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6BM42A8G0346458	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	17-Nov-16	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	FRONT BUMPER MBHR3-50-031BBB	20.0	\$ 1,031.70
2	1	RETAINER RHS MBHN1-50-0T1F	5.0	\$ 18.70
3	1	COVER RHS, FRONT BUMPER MBHN1-50-101	4.0	\$ 28.00
4	1	CHROME RHS, FOGLAMP MBE1-50-C12	4.0	\$ 106.70
5	1	COVER RHS, FOGLAMP MBE1-50-C11A	4.0	\$ 46.40
6	1	FRONT REINFORCEMENT MB45A-50-070A	4.0	\$ 444.50
7	12	CLIP, FRONT BUMPER MC274-50-133	2.0	\$ 42.00
8	2	FASTENER, FRONT BUMPER MB45A-56-146A	2.0	\$ 5.60
9	2	GROMMET, FRONT BUMPER MGHP9-50-025	2.0	\$ 5.40
10	1	BRACKET LHS, FRONT BUMPER MBHN1-50-152	3.0	\$ 15.10
11	1	GRILLE TOP MBHN1-50-033 62	21.5	\$ 335.00
12	6	RIVET, GRILLE TOP MS515-51-833	2.0	\$ 22.80
13	4	RIVET, GRILLE TOP MTK21-50-355	2.0	\$ 34.80
14	1	BRACKET TOP, GRILLE MBHN1-50-717D	1.0	\$ X 102.40
15	8	FASTENER, GRILLE MGD7A-50-EA1	2.0	\$ 24.00
16	1	CHROME LHS MBHN1-50-7K1A	1.0	\$ X 176.70
17	1	CHROME RHS MBHN1-50-7J1A	1.0	\$ 176.70
18	1	MASCOT, FRONT MC235-51-731A	2.0	\$ 44.20
19	1	FRONT GRILLE MBE1-50-712B	1.0	\$ 581.60
20	1	BRACKET LHS, FRONT GRILLE MBHN1-50-163	2.0	\$ 15.10
21	1	BRACKET RHS, FRONT GRILLE MBHN1-50-153	2.0	\$ 15.10
22	2	GROMMET, FRONT GRILLE MKD45-50-ES1	2.0	\$ 5.40
23	2	PIN LOCATOR, FRONT GRILLE MKD45-50-1K5A	1.0	\$ 5.40
24	2	RIVET, FRONT GRILLE MEA01-50-037	1.0	\$ 15.20
25	1	FRONT PANEL UPPER MB45A-53-150A	1.0	\$ 124.00
26	1	STAY LOCK MB45A-52-15Y	1.0	\$ 38.80
27	1	FRONT SUPPORT PANEL MGHR5-53-110B	1.0	\$ 469.70
28	4	FASTENER, PLATE SEAL MKD45-50-EA1	1.0	\$ 10.00
29	1	PLATE SET , FRONT REINFORCEMENT MBHN3-50-1C0	1.0	\$ 92.70
30	4	FASTENER, PLATE SET MGD7A-50-EA1	1.0	\$ 12.00

31	BONNET	1	MBHY0-52-31XA	10/540	\$ 1,067.30	✓
32	WEATHERSTRIP, BONNET	1	MBHN9-56-770A	20	\$ 63.60	✓
33	HEADLAMP RHS	1	MBHT6-51-031A	17	\$ 2,245.00	✓
34	HID CONTROL UNIT	1	MBHN3-51-0H3	17	\$ 895.50	✓
35	GASKET, CONTROL UNIT	1	MC236-51-0B2	17	\$ 13.60	✓
36	RIVET, HEADLAMP	1	MB092-51-833	17	\$ 3.30	✓
37	CLIP, HEADLAMP	2	MFB01-50-133C	17	\$ 7.60	✓
38	RADIATOR COOLANT	1		00	\$ 68.50	✓
TOTAL PARTS					\$ 8,410.10	
LESS 10%					\$ 841.01	
TOTAL PARTS COST					\$ 7,569.09	

Labour Description					
1	MZ-BR-FRONT4	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND BONNET. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	1320	\$ 2,640.00
2	MZ-SP-SFRT04	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND BONNET.	630	1260	\$ 2,520.00
3	MZ-BR-PANEL1	TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND FRONT SUPPORT PANEL. TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST.		17X	\$ 660.00
4	MZ-BR-TOP-UP	TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE AND TOP-UP GAS COOLING SYSTEM.		17X	\$ 660.00
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	17	NETT	\$ 70.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		17X	\$ 250.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		120	\$ 250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		150	\$ 350.00
9	MZ-BR-SUNDRI	SUNDRIES.	20	NETT	\$ 100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED

TOTAL LABOUR	\$ -	\$ 7,500.00
TOTAL PARTS	\$ -	\$ 7,569.09
TOTAL	\$ -	\$ 15,069.09
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED
ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Teo Chek Wei ADDRESS : Blk 5 Lorong Lew Lian #10-108 Singapore 530005 TEL : 83220244		WIP : 31633 EXCESS : DATE: 13-Oct-18	
VEH NO :	SLH7639C	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6BM42A8G0346458	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	17-Nov-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	FRONT BUMPER	1	MBHR3-50-0318BB	\$ 1,031.70	\$ 1,031.70
2	RETAINER RHS	1	MBHN1-50-0T1F	\$ 18.70	\$ 18.70
3	COVER RHS, FRONT BUMPER	1	MBHN1-50-101		\$ 28.00
4	CHROME RHS, FOGLAMP	1	MBJE1-50-C12		\$ 106.70
5	COVER RHS, FOGLAMP	1	MBJE1-50-C11A		\$ 46.40
6	FRONT REINFORCEMENT	1	MB45A-50-070A		\$ 444.50
7	CLIP, FRONT BUMPER	12	MC274-50-133	\$ 42.00	\$ 42.00
8	FASTENER, FRONT BUMPER	2	MB45A-56-146A	\$ 5.60	\$ 5.60
9	GROMMET, FRONT BUMPER	2	MGHP9-50-025	\$ 5.40	\$ 5.40
10	BRACKET LHS, FRONT BUMPER	1	MBHN1-50-152	\$ 15.10	\$ 15.10
11	GRILLE TOP	1	MBHN1-50-033 62	\$ 335.00	\$ 335.00
12	RIVET, GRILLE TOP	6	MS515-51-833	\$ 22.80	\$ 22.80
13	RIVET, GRILLE TOP	4	MTK21-50-355	\$ 34.80	\$ 34.80
14	BRACKET TOP, GRILLE	1	MBHN1-50-717D		\$ 102.40
15	FASTENER, GRILLE	8	MGD7A-50-EA1	\$ 24.00	\$ 24.00
16	CHROME LHS	1	MBHN1-50-7K1A		\$ 176.70
17	CHROME RHS	1	MBHN1-50-7J1A	\$ 176.70	\$ 176.70
18	MASCOT, FRONT	1	MC235-51-731A	\$ 44.20	\$ 44.20
19	FRONT GRILLE	1	MBJE1-50-712B	\$ 581.60	\$ 581.60
20	BRACKET LHS, FRONT GRILLE	1	MBHN1-50-163	\$ 15.10	\$ 15.10
21	BRACKET RHS, FRONT GRILLE	1	MBHN1-50-153	\$ 15.10	\$ 15.10
22	GROMMET, FRONT GRILLE	2	MKD45-50-ES1		\$ 5.40
23	PIN LOCATOR, FRONT GRILLE	2	MKD45-50-1K5A		\$ 5.40
24	RIVET, FRONT GRILLE	2	MEA01-50-037		\$ 15.20
25	FRONT PANEL UPPER	1	MB45A-53-150A		\$ 124.00
26	STAY LOCK	1	MB45A-52-15Y		\$ 38.80
27	FRONT SUPPORT PANEL	1	MGHR5-53-110B		\$ 469.70
28	FASTENER, PLATE SEAL	4	MKD45-50-EA1		\$ 10.00
29	PLATE SET , FRONT REINFORCEMENT	1	MBHN3-50-1C0		\$ 92.70
30	FASTENER, PLATE SET	4	MGD7A-50-EA1		\$ 12.00
31	BONNET	1	MBHY0-52-31XA	\$ 1,067.30	\$ 1,067.30

32	WEATHERSTRIP, BONNET	1	MBHN9-56-770A	\$ 63.60	\$ 63.60
33	HEADLAMP RHS	1	MBHT6-51-031A		\$ 2,245.00
34	HID CONTROL UNIT	1	MBHN3-51-0H3		\$ 895.50
35	GASKET, CONTROL UNIT	1	MC236-51-0B2		\$ 13.60
36	RIVET, HEADLAMP	1	MB092-51-833		\$ 3.30
37	CLIP, HEADLAMP	2	MFB01-50-133C		\$ 7.60
38	RADIATOR COOLANT	1			\$ 68.50
TOTAL PARTS				\$ 3,498.70	\$ 8,410.10
LESS 10%				\$ 349.87	\$ 841.01
TOTAL PARTS COST				\$ 3,148.83	\$ 7,569.09

Labour Description

1	MZ-BR-FRONT4	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND BONNET. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,320.00	\$ 2,640.00
2	MZ-SP-SFRT04	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND BONNET.	\$ 1,260.00	\$ 2,520.00
3	MZ-BR-PANEL1	TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND FRONT SUPPORT PANEL. TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST.		\$ 660.00
4	MZ-BR-TOP-UP	TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE AND TOP-UP GAS COOLING SYSTEM.		\$ 660.00
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.		\$ 70.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
9	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
TOTAL LABOUR			\$ 2,870.00	\$ 7,500.00
TOTAL PARTS			\$ 3,148.83	\$ 7,569.09
TOTAL			\$ 6,018.83	\$ 15,069.09
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 6,018.83	
GST 7%			\$ 421.32	\$ -
GRAND TOTAL			\$ 6,440.15	\$ -

REMARKS:

5 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EG18018657/Uvbn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 12-12-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGV 1019S	Veh. Inspected	SLH 7639C	
Policy No.		Coverage (\$)	0.00	
Claim No.	SGV1019S/SA/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	15/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BM42A8G0346458	Colour	RED	
Odometer	37451	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	BRIDGESTONE	7 mm	
L/H Front Tyre	205/60 R16	BRIDGESTONE	7 mm	
R/H Rear Tyre	205/60 R16	BRIDGESTONE	7 mm	
L/H Rear Tyre	205/60 R16	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/10/2018	Inspection Date	18/10/2018	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 7639C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	TORN	1,031.70	1,031.70
1	RETAINER RHS	BENT	18.70	18.70
1	COVER RHS,FRONT BUMPER	NOT NECESSARY	28.00	-
1	CHROME RHS,FOGLAMP	NOT NECESSARY	106.70	-
1	COVER RHS,FOGLAMP	NOT NECESSARY	46.40	-
1	FRONT REINFORCEMENT	NOT NECESSARY	444.50	-
12	CLIP,FRONT BUMPER	NECESSARY	42.00	42.00
2	FASTENER,FRONT BUMPER	NECESSARY	5.60	5.60
2	GROMMET,FRONT BUMPER	NECESSARY	5.40	5.40
1	BRACKET LHS,FRONT BUMPER	BENT	15.10	15.10
1	GRILLE TOP	DISTORTED	335.00	335.00
6	RIVET,GRILLE TOP	NECESSARY	22.80	22.80
4	RIVET,GRILLE TOP	NECESSARY	34.80	34.80
1	BRACKET TOP,GRILLE	NOT NECESSARY	102.40	-
8	FASTENER,GRILLE	NECESSARY	24.00	24.00
1	CHROME LHS	NOT NECESSARY	176.70	-
1	CHROME RHS	CRACKED	176.70	176.70
1	MASCOT,FRONT	NECESSARY	44.20	44.20
1	FRONT GRILLE	CRACKED	581.60	581.60
1	BRACKET LHS,FRONT GRILLE	NECESSARY	15.10	15.10
1	BRACKET RHS,FRONT GRILLE	NECESSARY	15.10	15.10
2	GROMMET,FRONT GRILLE	NOT NECESSARY	5.40	-
2	PIN LOCATOR,FRONT GRILLE	NOT NECESSARY	5.40	-
2	RIVET,FRONT GRILLE	NOT NECESSARY	15.20	-
1	FRONT PANEL UPPER	NOT NECESSARY	124.00	-
1	STAY LOCK	NOT NECESSARY	38.80	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	469.70	-
4	FASTENER,PLATE SEAL	NOT NECESSARY	10.00	-
1	PLATE SET,FRONT REINFORCEMENT	NOT NECESSARY	92.70	-
4	FASTENER,PLATE SET	NOT NECESSARY	12.00	-

Report Ref No. CS/EG18018657/Uvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET	DENTED / BUCKLED	1,067.30	1,067.30
1	WEATHERSTRIP, BONNET	NECESSARY	63.60	63.60
1	HEADLAMP RHS	NOT NECESSARY	2,245.00	-
1	HID CONTROL UNIT	NOT NECESSARY	895.50	-
1	GASKET, CONTROL UNIT	NOT NECESSARY	13.60	-
1	RIVET, HEADLAMP	NOT NECESSARY	3.30	-
2	CLIP, HEADLAMP	NOT NECESSARY	7.60	-
1	RADIATOR COOLANT	NOT NECESSARY	68.50	-
	LESS 10% DISCOUNT		-841.01	-349.87
			7,569.09	3,148.83
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
1	NUMBER PLATE (SN)	NOT NECESSARY	70.00	-
			170.00	20.00
	LABOUR			
	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND BONNET. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		2,640.00	1,320.00
	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND BONNET.		2,520.00	1,260.00
	TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND FRONT SUPPORT PANEL TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST.	NOT NECESSARY	660.00	-
	TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE AND TOP-UP GAS COOLING SYSTEM.	NOT NECESSARY	660.00	-
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	150.00
			7,330.00	2,850.00
	GRAND TOTAL		15,069.09	6,018.83
	RECOMMENDED COST OF REPAIRS			6,018.83

Report Ref No. CS/EGI18018657/Uvbn2



Report Ref No. CS/EGI18018657/Uvbn2

A handwritten signature in black ink, appearing to be 'Chua' followed by a stylized 'K' and 'S'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.