



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Teo Chek Wei ADDRESS : Blk 5 Lorong Lew Lian #10-108 Singapore 530005 TEL : 83220244		WIP : 31633 EXCESS : DATE: 13-Oct-18	
VEH NO :	SLH7639C	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6BM42A8G0346458	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	17-Nov-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	FRONT BUMPER	1	MBHR3-50-031BBB		\$ 1,031.70
2	RETAINER RHS	1	MBHN1-50-0T1F		\$ 18.70
3	COVER RHS, FRONT BUMPER	1	MBHN1-50-101		\$ 28.00
4	CHROME RHS, FOGLAMP	1	MBJE1-50-C12		\$ 106.70
5	COVER RHS, FOGLAMP	1	MBJE1-50-C11A		\$ 46.40
6	FRONT REINFORCEMENT	1	MB45A-50-070A		\$ 444.50
7	CLIP, FRONT BUMPER	12	MC274-50-133		\$ 42.00
8	FASTENER, FRONT BUMPER	2	MB45A-56-146A		\$ 5.60
9	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5		\$ 5.40
10	BRACKET LHS, FRONT BUMPER	1	MBHN1-50-152		\$ 15.10
11	GRILLE TOP	1	MBHN1-50-033 62		\$ 335.00
12	RIVET, GRILLE TOP	6	MS51S-51-833		\$ 22.80
13	RIVET, GRILLE TOP	4	MTK21-50-355		\$ 34.80
14	BRACKET TOP, GRILLE	1	MBHN1-50-717D		\$ 102.40
15	FASTENER, GRILLE	8	MGD7A-50-EA1		\$ 24.00
16	CHROME LHS	1	MBHN1-50-7K1A		\$ 176.70
17	CHROME RHS	1	MBHN1-50-7J1A		\$ 176.70
18	MASCOT, FRONT	1	MC235-51-731A		\$ 44.20
19	FRONT GRILLE	1	MBJE1-50-712B		\$ 581.60
20	BRACKET LHS, FRONT GRILLE	1	MBHN1-50-163		\$ 15.10
21	BRACKET RHS, FRONT GRILLE	1	MBHN1-50-153		\$ 15.10
22	GROMMET, FRONT GRILLE	2	MKD45-50-ES1		\$ 5.40
23	PIN LOCATOR, FRONT GRILLE	2	MKD45-50-1K5A		\$ 5.40
24	RIVET, FRONT GRILLE	2	MEA01-50-037		\$ 15.20
25	FRONT PANEL UPPER	1	MB45A-53-150A		\$ 124.00
26	STAY LOCK	1	MB45A-52-15Y		\$ 38.80
27	FRONT SUPPORT PANEL	1	MGHR5-53-110B		\$ 469.70
28	FASTENER, PLATE SEAL	4	MKD45-50-EA1		\$ 10.00
29	PLATE SET , FRONT REINFORCEMENT	1	MBHN3-50-1C0		\$ 92.70
30	FASTENER, PLATE SET	4	MGD7A-50-EA1		\$ 12.00

31	BONNET	1	MBHY0-52-31XA		\$ 1,067.30
32	WEATHERSTRIP, BONNET	1	MBHN9-56-770A		\$ 63.60
33	HEADLAMP RHS	1	MBHT6-51-031A		\$ 2,245.00
34	HID CONTROL UNIT	1	MBHN3-51-0H3		\$ 895.50
35	GASKET, CONTROL UNIT	1	MC236-51-0B2		\$ 13.60
36	RIVET, HEADLAMP	1	MB092-51-833		\$ 3.30
37	CLIP, HEADLAMP	2	MFB01-50-133C		\$ 7.60
38	RADIATOR COOLANT	1			\$ 68.50
			TOTAL PARTS		\$ 8,410.10
			LESS 10%		\$ 841.01
			TOTAL PARTS COST		\$ 7,569.09

Labour Description					
1	MZ-BR-FRONT4	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND BONNET. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 2,640.00
2	MZ-SP-SFRT04	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND BONNET.			\$ 2,520.00
3	MZ-BR-PANEL1	TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND FRONT SUPPORT PANEL. TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST.			\$ 660.00
4	MZ-BR-TOP-UP	TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE AND TOP-UP GAS COOLING SYSTEM.			\$ 660.00
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.			NETT \$ 70.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 250.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 350.00
9	MZ-BR-SUNDRI	SUNDRIES.			NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 7,500.00
TOTAL PARTS	\$ -	\$ 7,569.09
TOTAL	\$ -	\$ 15,069.09
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD
THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF
REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING
CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED

TRANS EUROKARS PTE LTD