

ASS. REC. BY:

REF:

CS/CTI/8018660/49d312

Special Instruction:

Surveyor
men

March 8

ASSIGNMENT (Office)

From (Person):

Catherine Frick

of

Cf

Date/Time: 12/10/18 @ 5:25 pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

SLQ 3696R

Insured:

S/Q 2182L

at Workshop m/s

Kah motor

Tel:

9072 1766

of

15 Ubi Rd 4

Policy No:

DMPCSN 1515531803

Claim No.:

SNM18D04877C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/10/2018

CA / REV / REP. / REV 24 HRS (wp)

16/10/2018 @ 9:30am ow

H.O.D. Endorsement:

Date/Time:

10/6 am 15/10/18

Person Contacted:

Rueben

Vehicle IN (OUT)

[illegible]

REF: CT1

ASSIGNMENT

From: _____ Date: 16/10/2018

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 3696R

at Workshop m/s Kah Motor

of 15 Ubi Road 4

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 1.51 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up) LTA 62157

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLQ3696R Yr Regn: 7.17

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Honda Civic 1.5 Turbo c.c 1498

Colour: ~~Black~~ / purple A/C: Insured / Std / NI / NA

Sp. Reading: 26522 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRHFC1660MT000211

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50 R17 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 10/10/18 D.O.I. 16/10/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/11/18 conf. email final by \$8041.70 with Ruben. (Red B 4241.84, 35%/-)

RECEIVED 07 NOV 2018

Date/Time, File Pass to?

☐

Preli. Report

1) 07/11/18

☐

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Report Format: MEK-7P

Lump Sum / I.B.I. (\$) 8041.70

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Oct 2018		12 Oct 2018 17:25 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	BOH GEOK LING, ID: S7206146B		
Main Claimant:	HENG MENG KWONG		
Vehicle Reg. No.:	SLQ3696R	Date of Loss:	10/10/2018 18:00 - :59
Claim Type:	TP / SNM18D04877C02	Policy/Cover Note No.:	DMPCSN1515531803 (Comprehensive)
Vehicle Reg. No. (Insured):	SJQ2182L	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/10/2018]		
Adj Asg. Remarks:	EST \$13,143.39, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	9040D

Vehicle Details

Vehicle No.:	SLQ3696R
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.5 TURBO VTIS SR
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	L15B72453228
Chassis No.:	MRHFC1660HT000211
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$26,873.00
Original Registration Date:	06 Jul 2017
First Registration Date:	06 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$24,623.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Jul 2027
PARF Rebate Amount:	\$18,467.00

Intended COE Rebate Details

COE Expiry Date:	05 Jul 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,110.00
COE Rebate Amount:	\$43,690.00
Total Rebate Amount:	\$62,157.00

The information contained herein is correct as at 16 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/10/2018 14:30
Date Of Accident	10/10/2018 18:10
Exact Location Of Accident	ALONG PIE NEAR LORNIE ROAD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ3696R
Insured/Policyholder	
Name Of Registered Owner	HENG MENG KWONG
NRIC No	S6939040D
Email Address	MKPHYDA@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97594531
Alternative Phone No	OFFICE-97594531

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.5 TURBO VTI-S SR (A)
Exact Purpose for which vehicle was being used at time of accident	GOING HOME
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MU007601-R00
Cover Note Number	

Driver

Name of Driver	HENG MENG KWONG
NRIC No	S6939040D
Date Of Birth	09/11/1969
Occupation	INDOOR
Date Of Driving Pass	25/03/1996
Driving Experience	22 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97594531
Fax Number	
Contact Number	OFFICE-97594531
Email Address	MKPHYDA@YAHOO.COM

Address	413 ANG MO KIO AVENUE 2
Postcode	567862
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT - THIRD PARTY DIRECT SETTLEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJQ2182L
Vehicle Make/Model/Colour	TOYOTA/WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM CHYE KIM
NRIC/Passport Number	
Contact Number	91875888
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Vehicle No

SLQ3696R

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

11/10/18
 Policyholder's Signature / Date & Time
 11:55h

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

towards
TPX
←
along
PIE

my car

SLQ3696R

Please continue to Annex E

Vehicle No SLQ3696R

Annex E

Describe Circumstances of the Accident

- ① It was raining and road was wet
- ② I stopped the car as the car in front of me stopped.
- ③ Few seconds later SJQ3182L cannot stop in time and braked onto my rear.
- ④ The driver apologised and blame that the road was wet and he could not stop in time
- ⑤ We took pictures and exchange phone numbers and name.

Declaration

We declare the foregoing particulars are true in every respect.

[Signature] 11/10/18
115145

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

[Signature]

Witnessed by Reporting Centre Personnel

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18004354	Page	1
	3 ANSON ROAD #16-00	Date	: 12. Oct 2018		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SLQ3696R	Engine No	: L15B72453228		
Chassis No	: MRHFC1660HT000211	Date Time	: 12. Oct 2018 8:42:04 AM		
Model	: CIVIC 1.5 TURBO VTIS YM2017	Surveyor Name	:		
Owner's Name	: HENG MENG KWONG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 10/10/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: HENG MENG KWONG						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 10/10/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: CHINA TAIPING INSURANCE						
	TP VEH: SJQ2182L						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	17	1	45.00	X	45.00	3.15 48.15
68500-TEA-N00ZZ	LID COMP TRUNK	DP/Buc	1	472.10	— 25	354.07	24.78 378.85
74865-TEA-T01	WEATHERSTRIPTRUNK LID	17	1	70.00	— 25	52.50	3.68 56.18
68660-TEA-T10ZZ	HINGE COMPL.TRUNK	17	1	43.50	X 25	32.62	2.28 34.90
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	17	1	43.50	X 25	32.62	2.28 34.90
74851-TEA-003	LOCK ASSYTRUNK	17	1	72.20	— 25	54.15	3.79 57.94
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	17	1	97.70	X 25	73.27	5.13 78.40
75701-TBA-A10	EMBLEM,H-MARK	26	1	11.90	— 25	8.92	0.62 9.54
90301-ST0-003	NUTPUSH 3MM	26	2	1.90	— 25	2.85	0.20 3.05
75722-TBA-A00	EMBLEM SETRR.	26	1	11.50	— 25	8.62	0.60 9.22
75724-TBA-A00	EMBLEM	26	1	23.50	— 25	17.62	1.23 18.85
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	79	1	617.20	— 25	462.90	32.40 495.30
91505-TM8-003	CLIPBUMPER	26	8	2.00	— 25	12.00	0.84 12.84
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	34	1	11.50	— 25	8.62	0.60 9.22
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	34	1	11.50	— 25	8.62	0.60 9.22
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	34	1	2.20	— 25	1.65	0.12 1.77
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	34	1	2.20	— 25	1.65	0.12 1.77
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	13	1	38.20	— 25	28.65	2.01 30.66
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE	17	1	7.60	— 25	5.70	0.40 6.10
71503-TEA-T00	GARNISHR.RR.BUMPER SIDE	17	1	7.60	X 25	5.70	0.40 6.10
33555-TEA-T01	REFLECTOR ASSYL.RR.	17	1	7.00	X 25	5.25	0.37 5.62

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18004354	Page	2
	3 ANSON ROAD #16-00	Date	: 12. Oct 2018		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SLQ3696R	Engine No	: L15B72453228		
Chassis No	: MRHFC1660HT000211	Date Time	: 12. Oct 2018 8:42:04 AM		
Model	: CIVIC 1.5 TURBO VTIS YM2017	Surveyor Name	:		
Owner's Name	: HENG MENG KWONG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 10/10/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
33505-TEA-T01	REFLECTOR ASSY.RR.	1	7.00	25	5.25	0.37	5.62
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	173.00	25	129.75	9.08	138.83
66100-TEC-307ZZ	PANEL SETRR.	1	236.00	25	177.00	12.39	189.39
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87
65550-TED-P00ZZ	PAN COMPSPARE TIRE	1	210.40	25	157.80	11.05	168.85
72841-SH3-315	OILSHEET	1	39.90	25	29.92	2.09	32.01
34155-TEX-Y01	LIGHT ASSYL.LID	1	118.70	25	89.02	6.23	95.25
34150-TEX-Y01	LIGHT ASSYR.LID	1	118.70	25	89.02	6.23	95.25
33550-TEA-T01	TAILLIGHT ASSYL.	1	273.10	25	204.82	14.34	219.16
33500-TEA-T01	TAILLIGHT ASSYR.	1	253.80	25	190.35	13.32	203.67
38387-TZ5-A01	ANTENNA ASSYL.F.	1	58.10	25	43.57	3.05	46.62
74940-SZW-003	BUZZER ASSYSMART	1	60.10	25	45.07	3.15	48.22
32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS	1	27.20	25	20.40	1.43	21.83
39680-TEX-Y41ZT	SENSOR ASSY,PARKING	2	133.90	25	200.85	14.06	214.91
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
84521-TEA-Q01ZA	LID ASSYSPARE TIRE	1	58.40	25	43.80	3.07	46.87
84620-TEA-Z11ZA	LINING ASSYTRUNK LID	1	32.00	25	24.00	1.68	25.68
84651-TEA-Q01ZA	LINING ASSYL.TRUNK SIDE	1	47.40	25	35.55	2.49	38.04
84542-TET-H00	BOX COMPTOOL	1	36.90	25	27.67	1.94	29.61
Sum Item					2813.54	196.95	3,010.49
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00	80	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00	80	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	80	100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	180	250.00	17.50	267.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00	80	130.00	9.10	139.10
BOMISC1	RESET VEHICLE SMART ENTRY SYSTEM (N)	1	320.00	300	320.00	22.40	342.40
BOMISC1	REMOVE, INSTALL & ADJUST REAR VIEW CAMERA (N)	1	320.00	300	320.00	22.40	342.40

Printed on 12/10/2018 10:06:41 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18004354	Page	3
	3 ANSON ROAD #16-00	Date	: 12. Oct 2018		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SLQ3696R	Engine No	: L15B72453228		
Chassis No	: MRHFC1660HT000211	Date Time	: 12. Oct 2018 8:42:04 AM		
Model	: CIVIC 1.5 TURBO VTIS YM2017	Surveyor Name	:		
Owner's Name	: HENG MENG KWONG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 10/10/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00	250	350.00	24.50	374.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TRUNK. ADJUST &	1	350.00	✓	350.00	24.50	374.50
BKRP02M	CUT OFF & RENEW RR PANEL, CUT RR FLOOR	1	4500.00	2240	4500.00	315.00	4815.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2900.00	2250	2900.00	203.00	3103.00
					Sum Labor	9470.00	662.90
							10,132.90

Survey By

Date & Time

Excess

Status

Signature

marcus kkk
16/10/18 @ 9:30
not authorized
take photo before repair.
6 day.

Total Amount 12,283.54 859.85 13,143.39

Total (Inclusive of GST) 13,143.39

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 12/10/2018 10:06:41 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

30/10/2018

Page 1/2



(C) SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

ATTN: MARCUS CHUA

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

WD: 6 DAYS

Customer: WZC008 / CHINA TAIPING
Chassis No: MRHFC1660HT000211
License No: SLQ3696R
Mileage: 26799
Engine No: L15B72453228

Document No: SVO18062325
Printed By: JESHURUEBEN
Order Date: 22. October 2018
Order Time: 8:52:28 AM
Service Advisor: RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 71449)						
	OWNER: HENG MENG KWONG						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 10/10/2018						
	SURVEYED BY: MARCUS (LKK)						
	DATE: 16/10/2018						
	REF NO: SNM18D04877C02						
	TP INSURER: CHINA TAIPING INSURANCE						
	TP VEH: SJQ2182L						
68500-TEA-N00ZZ	LID COMP TRUNK	1	472.10	25	354.07	24.78	378.85
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
74851-TEA-003	LOCK ASSYTRUNK	1	72.20	25	54.15	3.79	57.94
75701-TBA-A10	EMBLEM,H-MARK	1	11.90	25	8.92	0.62	9.54
90301-ST0-003	NUTPUSH 3MM	2	1.90	25	2.85	0.20	3.05
75722-TBA-A00	EMBLEM SETRR.	1	11.50	25	8.62	0.60	9.22
75724-TBA-A00	EMBLEM	1	23.50	25	17.62	1.23	18.85
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
91505-TM8-003	CLIPBUMPER	8	2.00	25	12.00	0.84	12.84
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.20	25	1.65	0.12	1.77
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1	2.20	25	1.65	0.12	1.77
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	38.20	25	28.65	2.01	30.66
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE	1	7.60	25	5.70	0.40	6.10
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	173.00	25	129.75	9.08	138.83
66100-TEC-307ZZ	PANEL SETRR.	1	236.00	25	177.00	12.39	189.39
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87
33550-TEA-T01	TAILLIGHT ASSYL.	1	273.10	25	204.82	14.34	219.16
39680-TEX-Y41ZT	SENSOR ASSY,PARKING	1	133.90	25	100.42	7.03	107.45
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	50.30	25	37.72	2.64	40.36
74940-TZ5-A01	BUZZER ASSYSMART	1	59.30	25	44.47	3.11	47.58
	SUM PARTS:				1,761.70	123.32	1,885.02
BOSUN	0672	1	20.00		20.00	1.40	21.40
	SUNDRIES						
BML02I	EXT-YJ	1	80.00		80.00	5.60	85.60
	INSPECT RR LIGHTING MECHANISMS.						
	PERFORM WATER						
	TEST.(N)						
BOJSE	0672	1	80.00		80.00	5.60	85.60
	BODY JOINT SEALANT.						
BOBC	0672	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						
BP00R	EXT-YBH	1	180.00		180.00	12.60	192.60
	APPLY BODY UNDERSIDE COATING (N).						
BA02R	EXT-YJ	1	130.00		130.00	9.10	139.10
	REMOVE & RENEW REVERSE						
	SENSORS-4 PCS (N)						



© SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

 GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: MRHFC1660HT000211
License No: SLQ3696R
Mileage: 26799
Engine No: L15B72453228

Document No: SVO18062325
Printed By: JESHURUEBEN
Order Date: 22. October 2018
Order Time: 8:52:28 AM
Service Advisor: RUEBEN THOMAS

BOMISC1	0626 RESET VEHICLE SMART ENTRY SYSTEM (N)	1	300.00	300.00	21.00	321.00
BOMISC1	EXT-YJ REMOVE, INSTALL & ADJUST REAR VIEW CAMERA (N)	1	300.00	300.00	21.00	321.00
BMI03D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	250.00	250.00	17.50	267.50
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TRUNK. ADJUST & ALIGN TRUNK.(N)	1	350.00	350.00	24.50	374.50
BKRP02M	EXT-YJ CUT OFF & RENEW RR PANEL, CUT RR FLOOR ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	2,240.00	2,240.00	156.80	2,396.80
BP06R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2,250.00	2,250.00	157.50	2,407.50
			SUM LABOUR:	6,280.00	439.60	6,719.60
			TOTAL SGD	8,041.70	562.92	8,604.62
Total Payable (SGD)						8,604.62

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Oct 2018		12 Oct 2018 17:25 Edit Adj Rpt	S\$8,041.70 Edit Estimates	S\$8,041.70 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	BOH GEOK LING , ID: S7206146B								
Main Claimant:	HENG MENG KWONG								
Vehicle Reg. No.:	SLQ3696R	Date of Loss:	10/10/2018 18:00 - :59 [15 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04877C02	Policy/Cover Note No.:	DMPCSN1515531803 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJQ2182L	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 23/10/2018]								
Adj Asg. Remarks:	EST \$13,143.39, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ3696R (SNM18D04877C02)
[SJQ2182L]
TP
HENG MENG KWONG
Oct 10 2018 6:00PM
[BOH GEOK LING]
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print					
1	11/10/18 16:13	Accident Statement			Load HTM					
							3 per page		<input checked="" type="checkbox"/>	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print					
1	11/10/18 16:10	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>			
2	11/10/18 16:10	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>			
3	11/10/18 16:10	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>			
4	11/10/18 16:10	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>			
5	11/10/18 16:10	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>			
6	11/10/18 16:10	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>			
7	11/10/18 16:10	SCENE [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>			
8	11/10/18 16:10	SCENE [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
2	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
3	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
4	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
5	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
6	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
7	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
8	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
9	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
10	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
11	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
12	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
13	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
14	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
15	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
16	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
17	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
18	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
19	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
20	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
21	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			
22	16/10/18 12:45	General View			Load JPG		<input checked="" type="checkbox"/>			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
23	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
24	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
25	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
26	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
27	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
28	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
29	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
30	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
31	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
32	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
33	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
34	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
35	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
36	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
37	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
38	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
39	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
40	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
41	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
42	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
43	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
44	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
45	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
46	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
47	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
48	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
49	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
50	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
51	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
52	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
53	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
54	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
55	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
56	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
57	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
58	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
59	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
60	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
61	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
62	16/10/18 12:45	General View	 Load JPG	<input checked="" type="checkbox"/>
63	16/10/18 12:45	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
64	16/10/18 12:45	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
65	07/11/18 11:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	07/11/18 11:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	07/11/18 11:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	07/11/18 11:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	07/11/18 11:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	07/11/18 11:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	07/11/18 11:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	07/11/18 11:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
73	07/11/18 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
74	07/11/18 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
75	07/11/18 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
76	07/11/18 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
77	07/11/18 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
78	07/11/18 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
79	07/11/18 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
80	07/11/18 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
81	07/11/18 11:32	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/10/18 17:24	EMAIL FM KAH		<input checked="" type="checkbox"/>
2	12/10/18 17:24	REPAIR EST WITH TP GIA		<input checked="" type="checkbox"/>
3	12/10/18 17:24	OI GIA		<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	11/10/18 16:06	Sketch Plan [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
2	11/10/18 16:06	Sketch Plan #2 [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
3	11/10/18 16:07	DRIVER DL [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
4	11/10/18 16:07	DRIVER IC [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
5	11/10/18 16:07	OWNER IC [Linked Accident Report Documents]		<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print	
1	11/10/18 16:13	Accident Statement		Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print	
1	11/10/18 16:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	11/10/18 16:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	11/10/18 16:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	11/10/18 16:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	11/10/18 16:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	11/10/18 16:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	11/10/18 16:10	SCENE		Load JPG	<input checked="" type="checkbox"/>
8	11/10/18 16:10	SCENE		Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print	
1	11/10/18 16:06	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	11/10/18 16:06	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>
3	11/10/18 16:07	DRIVER DL		Load JPG	<input checked="" type="checkbox"/>
4	11/10/18 16:07	DRIVER IC		Load JPG	<input checked="" type="checkbox"/>
5	11/10/18 16:07	OWNER IC		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18018660/UQD3E2

Date: 14/11/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1515531803

Claimant Vehicle
No: SLQ3696RInsured Vehicle
No: SJQ2182L

Date of Loss: 10/10/2018

Nature of Claim: TP

Claim
No: SNM18D04877C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ3696R**

Make & Model: HONDA CIVIC, 1.5 TURBO VTI-S SR (A)

Engine No: L15B72453228

Reg. Date: 06/07/2017 (Man. Year: 2017)

Chassis No: MRHFC1660HT000211

Colour: Purple

Odometer: 26522 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,863.54	1,781.70	1,081.84	37.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,420.00	6,260.00	3,160.00	33.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,283.54	8,041.70	4,241.84	34.53
+ GST 7.00/7.00% (S\$)	859.85	562.92	296.93	34.53
Nett Amount (S\$)	13,143.39	8,604.62	4,538.77	34.53

INSPECTION

Date of Assignment: 12/10/2018

Date Inspected: 16/10/2018

Inspected At:

Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2018)
Parts:	143	HONDA CIVIC 1.5 TURBO VTI-S SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ3696R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE WITH CASING	Not Necessary	45.00 FS	*- FS
2	1		*LID COMP TRUNK	Dented / Buckled	354.07 FS	*354.07 FS
3	1		*WEATHERSTRIPTRUNK LID	Twisted	52.50 FS	*52.50 FS
4	1		*HINGE COMPL. TRUNK	Not Necessary	32.62 FS	*- FS
5	1		*HINGE COMPR. TRUNK	Not Necessary	32.62 FS	*- FS
6	1		*LOCK ASSYTRUNK	Twisted	54.15 FS	*54.15 FS
7	1		*GARNISH ASSYRR. LICENSE	Not Necessary	73.27 FS	*- FS
8	1		*EMBLEM, H-MARK	Necessary	8.92 FS	*8.92 FS
9	1		*NUTPUSH 3MM (2PCS)	Necessary	2.85 FS	*2.85 FS
10	1		*EMBLEM SETRR.	Necessary	8.62 FS	*8.62 FS
11	1		*EMBLEM	Necessary	17.62 FS	*17.62 FS
12	1		*FACE ASSY, RR BUMPER	Distorted	462.90 FS	*462.90 FS
13	8		*CLIPBUMPER	Necessary	12.00 FS	*12.00 FS
14	1		*SPACERL.RR.BUMPER SIDE	Bent	8.62 FS	*8.62 FS
15	1		*SPACERR.RR.BUMPER SIDE	Bent	8.62 FS	*8.62 FS
16	1		*BRACKETL.RR.BUMPER SIDE	Bent	1.65 FS	*1.65 FS
17	1		*BRACKETR.RR.BUMPER SIDE	Bent	1.65 FS	*1.65 FS
18	1		*GARNISH,RR.BUMPER LOWER	Distorted	28.65 FS	*28.65 FS
19	1		*GARNISHL.RR.BUMPER SIDE	Cut	5.70 FS	*5.70 FS
20	1		*GARNISHR.RR.BUMPER SIDE	Not Necessary	5.70 FS	*- FS
21	1		*REFLECTOR ASSYL.RR	Not Necessary	5.25 FS	*- FS
22	1		*REFLECTOR ASSYR.RR	Not Necessary	5.25 FS	*- FS
23	1		*BEAM COMPRR.BUMPER	Distorted	129.75 FS	*129.75 FS
24	1		*PANEL SETRR.	Badly Dented	177.00 FS	*177.00 FS
25	1		*STIFFENERL.RR.PANEL SIDE	Bent	19.50 FS	*19.50 FS
26	1		*STIFFENER,R.RR.PANEL SIDE	Bent	19.50 FS	*19.50 FS
27	1		*PAN COMPSPARE TIRE	Not Necessary	157.80 FS	*- FS
28	1		*OILSHEET	Not Necessary	29.92 FS	*- FS
29	1		*LIGHT ASSYL.LID	Not Necessary	89.02 FS	*- FS
30	1		*LIGHT ASSYR.LID	Not Necessary	89.02 FS	*- FS
31	1		*TAILLIGHT ASSYL	Broken	204.82 FS	*204.82 FS
32	1		*TAILLIGHT ASSYR	Not Necessary	190.35 FS	*- FS
33	1		*ANTENNA ASSYL.F	Not Necessary	43.57 FS	*- FS
34	1		*BUZZER ASSYSMART	Cracked	45.07 FS	*44.47 FS
35	1		*SUB CORDRR.BUMPER CORNER SENS	Not Necessary	20.40 FS	*- FS
36	1		*SENSOR ASSY, PARKING (2PCS)	Shorted-1pc only	200.85 FS	*100.42 FS
37	1		*LINING ASSYRR.PANEL	Twisted	37.72 FS	*37.72 FS
38	1		*LID ASSYSPARE TIRE	Not Necessary	43.80 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*LINING ASSYTRUNK LID	Not Necessary	24.00 FS	*- FS
40	1		*LINING ASSYL.TRUNK SIDE	Not Necessary	35.55 FS	*- FS
41	1		*BOX COMPTOOL	Not Necessary	27.67 FS	*- FS
42	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
Total Parts (S\$)					2,863.54	1,781.70

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	100.00	80.00
2	BODY JOINT SEALANT	New	100.00	80.00
3	BODY UNDERSIDE COATING	New	100.00	100.00
4	APPLY BODY UNDERSIDE COATING	New	250.00	180.00
5	REMOVE & RENEW REVERSE SENSOR - 4PCS	New	130.00	130.00
6	RESET VEHICLE SMART ENTRY SYSTEM	New	320.00	300.00
7	REMOVE, INSTALL & ADJUST REAR VIEW CAMERA	New	320.00	300.00
8	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	350.00	250.00
9	REMOVE & TRANSFER ITEMS TO NEW TRUNK. ADJUST &	New	350.00	350.00
10	CUT OFF & RENEW RR PANEL, CUT RR FLOOR	New	4,500.00	2,240.00
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	2,900.00	2,250.00
Gross Labour Cost (\$\$)			9,420.00	6,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >