

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 4672J

DATE : 12.10.2018

MAKE :

MODEL : HYUNDAI i40

China
ju:

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet			\$ 2,265.90
	Bonnet Hinge (LH/RH) <i>X su</i>		\$ 41.00	\$ 82.00
	Bonnet Lock			\$ 36.90
	Bonnet Insulator <i>X su</i>			\$ 196.50
	Bonnet Insulator Clips			\$ 8.40
	Radiator Grille			\$ 1,110.10
	Radiator Grille H Emblem			\$ 28.70
	Front Bumper Cover			\$ 1,082.20
	Front Bumper Sponge <i>X su</i>			\$ 99.20
	Front Bumper Reinforcement			\$ 402.10
	Front Bumper Bracket Top (LH/RH) <i>X su</i>		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) <i>X su</i>		\$ 24.60	\$ 49.20
	Headlamp Support Top Cover			\$ 222.60
	Headlamp Support Panel Assy			\$ 907.40
	Headlamp (LH/RH) <i>X su</i>		\$ 1,388.00	\$ 2,776.00
	Radiator <i>X su</i>			\$ 698.30
	Radiator Fan Blade, Cowling, Motor Assy <i>X su</i>			\$ 792.95
	Radiator Bracket (RH/LH) <i>X su</i>		\$ 6.50	\$ 13.00
	Radiator Guard <i>X su</i>		\$ 20.00	\$ 40.00
	Horn Unit (LH/RH) <i>X su</i>		\$ 73.80	\$ 147.60
	Aircon Condenser <i>X su</i>			\$ 927.50
	Inter Cooler <i>X su</i>			\$ 1,032.50
	Inter Cooler Mounting (2 PCS) <i>X su</i>			\$ 25.90
	SUB TOTAL			\$ 12,970.55
	LESS 20% (to resurvey before/after spray painting)			\$ 2,594.11
	DISCOUNTED TOTAL			\$ 10,376.44
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: <i>Kahin</i> Date: <i>12/10/18 1605h</i>			
	Labour Charge			
	Panel Beating			\$ 1,000.00 <i>400</i>
	Spray Painting Charge			\$ 500.00 <i>400</i>
	Wiring Charge			\$ 50.00 <i>X 40</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Towing Charge			\$ 50.00 <i>X 90</i>
	Remove/Refill Aircon & Refill Gas			\$ 150.00 <i>100</i>
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 <i>X 40</i>
	TOTAL LABOUR			\$ 2,280.00
	ESTIMATE TOTAL			\$ 12,656.44
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				