



CHEVROLET

Repair Estimate

Date :12/10/2018

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SDD128Y
CHASSIS NO.: KL1JA69E9GK346784
ENGINE NO.: F16D4160880475

Name of insured : LAM CHEE SIONG
Date of accident.: 11/10/2018

Reference: CHEVROLET
LKR Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET	\$ 1,650.00
2	1	FRT BONNET RUBBER SEAL, Front	\$ 93.00
3	1	FRT BONNET RUBBER SEAL, RH	\$ 71.00
4	1	FRT BONNET RUBBER SEAL, LH	\$ 71.00
5	1	FRT BONNET LOCK	\$ 168.00
6	10	FRT BONNET INSULATOR CLIP	\$ 65.00
7	1	FRT BUMPER	\$ 1,446.00
8	1	FRT BUMPER LOW CENTER GRILLE	\$ 274.00
9	1	FRT BUMPER LOGO	\$ 204.00
10	1	FRT NUMBER PLATE BASE	\$ 40.00
11	10	FRT BUMPER CLIP	\$ 65.00
12	1	FRT BUMPER SIDE RETAINER LH	\$ 86.00
13	1	FRT BUMPER SIDE RETAINER RH	\$ 86.00
14	1	FRT BUMPER SPONGE	\$ 140.00
15	1	FRT BUMPER REINFORCEMENT	\$ 1,030.00
16	1	FRT SUPORT PANEL TOP GARNISH	\$ 227.00
17	1	FRT BUMPER GRILLE, UPPER	\$ 352.00
18	1	FRT BUMPER GRILLE, LOWER	\$ 526.00
19	1	RH HEADLAMP	\$ 2,702.00
20	1	LH HEADLAMP	\$ 2,702.00
21	1	RADIATOR SUPORT PANEL TOP	\$ 420.00
22	1	RADIATOR	\$ 1,098.00
23	1	RADIATOR FAN COWLING	\$ 379.00
24	1	RADIATOR FAN BLADE & MOTOR	\$ 783.00
25	2	RADIATOR BRACKET UPPER	\$ 176.00
26	2	RADIATOR TOP MOUTING	\$ 126.00
27	2	RADIATOR BRACKET LOWER	\$ 220.00
28	1	RADIATOR TOP HOSE, Inlet	\$ 118.00
29	1	RADIATOR LOW HOSE, Outlet	\$ 162.00
30	1	TURBO INTAKE COOLER	\$ 653.00
31	1	A/C CONDENSER	\$ 1,052.00
32	1	INTAKE AIR DUCT AIR HOSE(air duct to resonator box)	\$ 224.00
33	1	INTAKE AIR RESONATOR BOX	\$ 328.00
34	1	FRT FOG LAMP RH	\$ 298.00
35	1	FRT FOG LAMP COVER RH	\$ 130.00
36	1	FRT BUMPER LOWER LIP	\$ 120.00
37	1	FRT BUMPER UNDER DUST COVER, Deflector	\$ 135.00

38	1	FRT FENDER RH	Bushes	\$	832.00	✓
39	1	FRT FENDER INNERSHIELD RH	lit	\$	228.00	✓
40	1	FRT FENDER BRACKET RH	?	\$	112.00	✓
41	1	FRT FENDER TOP GARNISH RH	new	\$	89.00	+
42	1	RR BUMPER	Rebrand	\$	1,256.00	✓
43	1	RR BUMPER CHROME MLDG RH	?	\$	152.00	✓
44	1	RR BUMPER CHROME MLDG LH	3 new	\$	152.00	✓
45	1	RR BUMPER CHROME MLDG CENTRE		\$	205.00	✓
46	1	RR BUMPER REINFORCEMENT	new	\$	736.00	+
47	1	RR BUMPER SIDE RETAINER LH(INNER)	3 new	\$	116.00	✓
48	1	RR BUMPER SIDE RETAINER LH(OUTER)	3 new	\$	116.00	✓
49	1	RR BUMPER CENTRE RETAINER	new	\$	130.00	+
50	1	RR BUMPER SIDE RETAINER RH(INNER)	3 new	\$	116.00	✓
51	1	RR BUMPER SIDE RETAINER RH(OUTER)	3 new	\$	116.00	✓
52	1	RR BUMPER REVERSE SENSOR	3 new	\$	215.00	+
53	1	RR BUMPER REVERSE SENSOR RUBBER SEAL		\$	13.00	+

Parts Total: \$ 23,004.00

Less 10%: \$ 2,300.40

Total : \$ 20,703.60

Labour

No.	Labour Description	Price (SGD)	
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 3,300.00	2200
2	Carry out spray painting on affected area	\$ 2,500.00	1750
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00	60
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 220.00	180
5	To remove and refix radiator and conduct pressure test	\$ 120.00	60

Labour Total : \$ 6,260.00

Others

No.	Other Description	Price (SGD)	
1	FRT NUMBER PLATE	\$ 65.00	✓
2	RADIATOR COOLANT	\$ 80.00	50

Other Total: \$ 145.00

TOTAL: \$ 27,108.60

GST (7%): \$ 1,897.60

GRAND TOTAL : \$ 29,006.20

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor

Adrian Lim
P/P 15/10/18
06 Impr