Surveyor:	Court 1 Oak	ASSIGNMENT (selvalina a al a
		_ of		Date/Time: 15/10/18/0 9-4/an
Con TRANS		Bill to	-	
To Inment V	FTT RES / OD RES / E			
	hicle No:	3DD 128 Y	Insured	
at workshop i	n/s F1	ist Autowork	S Tel	82988 933
of	23 Kak	Bukit Ave 4	# 04-01	
Policy No:		7		/18/VP05/021013
Sum Insured		Е	ccess:	
Make of Veh:				D.O.A. 11/10/2018
(Client's Recerd				
con a classical i	1000			
CA /(REI)	REP. / REV 24 HRS			H.O.D. Endorsement:
Date/Time: 10	1-10ma Ish - 110	Person Contacted:	uheimi .	H.O.D. Endorrement:
Date/Time: \(\)	-49am@ Isholle		uheimi	
Date/Time: \(\)	Action/Instruction (/) Estimate	uheimi .	
Date/Time: \(\)	-49am@ Isholle	/) Estimate	uheimi	
Date/Time: \(\)	Action/Instruction (/) Estimate	uheimi	
Date/Time 16 to 8	Action/Instruction (SDD 1284-			/chide_ID/LOUT
Date/Time: \(\)	Action/Instruction (- SDD 1284- Revert to G	Estimate -> Devald, pending	repair cost	Avom repairer by emil
Date/Time Date/Time	Action/Instruction (SDD 1284 - Revert to G	Estimate X Verald, pending Re repair from	repair cost Gerald by	Avom repairer by emil

ASSIGNMENT

From Date:	Veh No. 5001287 - Yr Regn 2016 Nov .
Estimuted Cost:	Type (M.Cal) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make Chevrolet Cruse as 1598
at Workshop m/s	Colour while A/C Insured / Std / NI / NA
of	Sp.Reading 40294 - T/Radio Insured / Std / NI / NA
Insured	Eng/No:
Policy No.	CINO: KLIJA69E96K346184
Claims No.	Gen. Cond Good / Fair / Poor / Burnt
Sum Insured Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Injurder / Jammed / Leaked / Burnt or
Make of Veh:	Modi Nil S/Rim / STD A/Rim or
	Tyre Size F: 215/60R16 Hifly R: 215/60R16 Kumho -
(Policy Condition)	R: 215/60R16 Kumho -
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value:	Eront Rear /
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. Ob mm R/Bal. 8G mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 06 mm L/Bal 06 mm
Est. Repairs: days Res.: Yes or No	D.O.A D.O.I. 15/15/18
Lum Sum: % 3 Val.: Yes or No	Survey held at Alpine Molor I
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction OD La Pac	
30/11/18 @316pm Kelvin will email i	is liabled
Solution Carolin Main Mill Share I	as divarso
mV, 68K.	
PV. SHIK PECELV	ED 1 2 DEC 2018
nett: 16.91c	10 12 2010
	(0.1
11/13/18 LS \$ 15,000 confirmed by email	(Red 14, 233.60, 499) (Spoul 30% disc on
Date/Tirtse. File Pass to? : Preli. Report	Days Of Repair: 6 (GC+S)
: Final Report	Resurvey No. of Trip: Survey Fee /20+285
Dute/Time, File Raturn to?	Transportation. 50
1 1/12 - typist Add Fee	
	Interview (\$) Photos SP 102
Report Format :	Tech Invs (\$) cast (0
Lump Sum / I.B.I: (\$ \$15,000 2	:Weekend (\$
16.7	G974 118 657

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Wednesday, 17 October 2018 10:08 AM

To:

SUR; 'suhaimi@alpinemotors.sg'; 'kelvin.chew@alpinemotors.sg'

Subject:

RE: SDD 128Y-DOA: 11/10/2018 (LONPAC OD)

Dear Kelvin/Suhaimi,

As instructed by our client, please proceed to repair the insured vehicle SDD 128Y not exceeding part by part \$15,000.00/-(Excess -).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Tuesday, 16 October 2018 10:09 AM

To: SUR <sur@lkkauto.com>; 'suhaimi@alpinemotors.sg' <suhaimi@alpinemotors.sg>;

kelvin.chew@alpinemotors.sg

Subject: RE: SDD 128Y-DOA: 11/10/2018 (LONPAC OD)

Dear Suhaimi/Kelvin,

Kindly check vehicle able to repair at part by part not exceeding \$15,000/-

Subject to insurance approval.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From:

GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent:

Tuesday, 16 October 2018 11:45 AM

To:

Veron Chen (LKKAuto)

Cc:

MT_Claim_SG

Subject:

RE: SDD128Y - CRUZE 1.6 - OWN DAMAGED - LONPAC INSURANCE BHD - DOA

11-10-2018

Dear Veron,

Your Preliminary Advice dated 16 October 2018 refers.

Kindly proceed to authorize repair as adjusted.

Best Regards Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Tuesday, 16 October, 2018 11:15 AM

To: GERALD POH WEE BIN Cc: MT_Claim_SG; SUR

Subject: FW: SDD128Y - CRUZE 1.6 - OWN DAMAGED - LONPAC INSURANCE BHD - DOA 11-10-2018

Dear Gerald.

Enclosed herewith survey photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Tuesday, 16 October 2018 10:00 AM

To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; SUR <sur@lkkauto.com>

Subject: RE: SDD128Y - CRUZE 1.6 - OWN DAMAGED - LONPAC INSURANCE BHD - DOA 11-10-2018

Dear Gerald,

Enclosed preliminary revised of vehicle SDD 128Y

Number of days: 6 days

Pending repair cost from repairer

We have Not authorise repair.

Please create claim in merimen.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, 15 October 2018 10:53 AM

To: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; assignments <assignments@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; SUR <sur@lkkauto.com>

Subject: RE: SDD128Y - CRUZE 1.6 - OWN DAMAGED - LONPAC INSURANCE BHD - DOA 11-10-2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]

Sent: Monday, 15 October 2018 9:41 AM

To: admin-d@lkkauto.com

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: FW: SDD128Y - CRUZE 1.6 - OWN DAMAGED - LONPAC INSURANCE BHD - DOA 11-10-2018

Dear Catherine/ Nivitha,

Kindly proceed to survey and revert.

There is no excess applicable under the Motor policy.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Vincent Sim [mailto:vincent.sim@alpinemotors.sg]

Sent: Monday, 15 October, 2018 9:31 AM

To: MT_Claim_SG

Cc: Kelvin Chew; suhaimi@alpinemotors.sg

Subject: SDD128Y - CRUZE 1.6 - OWN DAMAGED - LONPAC INSURANCE BHD - DOA 11-10-2018

Dear Sir,
Kindly dispatch survey for the above vehicle as attached,
location as:
Person in charge;
Suhaimi, Kelvin – 82925595 H/P,
68441985 – office phone
E-mail;
suhaimi@alpinemotors.sg
Kelvin.chew@alpinemotors.sg

Add; First Autoworks Pte Ltd 23, Kaki Bukit Ave 4 #04-01 (South Wing) singapore 415933 (Vicom Building) tel; 6844-1985

Regards, Vincent Sim- Claims Dept

vincent.sim@alpinemotors.sg

65113022 ext 343

The information contained in this message is intended only for the recipient, and may be a confidential afformey-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

×

This email has been checked for viruses by AVG antivirus software, www.avg.com



51 UBLAVE 1, #02-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

PLEASE ADVISED

Our ref:

CS/LPC18018665/Avd3

Date: 16/10/2018

The Motor Claims Department M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.SDD 128Y

We thank you for your instruction on

15/10/2018

: S\$16,286.00

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/10/2018 at the premises of M/s FIRST AUTOWORKS PTE LTD

and have the following to report:-

 Workshop Estimate Amount
 : S\$27,108.60

 Revised Estimate Amount
 : S\$16,025.40

 "Check" Items Amount
 : S\$6,807.60

 Total
 : S\$22,833.00

 Market Value
 : S\$68,000.00

 LTA Reimbursement Value
 : S\$51,714.00

Description of Damage: The vehicle sustained damages at the front portion rear front offside

Comments/Present Status:

Damages Consistent

Nett Value

Pending repair cost from repairer

Yours faithfully,

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent: Monday, 15 October 2018 9:41 AM

To: admin-d@lkkauto.com

Cc: MT_Claim_SG

Subject: FW: SDD128Y - CRUZE 1.6 - OWN DAMAGED - LONPAC INSURANCE BHD - DOA

11-10-2018

Attachments: SDD128Y - ESTIMATE _0001.jpg; SDD128Y - ESTIMATE _0002.jpg; SDD128Y -

ESTIMATE_INS CERT.jpg; SDD128Y - GIA.jpg

Dear Catherine/ Nivitha,

Kindly proceed to survey and revert.

There is no excess applicable under the Motor policy.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Vincent Sim [mailto:vincent.sim@alpinemotors.sg]

Sent: Monday, 15 October, 2018 9:31 AM

To: MT_Claim_SG

Cc: Kelvin Chew; suhaimi@alpinemotors.sg

Subject: SDD128Y - CRUZE 1.6 - OWN DAMAGED - LONPAC INSURANCE BHD - DOA 11-10-2018

Dear Sir,
Kindly dispatch survey for the above vehicle as attached,
location as:
Person in charge;
Suhaimi, Kelvin – 82925595 H/P.
68441985 – office phone
E-mail;
suhaimi@alpinemotors.sg
Kelvin.chew@alpinemotors.sg

Add; First Autoworks Pte Ltd 23, Kaki Bukit Ave 4 #04-01 (South Wing) singapore 415933 (Vicom Building) tel; 6844-1985

Regards, Vincent Sim- Claims Dept

vincent.sim@alpinemotors.sq

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	A PRODUCT OF THE PARTY OF THE P
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	9733F
Vehicle No.:	SDD128Y
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	CRUZE NB 1.6D 6AT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	F16D4160880475
Chassis No.:	KL1JA69E9GK346784
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$13,813.00
Original Registration Date:	28 Nov 2016
First Registration Date:	28 Nov 2016
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$13,813.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2026
PARF Rebate Amount: Intended COE Rebate Details	\$10,359.00
COE Expiry Date:	27 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,951.00
COE Rebate Amount:	\$41,355.00
Total Rebate Amount:	\$51,714.00

The information contained herein is correct as at 15 Oct 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	9733F
Vinicle Details	
Vehicle No.:	5DD128Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Oct 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	CRUZE NB 1.6D 6AT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	F16D4160880475
Chassis No.:	KL1JA69E9GK3467B4
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$13.813.00
Original Registration Date:	28 Nov 2016
First Registration Date:	28 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$13.813.00
Intended PARE Rehato Details	\$15,615.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2026
PARF Rebate Amount:	\$10,359.00
Intensies COE Rabata Datalla	
COE Expiry Date:	27 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,951.00
COE Rebate Amount:	\$40,760.00
Total Rebate Amount:	\$51,119.00
information contained herein is correct as at 15 Oct 2018	



About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2018 sgCarMart. All rights reserved.

SGCARMART.COM

Login Sign up

New Cars

Post an Ad

Dwed Car

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

dealers competed to buy my car!



Ways of Selling

Sell ur Car for More Cash
Highest Price or Get \$100 Free
Get Paid Now, Handover Later

SELL YOUR CAR


QUOTZ

Post an Advertisement Sell it yourself Advertise it at just \$58 until it's SOLD!

Advertiser Logis

(V Credit Pte Urt

click here to view our PRISTINE USED CARS at GREAT PRICES



Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sqCarNart is the number are our committed for parallel import cars. Toyota, Honda, Nassar, Missabshi & BHW. There are plenty of cars for sain, from yons, specia, action cars. I searly cars, or stationwagens, SUV, MPV, hatchback, to COE cars & OPC cars. You can viso buy from a car auction, lock up car toons, low mileage cars, car blands, carpain rates is car insurance. Find buy used Chevrolet Cruze, Chevrolet Cruze, Chevrolet Cruze, used Chevrolet Cruze, said section of care care care comprising parallel importers, authorised car dealers on our site. Find new car price lab., new care Sunches and new car promotions, visit our partner sites for some care care care care. Sob openings for Singapore yobs, real estate properties for sain, myself and care care care.

All prices and other information displayed on spCartMart.com are gathered from sources and based on algorithms that are believed by spCartMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, spCartMart.com does not accurate any responsibility for errors or nominion or nation the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement | ©2004-2018 sgCarMart. All rights reserved.

For old advertisements, view Expired adv.

20 * results/page

CERTIFICATE OF INSURANCE

MCTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 189) REPUBLIC OF SINGAPORE. MCTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF SINGAPORE). RCAD TRANSPORT ACT 1967 (MALAYSIA). MCTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA).

Certificate No.: 217VP05016168

Type of Cover: COMPREHENSIVE

1. Index Mark and Vehicle Registration Number

CHEVROLET CRUZE 1.6

- SDD128Y

2. Name of Policy Holder

LAM CHEE SIONG

 Effective Date of the Commencement of Insurance for the purpose of the Act 28/11/2017

4. Date of Expiry of the Insurance

27/11/2018

- 5. Persons or Classes of Persons entitled to drive (A) THE POLICYHOLDER (B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER's ORDER OR WITH HIS/HER PERMISSION Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
- 6. Limitations as to use USE ONLY FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS. THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD, RACING, PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING OR THE CARRIAGE OF GOODS (OTHER THAN SAMPLES) IN CONNECTION WITH ANY TRADE OR BUSINESS OR USED FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

Excess

: S\$ 0.00 (SECTION 1) INSURED / NAMED DRIVERS

S\$ 1,000.00 (SECTION 1) UNNAMED DRIVERS

\$\$ 3,000.00 (SECTION 1) ADDITIONAL EXCESS FOR ELDERLY OR YOUNG AND/OR INEXPERIENCED DRIVERS

S\$ 100.00 WINDSCREEN EXCESS

LONPAC'S AUTHORISED WORKSHOPS

Condition

: ACCIDENT REPAIRS AT LONPAC'S AUTHORISED WORKSHOPS OR DISTRIBUTOR-OWNED MOTOR WORKSHOP

 Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore are not included under heading.

I/WE hereby certify that this covering Note is issued in accordance with the provisions of Part I/V of the Road Transport Act 1987 (Malaysia) and Motor Vehicles (Third-Party Risks and Compensation) Act (Cap 189) Republic of Singapore.

H.P. Owner: MAYBANK

CHIEF EXECUTIVE (Singapore Branch)

User ID: LENNY Date Issued: 20/11/2017 MSM118131949 / Specialists Motor Pie Ltd - HQ ENTRY DATE & TIME: 11/10/2018 13:23 SUBMITTED BY: Irene Ting Yen Hul

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centro established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

- ^ -	\sim	01-3	T ST	W 115	W-42	
					171-1	ш

Date Of Report 11/10/2018 13:23

Date Of Accident 11/10/2018 09:50

Exact Location Of Accident POTONG PASIR AVE 1 NEAR BLOCK 147

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SDD128Y

Insured/Policyholder

Name Of Registered Owner LAM CHEE SIONG

NRIC No S7119733F

Email Address COLINLCS5671@GMAIL.COM

Mobile Phone No (LOCAL) +65-92707567

Alternative Phone No OTHERS-90669444

Vehicle Particulars

Manufacturer CHEVROLET

Model CRUZE 1.6

Exact Purpose for which vehicle was being used at. PRIVATE USE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No. Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company LONPAC INSURANCE BHD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number Z17VP05016168

Cover Note Number

Driver

Name of Driver LAM CHEE SIONG

 NRIC No
 S7119733F

 Date Of Birth
 05/06/1971

 Occupation
 INDOOR

 Date Of Driving Pass
 07/11/1991

Driving Experience 26 YEARS AND 11 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-92707567

Fax Number

Contact Number OTHERS-90669444

EMail Address COLINLCS5671@GMAIL.COM

BLK 18 LIM AH PIN ROAD #04-01

Postcode

547837

OWNER

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

YES

Foreign Vehicle Registration Number

JQV1206 (MOTORCYCLE)

Number of vehicles involved in the accident

3 NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/affering accident claims assistance.

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER]

POLICE

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ATTACHED POLICE REPORT NO.T/20181011/2096

Attachment(s)

Are accident photos available for attachment?

NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

VIDEO

Was there any audio recorded?

NO

Details of Witness 1

Name

TERENCE

Phone Number

97588444

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

SGK5216X

Details Of Properties

CAR B

Vehicle Category

PRIVATE CAR

Name of Driver

SHAIK ISMAIL BIN SYED AHMAD

NRIC/Passport Number

S1282643E

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

JQV1206

Vehicle Make/Model/Colour

Details Of Properties

Martine Calanna

Vehicle Category Name of Driver MOTORCYCLE YEE CHEW HING

NRIC/Passport Number

5 10449061

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature Date & Time:

11102018

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name:

NRIC/FIN No .:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Attached	police	report	no	7/201011	12096
11.0	P	-/-			/

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 1/102018

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:









CHEVROLET

Repair Estimate

Date: 12/10/2018

To Whom It May Concern

Dear Sir.

RE: VEHICLE .: SDD128Y

CHASSIS NO.: KL1JA69E9GK346784 ENGINE NO.: F16D4160880475

Name of insured .: LAM CHEE SIONG

Date of accident.: 11/10/2018

Reference: CHEMROLETURY

the RedMake: GRUZEing:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" beels.
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty		Price (SGD)
1	1	FRT BONNET - Quited .	\$ 1,650.00
2	1	FRT BONNET RUBBER SEAL, Front 2	\$ 93.00
3	1	FRT BONNET RUBBER SEAL, RH	\$ 71.00
4	1	FRT BONNET RUBBER SEAL, LH	\$ 71.00
5	1	FRT BONNET LOCK AND AND	- \$ 168.00
6	10	FRT BONNET INSULATOR CLIP	\$.65:00
7	1	FRT BUMPER	\$ 1,446,00
8	1	FRT BUMPER LOW CENTER GRILLE	\$ 274.00
9	1	FRT BUMPER LOGO	\$ 204.00
10	1	FRT NUMBER PLATE BASE	\$ 40.00
-	10	FRT BUMPER CLIP 7.	\$ 65:00
12	1	FRT BUMPER SIDE RETAINER LH	\$ 86.00
13	1	FRT BUMPER SIDE RETAINER RH	\$ 86.00
14	1	FRT BUMPER SPONGE	\$ 140.00
15	1	FRT BUMPER REINFORCEMENT 34.	\$ 1,030.00
16	1	FRT SUPORT PANEL TOP GARNISH	\$ 227.00
17	1	FRT BUMPER GRILLE, UPPER 2	\$ 352.00
18	1	FRT BUMPER GRILLE, LOWER	\$ 526.00
19	1	RH HEADLAMP Crube	\$ 2,702.00
20	1	LH HEADLAMP	S 2,702.00
21	1	RADIATOR SUPORT PANEL TOP 7	\$ 420.00
22	1	RADIATOR 7	\$ 1,098.00
23	1	RADIATOR FAN COWLING 7	S 379.00
24	1	RADIATOR FAN BLADE & MOTOR AND AND	S 783.00
25	2	RADIATOR BRACKET UPPER 7	S 176.00
26	2	RADIATOR TOP MOUTING 7	\$ 126.00
27	2	RADIATOR BRACKET LOWER	\$ 220.00
28	1	RADIATOR TOP HOSE, Inlet	\$ 118,00
29	1	RADIATOR LOW HOSE, Outlet	\$ 162.00
30	1	TURBO INTAKE COOLER ?	\$ 653,00
31	1	A/C CONDENSER 7	\$ 1,052.00
32	1	INTAKE AIR DUCT AIR HOSE(air duct to resonator box)	
33		INTAKE AIR RESONATOR BOX 7	\$ 328.00
34	1	FRT FOG LAMP RH 7	\$ 298.00
35	1	FRT FOG LAMP COVER RH	\$ 130.00
36	1	FRT BUMPER LOWER LIP	\$ 120.00
37	1	FRT BUMPER UNDER DUST COVER, Deflector	\$ 135.00

38	1	FRT FENDER RH Bruked	\$ 832.00
39	1	FRT FENDER INNERSHIELD RH	\$ 228.00
40	1	FRT FENDER BRACKET RH	S 112.00
41	T	FRT FENDER TOP GARNISH RH	\$ 89.00
42	1	RR BUMPER Delind	\$ 1,256.00
43	1	RR BUMPER CHROME MLDG RH 7	\$ 152.00
44	1	RR BUMPER CHROME MLDG LH	\$ 152.00
45	1	RR BUMPER CHROME MLDG CENTRE	\$ 205.00
46	1	RR BUMPER REINFORCEMENT	\$ 736.00
47	1	RR BUMPER SIDE RETAINER LH(INNER) 2	\$ 116.00
48	1	RR BUMPER SIDE RETAINER LH(OUTER)	\$ 116.00
49	1	RR BUMPER CENTRE RETAINER	\$ 130.00
50	1	RR BUMPER SIDE RETAINER RH(INNER) 2	\$ 116.00
51	1	RR BUMPER SIDE RETAINER RH(OUTER)	\$ 116.00
52	1	RR BUMPER REVERSE SENSOR 4 ALL AM-	\$ 215.00
53	1	RR BUMPER REVERSE SENSOR RUBBER SEAL	\$ 13.00

Parts Total: \$ 23,004.00

Less10%: \$ 2,300.40

Total: \$ 20,703.60

Labour

Labour Description

No.		Price	e (SGD)	
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	s	3,300.00	2200
2	Carry out spray painting on affected area	\$	2,500.00	175
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	s	120.00	60
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$	220:00	180
5	To remove and refix radiator and conduct pressure test	\$	120.00	60

Labour Total: \$ 6,260.00

Others

Other Description

No.		Price (SGD)
1	FRT NUMBER PLATE Could	\$ 65.00
2	RADIATOR COOLANT	\$ 80.00 50

Other Total: \$ 145.00

TOTAL: \$ 27,108.60 GST (7%): \$ 1,897.60

29,006.20 **GRAND TOTAL: \$**

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor

Adrian hiny.
P/P 15/10/18.
06 Days.

CHEVROLET

Repair Estimate

Date:12/10/2018

Reference: CHEVROLET Make: CRUZE

To Whom It May Concern

Dear Sir.

RE: VEHICLE .: SDD128Y

CHASSIS NO.: KL1JA69E9GK346784 ENGINE NO.: F16D4160880475

Name of insured .: LAM CHEE SIONG

Date of accident.: 11/10/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

4	Qty	r a	rt Description	Pric	ce (SGD)
2	1	FRT BONNET	Served.	\$	1,650.00
3	1	FRT BONNET RUBBER SEAL, Fro	ont 2	S	93.00
4	1	FRT BONNET RUBBER SEAL, RH	1 per	S	71.00
5	1	FRT BONNET RUBBER SEAL, LH		\$	71.00
_	1	FRT BONNET LOCK		. 5	168.00
7	10	FRT BONNET INSULATOR CLIP	Mer	S	-65.00
8	1	FRT BUMPER	viscolie!	S	1,446.00
_	1	FRT BUMPER LOW CENTER GRI		S	274.00
9	1	FRT BUMPER LOGO	per	S	204.00
diam'r.	1	FRT NUMBER PLATE BASE	autic	S	40.00
11	10	FRT BUMPER CLIP	7.	S	45.00 65.00
2	1	FRT BUMPER SIDE RETAINER LE	1 per	S	
3	1	FRT BUMPER SIDE RETAINER RE	1 0	S	86.00
4	1	FRT BUMPER SPONGE	cente	\$	86.00
5	1	FRT BUMPER REINFORCEMENT	34,	5	140.00
6	1	FRT SUPORT PANEL TOP GARNIS	SH Deit d	S	1,030.00
7	1	FRT BUMPER GRILLE, UPPER	2	S	227.00
8	1	FRT BUMPER GRILLE, LOWER	Tende	S	352.00
9		RH HEADLAMP	and	\$	526.00
2		LH HEADLAMP	zuld	\$	2,702.00
1	1	RADIATOR SUPORT PANEL TOP	7.ken		2,702.00
2		RADIATOR 7	Secret	\$	420.00
3	1	RADIATOR FAN COWLING	and un	5	1,098.00
1	1	RADIATOR FAN BLADE & MOTOR	R Hall m	5	379.00
5	2	RADIATOR BRACKET UPPER	Men	5	783.00
3	2	RADIATOR TOP MOUTING	2 d	\$	176.00
7	2	RADIATOR BRACKET LOWER	2 1	\$	126.00
3	1	RADIATOR TOP HOSE, Inlet		\$	220.00
9	1	RADIATOR LOW HOSE, Outlet	Zuin	\$	118.00
0	1	TURBO INTAKE COOLER	766-	\$	162.00
	1	A/C CONDENSER	20.1	\$	653.00
		INTAKE AIR DUCT AIR HOSE(air d		\$	1,052.00
	1	INTAKE AIR RESONATOR BOX	To A d	\$	224.00
1	1	FRT FOG LAMP RH	Dend	\$	328.00
5	1 1	FRT FOG LAMP COVER RH	Deta:	\$	298.00
	1 1	FRT BUMPER LOWER LIP	Deld	\$	130.00
8				S	

<u>38</u>	1	FRT FENDER RH	Sulls	S	832.0
39	_1	FRT FENDER INNERSHIELD RH	w	- 6	
40	1	FRT FENDER BRACKET RH	It now	3	228.0
41	1	FRT FENDER TOP GARNISH RH	ne ne	2	112.00
42	1	RR BUMPER	Delind	\$	89.00
43	1	RR BUMPER CHROME MLDG RH	2	\$	1,256.00
44	1	RR BUMPER CHROME MLDG LH	Tue	\$	152.00
45	1	RR BUMPER CHROME MLDG CEN	TRE	\$	152.00
46	1	RR BUMPER REINFORCEMENT	Nen	\$	205.00
47	I	RR BUMPER SIDE RETAINER LH(I	NIVERY 2	- 8	736.00
48	I	RR BUMPER SIDE RETAINER LH(NITERY CALL	S .	116.00
49	1	RR BUMPER CENTRE RETAINER		\$	116.00
50	1	RR BUMPER SIDE RETAINER RH(I	Nen	S	130.00
51	1	RR BUMPER SIDE RETAINER RH(NNER) Gree	\$	116.00
52	Ť	RR BUMPER REVERSE SENSOR		S	116.00
53	1		* Ne m	\$	215.00
00	-1	RR BUMPER REVERSE SENSOR RI	UBBER SEAL 3	\$	13.00

Parts Total: \$

23,004.00

Less10%: \$

2,300.40

Total: \$

20,703.60

Labour

Labour Description

To dismantia / reason the	Price (SGD)	
beating,reshape,straighten,orientate and align repair /replacement parts.	\$ 3,300.00	2200
Carry out spray painting on affected area	\$ 2,500,00	175
To disconnect front wire harness of electrical component to facilitate		Company of the Compan
To remain and check electrical function after repair	\$ 120.00	60
system system	\$ 220.00	180
To remove and refix radiator and conduct procesure test	\$ 120.00	60
֡֡֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜֜	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair. To remove and refit aircon condensor, vacuum, refill and check air con gas.	beating,reshape,straighten,orientate and align repair /replacement parts. Carry out spray painting on affected area To disconnect front wire harness of electrical component to facilitate repairs,reconnect and check electrical function after repair To remove and refit aircon condensor,vacuum,refill and check air con gas \$ 2,500.60 \$ 120.60

Labour Total: \$

6,260.00

Others

Other Description

No.	FRT NUMBER PLATE			Price (SGD)	
2		mcc		\$ 65	.00 -
2	RADIATOR COOLANT	pe			00-5
			Other Total:		-

29,233.60

145.00

TOTAL: \$ GST (7%): \$

27,108.60

29.021.10

1,897.60

GRAND TOTAL: \$

29,006.20

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor

Adrian hiny.
P/P 15/10/18.

SUPPLEMENTARY

VEHICLE NO: SDD1284

QTY PARTS DESCRIPTION	PRICE
1 Alc Condenser bracket RH Bet	125
1 Fed Bumps Tow Cove Deld	94
1 P.S.F Cooler Best	659
1 A/c Compresser belt snapped	118
1 Alc & Gas Pressury reason and	197
1 A.T.F Cooler Best	932
The court box	127



FINALIZE

LONPAC INSURANCE BHD

GST Ref. No:

20-0000274-Z

Drive (SCD)

Vehicle No: SDD128Y

Invoice No:

Chasis No: KL1JA69E9GK346784

Engine No: F16D1460880475 Date of accident :11/10/2018 Invoice Date:

DESCRIPTION

Parts

AMOUNT SGD

No.	Qty.	Description	Price (SGD)
1	1	FRT BONNET	\$ 1,650.00
2	1	FRT BONNET RUBBER SEAL , FRONT	\$ 93.00
3	1	FRT BONNET RUBBER SEAL , RH	\$ 71.00
4	1	FRT BONNET RUBBER SEAL , LH	\$ 71.00
5	5	FRT BONNET INSULATOR CLIP	\$ 30.00
6	1	FRT BUMPER	\$ 1,446.00
7	1	FRT BUMPER LOW CENTER GRILLE	\$ 274.00
8	1	FRT BUMPER LOGO	\$ 204.00
9	1	FRT NUMBER PLATE BASE	\$ 40.00
10	5	FRT BUMPER CLIP	\$ 30.00
11	1	FRT BUMPER SIDE RETAINER LH	\$ 86.00
12	1	FRT BUMPER SIDE RETAINER RH	\$ 86.00
13	1	FRT BUMPER SPONGE	\$ 140.00
14	1	FRT BUMPER REINFORCEMENT	\$ 1,030.00
15	1	FRT SUPPORT PANEL TOP GARNISH	\$ 227.00
16	1	FRT BUMPER GRILLE , UPPER	\$ 352.00
17	1	FRT BUMPER GRILLE , LOWER	\$ 526.00
18	1	RH HEADLAMP	\$ 2,702.00
19	1	LH HEADLAMP	\$ 2,702.00
20	1	RADIATOR	\$ 1,098.00
21	2	RADIATOR TOP MOUTING	\$ 126.00
22	2	RADIATOR BRACKET LOWER	\$ 220.00
23	1	A/C CONDENSER	\$ 1,052.00
24	1	INTAKE AIR DUCT AIR HOSE (air duct to resonator box)	\$ 224.00
25	1	INTAKE AIR RESONATOR BOX	\$ 328.00
26	1	FRT FOG LAMP RH	\$ 298.00
27	1	FRT FOG LAMP COVER RH	\$ 130.00
45 7500	100	The state of the s	

1

1

FRT BUMPER LOWER LIP

FRT FENDER INNERSHIELD RH

FRT FENDER RH

FRT BUMPER UNDER DUST COVER, deflector

28

29

30

31

\$

S

\$

5

120.00

135.00

832.00

228.00

32	1	RR BUMPER	\$ 1,256.00
33	1	RR BUMPERCHROME MLDG RH	\$ 152.00
34	1	RR BUMPER CHROME MLDG LH	\$ 152.00
35	- 1	RR BUMPER CHROME MLDG CENTRE	\$ 205.00
36	1	RR BUMPER SIDE RETAINER LH (INNER)	\$ 116.00
37	1	RR BUMPER SIDE RETAINER LH (OUTER)	\$ 116.00
38	1	RR BUMPER SIDE RETAINER RH (INNER)	\$ 116,00
39	1	RR BUMPER SIDE RETAINER RH (OUTER)	\$ 116.00
40	1		A REST
	1		Comban ETC ETC SANCE

Supplementry

1	1	A/C CONDENSER BRACKET RH	\$ 125.00
2	1	FRT BUMPER TOW COVER	\$ 94.00
1		P.S.F COOLER	\$ 659,00
1	-	A/C COMPRESSER BELT	\$ 118.00
1		A/C GAS PRESSURE SENSOR	\$ 197.00
1	-	A.T.F COOLER	\$ 932.00

Total: \$ 20,905.00

Special Less 30%: \$ 6,271.50

Parts Total: \$ 14,633.50

Labour

No.		Price	(SGD)
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIRED / REPLACEMENT PARTS.	s	2,200.00
2	CARRY OUT SPRAY PAINTING OF ACCIDENT AFFECTED AREA.FRT FENDER LH, FRT DOOR LH, RR DOOR LH, RR FENDER LH,ROCKER PANEL LH, RR BUMPER	\$	1,750.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	\$	60.00
	TO REMOVE AND REFIT AIRCON CONDENSOR, VACUUM, REFILL AND CHECK AIR CON GAS SYSTEM	\$	180.00
4	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$	60.00

Labour Total: \$ 4,250.00

Other

No.		Price	(SGD)
1 1	FRONT NUMBER PLATE	\$	65.00
2 1	RADIATOR COOLANT	\$	50.00
	Other Total :	\$	115.00
	Total:	\$	18,998.50
	Less Lump Sum 20% :	S	3,799.70
	Total Lum Sum Amount :	\$	15,198.80
	Amount Agree :	\$	15,000.00
	Excess:	\$	
	GST (7%):	\$	1,050.00

Grand Total: \$

16,050.00

Yours Faithfully,

Kelvin Chew Service Advisor

Tel: 68441985 Fax:68445185

Please check and finalize with me

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Tuesday, 11 December 2018 4:39 PM

To:

'Kelvin.chew@alpinemotors.sg'; SUR

Cc:

suhaimi@firstautoworks.com.sg

Subject:

RE: SDD 128 Y CHEVROLET CRUZE LONPAC OD DOA 11.10.2018 FINALIZE

Dear Kelvin,

Lump sum \$15,000.00 confirm excess waived @ 6 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kelvin Chew <Kelvin.chew@alpinemotors.sg>

Sent: Thursday, 6 December 2018 9:08 PM

To: SUR <sur@lkkauto.com>

Cc: suhaimi@firstautoworks.com.sg

Subject: SDD 128 Y CHEVROLET CRUZE LONPAC OD DOA 11.10.2018 FINALIZE

Hi Lkk.

attach is finalize report.

lump sum as amount agree \$15,000.00, excess waived @ 6 working days. kindly please check & confirm with me. thanks.

from, kelvin chew 8292 5595

The information contained in this message is intended only for the recipient, and may be a confidential altomoy-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

LON	IPAC INSURANCE	BHD	Ref : CS/LPC180186	65/Avd3e2
	BEACH ROAD 04/07 THE CONC	OURSESINGAPORE 199555	Date: 14-12-2018 Code: LPC2	
١.		Policy Particul	ars :- OWN DAMAGE	
	Insured Veh.		Veh. Inspected	SDD 128Y
	Policy No.	Z17VP05016168	Coverage (\$)	0.00
	Claim No.	17/18/18/VP05/021013	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	15/10/2018
2.		Vehicle Parti	culars & Condition	
	Make & Model	CHEVROLET CRUZE	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KL1JA69E9GK346784	Colour	WHITE
	Odometer	40294	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Condit	ions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	HIFLY	6 mm
	L/H Front Tyre	215/60 R16	HIFLY	6 mm
	R/H Rear Tyre	215/60 R16	кимно	6 mm
	L/H Rear Tyre	215/60 R16	KUMHO	6 mm
4.		Descripti	on of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE FR	ONT PORTION.	
	DAMAGES SEE D	ETAILS.		
5,		Genera	I Information	
	Accident Date	11/10/2018	Inspection Date	15/10/2018
	Survey held at	1ST AUTOWORKS PTE LTD		
		23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933		
5a.		R	emarks	HE LEVEL IN THE
	A)THE MARKET V	ALUE IS S\$68,000.00(EST. AVE	RAGE) VE HAVE AUTHORISED R	REPAIRS.
5b.			Days of Repair	
1000	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	6 Working Day	16



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDD 128Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BONNET	DENTED	1,650.00	1,650.00
1	FRT BONNET RUBBER SEAL, FRONT	NECESSARY	93.00	93.00
1	FRT BONNET RUBBER SEAL, RH	NECESSARY	71.00	7.1.00
1	FRT BONNET RUBBER SEAL, LH	NECESSARY	71.00	71.00
1	FRT BONNET LOCK	NOT NECESSARY	168.00	
10	FRT BONNET INSULATOR CLIP	NECESSARY	65.00	30.00
1	FRT BUMPER	DISTORTED	1,446.00	1,446.00
1	FRT BUMPER LOW CENTER GRILLE	DEFORMED	274.00	274.00
1	FRT BUMPER LOGO	NECESSARY	204.00	204.00
1	FRT NUMBER PLATE BASE	CRACKED	40.00	40.00
10	FRT BUMPER CLIP	NECESSARY	65.00	30.00
1	FRT BUMPER SIDE RETAINER LH	NECESSARY	86.00	86.00
1	FRT BUMPER SIDE RETAINER RH	NECESSARY	86:00	86.00
1	FRT BUMPER SPONGE	CRACKED	140.00	140.00
1	FRT BUMPER REINFORCEMENT	BENT	1,030.00	1,030.00
1	FRT SUPORT PANEL TOP GARNISH	DEFORMED	227.00	227.00
1	FRT BUMPER GRILLE, UPPER	CRACKED	352.00	352.00
1	FRT BUMPER GRILLE, LOWER	CRACKED	526.00	526.00
1	RH HEADLAMP	CRACKED	2,702.00	2,702.00
1	LH HEADLAMP	CRACKED	2,702.00	2,702.00
1	RADIATOR SUPORT PANEL TOP	NOT NECESSARY	420.00	
1	RADIATOR	BENT	1,098.00	1,098.00
1	RADIATOR FAN COWLING	NOT NECESSARY	379.00	
1	RADIATOR FAN BLADE & MOTOR	NOT NECESSARY	783.00	
2	RADIATOR BRACKET UPPER	NOT NECESSARY	176.00	-
2	RADIATOR TOP MOUNTING	DAMAGED	126.00	126.00
2	RADIATOR BRACKET LOWER	DAMAGED	220.00	220.00
1	RADIATOR TOP HOSE, INLET	NOT NECESSARY	118.00	
1	RADIATOR LOW HOSE, OUTLET	NOT NECESSARY	162.00	1
1	TURBO INTAKE COOLER	NOT NECESSARY	653.00	
1	A/C CONDENSER	BENT	1,052.00	1,052.00
1	INTAKE AIR DUCT AIR HOSE (AIR DUCT TO RESONATOR BOX)	DEFORMED	224.00	224.00
1	INTAKE AIR RESONATOR BOX	DEFORMED	328.00	328.00

Report Ref No. CS/LPC18018665/Avd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT FOG LAMP RH	DAMAGED	298.00	298.00
1	FRT FOG LAMP COVER RH	DEFORMED	130.00	130.00
1	FRT BUMPER LOWER LIP	DEFORMED	120.00	120.00
1	FRT BUMPER UNDER DUST COVER, DEFLECTOR	DEFORMED	135.00	135.00
1	FRT FENDER RH	BUCKLED	832.00	832.00
1	FRT FENDER INNERSHIELD RH	CUT	228.00	228.00
1	FRT FENDER BRACKET RH	NOT NECESSARY	112.00	
†	FRT FENDER TOP GARNISH RH	NOT NECESSARY	89.00	
1	RR BUMPER	DEFORMED	1,256.00	1,256.00
1	RR BUMPER CHROME MLDG RH	NECESSARY	152.00	152.00
- 1	RR BUMPER CHROME MLDG LH	NECESSARY	152.00	152.00
1	RR BUMPER CHROME MLDG CENTRE	NECESSARY	205.00	205.00
1	RR BUMPER REINFORCEMENT	NOT NECESSARY	736.00	
1	RR BUMPER SIDE RETAINER LH (INNER)	NECESSARY	116.00	116.00
1	RR BUMPER SIDE RETAINER LH (OUTER)	NECESSARY	116.00	116.00
1	RR BUMPER CENTRE RETAINER	NOT NECESSARY	130.00	
1	RR BUMPER SIDE RETAINER RH (INNER)	NECESSARY	116.00	116.00
1	RR BUMPER SIDE RETAINER RH (OUTER)	NECESSARY	116.00	116.00
1	RR BUMPER REVERSE SENSOR	NOT NECESSARY	215.00	
1	RR BUMPER REVERSE SENSOR RUBBER SEAL	NOT NECESSARY	13.00	
1	A/C CONDENSER BRACKET RH (ADDITIONAL)	BENT	125.00	125.00
1	FRT BUMPER TOW COVER (ADDITIONAL)	DEFORMED	94.00	94.00
1	P.S.F COOLER (ADDITIONAL)	BENT	659.00	659.00
1	A/C COMPRESSER BELT (ADDITIONAL)	SNAPPED	118.00	118.00
1	A/C GAS PRESSURE SENSOR (ADDITIONAL)	DAMAGED	197.00	197.00
1	A.T.F COOLER (ADDITIONAL)	BENT	932.00	932.00
	LESS 10% DISCOUNT		-2,512.90	
	LESS 30% DISCOUNT			-6,271.50
			22,616.10	14,633.50
	SPECIAL NETT ITEMS			
1	FRT NUMBER PLATE (SN)	CRACKED	65.00	65.00
1	RADIATOR COOLANT (SN)	NECESSARY	80.00	50.00
	62 1120		145.00	115.00



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS.		3,300.00	2,200.00
	CARRY OUT SPRAY PAINTING ON AFFECTED AREA.		2,500.00	1,750.00
	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		120.00	60.00
	TO REMOVE AND REFIT AIRCON CONDENSOR, VACUUM, REFILL AND CHECK AIR CON GAS SYSTEM.		220.00	180.00
	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.		120.00	60.00
			6,260.00	4,250.00
	GRAND TOTAL		29,021.10	18,998.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			15,000.00

Report Ref No. CS/LPC18018665/Avd3e2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsuever, in contact or lost, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.