



FINAL REPORT

Estimate No. : **b1 48659**
Date Estimated : **03/10/2018**
Prepared By : **Han Kwan Yong**

Page No. :

REPAIR FOR -
Lee Jim Hiang
Blk 341 Bukit Batok Street 34
#08-66

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 650341

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SLM2598T	0F72669	30/09/2016	X3 xDrive28i	0
DESCRIPTION		ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include knocking out dented areas caused by the accident		850.00		850.00
To respray rear bumper		934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function		150.00		150.00
Sundries		80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
COVER MIDDLE BOTTOM	70.40	1.00		70.40
# REAR BUMPER CLADDING (PDC/SCHWARZ) *	202.25	1.00		202.25
REAR BUMPER PANEL PRIMED (XLINE/PDC	1,444.70	1.00		1,444.70
UNDERRIDE GUARD PRIMED REAR (X LINE	260.00	1.00		260.00
C CLIP NUT	1.30	10.00		13.00

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,990.35
Total Labour & Parts :	4,004.35
Deduction for Excess :	0.00
Total Repair Costs less Excess:	4,004.35
GST @7%:	280.30
Grand Total :	4,284.65