

(08/11/13)

Surveyor: Kelvin

REF: NS/INC18018676 / Klsbnz

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SLK 4559DPolicy No: 5097209192 170118 - 160119Claims No: MT/1015454 - 002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD 7183T Yr Regn: 17 Nov 2006

Type: M.Car / M.Cycle / Bus / Van / Lorry / T.O. / Prime Mover /

Truck / Trailer or

Make: Hyundai cc 1685Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 383252 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLB414AH4096415Gen. Cond: Good / OK / Poor / BurntSteering: Ignored / OK / Jammed / Leaked / Burnt orBrake: Ignored / OK / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Canyon

Front Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 12/10/18 D.O.I. 15/10/18Survey held at CHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHD 7183T - CC4 / M18012035 / Ajb3
	SLK 4559D - X
17/10/18	Confirmed P/P \$ 2858.72 / 3 Pys.
18/10/18	Confirmed P/P \$ 2,858.72 @ 3 days with Kelvin. (\$ 398.32 Ad - 12%)
	RECEIVED 18 OCT 2018
	C15

Date/Time, File Pass to?

☐ : Prel. Report1) Typist☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$) 2,858.72

160

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)
[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="12/10/2018 16:53"/>							
Vehicle No.(For Motor)	<input type="text" value="SLK4559D"/>	Certificate Number	<input type="text"/>							
<input type="button" value="Search"/>										
Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5097209192		JUHARI BIN KASSIM	S1372612D	GPC	drive CLASSIC	SLK4559D	SLK4559D	17/01/2018	16/01/2019
<input type="button" value="Continue"/>										

TP Claims against NTUC Income: Follow-Through Survey

Date : 18/10/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/1015866-002	COMFORT TRANSPORTATION PTE LTD	SHA 2203T	SIH 3736E	13/10/2018	\$ 1,828.53	\$ 1,644.00
2	MT/1015454-002	COMFORT TRANSPORTATION PTE LTD	SHD 7183T	SLK 4559D	12/10/2018	\$ 3,257.04	\$ 2,858.72

Claim received from LKK Auto

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/10/2018 11:09
Date Of Accident	12/10/2018 22:15
Exact Location Of Accident	TAMPINES ST 23 TOWARDS TAMPINES AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD7183T
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	NEO ENG HOE
NRIC No	S1272092J
Date Of Birth	12/01/1957
Occupation	OUTDOOR
Date Of Driving Pass	19/10/1978
Driving Experience	39 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90073883
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	124 #07-1442 HOUGANG AVENUE 1
Postcode	530124
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : MALE
Passenger 3	NAME: : - GENDER: : MALE
Passenger 4	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK4559D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver	JUHARI BIN KASSIM
NRIC/Passport Number	S1372612D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	LEFT FRT
No. Of Passenger (Including Driver)	

SKETCH PLAN

A = 2HD7183T
B = SLK459TD
(Nissan)

Tampines Ave 2

Tampines
St 23

BLK
201

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Kindly refer statement as per attached.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
COMFORT TRANSPORTATION PTE LTD
CO. REG NO 199303821R

Policyholder's Signature

Driver's Signature

Reporting Centre Personnel's Signature

H2SIDE : JUNCTION

On the 12/10/2018 @ about 22:15hrs, I was driving along Tampines St 23 towards Tampines Ave 2.

As a result vehicle SLK4559D left front collided onto my right front of my taxi.




03 male and 01 female passenger on board my taxi and no injury reported at the point of
accident.


I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature/Date &
Time

Driver's Signature (If driver is not the policyholder)/Date
& Time

Witnessed by Reporting
Centre Personnel





REPAIR ESTIMATE*

VEHICLE NO : SH 7183T

MAKE :

MODEL : HYUNDAI i40

DATE 15/10/2018 9:33

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover — cm			\$ 544.50
	Front Bumper Bracket Top (RH) X 5cm			\$ 22.40
	Front Bumper Bracket (RH) — cm			\$ 24.60
	Headlamp (RH) — cm			\$ 1,388.00
	Front Fender (RH) — cm			\$ 566.30
	Front Fender Shield (RH) X 5cm			\$ 175.90
	Front Fender Retainer X 5cm			\$ 24.60
SUB TOTAL				\$ 2,746.30
LESS 20%				\$ 549.26
DISCOUNTED TOTAL				\$ 2,197.04
	Front Fender Advertisement Logo (RH) — cm			\$ 100.00
				\$ 100.00
Labour Charge				\$ 300
Panel Beating				\$ 440.00
Spray Painting Charge				\$ 440.00
Wiring				\$ 30.00
Tuff Kote				\$ 50.00
TOTAL LABOUR				\$ 960.00
ESTIMATE TOTAL				\$ 3,257.04

Nett

400

20

20

Kala 10/10/14

15/10/18 1045h

3 Dg

PIP

Before Paint photo

LKK Auto Consultants to be notified
the Repairer of the following:

- To resurvey before any painting
- To display damaged parts during resurvey
- Parts prices are subject to the repairer's own
- Third party survey is on a 'no liability' basis
- No illegal modification is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Date/Time: 13.10.2018 12:12

Page : 1

member of COMFORTDELGRO

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order: 3864624

JC NO.: 305225500

OMER
IS COMFORT TRANSPORTATION PTE LTD
OMER NO. 7010045
IESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)

REGN NO.: SHD7183T	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 13.10.2018 08:50
YR OF MANU. 17.11.2016	TARGET DATE
CHASSIS CODE KMHLB41UMHU096415	COMPLETION DATE/TIME:

JUNT CARD NO.


JOB DESCRIPTION

Accident Date: 12.10.2018
NATURE: 3P 12.10.18/B-

NTUC

S/NO LABOR CODE

DESCRIPTION



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHD7183T

FZ NTUC

Vehicle No.:

SHD7183T

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305225500
REGN NO : SHD7183T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 17.11.2016
DATE/TIME IN : 13.10.2018 08:50
ACCIDENT DATE : 12.10.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1	544.50	20.00	435.60
0002 04-01-0103-0638-G	I40V2 BRKT ASSY-FR BPR UP	1	24.60	20.00	19.68
0003 04-01-0103-0782-A	I40V2 LAMP ASSY-HEAD RH#	1	1,388.00	20.00	1,110.40
0004 04-01-0103-0573-A	I40VC PANEL-FENDER RH+	1	566.30	20.00	453.04

SUB-TOTAL : 2,018.72

JOB NATURE

0000 L	PANEL BEATING	300.00
0001 L	SPRAY PAINTING CHARGE	400.00
0002 L	WIRING CHARGE	20.00
0003 L	TUFF KOTE	20.00
0004 20-05	RENEW ADVERTISEMENT FRONT FENDER RH	100.00

SUB-TOTAL : 840.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305225500
REGN NO : SHD7183T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 17.11.2016
DATE/TIME IN : 13.10.2018 08:50
ACCIDENT DATE : 12.10.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,858.72

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305225500
Date : 17.10.2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN
Vehicle Reg No. : SHD7183T

Fax :

Date of Accident : 12.10.2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SLK4559D
2. The finalized amount shall be:


(a) Spare Parts after List discount		\$2,018.72
(b) Labour Charges		\$840.00
Total for Part-By-Part Repair Cost		\$2,858.72
(c.) Lumpsum Repair (if applicable)		
Total for Lumpsum repair cost after Less:	20%	\$0.00
Final Lumpsum Repair cost		\$0.00


3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : FAUZY BIN MOKHTAR
Tel : 62148319
Fax : 65468156

Signature : 
Name : Kalvin
Date : 17/10/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18018676/K1sbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 26-10-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 4559D	Veh. Inspected	SHD 7183T
Policy No.	5097209192	Coverage (\$)	0.00
Claim No.	MT/1015454-002	Excess (\$)	0.00
Assign From		Assign Date	15/10/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMHU096415	Colour	BLUE
Odometer	383252	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	CAMPEON	7 mm
L/H Front Tyre	205/60 R16	CAMPEON	7 mm
R/H Rear Tyre	205/60 R16	CAMPEON	7 mm
L/H Rear Tyre	205/60 R16	CAMPEON	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/10/2018	Inspection Date	15/10/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7183T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER COVER	CRACKED	544.50	544.50
1	FRONT BUMPER BRACKET TOP (RH)	SERVICEABLE	22.40	-
1	FRONT BUMPER BRACKET (RH)	CRACKED	24.60	24.60
1	HEADLAMP (RH)	CRACKED	1,388.00	1,388.00
1	FRONT FENDER (RH)	DENTED	566.30	566.30
1	FRONT FENDER SHIELD (RH)	SERVICEABLE	175.90	-
1	FRONT FENDER RETAINER	SERVICEABLE	24.60	-
	LESS 20% DISCOUNT		-549.26	-504.68
			2,197.04	2,018.72
SPECIAL NETT ITEMS				
1	FRONT FENDER ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
			100.00	100.00
LABOUR				
	PANEL BEATING.		440.00	300.00
	SPRAY PAINTING CHARGE.		440.00	400.00
	WIRING.		30.00	20.00
	TUFF KOTE.		50.00	20.00
			960.00	740.00
GRAND TOTAL			3,257.04	2,858.72
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,858.72

Report Ref No. NS/INC18018676/K1sbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.